



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SLL4878C

CLAIM TYPE : THIRD PARTY

TP INS. CO. : FWD SINGAPORE PTE LTD

ACCIDENT DATE : 24/04/2019

TP VEH REG NO : SLL4878C

ESTIMATE

NO : QUOT201904-000097(00)

DATE : 26/04/2019

POLICY NO : 999995580

VEH REG NO : GBD3295B

MAKE/MODEL : PEUGEOT PARTNER 1.6 HDI
ETG LWB

CHASSIS NO : VF37F9HF8EJ735567

ENGINE NO : 10JBFR0012800

REG. DATE : 2014

Estimate Repair Cost to Vehicle No : GBD3295B

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Rear door - RH	1	1,200.00	1,200.00
2 Rear door 'PARTNER' emblem - RH	1	122.00	122.00
3 Rear door 'e HDI' emblem - RH	1	102.00	102.00
4 Rear door trimboard - RH	1	355.00	355.00
5 Rear door inner trimboard clips - RH	10	6.00	60.00
6 Rear door - LH	1	1,320.00	1,320.00
7 Rear door 'PEUGEOT' emblem - LH	1	123.00	123.00
8 Rear door inner trimboard clips - LH	10	6.00	60.00
9 Rear end panel (outer)	1	380.00	380.00
10 Rear bumper	1	550.00	550.00
11 Rear bumper pad - RH / LH	2	280.00	560.00
12 Rear bumper tow cover	1	39.00	39.00
			4,871.00
		Less 10%	487.10
			4,383.90
SPECIAL NET			
13 Rear door glass sealant - RH	1	50.00	50.00
14 Rear door glass sealant - LH	1	50.00	50.00
15 Rear bumper reverse sensor (set)	1	380.00	380.00
16 Rear door '70km/h' sticker - LH	1	25.00	25.00
17 Rear door '6pax' sticker - RH	1	15.00	15.00
18 Rear number plate	1	40.00	40.00
			560.00
LABOUR			
19 To check and rectify wiring system	1	80.00	80.00
20 To remove and refix both side door glass	1	200.00	200.00
21 To transfer both side rear door interior mechanism to new door	1	200.00	200.00
22 To panel beat rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
23 To putty and spray paint on affected areas	1	1,000.00	1,000.00
24 To apply rust-proofing on repaired and replaced panels	1	120.00	120.00
25 To supply and paste sticker on both side rear door	1	680.00	680.00
			3,280.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SLL4878C

CLAIM TYPE : THIRD PARTY

TP INS. CO. : FWD SINGAPORE PTE LTD

ACCIDENT DATE : 24/04/2019

TP VEH REG NO : SLL4878C

ESTIMATE

NO : QUOT201904-000097(00)

DATE : 26/04/2019

POLICY NO : 999995580

VEH REG NO : GBD3295B

MAKE/MODEL : PEUGEOT PARTNER 1.6 HDI
ETG LWB

CHASSIS NO : VF37F9HF8EJ735567

ENGINE NO : 10JBFR0012800

REG. DATE : 2014

Estimate Repair Cost to Vehicle No : GBD3295B

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 8,223.90
		ADD GST @ 7%	575.67
		GRAND TOTAL	S\$ 8,799.57

SINGAPORE DOLLAR EIGHT THOUSAND SEVEN HUNDRED NINETY-NINE AND CENTS FIFTY-SEVEN ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE