



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SLL4878C

CLAIM TYPE : THIRD PARTY

TP INS. CO. : FWD SINGAPORE PTE LTD

ACCIDENT DATE : 24/04/2019

TP VEH REG NO : SLL4878C

ESTIMATE

NO : QUOT201904-000097(00)

DATE : 26/04/2019

POLICY NO : 999995580

VEH REG NO : GBD3295B

MAKE/MODEL : PEUGEOT PARTNER 1.6 HDI
ETG LWB

CHASSIS NO : VF37F9HF8EJ735567

ENGINE NO : 10JBFR0012800

REG. DATE : 2014

Not Authorized

U/Sy B?

Missing After Paint

5-6 days

29/4/19 @ 1145 hrs

Estimate Repair Cost to Vehicle No : GBD3295B

Description	Quantity	Unit Price S\$	Amount S\$
LIST PRICE	1	Rt 1,200.00	1,200.00
1 Rear door - RH	1	122.00	122.00
2 Rear door 'PARTNER' emblem - RH	1	102.00	102.00
3 Rear door 'e HDI' emblem - RH	1	CM 355.00	355.00
4 Rear door trimboard - RH	10	6.00 50SN	60.00
5 Rear door inner trimboard clips - RH	1	Rt 1,320.00	1,320.00
6 Rear door - LH	1	123.00	123.00
7 Rear door 'PEUGEOT' emblem - LH	10	6.00 50SN	60.00
8 Rear door inner trimboard clips - LH	1	380.00	380.00
9 Rear end-panel (outer)	1	Bu 550.00	550.00
10 Rear bumper	1	280.00	280.00
11 Rear bumper pad - RH	1	39.00	39.00
12 Rear bumper tow cover			4,871.00
Rear bumper reinforcement		Less 10%	487.10
			4,383.90
SPECIAL NET			
13 Rear door glass sealant - RH	1	50.00	50.00
14 Rear door glass sealant - LH	1	50.00	50.00
15 Rear bumper reverse sensor (set)	1	380.00	380.00
16 Rear door '70km/h' sticker - LH	1	25.00	25.00
17 Rear door '6pax' sticker - RH	1	15.00	15.00
18 Rear number plate	1	40.00	40.00
LABOUR			
19 To check and rectify wiring system	1	80.00	80.00
20 To remove and refix both side door glass	1	200.00	200.00
21 To transfer both side rear door interior mechanism to new door	1	200.00	200.00
22 To panel beat rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
23 To putty and spray paint on affected areas	1	1,000.00	1,000.00
24 To apply rust-proofing on repaired and replaced panels	1	120.00	120.00
25 To supply and paste sticker on both side rear door	1	680.00	680.00
			3,280.00
			1960



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :
ATTN : ACCOUNTS DEPT

YOUR REF NO : SLL4878C
CLAIM TYPE : THIRD PARTY
TP INS. CO. : FWD SINGAPORE PTE LTD
ACCIDENT DATE : 24/04/2019
TP VEH REG NO : SLL4878C

ESTIMATE

NO : QUOT201904-000097(00)
DATE : 26/04/2019
POLICY NO : 999995580
VEH REG NO : GBD3295B
MAKE/MODEL : PEUGEOT PARTNER 1.6 HDI
ETG LWB
CHASSIS NO : VF37F9HF8EJ735567
ENGINE NO : 10JBFR0012800
REG. DATE : 2014

Estimate Repair Cost to Vehicle No : GBD3295B

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 8,223.90
		ADD GST @ 7%	575.67
		GRAND TOTAL	S\$ 8,799.57

SINGAPORE DOLLAR EIGHT THOUSAND SEVEN HUNDRED NINETY-NINE AND CENTS FIFTY-SEVEN ONLY

\$ 6,344.40
20% 1,268.88
\$ 5,075.52

Lump Sum \$ 5,050.00
7% 353.50
\$ 5,403.50

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

**PRINTLAB**

redefining print

PRINT LAB PTE LTD25 Ubi Road 4 #01-01 Weltech Building Singapore 408621
Tel : 6749 0526 Fax : 6749 0683 Email: info@printlab.com.sgCo. Reg No. 200711847C
GST No. 200711847-C**Sold To:**Tong Luck Auto Pte Ltd
160 Sin Ming Drive
#07-01/06 Sin Ming Autocity
Singapore 575722

Attn: Terence Tan

Tel: 6250 0088

TAX INVOICE**Invoice No** : IV-111804**Date** : 06-May-19

Reference No.	Customer P.O. No.	Payment Terms	Due Date	Job Issue By
Q00023334		0	06/05/19	Terence
Quantity	Description	Unit Price	Total Amount	
1	RE: Peugeot_GBD3295B Peugeot_Back only_GBD3295B Subject : L_062G_070G_SCHNEIDER_1200x200MM_1PC Material : Block Out Sticker (MB) Finishing : Size: 1200mm (W) x 200mm (H)	400.00	400.00	

Please note that any overdue payment/s will be listed in the Singapore Commercial Credit Bureau (SCCB) records and this record may be assessed by financial institutions and other approving Credit companies.

*** BANK Information**Name: PRINT LAB PTE LTD
Bank Name: Standard Chartered Bank, Singapore Branch
Bank Code: 7144
Branch Code: 001
Account No.: 0119156865
Swift code: SCBLSGSG
Address: 6 Battery Road Singapore 049909**Subtotal****400.00****GST@7%****28.00****Total (SGD)****428.00****Received, checked & accepted by**

E. & O.E

**This is a computer generated form.
No signature is required.**

Cheques should be crossed and made payable to PRINT LAB PTE LTD
All goods sold are not refundable. Interest at 1.5% per month will charged on unpaid invoices.