



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

29 April 2019

REG NO. : SJK 4989 U
MAKE/MODEL : HONDA JAZZ

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear windscreen glass	\$ 686.20
1	Rear windscreen moulding	\$ 82.90
1	Rear tailgate	\$ 762.20
2	Rear tailgate dampers	\$ 219.00
2	Rear tailgate hinges	\$ 85.00
1	Rear tailgate inner handle	\$ 42.50
1	Rear tailgate inner lock	\$ 168.50
1	Rear tailgate inner trim board	\$ 194.40
1	Rear tailgate logo	\$ 22.50
1	Rear tailgate outer garnish	\$ 112.30
1	Rear tailgate rubber	\$ 89.80
1	Rear tailgate third brake lamp	\$ 115.00
1	Rear tailgate "JAZZ" emblem	\$ 28.80
1	Rear wiper arm	\$ 23.70
1	Rear wiper arm cover	\$ 18.50
1	Rear wiper motor	\$ 237.80
2	Rear taillamps	\$ 774.00
2	Rear taillamp panels	\$ 251.60
1	Rear end panel	\$ 296.60
1	Rear end panel inner garnish	\$ 58.40
1	Rear bumper	\$ 520.80
2	Rear bumper brackets	\$ 116.00
2	Rear bumper side retainers	\$ 37.20
1	Rear spare tyre board	\$ 179.70
1	Rear spare tyre panel	\$ 737.00
1	Rear spare tyre tool sponge tray	\$ 195.00
1	Rear exhaust silencer	\$ 462.40
2	Rear exhaust mountings	\$ 57.00
1	Rear exhaust heat shield	\$ 89.50
1	Rear fender -R/H	\$ 614.40
1	Rear fender air gate	\$ 28.50
1	Rear fender inner shield	\$ 48.60
2	Rear fender inner trim boards	\$ 393.00
1	Rear fender quarter glass inner seal	\$ 80.00
		\$ 7,828.80
Less 20%		\$ 1,565.76
		\$ 6,263.04

SPECIAL NETT ITEMS

1	Rear windscreen sealant	\$	80.00
1	Rear tailgate top spoiler	\$	650.00
1	Rear wiper blade	\$	45.00
1	Rear bumper clip (1 set)	\$	50.00
1	Rear number plate with holder	\$	50.00
1	Rear reverse sensor (1 set)	\$	350.00
1	Rear fender quarter glass sealant	\$	50.00
			<hr/>
		\$	1,275.00

S/N**LABOUR CHARGES**

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00
2	To remove and refit inner garnishes.	\$	150.00
3	To remove and refit rear reverse sensor.	\$	150.00
4	To transfer rear tailgate mechanism and wiring assembly.	\$	120.00
5	To remove and refit rear windscreen glass.	\$	180.00
6	To remove, refit and replace exhaust silencer and mountings.	\$	150.00
7	To apply undercoating.	\$	200.00
8	Panel beating.	\$	1,600.00
9	To re-spray painting on the affected areas.	\$	1,500.00
			<hr/>
		\$	4,130.00

GRAND TOTAL :

\$ 11,668.04
