

REPAIR ESTIMATE\*

VEHICLE NO : SHC 2188T

DATE 29/4/2019 11:17

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender (RH) ✓			\$ 593.00
	Front Fender Shield (RH) X			\$ 86.00
	Front Fender Retainer X			\$ 9.20
	Front Wheel Hub Cap (RH) X			\$ 145.00
	Front Bumper X Repair			
	<b>SUB TOTAL</b>			<b>\$ 833.20</b>
	<b>LESS 20%</b>			<b>\$ 166.64</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 666.56</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>400.00</del> <sup>200</sup>
	Spray Painting Charge-Bumper/Fender			\$ <del>600.00</del> <sup>400</sup>
	Tuff Kote			\$ <del>50.00</del> <sup>20</sup>
	FRT Wheel Alignment			\$ <del>80.00</del> <sup>10</sup>
	<i>Mina Fe</i>			
	<b>TOTAL LABOUR</b>			<b>\$ 1,130.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 1,796.56</b>
<p><i>Kalvin</i></p> <p><i>29/4/19 1150h</i></p> <p><i>2 hrs</i></p> <p><i>U/S</i></p> <p><i>After Repair photo.</i></p>				
<div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modifications is allowed</li> <li>• Supply company name(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				