

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

CARRO LEASING PTE LTD
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

TP AXA

'30th APRIL 2019

Vivian.

Accident date: 27th APRIL 2019

Estimated repair cost for vehicle no: SLE6505C HONDA VEZEL 1.5X A

S/n	Qty	Items	U/price	Amount	
1	1	Front R/H fender <i>Dented</i>		\$705.00	✓
2	1	Front R/H fender cowling		\$107.40	✓
3	10	Front R/H fender cowling clips	\$5.00	\$50.00	✓
4	1	Front R/H lower arm		\$226.50	✓
5	1	Front R/H knuckle arm		\$318.00	✓
6	1	Front R/H knuckle arm bearing		\$147.70	✓
7	1	Front R/H shock absorber		\$469.70	✓
8	1	front R/H Tyre <i>HEM</i>		\$450.00	✓
9	1	front R/H rim <i>HEM</i>		\$650.00	✓
10	1	front Door-RH <i>Distorted</i>		\$1,008.10	✓
11	2	Front R/H door top & lower hinge	\$80.00	\$160.00	✓
12	1	Front R/H door side mirror assy		\$620.00	✓
13	1	Front R/H door top moulding		\$76.00	✓
14	1	Front R/H door outer handle		\$144.90	✓
15	1	Front R/H door inner lock		\$226.70	✓
16	1	Front R/H door inner trim board		\$521.70	✓
17	1	Front R/H door inner rubber		\$93.40	✓
18	1	Front R/H door glass		\$411.30	✓
19	1	Front R/H door inner gear & motor		\$432.40	✓
20	1	Front R/H door inner glass rubber		\$179.00	✓
21	1	Front R/H door inner lock handle		\$144.90	✓
22	1	Front R/H door pillar		\$841.30	✓
23	1	locker panel		\$233.72	✓
24	1	locker panel lower garnish		\$145.00	✓
25	1	Center R/H door pillar		\$556.70	✓
26	1	Center R/H door inner pillar		\$751.20	✓
27	1	locker panel rubber		\$280.00	✓

28	1	Rear R/H door <i>Distorted</i>	\$853.70	✓
29	1	Rear R/H door inner gear motor	\$432.40	+
30	1	Rear R/H door inner trim board	\$521.70	+
31	1	Rear R/H door inner lock	\$226.70	+
32	1	Front R/H Fender Wheel Arc Garnish <i>cut</i>	184.20	✓
33	1	Front R/H Fender Wheel Arc Garnish <i>clips</i>	30	✓
Subtotal :-			\$11,985.12	

3823.40 SW:450
3058.72

Labour charges

To Remove & refix cushion

\$120.00 ✓

Tuff kote

\$120.00 X

WHEEL alignment (computer)

\$150.00 80

to remove & install front RH undercarriage

\$280.00 X

Towing charges

\$100.00 X

1730

To Check Wiring System

\$80.00 30

Panel beating

\$1,000.00 700

Spray painting

\$1,000.00 800

Subtotal :- \$2,850.00

Total:- \$14,835.12

total: 5238.72
H/S: 4.2k.
06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: