

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

CARRO LEASING PTE LTD
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

'30th APRIL 2019

Accident date: 27th APRIL 2019

Estimated repair cost for vehicle no: SLE6505C HONDA VEZEL 1.5X A

S/n	Qty	Items	U/price	Amount
1	1	Front R/H fender		\$705.00
2	1	Front R/H fender cowl		\$107.40
3	10	Front R/H fender cowl clips	\$5.00	\$50.00
4	1	Front R/H lower arm		\$226.50
5	1	Front R/H knuckle arm		\$318.00
6	1	Front R/H knuckle arm bearing		\$147.70
7	1	Front R/H shock absorber		\$469.70
8	1	front R/H Tyre		\$450.00
9	1	front R/H rim		\$650.00
10	1	front Door-RH		\$1,008.10
11	2	Front R/H door top & lower hinge	\$80.00	\$160.00
12	1	Front R/H door side mirror assy		\$620.00
13	1	Front R/H door top moulding		\$76.00
14	1	Front R/H door outer handle		\$144.90
15	1	Front R/H door inner lock		\$226.70
16	1	Front R/H door inner trim board		\$521.70
17	1	Front R/H door inner rubber		\$93.40
18	1	Front R/H door glass		\$411.30
19	1	Front R/H door inner gear & motor		\$432.40
20	1	Front R/H door inner glass rubber		\$179.00
21	1	Front R/H door inner lock handle		\$144.90
22	1	Front R/H door pillar		\$841.30
23	1	locker panel		\$233.72
24	1	locker panel lower garnish		\$145.00
25	1	Center R/H door pillar		\$556.70
26	1	Center R/H door inner pillar		\$751.20
27	1	locker panel rubber		\$280.00

28	1	Rear R/H door	\$853.70
29	1	Rear R/H door inner gear motor	\$432.40
30	1	Rear R/H door inner trim board	\$521.70
31	1	Rear R/H door inner lock	\$226.70

Subtotal :- \$11,985.12

Labour charges

To Remove & refix cushion \$120.00

Tuff kote \$120.00

WHEEL alignment (computer) \$150.00

to remove & install front RH undercarriage \$280.00

Towing charges \$100.00

To Check Wiring System \$80.00

Panel beating \$1,000.00

Spray painting \$1,000.00

Subtotal :- \$2,850.00

Total:- \$14,835.12