



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGAI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

Arrange By _____ Driver ALLO

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 0745 9939

VW Audi Dept Direct: 6305 9810
Mazda Ford KIA Hyundai Dept Direct: 6417 9795
Subaru NISSAN Dept Direct: 6417 9790 Dept Direct: 6417 9793

ACCORD AUTO SERVICES PTE LTD(AV)
BLK 1009 #01-80
BUKIT MERAH LANE 3
SINGAPORE 159723
TEL : 6271 5133 FAX : 6274 5715
ATTN : GILBERT 92299191
SEND TO: BLK 1004 #01-29 BUKIT MERAH LANE 3

TAX INVOICE : AR201905-06226
DATE : 13/05/2019
CUSTOMER ID : ACC003
VEH REG. NO. : SLL7895H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	H3861 5-R1 A-A02 RUI RU3	A/C SHROUD MS (Est No. 54)	PA PL1-NI-10G	1	60.00	60.00

SUB-TOTAL : 60.00
ADD GST 7.00 % 4.20

E. & O E TOTAL AMOUNT S\$: 64.20

[P] 13/05/2019 1:01:13PM

[E] 13/05/2019 12:59:10PM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.
Sales Executive: LONG



This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
 TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
 48A SUNGEI KADUT AVE SINGAPORE 729672
 TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
 GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



=====

ACCORD AUTO SERVICES PTE LTD(AV)
 BLK 1009 #01-80
 BUKIT MERAH LANE 3

SINGAPORE 159723
 TEL : 6271 5133 FAX : 6274 5715
 ATTN : GILBERT 92299191

TAX INVOICE : AR201
 DATE : 01/06
 CUSTOMER ID : ACCO
 VEH REG. NO. : SLL7895H
 TERMS : 30 days
 PO NO. :
 PAGE NO. : Page 1 of 1
 CURR. : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	H77810-T5A-N80/81ZA RU1 GK5	AIR BAG (Est No. 66)	WH HL2-F1	1	720.00	720.00
2.	H77820-T7A-J80 RU1	AIR BAG LH (Est No. 65)	WH HL2-F2	1	1100.00	1,100.00
3.	H77100-T7A-000ZA RU1	DASHBOARD NH900L (Est No. 71)	WH HL1-F12	1	600.00	600.00
4.	H77930-T6A-J21 RC1 RU1	SENSOR ASSY, FR CRASH (Est No. 64)	WH HL2-G12-C	1	90.00	90.00
5.	H77960-T7A-J81/82 RU1/RU3	UNIT ASSY SRS (Supp 4 Est No. 1)	WH HL2-A4	1	650.00	650.00
6.	H81450-T7A-J02ZA	SEAT BELT RH (Est No. 68)	WH L2-P1	1	380.00	380.00
7.	H81850-T7A-J02ZA	SEAT BELT LH (Est No. 67)	WH L2-P1	1	380.00	380.00

SUB-TOTAL : 3,920.00
 ADD GST 7.00 % 274.40

 E. & O.E TOTAL AMOUNT S\$: 4,194.40

Goods Sold are not refundable for Cash.
 Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

AE Auto Pte. Ltd.
 Sales Executive : LONG



This is computer generated document.
 No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Apr 2019 Sendback Est	29 Apr 2019 16:23 S\$17,414.70	29 Apr 2019 16:37 Edit Adj Rpt	S\$18,806.00 Edit Estimates	S\$18,806.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	13 May 2019 19:58	13 May 2019 20:07 S\$3,325.30	13 May 2019 20:07			(Combined)	Combined with Main Uncombine Suppl.
Supp #2	11 Jun 2019 16:31	11 Jun 2019 16:45 S\$104.50	11 Jun 2019 16:45			(Combined)	Combined with Main Uncombine Suppl.
Supp #3	11 Jun 2019 16:47	11 Jun 2019 16:48 S\$400.00	11 Jun 2019 16:48			(Combined)	Combined with Main Uncombine Suppl.
Supp #4	14 Jun 2019 14:09	14 Jun 2019 14:11 S\$715.00	14 Jun 2019 14:11			(Combined)	Combined with Main Uncombine Suppl.

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	PIRAGASAM S/O MUNISAMY, ID: S1669907A, Tel: +6597838360		
Vehicle Reg. No.:	SLL7895H	Date of Loss:	26/04/2019 19:00 - :59 [25 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / CMTD1902082	Policy/Cover Note No.:	D19MTPV01003356 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point, 568047 Ang Mo Kio - Tel: 64819517/85715140		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 09/05/2019]		
Driver/Custodian:	RAVEEN PIRAGASAM (21 / Male) , NRIC: S9715223C, Tel: +6593880794 Email: raveen97@gmail.com		
Adj Asg. Remarks:	VEH IN AT BUKIT MERAH - FOR EXCESS & AUTHORISATION, PLEASE REFER TO THE HANDLER		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- SOMPO_SG (25/06/2019): Alert - Adj Mandate Approved (S\$20134.50) - SLL7895H - Claim Handler: CHAN SHU H...
- SOMPO_SG (17/05/2019): Alert - Adj Mandate Approved (S\$18915.00) - SLL7895H - Claim Handler: CHAN SHU H...
- SOMPO_SG (02/05/2019): Alert - Adj Mandate Approved (S\$15589.70) - SLL7895H - Claim Handler: CHAN SHU H...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLL7895H (CMTD1902082)
OD
Apr 26 2019 7:00PM
[PIRAGASAM S/O MUNISAMY]
Accord Auto Services Pte Ltd

View

Assessment Reports

1 per page

No	Finalized On	Accord Auto Services Pte Ltd (HQ)		Thumbnail	Print
1	29/04/19 10:46	Accident Statement		Load HTM	
2	29/04/19 16:23	Repairer Estimates		Load HTM	
3	13/05/19 20:07	Repairer Estimates Suppl. #1		Load HTM	
4	11/06/19 16:45	Repairer Estimates Suppl. #2		Load HTM	
5	11/06/19 16:48	Repairer Estimates Suppl. #3		Load HTM	
6	14/06/19 14:11	Repairer Estimates Suppl. #4		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/05/19 11:39	Adjuster Immediate Advice		Load HTM	
2	15/05/19 18:16	Adjuster Immediate Advice		Load HTM	
3	25/06/19 12:03	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
2	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
3	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
4	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
5	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
6	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
7	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
8	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
9	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
10	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
11	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
12	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
13	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
14	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
15	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
16	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
17	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
18	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
19	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
20	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
21	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
22	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
23	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
24	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
25	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
26	15/05/19 18:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Accord Auto Services Pte Ltd (HQ)	Thumbnail	Print
27	15/05/19 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	15/05/19 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	15/05/19 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	15/05/19 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	15/05/19 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	15/05/19 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	15/05/19 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	15/05/19 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	15/05/19 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	15/05/19 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	15/05/19 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	15/05/19 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	15/05/19 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	15/05/19 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	15/05/19 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	15/05/19 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	15/05/19 18:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Accord Auto Services Pte Ltd (HQ)		Thumbnail	Print
75	15/05/19 18:17	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
76	15/05/19 18:17	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
77	15/05/19 18:17	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
78	15/05/19 18:17	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
79	15/05/19 18:17	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
80	15/05/19 18:17	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
81	15/05/19 18:17	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
82	15/05/19 18:17	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
83	15/05/19 18:17	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
84	15/05/19 18:17	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
85	15/05/19 18:17	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
86	15/05/19 18:17	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
87	15/05/19 18:17	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
88	15/05/19 18:17	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
89	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
90	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
91	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
92	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
93	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
94	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
95	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
96	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
97	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
98	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
99	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
100	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
101	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
102	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
103	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
104	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
105	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
106	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
107	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
108	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
109	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
110	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
111	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
112	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
113	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
114	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
115	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
116	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
117	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
118	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
119	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
120	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
121	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>
122	15/05/19 18:17	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Accord Auto Services Pte Ltd (HQ)	Thumbnail	Print
123	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
124	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
125	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
126	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
127	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
128	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
129	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
130	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
131	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
132	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
133	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
134	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
135	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
136	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
137	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
138	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
139	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
140	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
141	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
142	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
143	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
144	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
145	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
146	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
147	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
148	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
149	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
150	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
151	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
152	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
153	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
154	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
155	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
156	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
157	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
158	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
159	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
160	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
161	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
162	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
163	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
164	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
165	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
166	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
167	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
168	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
169	15/05/19 18:17	General View	 Load JPG	<input checked="" type="checkbox"/>
170	15/05/19 18:17	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Accord Auto Services Pte Ltd (HQ)	Thumbnail	Print
171	25/06/19 12:08	Reinspection Photo		<input checked="" type="checkbox"/>
172	25/06/19 12:08	Reinspection Photo		<input checked="" type="checkbox"/>
173	25/06/19 12:08	Reinspection Photo		<input checked="" type="checkbox"/>
174	25/06/19 12:08	Reinspection Photo		<input checked="" type="checkbox"/>
175	25/06/19 12:08	Reinspection Photo		<input checked="" type="checkbox"/>
176	25/06/19 12:08	Reinspection Photo		<input checked="" type="checkbox"/>
177	25/06/19 12:08	Reinspection Photo		<input checked="" type="checkbox"/>
178	25/06/19 12:08	Reinspection Photo		<input checked="" type="checkbox"/>
179	25/06/19 12:08	Reinspection Photo		<input checked="" type="checkbox"/>
180	25/06/19 12:08	Reinspection Photo		<input checked="" type="checkbox"/>
181	25/06/19 12:08	Reinspection Photo		<input checked="" type="checkbox"/>
182	25/06/19 12:08	Reinspection Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/05/19 11:40	Estimate		<input type="checkbox"/>
2	15/05/19 18:21	SUPPLEMENTARY.pdf		<input type="checkbox"/>
3	25/06/19 12:07	SUPP 2, 3 & 4.pdf		<input type="checkbox"/>
4	26/06/19 14:14	ESTIMATE & SUPP MARKED .pdf		<input type="checkbox"/>
5	26/06/19 16:29	PARTS INVOICE		<input type="checkbox"/>

Linked Accident Report Documents

			View	View in Browser
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Accord Auto Services Pte Ltd (HQ)	Thumbnail	Print
1	27/04/19 15:10	Video - Accident		<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Accord Auto Services Pte Ltd (HQ)	Thumbnail	Print
1	29/04/19 10:46	Accident Statement		<input type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Accord Auto Services Pte Ltd (HQ)	Thumbnail	Print
1	27/04/19 12:56	Accident Photo		<input checked="" type="checkbox"/>
2	27/04/19 12:56	Accident Photo		<input checked="" type="checkbox"/>
3	27/04/19 12:56	Accident Photo		<input checked="" type="checkbox"/>
4	27/04/19 12:56	Accident Photo		<input checked="" type="checkbox"/>
5	27/04/19 12:56	Accident Photo		<input checked="" type="checkbox"/>
6	27/04/19 12:56	Accident Photo		<input checked="" type="checkbox"/>
7	27/04/19 12:56	Accident Photo		<input checked="" type="checkbox"/>
8	27/04/19 12:56	Accident Photo		<input checked="" type="checkbox"/>
9	27/04/19 12:56	Accident Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Accord Auto Services Pte Ltd (HQ)	Thumbnail	Print
1	27/04/19 12:59	Accident Sketch Plan		<input type="checkbox"/>
2	27/04/19 12:59	Accident Sketch Plan		<input type="checkbox"/>
3	27/04/19 12:59	CI		<input checked="" type="checkbox"/>
4	27/04/19 13:00	NRIC (Owner)		<input checked="" type="checkbox"/>
5	27/04/19 13:00	NRIC (Driver)		<input checked="" type="checkbox"/>
6	27/04/19 13:00	DL (Driver)		<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Repairer Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO19007510/T1SD3S2
Date: 26/06/2019

REFERENCE

Insured/Claimant: PIRAGASAM S/O MUNISAMY Policy No: D19MTPV01003356
Date of Loss: 26/04/2019 Nature of Claim: OD Claim No: CMTD1902082

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL7895H**
Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4408293
Reg. Date: 10/03/2017 (Man. Year: 2016) Chassis No: RU11208292
Colour: Blue Odometer: 73764 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$74,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55R17 Rear Tyre Size: 215/55R17
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,626.50	15,543.00	1,083.50	6.52
Miscellaneous Items	383.00	263.00	120.00	31.33
Labour	4,950.00	3,000.00	1,950.00	39.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,959.50	18,806.00	3,153.50	14.36
- Excess (S\$)	0.00	3,000.00	-3,000.00	
(S\$)	21,959.50	15,806.00	6,153.50	28.02
+ GST 7.00/7.00% (S\$)	1,537.17	1,106.42	430.75	28.02
Nett Amount (S\$)	23,496.67	16,912.42	6,584.25	28.02

INSPECTION

Date of Assignment: 29/04/2019 Present Location: Accord Auto Services Pte Ltd (HQ)
Date Inspected: 30/04/2019 Inspected At: BLK 1009 BUKIT MERAH LANE 3 #01-80
Estimated Period of Repair: 10.0 days Repairer: Accord Auto Services Pte Ltd

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 26 Jun 2019)**Parts:** M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SLL7895H)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front windscreen glass (WCP)	Cracked	1,300.00 F	*1,250.00 F
2	1		*Front windscreen glass moulding (top) (WCP)	Necessary	30.00 F	*40.00 F
3	1		*Front windscreen glass moulding (lower) (WCP)	Necessary	30.00 F	*40.00 F
4	1		*Front wiper garnish (WCP)	Not Necessary	135.00 F	*- F
5	1		*Bonnet (WCP)	Bent	400.00 F	*400.00 F
6	2		*Bonnet hinge (WCP)	Bent	60.00 F	*60.00 F
7	1		*Bonnet insulator pad (WCP)	Deformed	85.00 F	*85.00 F
8	4		*Bonnet seal (WCP)	Necessary	72.00 F	*72.00 F
9	1		*Bonnet lock (WCP)	Jammed	60.00 F	*85.00 F
10	1		*Bonnet lock cable (WCP)	Not Necessary	25.00 F	*- F
11	1		*Bonnet stand (WCP)	Missing	25.00 F	*15.00 F
12	1		*Bonnet stand clip (WCP)	Not Necessary	3.00 F	*- F
13	2		*Horn (WCP)	Not Necessary	50.00 F	*- F
14	1		*Front grille (WCP)	Cracked	190.00 F	*220.00 F
15	1		*Front grille outer garnish (WCP)	Cracked	130.00 F	*230.00 F
16	1		*Front grille lower moulding (WCP)	Cracked	35.00 F	*30.00 F
17	1		*Front grille logo (WCP)	Necessary	15.00 F	*18.00 F
18	1		*Front grille upp center beam (WCP)	Not Necessary	15.00 F	*- F
19	1		*Front grille up RH beam (WCP)	Not Necessary	10.00 F	*- F
20	1		*Front grille up LH beam (WCP)	Not Necessary	10.00 F	*- F
21	1		*LH headlamp (LED) (WCP)	Cracked	800.00 F	*880.00 F
22	1		*LH headlamp bracket (WCP)	Necessary	20.00 F	*20.00 F
23	1		*RH headlamp (LED) (WCP)	Cracked	800.00 F	*880.00 F
24	1		*RH headlamp bracket (WCP)	Necessary	20.00 F	*20.00 F
25	1		*Front bumper (WCP)	Deformed	190.00 F	*280.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*Front bumper low grille (WCP)	Not Necessary	40.00 F	*- F
27	1		*Front bumper fog lamp (RH) (WCP)	Cracked	120.00 F	*120.00 F
28	1		*Front bumper fog lamp cover (RH) (WCP)	Not Necessary	15.00 F	*- F
29	1		*Front bumper low lid (WCP)	Not Necessary	110.00 F	*- F
30	1		*Front bumper tow cover (WCP)	Missing	10.00 F	*12.00 F
31	2		*Front bumper air guide (WCP)	Not Necessary	24.00 F	*- F
32	1		*Front bumper reinforcement (WCP)	Bent	180.00 F	*180.00 F
33	2		*Front bumper reinforcement moulding (WCP)	Deformed	30.00 F	*20.00 F
34	2		*Front bumper side retainer (WCP)	Necessary	20.00 F	*40.00 F
35	1		*Support panel (WCP)	Bent	280.00 F	*350.00 F
36	1		*Support panel top garnish (WCP)	Not Necessary	38.00 F	*- F
37	1		*Front LH fender (WCP)	Bent	170.00 F	*180.00 F
38	1		*Front RH fender (WCP)	Bent	170.00 F	*180.00 F
39	1		*Front RH fender splash shield (WCP)	Twisted	55.00 F	*55.00 F
40	1		*Front RH fender protector (WCP)	Not Necessary	35.00 F	*- F
41	1		*Air-con condenser assy (WCP)	Bent	300.00 F	*280.00 F
42	2		*Air-con condenser top bush (WCP)	Not Necessary	10.00 F	*- F
43	2		*Air-con condenser bottom bush (WCP)	Not Necessary	10.00 F	*- F
44	1		*Air-con suction hose (WCP)	Not Necessary	90.00 F	*- F
45	1		*Air-con discharge hose (WCP)	Not Necessary	110.00 F	*- F
46	1		*Air-con pipe (receiver) (WCP)	Not Necessary	90.00 F	*- F
47	1		*Air-con ambient sensor (WCP)	Not Necessary	25.00 F	*- F
48	1		*Air-con ambient sensor clip (WCP)	Not Necessary	10.00 F	*- F
49	1		*Radiator assy (WCP)	Bent	700.00 F	*700.00 F
50	2		*Radiator top bracket (WCP)	Bent	30.00 F	*30.00 F
51	2		*Radiator bottom bush (WCP)	Not Necessary	20.00 F	*- F
52	1		*Radiator top hose (WCP)	Not Necessary	15.00 F	*- F
53	1		*Radiator bottom hose (WCP)	Not Necessary	15.00 F	*- F
54	1		*Air-con fan cowling (WCP)	Cracked	60.00 F	*60.00 F
55	1		*Air-con fan balde (WCP)	Not Necessary	35.00 F	*- F
56	1		*Air-con fan motor (WCP)	Not Necessary	150.00 F	*- F
57	1		*Radiator fan cowling (WCP)	Cracked	70.00 F	*70.00 F
58	1		*Radiator fan blade (WCP)	Not Necessary	40.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
59	1		*Radiator fan motor (WCP)	Not Necessary	190.00 F	*- F
60	1		*Radiator spare tank (WCP)	Deformed	25.00 F	*55.00 F
61	1		*Washer tank (WCP)	Deformed	45.00 F	*40.00 F
62	1		*Washer tank neck (WCP)	Deformed	20.00 F	*15.00 F
63	1		*Washer tank cover (WCP)	Missing	10.00 F	*10.00 F
64	2		*Washer tank motor (WCP)	Not Necessary	70.00 F	*- F
65	1		*Front LH air bag (passenger side) (WCP)	Activated	1,100.00 F	*1,100.00 F
66	1		*Front RH air bag (driver side) (WCP)	Activated	720.00 F	*720.00 F
67	1		*Front LH seat belt (WCP)	Activated	380.00 F	*380.00 F
68	1		*Front RH seat belt (WCP)	Activated	380.00 F	*380.00 F
69	1		*Airbag sensor (WCP)	Activated	90.00 F	*90.00 F
70	1		*Steering angle sensor (WCP)	Activated	130.00 F	*70.00 F
71	1		*Dashbaord (WCP)	Deformed	600.00 F	*600.00 F
Supplementary #1						
72	1		*FRONT BUMPER GRILLE MOULDING CHROME (WCP)	Missing	35.00 F	*35.00 F
73	1		*FRONT LH FENDER WHEEL ARCH (WCP)	Broken	50.00 F	*50.00 F
74	1		*MANIFOLD TUBE (WCP)	Torn	15.00 F	*15.00 F
75	1		*MANIFOLD (WCP)	Broken	260.00 F	*260.00 F
76	1		*COVER RELAY BLOCK UPPER (WCP)	Broken	5.00 F	*5.00 F
77	1		*MILLIMETER WAVE RADAR (WCP)	Broken	1,850.00 F	*1,850.00 F
78	1		*MILLIMETER WAVE RADAR RACKET (WCP)	Bent	480.00 F	*480.00 F
79	1		*RADIATOR SIDE AIR GUIDE RH (WCP)	Crushed	20.00 F	*20.00 F
80	1		*RADIATOR SIDE AIR GUIDE LH (WCP)	Crushed	28.00 F	*28.00 F
81	1		*LOCK COVER (WCP)	Missing	40.00 F	*40.00 F
82	1		*AIR INTAKE DUCT (WCP)	Crushed	40.00 F	*40.00 F
83	1		*AIR INTAKE TUBE (WCP)	Crushed	40.00 F	*40.00 F
84	1		*FILTER COVER LOWER (WCP)	Broken	95.00 F	*95.00 F
85	2		*WINDSCREEN MOULDING SIDE LH & RH (WCP)	Necessary	40.00 F	*40.00 F
86	1		*TOP RH NOZZLE HOSE (WCP)	Torn	10.00 F	*10.00 F
87	1		*FRONT RH FENDER ENCLOSURE (WCP)	Broken	15.00 F	*15.00 F
Supplementary #2						
88	1		*LOCK COVER BRACKET (Missing) (WCP)	Missing	10.00 F	*10.00 F
89	1		*TEMOERATURE SENSOR (Missing) (WCP)	Missing	35.00 F	*35.00 F
90	1		*AMBIENT SENSOR BRACKET (WCP)	Missing	10.00 F	*10.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
91	1		*UP BEAM FRT GRILLE (Aircon Condenser Bracket-Missing) (WCP)	Missing	20.00 F	*20.00 F
92	1		*UP BEAM RH FRT GRILLE (Missing) (WCP)	Missing	10.00 F	*10.00 F
93	1		*UP BEAM LH FRT GRILLE (Missing) (WCP)	Missing	10.00 F	*10.00 F
Supplementary #4						
94	1		*AIRBAG CONTROL UNIT (WCP)	Activated	650.00 F	*650.00 F

F=Franchise part.

	Sub Total (S\$)	15,115.00	14,130.00
	+ Margin on L,N Items 10.00/10.00% (S\$)	1,511.50	1,413.00
	Total Parts (S\$)	16,626.50	15,543.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Bonnet insulator pad clip (NECESSARY)	50.00	30.00
2	1	Front bumper clip (NECESSARY)	50.00	20.00
3	1	Front number plate with holder (BENT)	55.00	45.00
4	1	Front RH fender protector clip (NECESSARY)	18.00	18.00
5	1	Front RH fender splash shield clip (NECESSARY)	50.00	10.00
6	1	Front windscreen glass sealant/gum (NECESSARY)	80.00	80.00
7	1	IU bracket sticker (NECESSARY)	10.00	10.00
8	1	Radiator coolant (NECESSARY)	40.00	40.00
9	1	Support panel top garnish clip (NECESSARY)	30.00	10.00
Sub Total (S\$)			383.00	263.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Spray painting on all affected area.	New	900.00	800.00
2	Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	New	1,200.00	800.00
3	To check wiring system & light.	New	120.00	30.00
4	To remove and replace front windscreen glass.	New	150.00	120.00
5	To remove and replace air-con condenser, hoses, piping, fan assy & etc., vacuum and top up gas.	New	300.00	120.00
6	To remove and replace radiator, hoses, fan assy & etc..	New	250.00	100.00
7	To remove and replace front LH & RH airbag assy, airbag sensor, steering angle sensor.	New	350.00	200.00
8	To remove and replace front LH & RH seat belt.	New	300.00	100.00
9	To remove and replace dashboard.	New	380.00	180.00
10	To remain and adjust front main chassis.	New	300.00	0.00
11	Computer diagnostic	New	300.00	150.00
Supplementary #3				
Labour Items				
12	RE-PROGRAMMING RADAR SYSTEM , RE-ALIGNMENT OF FRT RADAR SENSOR & LABOUR CHARGE	New	400.00	400.00
Gross Labour Cost (S\$)			4,950.00	3,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >