

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 15 May 2019

## **Preliminary Advice**

Vehicle No	: SLL7895H	Accident Date	: 26/04/2019
Make	: HONDA VEZEL	Policy No.	: D19MTPV01003356
Assignment Date	: 29/04/2019	Excess	: S\$0.00
		Additional Excess	: S\$3,000.00
Date of Inspection	: 30/04/2019	Est. Duration of Repair	: 10.00
Inspection At	: ACCORD AUTO SERVICES PTE LTD (HQ) 10 ANG MO KIO IND PARK 2A #03-11, AMK AUTO POINT SINGAPORE 568047		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,740.00 (inclusive supplementary)
Revised Amount	:S\$	16,010.20 (inclusive supplementary)
Check Items (Estimated)	:S\$	2,904.80
Total	:S\$	18,915.00

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	74,000.00
COE / PARF Rebate	:S\$	46,175.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,825.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Supplementary amount is \$ 3,325.30.