

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 02 May 2019

Preliminary Advice

Vehicle No	: SLL7895H	Accident Date	: 26/04/2019
Make	: HONDA VEZEL	Policy No.	: D19MTPV01003356
Assignment Date	: 29/04/2019	Excess	: S\$0.00
		Additional Excess	: S\$3,000.00
Date of Inspection	: 30/04/2019	Est. Duration of Repair	: 10.00
Inspection At	: ACCORD AUTO SERVICES PTE LTD (HQ) 10 ANG MO KIO IND PARK 2A #03-11, AMK AUTO POINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,414.70
Revised Amount	:S\$	12,684.90
Check Items (Estimated)	:S\$	2,904.80
Total	:S\$	15,589.70

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	74,000.00
COE / PARF Rebate	:S\$	46,175.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,825.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation and confirm excess.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :