

(KND10)

INS. CASE OWNER:

Peter

CC 4 ASM AXA1900 7515

LKK:
IDAC

Surveyor:

KSC

DOI:

ASSIGNMENT

21/4/14

Date / Time:

21/4/14

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGA 864AT

Name of Insured:

UM SEA YEN

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

25/4/14

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SAM212H/113038

Policy No.:

GA45R0471

Make / Model:

Honda

Place of Accident:

SOMERSET RD TRNS VILMUN

If NO. Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SMY 11A0L

SGA 864AT

SMF 8245C



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

Cheng
Hue
TP

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SMF 8245C-X

SGA 864AT-X

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice:

Towing Invoice

LTA / GIA

Medical Bill

PIR:

Mandate/Reject Instruction

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

KENNEDY

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

LIS

SS 4450.00

5

days

Reduction:

42158.80 % 30

FINAL SETTLEMENT

Date/Time:

Confirm with:

JUNE

Email:

Cal:

Final Liability:

%

(80)

(Agreed / Assessed) BOLA S/N No.:

08

Repair Cost:

(W/GST)

SS 5296.50

Loss of Rental (LOR):

SS

700.00

1

days

4100

Loss of Use (LOU):

SS

-

(5

x

days)

Loss of Income (LOI):

SS

-

(5

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

LOR + LO

[Tick only one]

GIA/TA Search

SS

8.00

Medical:

SS

-

Disbursement:

SS

-

Legal Cost

SS

-

(e.g. Tow/Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4200

Total:

SS

6004.50

Global Sum SS:

6000.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Cal:

Payee 1:

SS

6000.00

Name 1:

Cheng Hoo motor Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT

ASS. REC. BY:

REF:

AA/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMF 8295C

Yr Regn:

07, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Wagon

Make:

Mc

B180

c.c

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading:

156215

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

W00 2452322-J565436

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

R:

225/45 ER17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

25/4/19

D.O.J.

29/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

45 \$4950

(Red. \$2158.80 / 30%)

* 5 repair days + 1 sun + 1 PRS + 1 sat = 8 days.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

- ...is to ... notify ... of the following:
- To ... below ... or ... painting
 - To display damaged parts during repair
 - Parts ... are subject to ...
 - Third party survey is on a ...
 - No illegal modification(s) ...
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Cheng Hoe Motor Pte Ltd

Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@smgnet.com.sg
 GST: 201001158E RCB NO: 201001158E

SMF 8295C
 TP/AXA

M/S: Acknowledged by Repairer
AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288
 ATTN: Motor Claim Department
 WS Ref: TP/AXA/YS
 Claim Type: Third Party
 Accident Date: 25/04/2019
 TP Veh Reg No: SGA8699T

FAX: 68804739

Estimate No: ES1991448/YISHUN
 Date: 26 Apr 2019
 Policy No: 5106469813
 Veh Reg No: SMF8295C
 Make/Model: MERCEDES B180
 Chassis No: WDD2452322J565436
 Engine No: 26694030746209
 Reg. Date: 21/07/2010

Not Authorized
11 Day @ 4950
Resurvey After Paint 5 days

Estimate Repair Cost to Vehicle No :SMF8295C

PAGE: 1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
Net Price				
1 REAR BUMPER	1,112.00	1 PC	1,112.00	✓
2 REAR BUMPER TOP CHROME PROTECTOR	176.00	1 PC	176.00	✓
3 REAR BUMPER REINFORCEMENT	480.00	1 PC	480.00	✓
4 REAR BUMPER MOULDINGS	146.00	2 PCS	292.00	✓
5 REAR BUMPER STICKER REFLECTORS	45.00	2 PCS	90.00	✓
6 REAR BUMPER LOWER SKIRT RUBBER	182.00	1 PC	182.00	✓
7 REAR BUMPER SIDE RETAINERS	26.00	2 PCS	52.00	✓
8 REAR TAILGATE	1,820.00	1 PC	1,820.00	✓
9 TAILGATE LOGO	49.00	1 PC	49.00	✓
10 TAILGATE EMBLEM (B180)	76.00	1 PC	76.00	✓
11 TAILGATE INNER LOCK	290.00	1 PC	290.00	✓
12 TAILGATE INNER RUBBER	188.00	1 PC	188.00	✓
13 REAR BUMPER SCREW COVERS	10.00	4 PCS	40.00	✓
14 REAR WINDSCREEN GLASS MOULDING with glass	585.00	1 PC	585.00	✓
			5,432.00	
			Less 10%	4,888.80
Special Net				
15 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
16 REVERSE SENSOR	280.00	1 SET	280.00	✓
			320.00	320.00
Labour				
17 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
18 PANEL BEATING	680.00	1 LA	680.00	550
19 REMOVE & REFIX REAR GARNISH, TRAY BOARD, CARPET, SEAT, ETC	80.00	1 LA	80.00	400
20 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	50.00	1 LA	50.00	✓
21 REMOVE & REFIX REVERSE SENSOR & RESET SYSTEM	50.00	1 LA	50.00	✓
22 PUTTY & RESPRAY ON REAR BUMPER, REAR PANEL, REAR TAILGATE & REAR AFFECTED AREAS	800.00	1 LA	800.00	660
23 STRAIGHTEN REAR EXHAUST & CHECK LEAKING	60.00	1 LA	60.00	✓
24 RUSTPROOFING	60.00	1 LA	60.00	300
			1,900.00	1,900.00
			Total	S\$ 7,108.80
			Add GST @ 7%	497.62
			Total Amount Payable	S\$ 7,606.42

1 pc rear centre panel inner top garnish @ 198 N cm
940
To RAR reverse camera and reset system @ 500
228,20

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SMF 8295C
 TP/AXA

M/S : AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288
 ATTN: Motor Claim Department
 WS Ref: TP/AXA/YS
 Claim Type: Third Party
 Accident Date: 25/04/2019
 TP Veh Reg No: SGA8699T

FAX: 68804739

Estimate No: ES1991448/YISHUN
 Date: 26 Apr 2019
 Policy No: 5106469813
 Veh Reg No: SMF8295C
 Make/Model: MERCEDES B180
 Chassis No: WDD2452322J565436
 Engine No: 26694030746209
 Reg. Date: 21/07/2010

Estimate Repair Cost to Vehicle No :SMF8295C

PAGE:1/1

Description	U/Price	Quantity	List Price SS	Amount SS
Net Price				
1 REAR BUMPER	1,112.00	1 PC	1,112.00	✓
2 REAR BUMPER TOP CHROME PROTECTOR	176.00	1 PC	176.00	✓
3 REAR BUMPER REINFORCEMENT	480.00	1 PC	480.00	?
4 REAR BUMPER MOULDINGS	146.00	2 PCS	292.00	✓
5 REAR BUMPER STICKER REFLECTORS	45.00	2 PCS	90.00	✓
6 REAR BUMPER LOWER SKIRT RUBBER	182.00	1 PC	182.00	✓
7 REAR BUMPER SIDE RETAINERS	26.00	2 PCS	52.00	✓
8 REAR TAILGATE	1,820.00	1 PC	1,820.00	✓
9 TAILGATE LOGO	49.00	1 PC	49.00	✓
10 TAILGATE EMBLEM (B180)	76.00	1 PC	76.00	✓
11 TAILGATE INNER LOCK	290.00	1 PC	290.00	?
12 TAILGATE INNER RUBBER	188.00	1 PC	188.00	?
13 REAR BUMPER SCREW COVERS	10.00	4 PCS	40.00	x
14 REAR WINDSCREEN GLASS MOULDING	585.00	1 PC	585.00	?
			5,432.00	
		Less 10%	543.20	4,888.80
Special Net				
15 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
16 REVERSE SENSOR	280.00	1 SET	280.00	✓
			320.00	320.00
Labour				
17 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
18 PANEL BEATING	680.00	1 LA	680.00	550
19 REMOVE & REFIX REAR GARNISH,TRAY BOARD,CARPET,SEAT,ETC	80.00	1 LA	80.00	?
20 REMOVE & REFIX REVERSE CARMERA & RESET SYSTEM	50.00	1 LA	50.00	✓
21 REMOVE & REFIX REVERSE SENSOR & RESET SYSTEM	50.00	1 LA	50.00	✓
22 PUTTY & RESPRAY ON REAR BUMPER,REAR PANEL,REAR TAILGATE & REAR AFFECTED AREAS	800.00	1 LA	800.00	660
23 STRAIGHTEN REAR EXHAUST & CHECK LEAKING	60.00	1 LA	60.00	?
24 RUSTPROOFING	60.00	1 LA	60.00	30
			1,900.00	1,900.00

Supp
 to RAR reverse

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Total SS 7,108.80
 Add GST @ 7% 497.62
 Total Amount Payable SS 7,606.42

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6341B
Vehicle Details	
Vehicle No.:	SMF8295C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Apr 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	B180
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	26694030746209
Chassis No.:	WDD2452322J565436
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$29,005.00
Original Registration Date:	21 Jul 2010
First Registration Date:	21 Jul 2010
Transfer Count:	2
Actual ARF Paid:	\$29,005.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jul 2020
PARF Rebate Amount:	\$15,952.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jul 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$35,909.00
COE Rebate Amount:	\$4,422.00
Total Rebate Amount:	\$20,374.00

The information contained herein is correct as at 26 Apr 2019

OK

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Monday, 29 April 2019 10:35 AM
To: assignments
Cc: Admin A
Subject: FW: Repair Survey (Single Joint Expert) - SMF8295C

****SMARTCLAIM NEW CASE****

SPOKEN TO JUNE – VEH IN***SHE WILL ARRANGE WITH KENNETH

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheng Hoe Motor Pte Ltd (Yishun-June) <chmotor@singnet.com.sg>
Sent: Friday, 26 April 2019 12:22 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Subject: Repair Survey (Single Joint Expert) - SMF8295C

Dear Sir,

OUR CLIENT – SMF8295C
DOA : 25/4/19 @8pm

AXA
INSURED : SGA8699T

We refer to the above.

Under Protocol - SJE, pls provide list of surveyors for our selection.

Thank you.

Regards
June
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

12.37pm @ 29/4/19
vehicle in
June will direct
call Kenneth.

<< Service Request Details

Claim

59M01LJH

Reference

None 

Loss Date

25 April 2019

Report Date

26 Apr 2019 2:13:30 PM

Request Date

29 April 2019

Due Date

29 April 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Previous Step	Next Step
---------------	-----------

Vehicle Information

Incident Vehicle Registration #

SMF8295C

Make

TPVD UNKNOWN

Model

Service Address



Primary Contact/Insured

LIM SZE YEN
10A CANBERRA DRIVE, #12-20, 768143, Singapore

ERICSONSY@GMAIL.COM

Claim Handler

WANG Peter

peter.wang@axa.com.sg
Additional Instructions

Information	Invoices	History	Documents	Assessment	Metrics	Notes
No Attachments						



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 21/02/2020

Survey Details:

Date of loss	25-Apr-19
Date of appointment	29-Apr-19
Date of survey	29-Apr-19
Location of survey	CHENG HOE MOTOR PL

Vehicle Details:

Claim Type:	Third party
Vehicle number	SMF 8295C
Make and Model	MERCEDES BENZ B180
Date of registration	21/7/2010
Excess	
Market Value	\$30,000
Parf Rebate	\$20,374
Nett Loss	\$9,626

Repair details:

Initial Estimate	\$ 7,108.80
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 4,622.00
Check items (estimate)	\$ -
Labour	\$ 1,550.00
Total	\$ 6,172.00
Lump Sum(if applicable)	\$ 4,950.00

Number of days for repair	5
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

05 RECOMMENDED REPAIR DAYS + 1SUNDAY + 1SATURDAY + 1PRS = 8
DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 5,296.50	W/GST
Loss of use	\$ -	
Loss of rental	\$ 800.00	8days x \$100
Loss of income	\$ -	
LTA search fees	\$ 8.00	
Others	\$ -	
Proposed Total	\$ 6,104.50	

**<MANDATE IA> - S9M01LJH {ACCIDENT INVOLVING SGA 8699T (OI) & SMF 8295C (TP) ON 25/04/2019}**

Type

Question

Message

LIABILITY: 100% BOLA S28 (OI 2ND) - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$6104.50 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL
21/02/2020

[Reply](#)

<<

Pls proceed DS with below LOR quantum

Type

 Question

Message

COR: \$5296.50 (as proposed) LOR: \$600.00 (\$100/day for 6 days - from LTA record); LTA: \$8.00. Total \$5904.50.

Reply



RE: Pls proceed DS with below LOR quantum

Type

🔔 Question

Message

Hi Peter, TP reject offer, propose G/S \$6000.00 (7 days LOR). Kindly let us have your approval/instruction.

Thanks - CCL 02/03/2020

Reply

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67537719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811
TEL: 63387288 FAX: 68804739
ATTN: Motor Claim Department
WS Ref: TP/AXA/YS
Claim Type: Third Party
Accident Date: 25/04/2019
TP Veh Reg No: SGA8699T

NO: CL8190925
Date: 29 Aug 2019
Policy No: 5106469813
Veh Reg No: SMF8295C
Make/Model: MERCEDES B180
Job No: JC1600400

Description	Quantity	List Price	PAGE:1
			Amount
To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges. (As recommended by your appointed surveyor)	1 PC	SS 4,950.00	SS 4,950.00

Total	SS 4,950.00
Add GST @ 7%	346.50
Total Amount payable	SS 5,296.50

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE



We will agree to GS settlement at \$6000 (all-in) with LOR proof


Type

🔍 Question

Message

Pls proceed.

Reply



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

Date: 01 OCT 2019

AXA Insurance (S) Pte Ltd
C/O LKK Auto Consultants

Attn : THE MOTOR CLAIMS DEPT

Dear Sir / Madam

**ACCIDENT INVOLVING VEHICLE NO. SMF8295C & SGA8699T ON 25/04/2019
ALONG SEMBAWANG RD.**

We are authorized by SMF8295C for their above matter.

Record reveals that you are the insurer of SGA8699T. We therefore wish to seek compensation from you as below:-

1. Cost of Repairs	S\$ 5296.50
2. Loss of Use	S\$ 0.00
3. Hire of Vehicle (S\$100 /- x 8 days)	S\$ 800.00
4. LTA Search Fee/GIA Reports	S\$ 8.00
TOTAL	S\$ 6104.50

Please let us have your reply soonest possible.

Thank you.

Yours faithfully



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19007515/Kga3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:PETER		Date : 10-03-2020 Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGA 8699T	Veh. Inspected	SMF 8295C
Policy No.	GA452647/1	Coverage (\$)	0.00
Claim No.	S9M01LJH	Excess (\$)	0.00
Assign From		Assign Date	29/04/2019
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ B180 (A)	c.c	0
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WDD2452322J565436	Colour	METALLIC GREY
Odometer	156215	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45Z R17	MICHELIN	8 mm
L/H Front Tyre	225/45Z R17	MICHELIN	8 mm
R/H Rear Tyre	225/45Z R17	MICHELIN	8 mm
L/H Rear Tyre	225/45Z R17	MICHELIN	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/04/2019	Inspection Date	29/04/2019
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 8295C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (N) (CONSISTENT)	BUCKLED	✓ 1,112.00	1,112.00
1	REAR BUMPER TOP CHROME PROTECTOR (N) (CONSISTENT)	NECESSARY	✓ 176.00	176.00
1	REAR BUMPER REINFORCEMENT (N) (CONSISTENT)	TO REPAIR SEE LABOUR	✓ 480.00	-
2	REAR BUMPER MOULDINGS @\$146.00(N) (CONSISTENT)	NECESSARY	✓ 292.00	292.00
2	REAR BUMPER STICKER REFLECTORS @\$45.00 (N) (CONSISTENT)	NECESSARY	✓ 90.00	90.00
1	REAR BUMPER LOWER SKIRT (N) (CONSISTENT)	DISTORTED / BUCKLED	✓ 182.00	182.00
2	REAR BUMPER SIDE RETAINERS @\$26.00 (N) (CONSISTENT)	SERVICEABLE	✓ 52.00	-
1	REAR TAILGATE (N) (CONSISTENT)	BENT	✓ 1,820.00	1,820.00
1	TAILGATE LOGO (N) (CONSISTENT)	NECESSARY	✓ 49.00	49.00
1	TAILGATE EMBLEM (B180) (N) (CONSISTENT)	NECESSARY	✓ 76.00	76.00
1	TAILGATE INNER LOCK (N) (CONSISTENT)	DENTED	✓ 290.00	290.00
1	TAILGATE INNER RUBBER (N) (CONSISTENT)	SERVICEABLE	✓ 188.00	-
4	REAR BUMPER SCREW COVERS @\$10.00 (N) (CONSISTENT)	SERVICEABLE	✓ 40.00	-
1	REAR WINDSCREEN GLASS MOULDING (N) (CONSISTENT)	MLDG NECESSARY	✓ 585.00	585.00
1	REAR CENTRE PANEL INNER TOP GARNISH (N) (CONSISTENT)	CRACKED	✓ 198.00	198.00
	LESS 10% DISCOUNT		-563.00	-487.00
			5,067.00	4,383.00
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN GLASS GUM (SN) (CONSISTENT)	NECESSARY	✓ 40.00	40.00
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	✓ 280.00	280.00
			320.00	320.00
LABOUR				
	TO R&R REVERSE CAMERA AND RESET SYSTEM.		✓ 50.00	50.00
	REMOVE AND REFIX REAR WINDSCREEN GLASS.		✓ 120.00	120.00

Report Ref No. CC4/ASM19007515/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT .		✓ 680.00	550.00
	REMOVE & REFIX REAR GARNISH ,TRAY BOARD ,CARPET ,SEAT ,ETC.		✓ 80.00	40.00
	REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM.		✓ 50.00	50.00
	REMOVE & REFIX REVERSE SENSOR & RESET SYSTEM.		✓ 50.00	50.00
	PUTTY & RESPRAY ON REAR BUMPER ,REAR PANEL,REAR TAILGATE & REAR AFFECTED AREAS.		✓ 800.00	660.00
	STRAIGHTEN REAR EXHAUST & CHECK LEAKING.	NOT NECESSARY	60.00	-
	RUSTPROOFING.		✓ 60.00	30.00
			1,950.00	1,550.00
GRAND TOTAL			7,337.00	6,253.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,950.00

Report Ref No. CC4/ASM19007515/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	59M01LJH
Reference	CC4/ASM19007515/Kga3a2
Loss Date	25 April 2019
Report Date	26 Apr 2019 2:13:30 PM
Request Date	7 August 2019
Due Date	
Vendor Name	LIAK AUTO CONSULTANTS PTE LTD (TPV)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for Approval Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	SMF8295C
Make	TPVO UNKNOWN
Model	
Service Address	
...	
Primary Contact/Insured	
LIM SZE YEN	
10A CANBERRA DRIVE, #12-20, 768143, Singapore	
ERIKSONSY@GMAIL.COM	
Claim Handler	
WANG Peter	
peter.wang@axa.com.sg	

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type		Document SubType	
+ Upload Documents			
NAME	TYPE	SUB-TYPE	AUTHOR
Accident Statement:		Reports & Statement	Meriment
			DATE UPLOADED

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKXInvoice1 (6).pdf	Invoice	Surveyor/ Assessor expense	LKX AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 LTA SEARCH.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 LKXInspection (1).pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 LKXAdjustment1a (2).pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKX AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKX AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKX AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 TP FINAL EST LIST.xls	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	21 February 2020
 LKX SURVEY PHOTO.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	21 February 2020
 LKX RESURVEY PHOTO.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	21 February 2020
 LKX RESURVEY PHOTO 2.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	21 February 2020
 MANDATE IA DO 21022020.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	21 February 2020
 LEO AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	21 February 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 PARF COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 February 2020
 SURVEYOR APPOINTED.mng	Reports & Statement	Survey Report	VISHNU BATHAM Shekhar	29 April 2019
 LIST OF SURVYOR RE- SENT.mng	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	29 April 2019
 TP GIA - SMF8295C(1st car).PDF	Reports & Statement	GIA Report	WANG Peter	29 April 2019
 LIST OF SURVYOR SENT.mng	Letters and Correspondence	Surveyor / Assessor	VISHNU BATHAM Shekhar	26 April 2019
 EMAIL TP FR1.mng	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	26 April 2019