

JIN AUTO SERVICES PTE LTD

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

16/7/2019

M/S AIG INSURANCE MRD 531493

DEAR SIR

ESTIMATE REPAIR COST FOR SJH207X

1	1 PC	FRONT BUMPER	De	369.10	✓
2	1 SET	FRONT BUMPER CLIPS	ME	50.00	✓
3	1 PC	FRONT BUMPER LH SIDE RETAINER	11	36.50	X
4	1 PC	LH HEADLAMP	11	X	
5	1 PC	FOGLAMP LH	12	X	
6	1 PC	FOGLAMP LH COVER	12	X	
7	1 PC	LH FRONT FENDER	12	X	

LESS 10%

- 8 TUFF COATING
- 9 WIRING
- 10 SPRAY PAINTING
- 11 LABOUR CHARGES

11 \$80.00 X
\$30.00 20
\$620.00 400
\$600.00 280

NETT TOTAL \$1,330.00

1014.32

LMS Auto Consultants hence notify
the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No litigation in writing is allowed
- Supplementary work must be surveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: