

Sheet 1

S M SPRAY PAINTING PTE LTD

BLOCK 25 KAKI BUKIT ROAD 4 #08-30 SYNERGY@ KB Singapore 417800
 Tel: 6384 1755/1766 Fax: 6384 1744

29th April 2019

SUTANTO IDRIES
 Bk 25 Kaki Bukit Rd 4
 # 08-30 SYNERGY @KB
 Singapore 417800

Accident date: 25th APRIL 2019
 Estimated repair cost for vehicle no: SJK907H VOLKSWAGEN GOLF

S/n	Qty	Items	U/price	Amount
				\$950.00
1	1	Rear fender RH		\$550.00
2	1	Rear tire-RH		\$800.00
3	1	Rim-RH		\$446.40
4	1	Rear shock absorber		\$712.60
5	1	Rear lower arm		\$695.40
6	1	Rear knuckle arm		\$385.20
7	1	Rear knuckle arm bearing		\$325.00
8	1	Rear boot lid side lamp -RH		\$425.00
9	1	Rear tail lamp-RH	\$8.50	\$34.00
10	4	Rear tail lamp clips		\$895.00
11	1	Rear Bumper	\$68.00	\$136.00
12	2	Rear Bumper Side Bracket	\$6.50	\$65.00
13	10	Rear bumper clips		\$50.00
14	1	rear bumper number plate		\$450.00
15	1	Rear bumper reverse sensor -SET		
Subtotal :-				\$6,919.60

Labour charges

To Remove & refix reverse Sensor	\$100.00
To Remove & refix cushion	\$100.00
Tuff kote	\$100.00
To Check Wiring System	\$80.00
Panel beating	\$800.00
Spray painting	\$800.00
Subtotal :-	\$1,980.00
Total:-	\$8,899.60