

# S M SPRAY PAINTING PTE LTD

BLOCK 25 KAKI BUKIT ROAD 4 #08-30 SYNERGY @ KB Singapore 417800  
Tel: 6384 1755/1766 Fax: 6384 1744

SUTANTO IDRIES  
Bk 25 Kaki Bukit Rd 4  
# 08-30 SYNERGY @KB  
Singapore 417800

PHI  
VIC

29<sup>th</sup> April 2019

WVWZZZ1KZ8W142330

Accident date: 25<sup>th</sup> APRIL 2019  
Estimated repair cost for vehicle no: SJK907H VOLKSWAGEN GOLF

| S/n         | Qty | Items                                        | U/price | Amount      |
|-------------|-----|----------------------------------------------|---------|-------------|
| 1           | 1   | Rear fender RH <i>Repair</i>                 |         | \$950.00 X  |
| 2           | 1   | Rear tire-RH <i>3 New</i>                    |         | \$550.00 X  |
| 3           | 1   | Rim-RH                                       |         | \$800.00 X  |
| 4           | 1   | Rear shock absorber                          |         | \$446.40 X  |
| 5           | 1   | Rear lower arm                               |         | \$712.60 X  |
| 6           | 1   | Rear knuckle arm                             |         | \$695.40 X  |
| 7           | 1   | Rear knuckle arm bearing                     |         | \$385.20 X  |
| 8           | 1   | Rear boot lid side lamp -RH                  |         | \$325.00 X  |
| 9           | 1   | Rear tail lamp-RH <i>ut</i>                  |         | \$425.00 ✓  |
| 10          | 4   | Rear tail lamp clips <i>New</i>              | \$8.50  | \$34.00 10  |
| 11          | 1   | Rear Bumper <i>Distorted</i>                 |         | \$895.00 ✓  |
| 12          | 2   | Rear Bumper Side Bracket <i>RH Damaged</i>   | \$68.00 | \$136.00 68 |
| 13          | 10  | Rear bumper clips <i>New</i>                 | \$6.50  | \$65.00 30  |
| 14          | 1   | rear bumper number plate                     |         | \$50.00 X   |
| 15          | 1   | Rear bumper reverse sensor -SET <i>3 New</i> |         | \$450.00 X  |
| Subtotal :- |     |                                              |         | \$6,919.60  |

1428

1285.10

Labour charges

To Remove & refix reverse Sensor

~~\$100.00~~ 50

To Remove & refix cushion

~~\$100.00~~ 40

Tuff kote

820

~~\$100.00~~ X

To Check Wiring System

~~\$80.00~~ 30

Panel beating

~~\$800.00~~ 300

Spray painting

~~\$800.00~~ 400

Subtotal :- \$1,980.00

Total:- \$8,899.60

total: 2105.20

H/S : 1650

04Days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: