

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7756X

MAKE :

MODEL : HYUNDAI SONATA

DATE 27/4/2019 11:39

AKK/kalwin
likeH/Sun
CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>Dent</i>			\$ 1,349.50
	Boot Lid Rubber <i>X su</i>			\$ 110.90
	Boot Lid Lock Upper <i>X su</i>			\$ 132.10
	Boot Lid Lock Lower <i>X su</i>			\$ 30.30
	Boot Lid Sonata Plate <i>X su</i>			\$ 43.60
	Boot Lid Hyundai Plate <i>X su</i>			\$ 24.20
	Boot Lid 'H' Emblem <i>— su</i>			\$ 26.10
	Boot Lid CRDI Plate <i>— su</i>			\$ 22.70
	Boot Lid Lamp (RH) <i>X su</i>			\$ 230.20
	Licence Lamp (RH) <i>X su</i>			\$ 32.50
	Rear Bumper <i>Rehild</i>			\$ 578.40
	Rear Bumper Reinforcement <i>X su</i>			\$ 483.30
	Rear Bumper Clip <i>— su</i>			\$ 22.00
	Rear Bumper Sponge <i>X su</i>			\$ 137.40
	Rear Bumper Under Cover <i>X su</i>			\$ 185.80
	Rear Bumper Protector (LH/RH) <i>X reg</i>		\$ 38.00	\$ 76.00
	Rear Panel <i>X reg</i>			\$ 391.80
	Rear Panel Garnish <i>X su</i>			\$ 95.80
	SUB TOTAL			\$ 3,972.60
	LESS 20%			\$ 794.52
	DISCOUNTED TOTAL			\$ 3,178.08
	Boot Lid City Cab Logo & Tel No. Sticker <i>— su</i>			\$ 30.00
	Rear No. Plate <i>X su</i>			\$ 25.00
	Rear Bumper Reverse Sensor <i>shld</i>			\$ 135.70
	Rear Bumper Advertisement Logo <i>— su</i>			\$ 50.00
	Rear Bumper Rubber Mat <i>— su</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) <i>— su</i>			\$ 200.00
				\$ 490.70
	Labour Charge			
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 750.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 80.00
	TOTAL LABOUR			\$ 1,780.00
	ESTIMATE TOTAL			\$ 5,448.78

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.