

## Veron Chen (LKKAuto)

---

**From:** glory.tan@premiumauto.com.sg  
**Sent:** Monday, 6 May 2019 4:16 PM  
**To:** SUR  
**Cc:** allan.wu@premiumauto.com.sg; claims@premiumautocare.com.sg; 'Claims'  
**Subject:** Check item photos for SKN 2658 K  
**Attachments:** WhatsApp Image 2019-05-03 at 10.25.09 AM.jpeg; WhatsApp Image 2019-05-03 at 10.25.31 AM.jpeg; WhatsApp Image 2019-05-03 at 10.25.42 AM.jpeg; WhatsApp Image 2019-05-03 at 10.25.51 AM.jpeg; WhatsApp Image 2019-05-03 at 10.26.02 AM.jpeg; WhatsApp Image 2019-05-03 at 10.26.16 AM.jpeg; WhatsApp Image 2019-05-03 at 10.26.25 AM.jpeg; WhatsApp Image 2019-05-03 at 10.26.41 AM.jpeg; WhatsApp Image 2019-05-03 at 10.26.49 AM.jpeg; WhatsApp Image 2019-05-03 at 10.27.05 AM.jpeg; WhatsApp Image 2019-05-03 at 10.27.15 AM.jpeg; WhatsApp Image 2019-05-03 at 10.27.31 AM.jpeg

Dear all,

Please refer to the attached for check item photos for SKN 2658 K.

Check Item number in marked estimate,

- 18. Horn-low torn. (SGD 262)
- 19. Horn bracket. (SGD 40)
- 23. Front fender brace-RH. (SGD 75)
- 26. Front wheel spoiler-RH. (SGD 242)
- 35. Headlight mounting-RH. (SGD 107)
- 41. Headlight lift cylinder-RH. (SGD 216)
- 42. Headlight lift cylinder hose-RH. (SGD 36)
- 43. Front bumper air guide-RH. (SGD 29)

Thank you.

Glory Tan

Bodyworks Department

**Premium Automobiles Pte Ltd** (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 f. +65 6841 1183

e. [glory.tan@premiumauto.com.sg](mailto:glory.tan@premiumauto.com.sg) w. [www.audi.com.sg](http://www.audi.com.sg)

**Audi Showroom, Audi Centre** 281 Alexandra Road Singapore 159938 p. +65 6836 2223

