

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0539/2019/DY/TF
Date : 26-Apr-19

Vehicle IS IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Ma Yulin
Address : Blk 943 Bukit Timah Road
#04-48
Singapore 589659
Telephone : HP +65 81387755
Type of Claim : Own Damage Claims
Policy No. : 2100374712-04
Vehicle No : **SKN 2658 K**
Model Code : Audi A6 C7 2.0 TFSI MU 4G
Model / Year : May-14
Engine No : CDN 407176
Chassis No : WAUZZZ4G6EN130090
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-Apr-19
Place of Accident : Bukit Timah Road Near Nexus

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKN 2658 K

S/n	Nature of Jobs		Estimated Charges	
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	s/n	\$ 360.00	✓
2	To dismantle and renew front bumper, bonnet, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.		\$ 3,150.00	1750
3	To respray front bumper, bonnet, hinges and rhs front fender. ✓		\$ 3,000.00	1650
4	To carry out diagnostic check.	s/n	\$ 192.00	✓
TOTAL LABOUR CHARGES			\$ 6,702.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKN 2658 K

<u>S/N</u>	<u>Parts Description</u>		<u>Damaged Parts & Prices</u>	
			<u>S/Nett</u>	
1	FRONT BUMPER <i>rehd</i>	\$	2,443.00	✓
2	FRONT BUMPER FIXING PARTS <i>rehd</i>	\$	249.00	+
3	FRONT BUMPER CLOSING ELEMENT <i>rehd</i>	\$	173.00	+
4	FRONT BUMPER SPOILER <i>rehd</i>	\$	227.00	+
5	RADIATOR GRILLE <i>green</i>	\$	1,227.00	+
6	RADIATOR GRILLE REAR COVER <i>green</i>	\$	33.00	+
7	FRONT BUMPER AIR GRILLE END CAP - RH <i>rehd</i>	\$	130.00	+
8	FRONT BUMPER AIR GRILLE - RH <i>Missing</i>	\$	139.00	✓
9	FOAM FILLER PIECE <i>?</i>	\$	90.00	?
10	FRONT BUMPER REINFORCEMENT <i>?</i>	\$	754.00	?
11	FRONT BUMPER TOP COVER <i>?</i>	\$	112.00	?
12	FRONT BUMPER GUIDE PIECE - RH <i>rehd</i>	\$	34.00	✓
13	CAUTION STICKER <i>?</i>	\$	13.00	?
14	A/C STICKER <i>rehd</i>	\$	18.00	✓
15	FRONT BUMPER HOLDER BRACKET - RH <i>rehd</i>	\$	237.00	+
16	FRONT BUMPER SENSOR <i>green</i>	2 \$	441.00	+
17	FRONT BUMPER SENSOR SEAL <i>green</i>	4 \$	5.00	+
18	HORN - LOW TONE <i>green</i>	\$	262.00	+
19	HORN BRACKET	\$	40.00	+
20	FRONT FENDER - RH <i>Dented</i>	\$	1,269.00	✓
	SUB-TOTAL SPARE PARTS CHARGES		\$ 7,896.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKN 2658 K

<u>S/N</u>	<u>Parts Description</u>		<u>Damaged Parts & Prices</u>
			<u>S/Nett</u>
21	FRONT FENDER ATTACHMENT PARTS ?	\$	38.00 ?
22	FRONT FENDER STONE GUARD FILM - RH <i>new</i>	\$	110.00 ✓
23	FRONT FENDER BRACE - RH ?	\$	75.00 ?
24	FRONT WHEEL HOUSING LINER - RH <i>new</i>	\$	256.00 +
25	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$	72.00 +
26	FRONT WHEEL SPOILER - RH <i>new</i>	\$	242.00 +
27	FRONT BONNET <i>Dented</i>	\$	4,965.00 ✓
28	FRONT BONNET ATTACHMENT PARTS ?	\$	130.00 ?
29	FRONT BONNET HINGE - LH / RH ?	\$	292.00 X
30	FRONT BONNET CATCH <i>not</i>	\$	127.00 +
31	FRONT BONNET LOCK BAR <i>new</i>	2 \$	90.00 +
32	FRONT BONNET LOCK WITH MICRO SWITCH <i>new</i>	\$	196.00 +
33	FRONT BONNET BOWDEN CABLE ?	\$	53.00 +
34	FRONT BONNET LOCK COVER <i>new</i>	\$	9.00 +
35	HEADLIGHT MOUNTING - RH <i>seen</i>	\$	107.00 +
36	HEADLIGHT - RH <i>could</i>	\$	3,050.00 ✓
37	HEADLIGHT GAS DISCHARGE BULB - RH ?	\$	398.00 +
38	HEADLIGHT POWER MODULE - RH <i>new</i>	\$	520.00 X
39	HEADLIGHT CONTROL UNIT - RH <i>new</i>	\$	1,051.00 +
40	HEADLIGHT VENTILATION HOSE - RH	\$	15.00 +
SUB-TOTAL SPARE PARTS CHARGES		\$	11,796.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKN 2658 K

<u>S/N</u>	<u>Parts Description</u>		<u>Damaged Parts & Prices</u>
			<u>S/Nett</u>
41	HEADLIGHT LIFT CYLINDER - RH		\$ 216.00 X
42	HEADLIGHT LIFT CYLINDER HOSE - RH		\$ 36.00 X
43	FRONT BUMPER AIR GUIDE - RH		\$ 29.00 X
44	FRONT BUMPER SEALING STRIP - RH		\$ 21.00 X
45	FRONT BUMPER INNER COVER - UPPER CENTRE		\$ 27.00 X
46	FRONT NO. PLATE	rel m	\$ 40.00 X
47	SUNDRIES	?	\$ 700.00 ?
TOTAL SPARE PARTS CHARGES			\$ 20,761.00
TOTAL LABOUR CHARGES			\$ 6,702.00
GRAND TOTAL			\$ 27,463.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 29/04/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 06 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant