

22/03/2019

REF: CS/smo/19007566/T1vd3524 Special Instruction:

SS. REC. BY:

Surveyor: Taufik

ASSIGNMENT (Office)

Date/Time: 30.4.19 9.09.19.m

From (Person): Gniah Pan Long

of SMO

Bill to:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

Insured:

To Inspect Vehicle No: SKZ 6439K

Tel: 64819517 | 9274 0999

at Workshop m/s Accord Auto Service

of 10 Amc Ind Rite 2A #03-11

Claim No: CMIT 1902077

Policy No: D19MTPV01000336

Excess:

Waive

Sum Insured:

D.O.A. 26.4.2019

Make of Veh:

(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time: 30.4.19 10.19.19.m

Person Contacted:

Jessie

Vehicle IN / OUT

Date/Time Action/Instruction Estimate (✓) SKZ 6439K - NA/TM 13002382/K4 D.O.A. = 05/02/2018

30/4/19 Rece authorize repair via merimen ex waived
30/4/19 Informed Celia c/A ex waived by email
2/5/19 Rece email from Celia vehicle can't repair LS
2/5/19 @ 1232pm Spoken to Pan Long proceed on part by part

REF: sm0

ASSIGNMENT

From:

Date: 30.4.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKZ 6939K

at Workshop n/s Accord Auto

of Blk 1009 Bukit Merah Lane 3 #01-80

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / (REV) / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKZ 6939K

Yr Regn:

206, Jun

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Maya 5

C.C.

1998

Colour:

Brnze

AC:

Insured / Std / NI / NA

Sp. Reading:

7098

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

30/4/19 04pm

Survey held at

Accord Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s, 4/C.

The U/C / Chassis frame / Body Structure affected due to collision.

Rebate \$48,220

Date / Time

Action / Instruction

16/5/19

Pending Supplementary approval

18/6/19

Final fig \$ 9442.57 confirmed by email (Ref 1972.30, 1790)

RECEIVED 18 JUN 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

15/6 - typist

Days Of Repair:

0

Resurvey No. of Trip:

>

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

merimen

Lump Sum / L.B.I. (\$)

9442.57

11

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Apr 2019 Sendback Est	29 Apr 2019 18:36 S\$8,843.00	30 Apr 2019 09:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	SIM JIXUAN, ID: S8819679A, Tel: +6598453430, Email: jixuan.s@gmail.com								
Vehicle Reg. No.:	SKZ6939K	Date of Loss:	26/04/2019 19:00 - :59 [38 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / CMTD1902077	Policy/Cover Note No.:	D19MTPV01000336 (Comprehensive)						
		Excess:							
Repairer:	Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point, 568047 Ang Mo Kio - Tel: 64819517/85715140								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/05/2019]								
Driver/Custodian:	SIM JIXUAN (30 / Male), NRIC: S8819679A, Tel: +6598453430 Email: jixuan.s@gmail.com								
Adj Asg. Remarks:	VEH AT BM - FOR EXCESS & AUTHORISATION, PLEASE REFER TO THE HANDLER								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

SKZ6939K (CMTD1902077)

OD

Apr 26 2019 7:00PM

[SIM JIXUAN]

Accord Auto Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Sampo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 18/06/2019 12:21 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$9442.57) - SKZ6939K - Claim Handler: GNOH PAU LOONG

Approved:9442.57.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	Sompo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	GNOH PAU LOONG	Date:	18 Jun 2019
Preliminary Advice			

Vehicle No	: SKZ6939K	Accident Date	: 26/04/2019
Make	: MAZDA 5	Policy No.	: D19MTPV01000336
Assignment Date	: 30/04/2019	Excess	: S\$0.00
Date of Inspection	: 30/4/2019	Est. Duration of Repair	: 10
Inspection At	: ACCORD AUTO SERVICES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,414.87 (incl.supplementary \$104.50)
Revised Amount	:S\$	9,442.57 (incl.supplementary \$104.50)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,442.57
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	48,220.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,780.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 17 May 2019 1:26 PM
To: Accord Claims(AV); SUR
Subject: RE: SKZ 6939K-DOA: 26/4/2019 (SOMPO OD)
Attachments: SUPPLEMENTARY MARKING.pdf

Dear Celia,

Insurance has approved the supplementary.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 30 April 2019 5:34 PM
To: Accord Claims(AV) <avclaims@mycarworkshop.com.sg>; SUR <sur@lkkauto.com>
Subject: SKZ 6939K-DOA: 26/4/2019 (SOMPO OD)

Dear Celia,

As instructed by our client , please proceed to repair the **insured vehicle SKZ 6939K (Excess WAIVED)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SKZ6939K (CMTD1902077)

OD

Apr 26 2019 7:00PM

[SIM JIXUAN]

Accord Auto Services Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From Sampo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 17/05/2019 13:11 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$9873.37) - SKZ6939K - Claim Handler: GNOH PAU LOONG

Approved:9873.37.

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 17 May 2019 1:22 PM
To: Gnoh, Pau Loong; SUR
Subject: RE: Sompom ref : CMTD1902077 ; SKZ6939K: Adj. Mandate Request

Dear Pau Loong,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Gnoh, Pau Loong <PauLoong.Gnoh@sompom.com.sg>
Sent: Friday, 17 May 2019 1:13 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: FW: Sompom ref : CMTD1902077 ; SKZ6939K: Adj. Mandate Request

Dear Veron,

As spoken for the above, mandate approved for the supplementary parts, thank you.

Best Regards

Gnoh Pau Loong

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompom Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompom.com.sg | **Facebook:** www.facebook.com/SompomSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompom SG



Download now @

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: do-not-reply@sompo.com.sg <do-not-reply@sompo.com.sg>
Sent: Wednesday, 15 May, 2019 6:40 PM
To: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>
Subject: Sompo ref : CMTD1902077 ; SKZ6939K: Adj. Mandate Request

This mail is associated with :
SKZ6939K (CMTD1902077)
OD

Apr 26 2019 7:00PM
[SIM JIXUAN]

Accord Auto Services Pte Ltd

There is a new adjuster mandate request for the above case. Please login to Merimen using your UserID PAULOONG to process the mandate request.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 15 May 2019

Preliminary Advice

Vehicle No	: SKZ6939K	Accident Date	: 26/04/2019
Make	: MAZDA 5	Policy No.	: D19MTPV01000336
Assignment Date	: 30/04/2019	Excess	: S\$0.00
Date of Inspection	: 30/04/2019	Est. Duration of Repair	: 8 days
Inspection At	: Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,310.37 (inclusive supplementary)
Revised Amount	:S\$	9,020.37 (inclusive supplementary)
Check Items (Estimated)	:S\$	853.00 (inclusive supplementary)
Total	:S\$	9,873.37
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	48,220.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,780.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : SUPPLEMENTARY AMOUNT IS \$ 2,467.37

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 2 May 2019 12:43 PM
To: Accord Claims(AV); Taufikh (LKKAUTO)
Cc: Gnoh, Pau Loong; Admin A; Admin-D (LKKAUTO)
Subject: RE: Own Damage Claim SKZ6939K DOA:26.4.2019

Dear Celia,

As instructed by our client, please proceed to repair the **insured vehicle SKZ 6939K on part by part (Excess WAIVED)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Accord Claims(AV) <avclaims@mycarworkshop.com.sg>

Sent: Thursday, 2 May 2019 10:26 AM

To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>

Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>

Subject: Own Damage Claim SKZ6939K DOA:26.4.2019

Morning Taufikh,

Fyi, for this own damage claim can't repair by lump sum. No used parts available.

Kindly advise.

Thank you.

Kind regards,
Celia Lai

Accord Auto Services Pte Ltd
Blk 1009 Bukit Merah Lane 3

#01-80

Singapore 159723

Mobile: (65) 9274 0999

Tel : (65) 6271 7433

Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

Veron Chen (LKKAUTO)

From: Accord Claims(AV) <avclaims@mycarworkshop.com.sg>
Sent: Thursday, 2 May 2019 10:26 AM
To: Taufikh (LKKAUTO)
Cc: Gnoh, Pau Loong; Admin A; Admin-D (LKKAUTO)
Subject: Own Damage Claim SKZ6939K DOA:26.4.2019

Morning Taufikh,

Fyi, for this own damage claim can't repair by lump sum. No used parts available.

Kindly advise.

Thank you.

Kind regards,
Celia Lai

Accord Auto Services Pte Ltd
Blk 1009 Bukit Merah Lane 3
#01-80
Singapore 159723

Mobile: (65) 9274 0999
Tel : (65) 6271 7433
Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 30 April 2019 5:34 PM
To: Accord Claims(AV); SUR
Subject: SKZ 6939K-DOA: 26/4/2019 (SOMPO OD)

Dear Celia,

As instructed by our client , please proceed to repair the **insured vehicle SKZ 6939K (Excess WAIVED)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SKZ6939K (CMTD1902077)

OD

Apr 26 2019 7:00PM

[SIM JIXUAN]

Accord Auto Services Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From Grace Teo (GraceTeo), sent on **30/04/2019 17:17 PM**.
To LKK_HQ; pauloong.gnoh@sompo.com.sg
CC PauLoong
Subject **OD EXCESS & AUTHORISATION**

Hi LKK,

Please be informed of the followings:-

To authorise if consistent.
Excess waived

Thanks

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	Sompo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	GNOH PAU LOONG	Date:	02 May 2019

Preliminary Advice

Vehicle No	: SKZ6939K	Accident Date	: 26/04/2019
Make	: MAZDA 5	Policy No.	: D19MTPV01000336
Assignment Date	: 30/04/2019	Excess	: S\$0.00
Date of Inspection	: 30/4/2019	Est. Duration of Repair	: 8
Inspection At	: ACCORD AUTO SERVICES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,843.00
Revised Amount	:S\$	7,181.00
Check Items (Estimated)	:S\$	615.00
Total	:S\$	7,796.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	48,220.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,780.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Vehicle repair on part by part as there is no 2nd parts available

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/04/2019 13:01
Date Of Accident	26/04/2019 19:00
Exact Location Of Accident	KAMPUNG BAHRU ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ6939K
Insured/Policyholder	
Name Of Registered Owner	SIM JIXUAN
NRIC No	S8819679A
Email Address	JIXUAN.S@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98453430
Alternative Phone No	OFFICE-98453430

Vehicle Particulars

Manufacturer	MAZDA
Model	5-2.0 5 DR WAGON (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D19MTPV01000336
Cover Note Number	

Driver

Name of Driver	SIM JIXUAN
NRIC No	S8819679A
Date Of Birth	07/06/1988
Occupation	INDOOR
Date Of Driving Pass	31/08/2007
Driving Experience	11 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98453430
Fax Number	
Contact Number	OFFICE-98453430
EEmail Address	JIXUAN.S@GMAIL.COM

Address	BLK 278 BISHAN STREET 24 #18-66
Postcode	570278
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 26/04/2019 about 7pm, vehicle A (SKZ6939K) was trying to filter to lane 2 and bang into vehicle B (SKE6751U) left rear bumper.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKE6751U
Vehicle Make/Model/Colour	CHEVROLET CRUZE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KOH SEE ENG
NRIC/Passport Number	S1234572J
Contact Number	96282689
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Passenger 1

NAME: :

GENDER: :

Accident Sketch Plan Pg. 1

SKETCH PLAN

Veh A: SKZ 6939K
Veh B: SKE 67514

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

Policyholder's Signature
Date & Time:

27/4/19

Driver's Signature
(If driver is not the policyholder)
Date & Time:

27/4/19

Reporting Centre Personnel's Signature
Name: Jessy See
NRIC/FIN No.: G0031072W




SKETCH PLAN

Veh A:

Veh B:

Kampong Bahru



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Veh A: SKZ 6939K

Veh B: 6751 M

Veh A was trying to filter to lane 2 and being into Veh B left rear bumper -

DECLARATION


DECLARATION
I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

27/4/19

Reporting Centre Personnel's Signature
Name: Jessy Soe
NRIC/FIN No.: 92031072W




SKETCH PLAN

Veh A:

Veh B:

Kampong Bahru.



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Veh A : SKZ 6939K

Veh B: 6751 M

Veh A was trying to filter to lane 2 and banging into veh B left rear bumper -

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature _____

(If driver is not the policyholder)


Date & Time:

27/4/19

Reporting Centre Personnel's Signature

Name: Jessy Doe

NRIC/FIN No.: 92031072 W



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9679A
Vehicle Details	
Vehicle No.:	SKZ6939K
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Apr 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 5-DOOR WAGON 2.0L SP6EAT SUNROOF
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	PE10302056
Chassis No.:	JM6CW1071G0123244
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$19,268.00
Original Registration Date:	29 Jan 2016
First Registration Date:	29 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$19,268.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jan 2026
PARF Rebate Amount:	\$14,451.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jan 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$51,000.00
COE Rebate Amount:	\$33,769.00
Total Rebate Amount:	\$48,220.00

The information contained herein is correct as at 30 Apr 2019

OK

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER: Somp Insurance Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D19MTPV01000336	Date of Loss:	26/04/2019
Vehicle Reg. No.:	SKZ6939K	Driveable?	NO
Driver Age/Info:	30 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SIM JIXUAN	Contact No:	+6598453430
Driver:	SIM JIXUAN		

Make/Model:	MAZDA 5, 2.0 5 DR WAGON (A)	Vehicle Reg. Date:	29/01/2016
Vehicle Colour:	GREY	Chassis No:	JM6CW1071G0123244
Engine No:	PE10302056		
Odometer:	0 KM		

Paint Type:
Total Loss?
Est. Duration of Repair (day)

NO
10

Handwritten:
Lump sum -
Resurvey after repair
sure/known before

Handwritten:
Tanfilla 97495749 / 674/8434
Not Authorise
30/4/19 24pm
Ex: to be advise.
08 days

Description of Accident/Loss: ON 26/04/2019 ABOUT 7PM, VEHICLE A (SKZ6939K) WAS TRYING TO FILTER TO LANE 2 AND BANG INTO VEHICLE B (SKE6751U) LEFT REAR BUMPER.

Remarks: VEHICLE IN WORKSHOP (AV) TEL: 6271 7433.

Present Location: ACCORD AUTO SERVICES PTE LTD (AV) TEL: 6271 7433

COST OF CLAIMS

		Amount
Parts		5,533.00
Miscellaneous Items		180.00
Labour		3,130.00
Paintwork Labour		0.00
Towing		0.00
Gross Total (S\$)		8,843.00
+ GST 7.00% (S\$)		619.01
Nett Amount (S\$)		9,462.01

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This claim is handled by: SOE JIE YI (JESSY)

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Bonnet insulator pad clip	50.00 ³⁰
2	1	Front bumper clip	50.00 ³⁰
3	1	Front RH fender splash shield clip	50.00 ²⁰
4	1	RH headlamp bulb	30.00
Sub Total (S\$)			180.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Spray painting on all affected area.	New	750.00 ⁷⁰⁰
2	Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	New	800.00 ⁷⁰⁰
3	To check wiring system & light.	New	80.00 ³⁰
4	To check & adjust computer/wheel alignment.	New	120.00 ⁸⁰
5	To remove and replace front RH rim, tyre and balancing.	New	60.00 ³⁰
6	To remove and replace power steering pump and high pressure pipe.	New	250.00 ¹⁰⁰
7	To remove and replace engine mounting.	New	120.00 [?]
8	To adjust and remain front chassis.	New	300.00 ^{photo 200}
9	To remove and reinstall air-con condenser, radiator & etc. to assist on repair.	New	300.00 ¹²⁰
10	To remove and replace front RH suspension and drive shaft.	New	350.00 ¹⁵⁰
Gross Labour Cost (S\$)			3,130.00

Accord Auto Services Pte Ltd/SKZ6939K/29/04/2019 18:36. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Accord Auto Services Pte Ltd (Co.Reg.No.201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER:

Sompo Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	26/04/2019
Policy No:	D19MTPV01000336	Date of Loss:	NO
Vehicle Reg. No.:	SKZ6939K	Driveable?	UNKNOWN
Driver Age/Info:	30 / MALE	Party At Fault:	YES
TP Injury Involved?	NO	Third Party Involved?	+6598453430
Insured/Claimant:	SIM JIXUAN	Contact No:	
Driver:	SIM JIXUAN		

Make/Model:	MAZDA 5, 2.0 5 DR WAGON (A)	Vehicle Reg. Date:	29/01/2016
Vehicle Colour:	GREY	Chassis No:	JM6CW1071G0123244
Engine No:	PE10302056		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		

Lump sum - Resurvey after repair sure/Member

Tanfilin 97495749/674/8434
Not authorize 30/4/19 24pm
Ex: to be advise. 08 days

Description of Accident/Loss

ON 26/04/2019 ABOUT 7PM, VEHICLE A (SKZ6939K) WAS TRYING TO FILTER TO LANE 2 AND BANG INTO VEHICLE B (SKE6751U) LEFT REAR BUMPER.

Remarks:

VEHICLE IN WORKSHOP (AV) TEL: 6271 7433.

Present Location:

ACCORD AUTO SERVICES PTE LTD (AV) TEL: 6271 7433

COST OF CLAIMS

Parts
Miscellaneous Items
Labour
Paintwork Labour
Towing

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Gross Total (S\$)

Amount

5,533.00

180.00

3,130.00

0.00

0.00

8,843.00

Acknowledged by Repairer

+ GST 7.00% (S\$)

619.01

Signature:

Nett Amount (S\$)

9,462.01

Date:

This claim is handled by: SOE JIE YI (JESSY)

4/30/2019

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 29 Apr 2019)
 Parts: N/A MAZDA 5 2.0 5 DR WAGON (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Accord Auto Services Pte Ltd/SKZ6939K/29/04/2019 18:36
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet	0.00	0.00	bt - *410.00 F
2	2		*Bonnet hinge	0.00	0.00	bt - *46.00 F
3	1		*Bonnet lock	0.00	0.00	x - *70.00 F
4	1		*Bonnet cable	0.00	0.00	2 - *25.00 F
5	1		*Bonnet insulator pad	0.00	0.00	de - *55.00 F
6	1		*Bonnet seal	0.00	0.00	de - *15.00 F
7	1		*LH headlamp	0.00	0.00	are - *470.00 F
8	1		*RH headlamp	0.00	0.00	as - *470.00 F
9	1		*Front RH fender	0.00	0.00	bt - *125.00 F
10	1		*Front RH fender splash shield	0.00	0.00	pu - *85.00 F
11	1		*Front bumper	0.00	0.00	de - *320.00 F
12	1		*Front bumper logo	0.00	0.00	na - *25.00 F
13	1		*Front bumper grille	0.00	0.00	de - *210.00 F
14	1		*Front bumper fog lamp (RH)	0.00	0.00	ar - *125.00 F
15	1		*Front bumper fog lamp cover (RH)	0.00	0.00	ar - *30.00 F
16	1		*Front bumper sponge	0.00	0.00	de - *35.00 F
17	1		*Front bumper reinforcement	0.00	0.00	bt - *240.00 F
18	2		*Front bumper side retainer	0.00	0.00	ar - *20.00 F
19	1		*Front bumper under cover	0.00	0.00	? - *120.00 F
20	1		*Support panel	0.00	0.00	are - *150.00 F
21	1		*Washer tank	0.00	0.00	de - *60.00 F
22	1		*Washer tank cover	0.00	0.00	de - *8.00 F
23	1		*Washer tank motor	0.00	0.00	de - *38.00 F
24	1		*Front RH shock absorber	0.00	0.00	bt - *130.00 F
25	1		*Front RH shock absorber mounting	0.00	0.00	ne - *45.00 F
26	1		*Front RH lower arm	0.00	0.00	bt - *130.00 F
27	1		*Front RH knuckle arm	0.00	0.00	bt - *135.00 F
28	1		*Front RH wheel bearing hub	0.00	0.00	bt - *65.00 F
29	1		*Front RH wheel bearing	0.00	0.00	ne - *48.00 F
30	1		*Front RH tie rod end	0.00	0.00	? - *45.00 F
31	1		*Front RH rack end	0.00	0.00	? - *50.00 F
32	1		*Power steering pump	0.00	0.00	ma - *870.00 F
33	1		*Power steering high pressure pipe	0.00	0.00	? - *95.00 F
34	1		*Engine mounting (RH)	0.00	0.00	? - *50.00 F
35	1		*Horn	0.00	0.00	? - *65.00 F
36	1		*Wiper garnish/cover	0.00	0.00	de - *150.00 F
37	1		*RH drive shaft *no price	0.00	0.00	? - *F

F=Franchise part.

Sub Total (\$\$) 5,030.00
 + Margin on L,N Items 10.00% (\$\$) 503.00
 Total Parts (\$\$) 5,533.00

Accord Auto Services Pte Ltd/SKZ6939K/29/04/2019 18:36. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars
<u>Miscellaneous Items</u>		
1	1	Bonnet insulator pad clip
2	1	Front bumper clip
3	1	Front RH fender splash shield clip
4	1	RH headlamp bulb

Amount

NH 50.00 30
 ne 50.00 30
 ne 50.00 20
 Chd 30.00

Sub Total (S\$) 180.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Spray painting on all affected area.	New	700. 750.00
2	Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	New	700 800.00
3	To check wiring system & light.	New	30. 80.00
4	To check & adjust computer/wheel alignment.	New	80. 120.00
5	To remove and replace front RH rim, tyre and balancing.	New	30. 60.00
6	To remove and replace power steering pump and high pressure pipe.	New	100. 250.00
7	To remove and replace engine mounting.	New	? 120.00
8	To adjust and remain front chassis.	New photo	200 300.00
9	To remove and reinstall air-con condenser, radiator & etc. to assist on repair.	New	120. 300.00
10	To remove and replace front RH suspension and drive shaft.	New	150. 350.00
Gross Labour Cost (S\$)			3,130.00

Accord Auto Services Pte Ltd/SKZ6939K/29/04/2019 18:36. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworks.com.sg

* No' Excess !

* Part by Parts !

INSURER:

Sompo Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D19MTPV01000336	Date of Loss:	26/04/2019
Vehicle Reg. No.:	SKZ6939K	Driveable?	NO
Driver Age/Info:	30 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SIM JIXUAN	Contact No:	+6598453430
Driver:	SIM JIXUAN		

Make/Model:	MAZDA 5, 2.0 5 DR WAGON (A)	Vehicle Reg. Date:	29/01/2016
Vehicle Colour:	GREY		
Engine No:	PE10302056	Chassis No:	JM6CW1071G0123244
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Lumpsum -
Reserving after repair
sure/known to be

Tanfilin 97495749 / 674/8434
Not Authorise
30/4/19 24pm
Ex: to be advise.
08 days 10 days

Description of Accident/Loss: ON 26/04/2019 ABOUT 7PM, VEHICLE A (SKZ6939K) WAS TRYING TO FILTER TO LANE 2 AND BANG INTO VEHICLE B (SKE6751U) LEFT REAR BUMPER.

Remarks: VEHICLE IN WORKSHOP (AV) TEL: 6271 7433.

Present Location: ACCORD AUTO SERVICES PTE LTD (AV) TEL: 6271 7433

COST OF CLAIMS

	Amount
Parts	5,533.00
Miscellaneous Items	180.00
Labour	3,130.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	8,843.00
+ GST 7.00% (S\$)	619.01
Nett Amount (S\$)	9,462.01

This claim is handled by: SOE JIE YI (JESSY)

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Bonnet insulator pad clip	AM 50.00 30
2	1	Front bumper clip	ne 50.00 30
3	1	Front RH fender splash shield clip	ne 50.00 20
4	1	RH headlamp bulb	Car 30.00
Sub Total (S\$)			180.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Spray painting on all affected area.	New	700 750.00
2	Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	New	700 800.00
3	To check wiring system & light.	New	30 80.00
4	To check & adjust computer/wheel alignment.	New	80 120.00
5	To remove and replace front RH rim, tyre and balancing.	New	30 60.00
6	To remove and replace power steering pump and high pressure pipe.	New	100 250.00
7	To remove and replace engine mounting.	New	ny X? 120.00
8	To adjust and remain front chassis.	New photo	200 300.00
9	To remove and reinstall air-con condenser, radiator & etc. to assist on repair.	New	120 300.00
10	To remove and replace front RH suspension and drive shaft.	New	150 350.00
Gross Labour Cost (S\$)			3,130.00

Accord Auto Services Pte Ltd/SKZ6939K/29/04/2019 18:36. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Supp

- 1) * Minor Front Garnish \$ 25/
- 2) Headlamp Lower Bracket \$ 15/
- 3) Side Skirt RH \$ 380/
- 4) Wiper Garnish Side LH & RH \$ 15 x 2/
- 5) ~~Rim \$ 450 (?)~~
- 6) Front RH Door \$ 400/
- 7) ~~Front Wheel Apron RH \$ 320/~~
- 8) Front RH Door Sticker upper \$ 28
- 9) Front RH Door Sticker Side \$ 20
- 10) Front RH Fender Stay \$ 18
- 11) Front RH Fender Stay upper \$ ~~110.70~~ 110.70

S/N Supp

- 1) Tyre \$ 220/
- 2) Number Plate Frame \$ 18/

Accord Auto Services Pte Ltd (Co.Reg No 201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

(SUPPLEMENTARY)**INSURER: Sompoo Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	D19MTPV01000336	Date of Loss:	26/04/2019
Vehicle Reg. No.:	SKZ6939K	Driveable?	NO
Driver Age/Info:	30 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SIM JIXUAN	Contact No:	+6598453430
Driver:	SIM JIXUAN		
Make/Model:	MAZDA 5, 2.0 5 DR WAGON (A)	Vehicle Reg. Date:	29/01/2016
Vehicle Colour:	Grey		
Engine No:	PE10302056	Chassis No:	JM6CW1071G012324
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	ON 26/04/2019 ABOUT 7PM, VEHICLE A (SKZ6939K) WAS TRYING TO FILTER TO LANE 2 AND BANG INTO VEHICLE B (SKE6751U) LEFT REAR BUMPER.		
Present Location:	ACCORD AUTO SERVICES PTE LTD (AV) TEL: 6271 7433		

COST OF CLAIMS	Amount
Parts	1,129.37
Miscellaneous Items	238.00
Labour	300.00
Paintwork Labour	800.00
Towing	0.00
Gross Total (S\$)	2,467.37
+ GST 7.00% (S\$)	172.72
Nett Amount (S\$)	2,640.09
+ Previous Estimates (S\$)	9,462.01
Claim Total (S\$)	12,102.10

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRON NUMBER PLATE FRAME	18.00
2	1	TYRE	220.00
Sub Total (S\$)			238.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAY PAINTING FRONT FENDER . FRONT LH & RH DOOR AND RH SIDE SKIRT	New	800.00
<u>Labour Items</u>			
2	To Remove/ Replace/ Refix Front RH Door Inner Compartment , Window Glass ,Mechemism & Assy To New Door	New	150.00
3	To Repair Front LH Fender ,Front LH Door On Damage And Install Side RH Skirt	New	150.00
Gross Labour Cost (S\$)			1,100.00

Accord Auto Services Pte Ltd/SKZ6939K/13/05/2019 20:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

(SUPPLEMENTARY)**INSURER: Somp Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D19MTPV01000336	Date of Loss:	26/04/2019
Vehicle Reg. No.:	SKZ6939K	Driveable?	NO
Driver Age/Info:	30 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SIM JIXUAN	Contact No:	+6598453430
Driver:	SIM JIXUAN		
Make/Model:	MAZDA 5, 2.0 5 DR WAGON (A)	Vehicle Reg. Date:	29/01/2016
Vehicle Colour:	GREY	Chassis No:	JM6CW1071G0123244
Engine No:	PE10302056		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		

Description of Accident/Loss ON 26/04/2019 ABOUT 7PM, VEHICLE A (SKZ6939K) WAS TRYING TO FILTER TO LANE 2 AND BANG INTO VEHICLE B (SKE6751U) LEFT REAR BUMPER.

Present Location: ACCORD AUTO SERVICES PTE LTD (AV) TEL: 6271 7433

COST OF CLAIMS

	Amount
Parts	104.50
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	104.50
+ GST 7.00% (S\$)	7.32
Nett Amount (S\$)	111.82
+ Previous Estimates (S\$)	12,102.10
Claim Total (S\$)	12,213.92

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 11 Jun 2019)**Parts:** N/A MAZDA 5 2.0 5 DR WAGON (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Accord Auto Services Pte Ltd/SKZ6939K/11/06/2019 15:43**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*PLATE SEAL RH(Inner Bumper Rh Bracket-Missing)	<i>mis</i> ✓ 0.00	0.00	*15.00 F
2	1		*SEAL PLATE ENGINE RH(Under Engine Cover Side-Missing)	<i>mis</i> ✓ 0.00	0.00	*20.00 F
3	1		*STOPER (At Support-Missing)	<i>mis</i> ✓ 0.00	0.00	*7.00 F
4	1		*COVER H/LAMP (Small-Missing)	<i>mis</i> ✓ 0.00	0.00	*10.00 F
5	1		*COVER H/LAMP (Inner-Missing)	<i>mis</i> ✓ 0.00	0.00	*20.00 F
6	1		*SOCKET H/LAMP SIGNAL (Missing)	<i>mis</i> ✓ 0.00	0.00	*8.00 F
7	1		*POWER STEERING SUCTION (Between Power Steering Pump To Tank)	<i>dis</i> ✓ 0.00	0.00	*15.00 F

F=Franchise part.

Sub Total (\$\$)	95.00
+ Margin on L,N Items 10.00% (\$\$)	9.50
Total Parts (\$\$)	104.50

Accord Auto Services Pte Ltd/SKZ6939K/11/06/2019 15:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Accord Auto Services Pte Ltd/SKZ6939K/11/06/2019 15:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450816 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

ARRANGE BY
DRIVER



Wiper blade: NWB (Nippon Wiper blade) SAE (Made in Korea)
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

=====

ACCORD AUTO SERVICES PTE LTD(AV)
BLK 1009 #01-80
BUKIT MERAH LANE 3

SINGAPORE 159723
TEL : 6271 5133 FAX : 6274 5715
ATTN : CELIA

SEND TO: BLK 1004 #01-29 BUKIT MERAH LANE 3

TAX INVOICE : AR201905-02387
DATE : 06/05/2019
CUSTOMER ID : ACC003
VEH REG. NO. : SKZ6939K
TERMS : 30 days
PO NO.
PAGE NO. : Page 1 of 1
CURR. : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	C513-53-27YA MZ5 CW 10-	F.W/HOUSE TOP RH (Supp Est No. 9)	UI SUPPLIER	1	110.70	110.70

Handwritten signature

SUB-TOTAL : 110.70
ADD GST 7.00 % 7.75

E. & O.E TOTAL AMOUNT S\$: 118.45

[P] 06/05/2019 2:38:49PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 06/05/2019 2:37:29PM

JAE Auto Pte. Ltd.

Sales Executive : ALAN

This is computer generated document.
No signature is required.



* AR201905-02387 *

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 9791 / 6745 9526



Dept Direct: 6256 6410



Dept Direct: 6417 9794



Dept Direct: 6256 6410



Dept Direct: 6417 9795




Dept Direct: 6256 6410



Dept Direct: 6417 9796



Dept Direct: 6256 6410



Dept Direct: 6417 9797



Dept Direct: 6256 6410



Dept Direct: 6417 9798

Wiper blade: NWB (Nippon Wiper blades - Seiper - Made in Korea)
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

=====

ACCORD AUTO SERVICES PTE LTD(AV)
BLK 1009 #01-80
BUKIT MERAH LANE 3

SINGAPORE 159723
TEL : 6271 5133 FAX : 6274 5715
ATTN : CELIA

SEND TO: BLK 1004 #01-29 BUKIT MERAH LANE 3

TAX INVOICE : AR201905-01355
DATE : 03/05/2019
CUSTOMER ID : ACC003
VEH REG. NO. : SKZ6939K
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. BBM6-67-481 MZ3 SD 09--	TANK F WIPER (W/O PUMP) (Est No. 21)	U1 SUPPLIER	1	65.00	65.00
2. CS13-66-79Y MZ5 11-	HORN RH (Est No. 35)	U1 SUPPLIER	1	45.00	45.00

[Handwritten signature]

SUB-TOTAL : 110.00
ADD GST 7.00 % 7.70

E. & O.E TOTAL AMOUNT S\$: 117.70

[P] 03/05/2019 3:33:49PM

[E] 03/05/2019 3:30:43PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

Goods Received in Good Order

JAE Auto Pte. Ltd.

Sales Executive : ALAN



AR201905-01355

This is computer generated document.
No signature is required.

ORIGINAL

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGAI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 9191 / 6745 9929



Dept Direct: 6417 9191

Dept Direct: 6417 9799

Dept Direct: 6417 9799

Dept Direct: 6417 9799

Wiper blade: NWB (Nippon Wiper blade) Sliper (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso, HIKK (Made in Japan)

ACCORD AUTO SERVICES PTE LTD (AV)
BLK 1009 #01-80
BUKIT MERAH LANE 3

SINGAPORE 159723
TEL: 6271 5133 FAX: 6274 5715
ATTN: CELIA

SEND TO: BLK 1004 #01-29 BUKIT MERAH LANE 3

TAX INVOICE : AR201905-01354
DATE : 03/05/2019
CUSTOMER ID : ACC003
VEH REG. NO. : SKZ6939K
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : S\$

SQ STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1. C291-51-731 MZ5 CW 09-	MASCOT F GRILLE (Est No. 13)	PA PL3-K1-03SR	1	18.00	18.00

SUB-TOTAL : 18.00
ADD GST 7.00 % 1.26

E. & O.E

TOTAL AMOUNT S\$: 19.26

[P] 03/05/2019 3:29:25PM

[E] 03/05/2019 3:28:52PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: ALAN

This is computer generated document.
No signature is required.



AR201905-01354

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司 JAE AUTO PTE LTD

BLK 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
46A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2590

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 9791 / 6745 9939



Wiper blade: NMB (Nippon Wiper blade), Sliper (Made in Korea)
Forch (Made in Germany)
Spark plug: Nippon Denso NGK (Made in Japan)

=====

ACCORD AUTO SERVICES PTE LTD(AV)
BLK 1009 #01-80
BUKIT MERAH LANE 3

SINGAPORE 159723
TEL : 6271 5133 FAX : 6274 5715
ATTN : CELIA

SEND TO: BLK 1004 #01-29 BUKIT MERAH LANE 3

TAX INVOICE : AR201905-01348
DATE : 03/05/2019
CUSTOMER ID : ACC003
VEH REG. NO. : SKZ6939K
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : S\$

SQ	STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1	BP4K-67-483A MZ3,5 --10	CAP. F WIPER TANK (Est No. 22)	U1 UIL1-F1-A-SD	1	13.00	13.00
2	BBP1-67-482 CX5 KE/ MZ3 BM BN	PUMP.F WIPER TANK (Est No. 22)	U1 MZ-A38	1	50.00	50.00
3	C513-50-0T1 OK MZ5 CW	RETAINER.F BUMPER RH (Est No. 18)	U1 MZ-A24	1	20.00	20.00
4	C513-50-0U1 OK MZ5 CW	RETAINER.F BUMPER LH (Est No. 18)	U1 MZ-A26-E	1	20.00	20.00

SUB-TOTAL : 103.00
ADD GST 7.00 % 7.21

E. & O.E TOTAL AMOUNT S\$: 110.21

[P] 03/05/2019 3:28:17PM

[E] 03/05/2019 3:20:58PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

Goods Received in Good Order

JAE Auto Pte. Ltd.

Sales Executive : ALAN



* A R 2 0 1 9 0 5 - 0 1 3 4 8 *

This is computer generated document.
No signature is required.

ORIGINAL

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Dept Direct: 6417 9791 / 0745 9633



Dept Direct: 6417 9794



Dept Direct: 6303 9610



Dept Direct: 6417 9795



Dept Direct: 6303 9611



Dept Direct: 6417 9796



Dept Direct: 6417 9792



Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blades) Slipper (Made in Korea)
Forch (Made in Germany)
Spark plug: Nippon Densu, NGK (Made in Japan)

ACCORD AUTO SERVICES PTE LTD(AV)

BLK 1009 #01-80

BUKIT MERAH LANE 3

SINGAPORE 159723

TEL : 6271 5133 FAX : 6274 5715

ATTN : CELIA

TAX INVOICE : AR201905-01025
DATE : 03/05/2019
CUSTOMER ID : ACC003
VEH REG. NO. : SKZ6939K
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : S\$

SEND TO: BLK 1004 #01-29 BUKIT MERAH LANE 3

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	C513-50-070A MZ5 CW	F REINFORCEMENT (Est No. 17)	PA PL3-F1-08B	1	240.00	240.00
2	C597-56-110A MZ5 CW -W/I STOP	F ENGINE COVER (Est No. 19)	PA PL3-B1-040	1	120.00	120.00

SUB-TOTAL : 360.00
ADD GST 7.00 % 25.20

E. A. O. R. TOTAL AMOUNT S\$: 385.20

[P] 03/05/2019 11:22:14AM

[E] 03/05/2019 11:20:39AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: ALAN

This is computer generated document.

No signature is required.



* A R 2 0 1 9 0 5 - 0 1 0 2 5 *

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date