

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworks.com.sg

* No' Excess !

* Part By Parts !

INSURER:

Sompo Insurance Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D19MTPV01000336	Date of Loss:	26/04/2019
Vehicle Reg. No.:	SKZ6939K	Driveable?	NO
Driver Age/Info:	30 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SIM JIXUAN	Contact No:	+6598453430
Driver:	SIM JIXUAN		

Make/Model:	MAZDA 5, 2.0 5 DR WAGON (A)	Vehicle Reg. Date:	29/01/2016
Vehicle Colour:	GREY		
Engine No:	PE10302056	Chassis No:	JM6CW1071G0123244
Odometer:	0 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) 10

Lumpsum -
Resuming after repair
sure/Man foran

Tanfilin 97495749 / 674/8434
Not authorise
30/4/19 24pm
Ex: to be advise.
08 days 10 days

Description of Accident/Loss: ON 26/04/2019 ABOUT 7PM, VEHICLE A (SKZ6939K) WAS TRYING TO FILTER TO LANE 2 AND BANG INTO VEHICLE B (SKE6751U) LEFT REAR BUMPER.

Remarks: VEHICLE IN WORKSHOP (AV) TEL: 6271 7433.

Present Location: ACCORD AUTO SERVICES PTE LTD (AV) TEL: 6271 7433

COST OF CLAIMS

	Amount
Parts	5,533.00
Miscellaneous Items	180.00
Labour	3,130.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (\$)	8,843.00
+ GST 7.00% (\$)	619.01
Nett Amount (\$)	9,462.01

This claim is handled by: **SOE JIE YI (JESSY)**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 29 Apr 2019)

Parts: N/A MAZDA 5 2.0 5 DR WAGON (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Accord Auto Services Pte Ltd/SKZ6939K/29/04/2019 18:36

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

Steve 14/5/19

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet ✓	0.00	0.00	bt - *410.00 F
2	2		*Bonnet hinge ✓	0.00	0.00	bt - *46.00 F
3	1		*Bonnet lock ✓ BT ✓	0.00	0.00	*70.00 F
4	1		*Bonnet cable X nn	0.00	0.00	*25.00 F
5	1		*Bonnet insulator pad ✓	0.00	0.00	de - *55.00 F
6	1		*Bonnet seal X nn	0.00	0.00	de - *15.00 F
7	1		*LH headlamp * \$550 ✓	0.00	0.00	cre - *470.00 F
8	1		*RH headlamp * \$550 ✓	0.00	0.00	ar - *470.00 F
9	1		*Front RH fender * \$160 ✓	0.00	0.00	bt - *125.00 F
10	1		*Front RH fender splash shield ✓	0.00	0.00	nn - *85.00 F
11	1		*Front bumper * \$360 ✓	0.00	0.00	de - *320.00 F
12	1		*Front bumper logo (* \$18) ✓	0.00	0.00	ne - *25.00 F
13	1		*Front bumper grille ✓	0.00	0.00	de - *210.00 F
14	1		*Front bumper fog lamp (RH) ✓	0.00	0.00	ar - *125.00 F
15	1		*Front bumper fog lamp cover (RH) ✓	0.00	0.00	ar - *30.00 F
16	1		*Front bumper sponge ✓	0.00	0.00	de - *35.00 F
17	1		*Front bumper reinforcement ✓	0.00	0.00	bt - *240.00 F
18	2		*Front bumper side retainer (\$20 x 2) BR 40 ✓	0.00	0.00	ar - *20.00 F
19	1		*Front bumper under cover ✓	0.00	0.00	? *120.00 F
20	1		*Support panel * \$180 ✓	0.00	0.00	cre - *150.00 F
21	1		*Washer tank \$65 ✓	0.00	0.00	de - *60.00 F
22	1		*Washer tank cover \$13 ✓	0.00	0.00	de - *8.00 F
23	1		*Washer tank motor \$50 ✓	0.00	0.00	dis - *38.00 F
24	1		*Front RH shock absorber nn X	0.00	0.00	bt - *130.00 F
25	1		*Front RH shock absorber mounting X nn	0.00	0.00	ne - *45.00 F
26	1		*Front RH lower arm ✓	0.00	0.00	bt - *130.00 F
27	1		*Front RH knuckle arm X nn	0.00	0.00	bt - *135.00 F
28	1		*Front RH wheel bearing hub X nn	0.00	0.00	bt - *65.00 F
29	1		*Front RH wheel bearing X nn	0.00	0.00	ne - *48.00 F
30	1		*Front RH tie rod end X nn	0.00	0.00	? *45.00 F
31	1		*Front RH rack end X nn	0.00	0.00	? *50.00 F
32	1		*Power steering pump ✓	0.00	0.00	cre - *870.00 F
33	1		*Power steering high pressure pipe X nn	0.00	0.00	? *95.00 F
34	1		*Engine mounting (RH) X nn	0.00	0.00	? *50.00 F
35	1		*Horn (* \$45) ✓ PD ✓	0.00	0.00	? *65.00 F
36	1		*Wiper garnish/cover X nn	0.00	0.00	de - *150.00 F
37	1		*RH drive shaft *no price X nn.	0.00	0.00	? *- F

photo u/c.

F=Franchise part.

Sub Total (\$\$)

5,030.00

+ Margin on L,N Items 10.00% (\$\$)

503.00

Total Parts (\$\$)

5,533.00

Accord Auto Services Pte Ltd/SKZ6939K/29/04/2019 18:36. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Bonnet insulator pad clip	50.00 ³⁰
2	1	Front bumper clip	50.00 ³⁰
3	1	Front RH fender splash shield clip	50.00 ²⁰
4	1	RH headlamp bulb	30.00
Sub Total (S\$)			180.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Spray painting on all affected area.	New	700. 750.00
2	Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	New	700. 800.00
3	To check wiring system & light.	New	30. 80.00
4	To check & adjust computer/wheel alignment.	New	80. 120.00
5	To remove and replace front RH rim, tyre and balancing.	New	30. 60.00
6	To remove and replace power steering pump and high pressure pipe.	New	100. 250.00
7	To remove and replace engine mounting.	New	ny X? 120.00
8	To adjust and remain front chassis.	New photo	200 300.00
9	To remove and reinstall air-con condenser, radiator & etc. to assist on repair.	New	120. 300.00
10	To remove and replace front RH suspension and drive shaft.	New	150. 350.00
Gross Labour Cost (S\$)			3,130.00

Accord Auto Services Pte Ltd/SKZ6939K/29/04/2019 18:36. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Supp

- 1) * Mirror Front Garnish \$ 25/
- 2) Headlamp Lower Bracket \$ 15/
- 3) Side Skirt RH \$ 380/
- 4) Wiper Garnish Side LH & RH \$ 15 x 2/
- 5) ~~Rim \$ 450 (?)~~
- 6) Front RH Door \$ 400/
- 7) ~~Front Wheel Apron RH \$ 320/~~
- 8) Front RH Door Sticker upper \$ 28
- 9) Front RH Door Sticker Side \$ 20
- 10) Front RH Fender stay \$ 18
- 11) Front RH Fender stay upper \$ ~~110.70~~ 110.70

S/N Supp

- 1) Tyre \$ 220/
- 2) Number Plate Frame \$ 18/