

(SUPPLEMENTARY)

INSURER: Somp Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM			
Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	D19MTPV01000336	Date of Loss:	26/04/2019
Vehicle Reg. No.:	SKZ6939K	Driveable?	NO
Driver Age/Info:	30 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SIM JIXUAN	Contact No:	+6598453430
Driver:	SIM JIXUAN		
Make/Model:	MAZDA 5, 2.0 5 DR WAGON (A)	Vehicle Reg. Date:	29/01/2016
Vehicle Colour:	Grey	Chassis No:	JM6CW1071G012324
Engine No:	PE10302056		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	ON 26/04/2019 ABOUT 7PM, VEHICLE A (SKZ6939K) WAS TRYING TO FILTER TO LANE 2 AND BANG INTO VEHICLE B (SKE6751U) LEFT REAR BUMPER.		
Present Location:	ACCORD AUTO SERVICES PTE LTD (AV) TEL: 6271 7433		

COST OF CLAIMS	Amount
Parts	1,129.37
Miscellaneous Items	238.00
Labour	300.00
Paintwork Labour	800.00
Towing	0.00
Gross Total (\$)	2,467.37
+ GST 7.00% (\$)	172.72
Nett Amount (\$)	2,640.09
+ Previous Estimates (\$)	9,462.01
Claim Total (\$)	12,102.10

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 13 May 2019)

Parts: N/A MAZDA 5 2.0 5 DR WAGON (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Accord Auto Services Pte Ltd/SKZ6939K/13/05/2019 20:30

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT MIRROR SIDE GARNISH / MIS	0.00	0.00	*25.00 F	✓
2	1		*FRONT HEADLAMP LOWER BRACKET / DR	0.00	0.00	*15.00 F	✓
3	1		*FRONT SKIRT RH / MIS	0.00	0.00	*380.00 F	✓
4	2		*FRONT WIPER SIDE GARNISH / CR4	0.00	0.00	*30.00 F	✓
5	1		*FRONT FRONT RH DOOR / DD	0.00	0.00	*400.00 F	✓
6	1		*FRONT RH DOOR STICKER UPPER / NEX	0.00	0.00	*28.00 F	✓
7	1		*FRONT RH DOOR STICKER SIDE / NEX	0.00	0.00	*20.00 F	✓
8	1		*FRONT RH FENDER STAY / ST	0.00	0.00	*18.00 F	✓
9	1		*FRONT RH FENDER STAY UPPER / ST	0.00	0.00	*110.70 F	✓
						Sub Total (\$)	1,026.70
						+ Margin on L,N Items 10.00% (\$)	102.67
						Total Parts (\$)	1,129.37

F=Franchise part.

Accord Auto Services Pte Ltd/SKZ6939K/13/05/2019 20:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Steve
14/5/19

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	FRON NUMBER PLATE FRAME
2	1	TYRE

176 8 1/2 X 18.00 220.00

Sub Total (\$\$) 238.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1	SPRAY PAINTING FRONT FENDER . FRONT LH & RH DOOR AND RH SIDE SKIRT
---	--

New 700 800.00

Labour Items

2	To Remove/ Replace/ Refix Front RH Door Inner Compartment , Window Glass ,Mechemism & Assy To New Door
3	To Repair Front LH Fender ,Front LH Door On Damage And Install Side RH Skirt

New 60 150.00

New 150.00

Gross Labour Cost (\$\$) 1,100.00

Accord Auto Services Pte Ltd/SKZ6939K/13/05/2019 20:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

(SUPPLEMENTARY)INSURER: **Sompo Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D19MTPV01000336	Date of Loss:	26/04/2019
Vehicle Reg. No.:	SKZ6939K	Driveable?	NO
Driver Age/Info:	30 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SIM JIXUAN	Contact No:	+6598453430
Driver:	SIM JIXUAN		

Make/Model:	MAZDA 5, 2.0 5 DR WAGON (A)	Vehicle Reg. Date:	29/01/2016
Vehicle Colour:	GREY		
Engine No:	PE10302056	Chassis No:	JM6CW1071G0123244
Odometer:	0 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 10

Description of Accident/Loss ON 26/04/2019 ABOUT 7PM, VEHICLE A (SKZ6939K) WAS TRYING TO FILTER TO LANE 2 AND BANG INTO VEHICLE B (SKE6751U) LEFT REAR BUMPER.

Present Location: ACCORD AUTO SERVICES PTE LTD (AV) TEL: 6271 7433

COST OF CLAIMS

	Amount
Parts	104.50
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	104.50
+ GST 7.00% (\$)	7.32
Nett Amount (\$)	111.82
+ Previous Estimates (\$)	12,102.10
Claim Total (\$)	12,213.92

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 11 Jun 2019)**Parts:** N/A MAZDA 5 2.0 5 DR WAGON (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Accord Auto Services Pte Ltd/SKZ6939K/11/06/2019 15:43**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount
1	1		*PLATE SEAL RH (Inner Bumper Rh Bracket-Missing)	mis ✓	0.00	0.00	*15.00 F
2	1		*SEAL PLATE ENGINE RH (Under Engine Cover Side-Missing)	mis ✓	0.00	0.00	*20.00 F
3	1		*STOPPER (At Support-Missing)	mis ✓	0.00	0.00	*7.00 F
4	1		*COVER H/LAMP (Small-Missing)	mis ✓	0.00	0.00	*10.00 F
5	1		*COVER H/LAMP (Inner-Missing)	mis ✓	0.00	0.00	*20.00 F
6	1		*SOCKET H/LAMP SIGNAL (Missing)	mis ✓	0.00	0.00	*8.00 F
7	1		*POWER STEERING SUCTION (Between Power Steering Pump To Tank)	dis ✓	0.00	0.00	*15.00 F

F=Franchise part.

Sub Total (\$\$)	95.00
+ Margin on L,N Items 10.00% (\$\$)	9.50
Total Parts (\$\$)	104.50

Accord Auto Services Pte Ltd/SKZ6939K/11/06/2019 15:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Accord Auto Services Pte Ltd/SKZ6939K/11/06/2019 15:43. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >