

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department

Claim No: MC1900340
Ref No: MF1900416
Date: 09 Jul 2019
Policy No: D18MTPV01015976
Veh Reg No: SLG3678X
Make/Model: HONDA SHUTTLE 1.5G
CVT

Your Ref No: SLG3678X
Claim Type: Own Damage/Third Party
Accident Date: 25/04/2019

Repair Cost to Vehicle No (For Finalization):SLG3678X

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 TAILAMP		1 PC	250.00	
2 REAR BUMPER		1 PC	480.00	
3 REAR BUMPER SIDE RETAINER RH		1 PC	15.00	
4 REAR FENDER RH (OUTER)		1 PC	620.00	
5 REAR FENDER GLASS MOULDING RH TOP		1 PC	20.00	
6 REAR FENDER GLASS MOULDING RH SIDE		1 PC	15.00	
7 REAR FENDER GLASS MOULDING RH LOWER		1 PC	30.00	
8 REAR FENDER COWLING RH		1 PC	55.00	
9 REAR DOOR RH		1 PC	420.00	
10 HORN RH		1 PC	25.00	
			1,930.00	
	Add 10%		193.00	2,123.00
Special Nett				
11 TYRE RHR - 90% x \$180		1 PC	162.00	
12 INNER SEAL		1 PC	20.00	
13 WINDSCREEN SEALANT		1 PC	40.00	
				222.00
LABOUR				
14 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	20.00	
15 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		1 PC	60.00	
16 TO REMOVE & REINSTALL/REPLACE REAR FENDER GLASS RH.		1 PC	60.00	
17 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		1 PC	100.00	
18 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.		1 PC	50.00	
19 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR FENDER RH,REAR FENDER INNER PANEL RH.TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	720.00	
20 TO SPRAY REAR BUMPER,REAR FENDER RH,REAR FENDER INNER PANEL RH,REAR DOOR RH,SIDE SKIRT RH.		1 PC	720.00	

Ah Lim Motor Company
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department

Claim No: MC1900340
Ref No: MF1900416
Date: 09 Jul 2019
Policy No: D18MTPV01015976
Veh Reg No: SLG3678X
Make/Model: HONDA SHUTTLE 1.5G
CVT

Your Ref No: SLG3678X
Claim Type: Own Damage/Third Party
Accident Date: 25/04/2019

Repair Cost to Vehicle No (For Finalization):SLG3678X

Description	U/Price	Quantity	Cost S\$	Amount S\$
				1,730.00

Amount Before Excess	S\$ 4,075.00
Less Excess	S\$ 0.00
Amount Before GST	S\$ 4,075.00
Add GST @ 7%	285.25
Total Amount payable	S\$ 4,360.25

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND THREE HUNDRED SIXTY AND CENTS TWENTY FIVE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 30/04/2019

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-CAUTHORISED SIGNATURE
Tel: 6483 1244 Fax: 6483 6170

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 29 Apr 2019)
 Parts: N/A HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ah Lim Motor Company/SLG3678X/29/04/2019 15:08
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*TAILAMP	CM	0.00	0.00	*250.00 F	✓
2	1		*TAILAMP-LOWER-BEAM RH - CHECK PRICE		0.00	0.00	*-F	7
3	1		*REAR BUMPER	R	0.00	0.00	*480.00 F	✓
4	1		*REAR BUMPER SIDE RETAINER RH	CM	0.00	0.00	*15.00 F	—
5	15		*REAR BUMPER CLIPS	CM	0.00	0.00	*30.00 F	—
6	1		*TAILAMP PANEL RH	R	0.00	0.00	*130.00 F	X
7	1		*REAR FENDER RH (OUTER)	R	0.00	0.00	*620.00 F	✓
8	1		*REAR FENDER GLASS	R	0.00	0.00	*280.00 F	X
9	1		*REAR FENDER GLASS MOULDING RH TOP	CM	0.00	0.00	*20.00 F	—
10	2		*REAR FENDER GLASS MOULDING RH SIDE	CM	0.00	0.00	*30.00 F	—
11	1		*REAR FENDER GLASS MOULDING RH LOWER	CM	0.00	0.00	*30.00 F	—
12	1		*REAR FENDER COWLING RH	CM	0.00	0.00	*55.00 F	29.00
13	8		*REAR FENDER COWLING CLIPS		0.00	0.00	*16.00 F	✓
14	1		*REAR FENDER INNER RH		0.00	0.00	*420.00 F	7
15	1		*REAR FENDER INNER TRIM RH	R	0.00	0.00	*195.00 F	X
16	1		*REAR DOOR RH	R	0.00	0.00	*420.00 F	✓
17	1		*REAR DOOR INNER LOCK	R	0.00	0.00	*130.00 F	X
18	1		*REAR DOOR RUBBER (AT DOOR) TOP	CM	0.00	0.00	*15.00 F	X
19	2		*REAR DOOR RUBBER (AT DOOR) SIDE	CM	0.00	0.00	*20.00 F	—
20	1		*REAR DOOR RUBBER (AT DOOR) LOWER	CM	0.00	0.00	*15.00 F	X
21	1		*SIDE SKIRT RH	R	0.00	0.00	*240.00 F	X
22	1		*REAR SHOCK ABSORBER RH - CHECK PRICE	R	0.00	0.00	*-F	X
23	1		*REAR SHOCK ABSORBER TOP MOUNTING RH - CHECK PRICE	R	0.00	0.00	*-F	X
24	1		*SPORT RIM RHR - CHECK PRICE	CM	0	0.00	*-FS	X
25	1		*TYRE RHR - CHECK PRICE	CM	0	0.00	*-FS	90.00
26	1		*INNER SEAL	CM	0	0.00	*20.00 FS	—
27	1		*WINDSCREEN SEALANT	CM	0	0.00	*40.00 FS	—

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	3,471.00
+ Margin on L,N Items 10.00% (\$\$)	341.10
Total Parts (\$\$)	3,812.10

Ah Lim Motor Company/SLG3678X/29/04/2019 15:08. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	201 40.00
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	601 80.00
3	TO REMOVE & REINSTALL/REPLACE REAR FENDER GLASS RH.	New	601 100.00
4	TO REMOVE AND REINSTALL CUSHIONS; SEATS; BACKREST; INNER TRIM; GARNISH; ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	1001 150.00
5	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	New	501 60.00
6	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR FENDER RH;REAR FENDER INNER PANEL RH.TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	7201 1,150.00
7	TO SPRAY REAR BUMPER;REAR FENDER RH;REAR FENDER INNER PANEL RH;REAR DOOR RH;SIDE SKIRT RH.	New	7201 1,000.00
Gross Labour Cost (S\$)			2,580.00

Ah Lim Motor Company/SLG3678X/29/04/2019 15:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department

Estimate No: MC1900340
Date: 09 May 2019
Policy No: D18MTPV01015976
Veh Reg No: SLG3678X
Make/Model: HONDA SHUTTLE 1.5G
CVT

Your Ref No: SLG3678X
Claim Type: Own Damage/Third Party
Accident Date: 25/04/2019

Estimate Repair Cost to Vehicle No :SLG3678X

Description	U/Price	Quantity	Cost S\$	Amount S\$
Supplementary Parts to Repair				
SPARE PARTS				
1 HORN RH		1 PC	25.00	
			25.00	
	Add 10%		2.50	27.50
Amount Before Excess				S\$ 27.50
GST Amount				S\$ 1.93
Total Amount payable				S\$ 29.43

The above vehicle was surveyed by KENNETH KONG -LKK on 30/04/2019

For AH LIM MOTOR COMPANY

BLK 10 ANG MO KIO IND. PARK 2A
#01-09, AMK AUTOPPOINT
SINGAPORE 568047

AUTHORISED SIGNATURE



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)



WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9701 / 6745 9939



Dept Direct: 6305 9510

Dept Direct: 6305 9511

Dept Direct: 6417 9702



Dept Direct: 6417 9704

Dept Direct: 6417 9705

Dept Direct: 6417 9706

Dept Direct: 6417 9707

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

=====

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

TAX INVOICE : AR201905-03532
DATE : 08/05/2019
CUSTOMER ID : AHL008
VEH REG. NO. : SLG3678X
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	H38100-SNB-W02 FIT 08	HORN RH	U1 L2-M50-B	1	25.00	25.00
2	H74552-T5B-003 GK8 GP7	FENDER,R.RR.INNER	U1 HL3-C3	1	55.00	55.00

SUB-TOTAL : 80.00
ADD GST 7.00 % 5.60

E. & O.E TOTAL AMOUNT SGD : 85.60

[P] 08/05/2019 10:36:27AM

[E] 08/05/2019 10:35:54AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : CHEN



* A R 2 0 1 9 0 5 - 0 3 5 3 2 *

This is computer generated document.

No signature is required.

Goods Received in Good Order

[Signature]

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9701 / 6745 9939



Dept Direct: 6395 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

=====

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047

TEL : 64831244 FAX : 64836170

ATTN : SIMON 96205405

TAX INVOICE : AR201905-03077

DATE : 07/05/2019

CUSTOMER ID : AHL008

VEH REG. NO. : SLG3678X

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	H33500-TE3-J01 GK8	TAIL LAMP RH	U1 HL2-C1	1	250.00	250.00
2	H71501-TD4-000ZC	REAR BUMPER RP50P	U1 HL2-L19	1	480.00	480.00
3	H71593-TD4-013/003 GP7	SPACER RH	U1 HL2-G8-B	1	15.00	15.00
4	H04636-TD4-J00/01ZZ GK8	RR FENDER RH	U1 HL1-A5-BA	1	620.00	620.00
5	H67510-T5L-T00ZZ GK5	RR DOOR RH	U1 HL1-B2	1	420.00	420.00
6	H73520-TD4-J01 GK8 SHUTTLE	RR FENDER RH MLD STRIGH	U1 HL2-E2-E	1	20.00	20.00

SUB-TOTAL : 1,805.00

ADD GST 7.00 % 126.35

E. & O.E

TOTAL AMOUNT SGD : 1,931.35

[P] 07/05/2019 1:51:12PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 07/05/2019 1:47:45PM

JAE Auto Pte. Ltd.

Sales Executive : CHEN



* A R 2 0 1 9 0 5 - 0 3 0 7 7 *

This is computer generated document.

No signature is required.

Goods Received in Good Order

(Handwritten signature)

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 979

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

=====

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

TAX INVOICE : AR201905-03079
DATE : 07/05/2019
CUSTOMER ID : AHL008
VEH REG. NO. : SLG3678X
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. H73521-TD4-J02 GK8	RR FENDER GLASS RH LOWER	MO SUPPLIER.	1	30.00	30.00 ✓
2. H73226-SZW-000 GK3 FIT / RC1 ODY 14"/RM3	RR GLASS TOP MLD	MO 1HSD	1	15.00	15.00 ✓

SUB-TOTAL : 45.00
ADD GST 7.00 % 3.15

E. & O.E TOTAL AMOUNT SGD : 48.15

[P] 07/05/2019 2:51:14PM

[E] 07/05/2019 1:51:22PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : CHEN

This is computer generated document.
No signature is required.



* A R 2 0 1 9 0 5 - 0 3 0 7 9 *

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL