

RHP: CS/SMO/9007578/Krd302 Special Instruction
 ASSIGMENT (Office)
 From (Person): Merimen Kenneth
Thelma Chuo of SMO Date/Time: 30/4/19 @ 9.01am
 Estimated Cost: _____ Bill to: _____
 (O) TP / WS / TP RUS / OD RUS / EVA / INV / MY / CS
 To Inspect Vehicle No: SLG 3678X Insured: _____
 at Workshop/adr: Ah Jim Motor Tel: 64831244
 of Blk 10 Amk Ind. Park 2A #01-09
 Policy No: D18M7PV01015976 Claim No: CMTD1902064
 Sum Insured: _____ Reason: -7BA Waived
 Make of Veh: _____ D.O.A: 28/4/2019
 (Client's Record)
 CA / (R) / REV / REV 24 HRS
 Date/Time: 9.00am @ 30/4/19 Person Contacted: Zila Vehicle: (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLG 3678X - X</u>
<u>2/5/19</u>	<u>Revert via merimen, vehicle repair on part by part</u>
<u>2/5/19</u>	<u>Rece approved from Thelma via merimen ex Waived</u>
<u>2/5/19</u>	<u>Informal Zila c/A ex Waived by email</u>
<u>9/7/19</u>	<u>@ 12:15pm Mui Hong will email us finalised</u>

ASSIGNMENT

From: Date: 30/4/2019

Veh No: SLG3678X Yr Regn: 09-16

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

VS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No: SLG 3678 X

Make: Honda Shuttle C.C. 1496

at Workshop n/s Ah Lim motor

Colour: M. Red A/C: Insured / Std / NI / NA

of 10 AMK Ind. Prk 2A #01-09

Sp. Reading: 60132 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: Excess: TBA

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or


Make of Veh: 1030am

Modi: Nil / SRim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 195/55R15

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value: 866k

Front

Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal. 9 mm

R/Bal. 9 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 9 mm

L/Bal. 9 mm

Est. Repairs: 06 days Res.: Yes or No

D.O.A. 25/4/19

D.O.I. 30/4/19

Lum Sum: 1.3.1 % 3 Val: Yes or No

Survey held at

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1017 84075 Confirm (Red 2317.10, 3690) (No LS)

RECEIVED 11 JUL 2019

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 6

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: 1

2) 1017 - typist

Add Fee: ☐ : Site Insp (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: Merimen

Lump Sum / I.B.I: (\$ 4075/2)

250

11

261

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Iss Auth'd	Status
Main	26 Apr 2019 Sendback Est.	29 Apr 2019 15:08 S\$6,392.10	30 Apr 2019 09:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	TING JUN LIN KRISMAN, ID: S8230785J, Tel: +6591398552, Email: geerad21@gmail.com								
Vehicle Reg. No.:	SLG3678X	Date of Loss:	25/04/2019 16:00 - :59 [30 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / CMTD1902064	Policy/Cover Note No.:	D18MTPV01015976 (Comprehensive)						
		Excess:							
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/05/2019]								
Driver/Custodian:	TING JUN LIN KRISMAN (36 / Male) , NRIC: S8230785J, Tel: +6591398552 Email: geerad21@gmail.com								
Adj Asg. Remarks:	WS: ZILA								
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
			View All	Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 2 May 2019 1:36 PM
To: SUR; zila
Subject: SLG 3678X-DOA: 25/4/2019 (SOMPO OD)

Dear Zila,

As instructed by our client, please proceed to repair the **insured vehicle SLG 3678X on part by part (Excess Waived)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SLG3678X (CMTD1902064)

OD

Apr 25 2019 4:00PM

[TING JUN LIN KRISMAN]

Ah Lim Motor Company

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Sampo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 02/05/2019 12:24 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$4436.60) - SLG3678X - Claim Handler: Thelma Choo

Approved:4436.60.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	Sompo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
-----	--	-------	---

Attn: Theima Choo Date: 02 May 2019

Preliminary Advice

Vehicle No	: SLG3678X	Accident Date	: 25/04/2019
Make	: HONDA SHUTTLE	Policy No.	: D18MTPV01015976
Assignment Date	: 30/04/2019	Excess	: S\$0.00
Date of Inspection	: 30/4/2019	Est. Duration of Repair	: 6
Inspection At	: AH LIM MOTOR COMPANY		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,392.10
Revised Amount	:S\$	3,896.50
Check Items (Estimated)	:S\$	540.10
Total	:S\$	4,436.60

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	42,883.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,117.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Vehicle repair on part by part

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 0785J

Vehicle Details

Vehicle No.: SLG3678X
Vehicle to be Exported: No
Intended Deregistration Date: 26 Apr 2019
Vehicle Make: HONDA
Vehicle Model: SHUTTLE 1.5G CVT
Primary Colour: Red
Manufacturing Year: 2015
Engine No.: L15B3533832
Chassis No.: GK81003200
Maximum Power Output: 97.0 kW (130 bhp)
Open Market Value: \$17,715.00
Original Registration Date: 28 Sep 2016
First Registration Date: 28 Sep 2016
Transfer Count: 0
Actual ARF Paid: \$7,715.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Sep 2026
PARF Rebate Amount: \$5,786.00

Intended COE Rebate Details

COE Expiry Date: 27 Sep 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$50,000.00
COE Rebate Amount: \$37,097.00
Total Rebate Amount: \$42,883.00

The information contained herein is correct as at 26 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	26/04/2019 13:55
Date Of Accident	25/04/2019 16:00
Exact Location Of Accident	PIONEER ROAD TURNING TO TUAS ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLG3678X
Insured/Policyholder	
Name Of Registered Owner	TING JUN LIN KRISMAN
NRIC No	S8230785J
Email Address	GEERAD21@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91398552
Alternative Phone No	OTHERS-91398552
Vehicle Particulars	
Manufacturer	HONDA
Model	SHUTTLE-1.5 G CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01015976
Cover Note Number	28/09/2018 - 27/09/2019
Driver	
Name of Driver	TING JUN LIN KRISMAN
NRIC No	S8230785J
Date Of Birth	22/09/1982
Occupation	INDOOR
Date Of Driving Pass	25/02/2003
Driving Experience	16 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91398552
Fax Number	
Contact Number	OTHERS-91398552
Email Address	GEERAD21@GMAIL.COM



Address	468B FERNVALE LINK #21-543
Postcode	792468
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE2931P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Officer's Signature
Name:
NRIC/FIN No.:



Sketch Plan Pg. 2

Date of accident: 25 April 2019 Time: 1600 Location: Pioneer Road turning to Tuos Road
 My Vehicle A: SLG 3678X Vehicle B: XE 2931P Vehicle C: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On this date (25 April 2019) at about 1600 I was driving my vehicle NO SLG3678X at along Pioneer Road towards Tuos Road. When traffic light turn green, Both Vehicle turning Right, Vehicle B NO XE2931P turning too wide in low speed and hit into my Vehicle NO SLG3678X, upon impact the vehicle B continues to accelerate even though I was braking. After both parties come down, driver B say he can't see my vehicle. I took several photo at the accident scene and driver B refuse to exchange Particular when I request for it. He call his collage down pass me name card and say claim through insurance.

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop:

Email address: gerald21@gmail.com

& myself:

Email address:

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre's Signature
Name:
NRIC/FIN No.:



AH LIM MOTOR COMPANY



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #20-01/02 Singapore Land Tower, Singapore 048623
Tel: 6461 6335 / Fax: 6221 3322 / Website: www.sompo.com.sg
Co Reg No: 198900492E / GST Reg No: M200903195

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No. : D18MTPV01015976
 Insured : TING JUN LIM, KRISMAN
 Motor Car (Registration No.) : SLG367EX
 Cover : Comprehensive - ExcelDrive GOLD
 Policy Commencement Date : 28 SEPTEMBER 2018 00:00
 Policy Expiry Date : 27 SEPTEMBER 2019 23:59
 Maximum Liability (Section I) : Market value at time of loss
 Excess* : \$500 - Section I
 (Waived up to \$51,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
 Voluntary Excess* : N/A
 Windscreen Excess* : \$5100.00 - Waived if Repair at ExcelDrive Workshop
 Loss of Use : Per Policy Schedule
 * Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the insured,
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

I/We HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP.27

Sompo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue : 18 SEPTEMBER 2018 10:28


IMPORTANT NOTICE

- o Keep the Certificate in your Motor Car.
- o Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
- o On the sale of the Motor Car or if for any reason the Insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company, if the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).
- o This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name : 11P04201 & PHILLIP SECURITIES PTE LTD CI Code: 22A XXXDM9D4RMBL1C1A



Q139 2532
d/c
No injury
No video
lpcx



AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A

#01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244

Fax: 6483 6170

Email: ahlmmc@singnet.com.sg

GST Reg No: M9-0009639-E

INSURER:

Sompo Insurance Singapore Pte. Ltd. (HQ)

SURVEYOR COPY

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D18MTPV01015976	Date of Loss:	25/04/2019
Vehicle Reg. No.:	SLG3678X	Driveable?	
Driver Age/Info:	36 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TING JUN LIN KRISMAN	Contact No:	+6591398552
Driver:	TING JUN LIN KRISMAN		
Make/Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Vehicle Reg. Date:	28/09/2016
Vehicle Colour:	RED	Chassis No:	GK81003200
Engine No:	L15B3533832		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	REFER TO THE SKETCH PLAN BY DRIVER		
Remarks:	CAR NOT IN - TO BE ARRANGE		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

COST OF CLAIMS

	Amount
Parts	3,812.10
Miscellaneous Items	0.00
Labour	2,580.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	6,392.10
+ GST 7.00% (\$\$)	447.45
Nett Amount (\$\$)	6,839.55

This claim is handled by: ZILA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 29 Apr 2019)

Parts: N/A HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database).

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ah Lim Motor Company/SLG3678X/29/04/2019 15:08

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*TAILAMP	CM	0.00	0.00	*250.00 F ✓
2	1		*TAILAMP LOWER BEAM RH - CHECK PRICE	A	0.00	0.00	*-F X
3	1		*REAR BUMPER	R	0.00	0.00	*480.00 F ✓
4	1		*REAR BUMPER SIDE RETAINER RH	CM	0.00	0.00	*15.00 F ✓
5	15		*REAR BUMPER CLIPS	N/A	0.00	0.00	*30.00 F X
6	1		*TAILAMP PANEL RH	R	0.00	0.00	*130.00 F X
7	1		*REAR FENDER RH (OUTER)	R	0.00	0.00	*620.00 F ✓
8	1		*REAR FENDER GLASS	R	0.00	0.00	*280.00 F X
9	1		*REAR FENDER GLASS MOULDING RH TOP	R	0.00	0.00	*20.00 F ✓
10	2		*REAR FENDER GLASS MOULDING RH SIDE	R	0.00	0.00	*30.00 F ✓
11	1		*REAR FENDER GLASS MOULDING RH LOWER	R	0.00	0.00	*30.00 F ✓
12	1		*REAR FENDER COWLING RH	CM	0.00	0.00	*55.00 F ✓
13	8		*REAR FENDER COWLING CLIPS	R	0.00	0.00	*16.00 F X
14	1		*REAR FENDER INNER RH	R	0.00	0.00	*420.00 F X
15	1		*REAR FENDER INNER TRIM RH	R	0.00	0.00	*195.00 F X
16	1		*REAR DOOR RH	R	0.00	0.00	*420.00 F ✓
17	1		*REAR DOOR INNER LOCK	R	0.00	0.00	*130.00 F X
18	1		*REAR DOOR RUBBER (AT DOOR) TOP	R	0.00	0.00	*15.00 F X
19	2		*REAR DOOR RUBBER (AT DOOR) SIDE	R	0.00	0.00	*20.00 F ✓
20	1		*REAR DOOR RUBBER (AT DOOR) LOWER	R	0.00	0.00	*15.00 F X
21	1		*SIDE SKIRT RH	R	0.00	0.00	*240.00 F X
22	1		*REAR SHOCK ABSORBER RH - CHECK PRICE	R	0.00	0.00	*-F X
23	1		*REAR SHOCK ABSORBER TOP MOUNTING RH - CHECK PRICE	R	0.00	0.00	*-F X
24	1		*SPORT RIM RHR - CHECK PRICE	R	0	0.00	*-FS X
25	1		*TYRE RHR - CHECK PRICE	CVT	0	0.00	*-FS 902
26	1		*INNER SEAL	R	0	0.00	*20.00 FS ✓
27	1		*WINDSCREEN SEALANT	R	0	0.00	*40.00 FS ✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	3,471.00
+ Margin on L,N Items 10.00% (\$\$)	341.10
Total Parts (\$\$)	3,812.10

Ah Lim Motor Company/SLG3678X/29/04/2019 15:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	201 40.00 ✓
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	601 80.00 ✓
3	TO REMOVE & REINSTALL/REPLACE REAR FENDER GLASS RH.	New	601 100.00 ✓
4	TO REMOVE AND REINSTALL CUSHIONS; SEATS; BACKREST; INNER TRIM; GARNISH; ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	1001 150.00 ✓
5	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	New	501 60.00 ✓
6	TO DISMANTLE ALL DAMAGED PARTS, TO CUT & WELD REAR FENDER RH; REAR FENDER INNER PANEL RH. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	7201 1,150.00 ✓
7	TO SPRAY REAR BUMPER; REAR FENDER RH; REAR FENDER INNER PANEL RH; REAR DOOR RH; SIDE SKIRT RH.	New	7201 1,000.00 ✓
* Gross Labour Cost (S\$)			2,580.00

Ah Lim Motor Company/SLG3678X/29/04/2019 15:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #05-01/06 SINGAPORE LAND TOWER
 SINGAPORE 048623
 TEL: 64616555
 ATTN: Motor Claim Department

Claim No: MC1900340
 Ref No: MF1900416
 Date: 09 Jul 2019
 Policy No: D18MTPV01015976
 Veh Reg No: SLG3678X
 Make/Model: HONDA SHUTTLE 1.5G
 CVT

Your Ref No: SLG3678X
 Claim Type: Own Damage/Third Party
 Accident Date: 25/04/2019

Repair Cost to Vehicle No (For Finalization):SLG3678X

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 TAILAMP		1 PC	250.00	
2 REAR BUMPER		1 PC	480.00	
3 REAR BUMPER SIDE RETAINER RH		1 PC	15.00	
4 REAR FENDER RH (OUTER)		1 PC	620.00	
5 REAR FENDER GLASS MOULDING RH TOP		1 PC	20.00	
6 REAR FENDER GLASS MOULDING RH SIDE		1 PC	15.00	
7 REAR FENDER GLASS MOULDING RH LOWER		1 PC	30.00	
8 REAR FENDER COWLING RH		1 PC	55.00	
9 REAR DOOR RH		1 PC	420.00	
10 HORN RH		1 PC	25.00	
			1,930.00	
	Add 10%		193.00	2,123.00
Special Nett				
11 TYRE RHR - 90% x \$180		1 PC	162.00	
12 INNER SEAL		1 PC	20.00	
13 WINDSCREEN SEALANT		1 PC	40.00	
				222.00
LABOUR				
14 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	20.00	
15 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		1 PC	60.00	
16 TO REMOVE & REINSTALL/REPLACE REAR FENDER GLASS RH.		1 PC	60.00	
17 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		1 PC	100.00	
18 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.		1 PC	50.00	
19 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR FENDER RH,REAR FENDER INNER PANEL RH.TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME		1 PC	720.00	
20 TO SPRAY REAR BUMPER,REAR FENDER RH,REAR FENDER INNER PANEL RH,REAR DOOR RH,SIDE SKIRT RH.		1 PC	720.00	

10 Ang Mo Kio Industrial Park 2A
 #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department

Claim No: MC1900340
Ref No: MF1900416
Date: 09 Jul 2019
Policy No: D18MTPV01015976
Veh Reg No: SLG3678X
Make/Model: HONDA SHUTTLE 1.5G
CVT

Your Ref No: SLG3678X
Claim Type: Own Damage/Third Party
Accident Date: 25/04/2019

Repair Cost to Vehicle No (For Finalization):SLG3678X

Description	U/Price	Quantity	Cost S\$	Amount S\$
				1,730.00

Amount Before Excess	S\$ 4,075.00
Less Excess	S\$ 0.00
Amount Before GST	S\$ 4,075.00
Add GST @ 7%	285.25
Total Amount payable	S\$ 4,360.25

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND THREE HUNDRED SIXTY AND CENTS TWENTY FIVE ONLY
The above vehicle was surveyed by KENNETH KONG -LKK on 30/04/2019

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
#01-AUTHORISED SIGNATURE

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 29 Apr 2019)
 Parts: N/A HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ah Lim Motor Company/SLG3678X/29/04/2019 15:08
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*TAILAMP	CM	0.00	0.00	*250.00 F ✓
2	1		*TAILAMP LOWER BEAM RH CHECK PRICE		0.00	0.00	*F ✓
3	1		*REAR BUMPER	R	0.00	0.00	*480.00 F ✓
4	1		*REAR BUMPER SIDE RETAINER RH	CM	0.00	0.00	*15.00 F ✓
5	15		*REAR BUMPER CLIPS	R	0.00	0.00	*30.00 F ✓
6	1		*TAILAMP PANEL RH	R	0.00	0.00	*130.00 F X
7	1		*REAR FENDER RH (OUTER)	R	0.00	0.00	*620.00 F ✓
8	1		*REAR FENDER GLASS	R	0.00	0.00	*280.00 F X
9	1		*REAR FENDER GLASS MOULDING RH TOP	R	0.00	0.00	*20.00 F ✓
10	2		*REAR FENDER GLASS MOULDING RH SIDE	R	0.00	0.00	*30.00 F ✓
11	1		*REAR FENDER GLASS MOULDING RH LOWER	R	0.00	0.00	*30.00 F ✓
12	1		*REAR FENDER COWLING RH	CM	0.00	0.00	*55.00 F 2 Pkts ✓
13	8		*REAR FENDER COWLING CLIPS		0.00	0.00	*16.00 F ✓
14	1		*REAR FENDER INNER RH		0.00	0.00	*420.00 F ✓
15	1		*REAR FENDER INNER TRIM RH	R	0.00	0.00	*195.00 F X
16	1		*REAR DOOR RH	R	0.00	0.00	*420.00 F ✓
17	1		*REAR DOOR INNER LOCK	R	0.00	0.00	*130.00 F X
18	1		*REAR DOOR RUBBER (AT DOOR) TOP	R	0.00	0.00	*15.00 F X
19	2		*REAR DOOR RUBBER (AT DOOR) SIDE	R	0.00	0.00	*20.00 F ✓
20	1		*REAR DOOR RUBBER (AT DOOR) LOWER	R	0.00	0.00	*15.00 F X
21	1		*SIDE SKIRT RH	R	0.00	0.00	*240.00 F X
22	1		*REAR SHOCK ABSORBER RH CHECK PRICE	R	0.00	0.00	*F X
23	1		*REAR SHOCK ABSORBER TOP MOUNTING RH CHECK PRICE	R	0.00	0.00	*F X
24	1		*SPORT RIM RHR CHECK PRICE	R	0	0.00	*FS X
25	1		*TYRE RHR - CHECK PRICE	CVT	0	0.00	*FS 902 ✓
26	1		*INNER SEAL	R	0	0.00	*20.00 FS ✓
27	1		*WINDSCREEN SEALANT	R	0	0.00	*40.00 FS ✓

F=Franchise part. S=SpcNeil.

Sub Total (\$\$)	3,471.00
+ Margin on L,N Items 10.00% (\$\$)	341.10
Total Parts (\$\$)	3,812.10

Ah Lim Motor Company/SLG3678X/29/04/2019 15:08. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	201 40.00
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	601 80.00
3	TO REMOVE & REINSTALL/REPLACE REAR FENDER GLASS RH.	New	601 100.00
4	TO REMOVE AND REINSTALL CUSHIONS; SEATS; BACKREST; INNER TRIM; GARNISH; ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	1001 150.00
5	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	New	501 60.00
6	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR FENDER RH;REAR FENDER INNER PANEL RH.TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	7201 1,150.00
7	TO SPRAY REAR BUMPER;REAR FENDER RH;REAR FENDER INNER PANEL RH;REAR DOOR RH;SIDE SKIRT RH.	New	7201 1,000.00
Gross Labour Cost (S\$)			2,530.00

Ah Lim Motor Company/SLG3678X/29/04/2019 15:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department

Estimate No: MC1900340
Date: 09 May 2019
Policy No: D18MTPV01015976
Veh Reg No: SLG3678X
Make/Model: HONDA SHUTTLE 1.5G
CVT

Your Ref No: SLG3678X
Claim Type: Own Damage/Third Party
Accident Date: 25/04/2019

Estimate Repair Cost to Vehicle No :SLG3678X

Description	U/Price	Quantity	Cost SS	Amount SS
Supplementary Parts to Repair				
SPARE PARTS				
1 HORN RH		1 PC	25.00	
Kenneth			25.00	
take photo			2.50	27.50
10-05-19				
10.15am				
Add 10%				
Amount Before Excess				S\$ 27.50
GST Amount				S\$ 1.93
Total Amount payable				S\$ 29.43

The above vehicle was surveyed by KENNETH KONG -LKK on 30/04/2019

For AH LIM MOTOR COMPANY

BLK 10 ANG MO KIO IND. PARK 2A
#01-09, AMK AUTOPPOINT
SINGAPORE 568047

AUTHORISED SIGNATURE



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLAZES
Deal Direct: 6417 8701 / 0745 5853



Dept Direct: 6417 8704

Dept Direct: 6417 8708

Dept Direct: 6417 8706

Dept Direct: 6417 871

Wiper blade: NWE (Nippon Wiper blade), Silliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

=====

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

TAX INVOICE : AR201905-03532
DATE : 08/05/2019
CUSTOMER ID : AHL008
VEH REG. NO. : SLG3678X
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	H38100-SNB-W02 FIT 08	HORN RH	U1 L2-M50-B	1	25.00	25.00
2	H74552-T5B-003 GK8 GP7	FENDER,R.RR INNER	U1 HL3-C3	1	55.00	55.00

SUB-TOTAL : 80.00
ADD GST 7.00 % 5.60

E. & O.E TOTAL AMOUNT SGD : 85.60

[P] 08/05/2019 10:36:27AM

[E] 08/05/2019 10:35:54AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : CHEN

This is computer generated document.
No signature is required.



* A R 2 0 1 9 0 5 - 0 3 5 3 2 *

Goods Received in Good Order

[Signature]

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 9781 / 6745 9020



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea L.
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL: 64831244 FAX: 64836170
ATTN: SIMON 96205405

TAX INVOICE : AR201905-03077
DATE : 07/05/2019
CUSTOMER ID : AHL008
VEH REG. NO. : SLG3678X
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	H33500-TE3-J01 GK8	TAIL LAMP RH	U1 HL2-C1	1	250.00	250.00
2	H71501-TD4-000ZC	REAR BUMPER RP50P	U1 HL2-L19	1	480.00	480.00
3	H71593-TD4-013/003 GP7	SPACER RH	U1 HL2-G8-B	1	15.00	15.00
4	H04636-TD4-J00/01ZZ GK8	RR FENDER RH	U1 HL1-A5-BA	1	620.00	620.00
5	H67510-T5L-T00ZZ GK5	RR DOOR RH	U1 HL1-B2	1	420.00	420.00
6	H73520-TD4-J01 GK8 SHUTTLE	RR FENDER RH MLD STRIGH	U1 HL2-E2-E	1	20.00	20.00

SUB-TOTAL : 1,805.00
ADD GST 7.00 % 126.35

E & O.E

TOTAL AMOUNT SGD : 1,931.35

[P] 07/05/2019 1:51:12PM

[E] 07/05/2019 1:47:45PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : CHEN

This is computer generated document.

No signature is required.



* AR201905-03077 *

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 0701 / 6745 9333



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

TAX INVOICE : AR201905-03079
DATE : 07/05/2019
CUSTOMER ID : AHL008
VEH REG. NO. : SLG3678X
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	H73521-TD4-J02 GK8	RR FENDER GLASS RH LOWER	MO SUPPLIER.	1	30.00	30.00 ✓
2.	H73226-SZW-000 GK3 FTT / RC1 ODY 14/RM3	RR GLASS TOP MLD	MO IHSD	1	15.00	15.00 ✓

SUB-TOTAL : 45.00
ADD GST 7.00 % 3.15

E. & O.E TOTAL AMOUNT SGD : 48.15

[P] 07/05/2019 2:51:14PM

[E] 07/05/2019 1:51:22PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : CHEN

This is computer generated document.
No signature is required.



* AR201905-03079 *

Goods Received in Good Order

Signature / Co Stamp / Date

Veron Chen (LKKAUTO)

From: Mui Hong @ Ah Lim Motor <muihong@ahlimmotor.com.sg>
Sent: Tuesday, 9 July 2019 5:01 PM
To: Kenneth Kong (LKKAUTO); Veron Chen (LKKAUTO)
Subject: Draft Finalisation - SLG3678X
Attachments: Draft Finalisation - SLG3678X-0001.pdf

Dear Kenneth ,

Pls see attached the Draft Finalisation – SLG3678X for your approval.

Pls advise.

Thanks

Best Regards,

Kee Mui Hong
Ah Lim Motor @ AMK
10, Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint S568047
Tel : 6483 1244 Fax : 6483 6170

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Apr 2019 Sendback Est	29 Apr 2019 15:08 S\$6,392.10	30 Apr 2019 09:01 Edit Adj Rpt	S\$4,075.00 Edit Estimates	S\$4,075.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	09 Jul 2019 16:59	09 Jul 2019 16:59 S\$27.50	09 Jul 2019 16:59			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	TING JUN LIN KRISMAN, ID: S82307853, Tel: +6591398552, Email: geerad21@gmail.com		
Vehicle Reg. No.:	SLG3678X	Date of Loss:	25/04/2019 16:00 - :59 [30 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / CMTD1902064	Policy/Cover Note No.:	D18MTPV01015976 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 10/05/2019]		
Driver/Custodian:	TING JUN LIN KRISMAN (36 / Male), NRIC: S82307853, Tel: +6591398552 Email: geerad21@gmail.com		
Adj Asp. Remarks:	WS: ZILA		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- SOMPO_SG (02/05/2019): **Alert - Adj Mandate Approved (S\$4436.60) - SLG3678X - Claim Handler: Thelma Choo**

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLG3678X (CMTD1902064)
OD
Apr 25 2019 4:00PM
[TING JUN LIN KRISMAN]
Ah Lim Motor Company

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	26/04/19 15:04	Accident Statement	1 Load HTM	
2	29/04/19 15:08	Repairer Estimates	1 Load HTM	
3	09/07/19 16:59	Repairer Estimates Suppl. #1	1 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/05/19 12:04	Adjuster Immediate Advice	1 Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/05/19 12:05	General View	1 Load JPG	
2	02/05/19 12:05	General View	1 Load JPG	
3	02/05/19 12:05	General View	1 Load JPG	
4	02/05/19 12:05	General View	1 Load JPG	
5	02/05/19 12:05	General View	1 Load JPG	
6	02/05/19 12:05	General View	1 Load JPG	
7	02/05/19 12:05	General View	1 Load JPG	
8	02/05/19 12:05	General View	1 Load JPG	
9	02/05/19 12:05	General View	1 Load JPG	
10	02/05/19 12:05	General View	1 Load JPG	
11	02/05/19 12:05	General View	1 Load JPG	
12	02/05/19 12:05	General View	1 Load JPG	
13	02/05/19 12:05	General View	1 Load JPG	
14	10/07/19 09:33	Reinspection Photo	1 Load JPG	
15	10/07/19 09:33	Reinspection Photo	1 Load JPG	
16	10/07/19 09:33	Reinspection Photo	1 Load JPG	
17	10/07/19 09:33	Reinspection Photo	1 Load JPG	
18	10/07/19 09:33	Reinspection Photo	1 Load JPG	
19	10/07/19 09:33	Reinspection Photo	1 Load JPG	

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/05/19 12:05	MARK ESTIMATE	1 Load PDF	
2	24/07/19 09:26	Parts Invoice	1 Load PDF	
3	24/07/19 09:27	Supplementary	1 Load PDF	

Linked Accident Report Documents

												View
												View in Browser
Assessment Reports												1 per page
No	Finalized On	Ah Lim Motor Company (AMK)							Thumbnail	Print		
1	26/04/19 15:04	Accident Statement						1	Load HTM			

Assessment Reports			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
Photos/Images			3 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	26/04/19 14:13	Accident Photo	 Load JPG	☒
2	26/04/19 14:13	Accident Photo	 Load JPG	☒
3	26/04/19 14:13	Accident Photo	 Load JPG	☒
4	26/04/19 14:13	Accident Photo	 Load JPG	☒
5	26/04/19 14:13	Accident Photo	 Load JPG	☒
6	26/04/19 14:13	Accident Photo	 Load JPG	☒
7	26/04/19 14:13	Accident Photo	 Load JPG	☒
8	26/04/19 14:13	Accident Photo	 Load JPG	☒
9	26/04/19 14:13	Accident Photo	 Load JPG	☒
10	26/04/19 14:13	Accident Photo	 Load JPG	☒
11	26/04/19 14:13	Accident Photo	 Load JPG	☒
12	26/04/19 14:13	Accident Photo	 Load JPG	☒
13	26/04/19 14:13	Accident Photo	 Load JPG	☒
14	26/04/19 14:13	Accident Photo	 Load JPG	☒
15	26/04/19 14:13	Accident Photo	 Load JPG	☒
16	26/04/19 14:13	Accident Photo	 Load JPG	☒
17	26/04/19 14:13	Accident Photo	 Load JPG	☒
18	26/04/19 14:13	Accident Photo	 Load JPG	☒
19	26/04/19 14:13	Accident Photo	 Load JPG	☒
20	26/04/19 14:13	Accident Photo	 Load JPG	☒
21	26/04/19 14:13	Accident Photo	 Load JPG	☒
22	26/04/19 14:13	Accident Photo	 Load JPG	☒
23	26/04/19 14:13	Accident Photo	 Load JPG	☒
24	26/04/19 14:13	Accident Photo	 Load JPG	☒
25	26/04/19 14:13	Accident Photo	 Load JPG	☒
26	26/04/19 14:13	Accident Photo	 Load JPG	☒
27	26/04/19 14:13	Accident Photo	 Load JPG	☒
28	26/04/19 14:13	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	26/04/19 15:04	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO19007578/KVD3E2

Date: 24/07/2019

REFERENCE

Insured/Claimant: TING JUN LIN KRISMAN Policy No: D18MTPV01015976
Date of Loss: 25/04/2019 Nature of Claim: OD Claim No: CMTD1902064

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG3678X**
Make & Model: HONDA SHUTTLE, 1.5 G CVT (A) Engine No: L15B3533832
Reg. Date: 28/09/2016 (Man. Year: 2015) Chassis No: GK81003200
Colour: Metallic Red Odometer: 60132 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$66,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
Front Left Side: Michelin 9 mm Rear Left Side: Michelin 9 mm
Front Right Side: Michelin 9 mm Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,839.60	2,345.00	1,494.60	38.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,580.00	1,730.00	850.00	32.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,419.60	4,075.00	2,344.60	36.52
+ GST 7.00/7.00% (S\$)	449.38	285.25	164.13	36.52
Nett Amount (S\$)	6,868.98	4,360.25	2,508.73	36.52

INSPECTION

Date of Assignment: 30/04/2019 Present Location: Ah Lim Motor Company (AMK)
Date Inspected: 30/04/2019 Inspected At: Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A, #01-09
AMK Autopoint
Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 24 Jul 2019)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG3678X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILAMP (WCP)	Cracked	250.00 F	*250.00 F
2	1		*TAILAMP LOWER BEAM RH - CHECK PRICE (NPA)	Serviceable	0.00 F	*- F
3	1		*REAR BUMPER (WCP)	Bent	480.00 F	*480.00 F
4	1		*REAR BUMPER SIDE RETAINER RH (WCP)	Cracked	15.00 F	*15.00 F
5	15		*REAR BUMPER CLIPS (WCP)	Not Necessary	30.00 F	*- F
6	1		*TAILAMP PANEL RH (WCP)	Repair	130.00 F	*- F
7	1		*REAR FENDER RH (OUTER) (WCP)	Bent	620.00 F	*620.00 F
8	1		*REAR FENDER GLASS (WCP)	Serviceable	280.00 F	*- F
9	1		*REAR FENDER GLASS MOULDING RH TOP (WCP)	Necessary	20.00 F	*20.00 F
10	2		*REAR FENDER GLASS MOULDING RH SIDE (WCP)	Necessary	30.00 F	*15.00 F
11	1		*REAR FENDER GLASS MOULDING RH LOWER (WCP)	Necessary	30.00 F	*30.00 F
12	1		*REAR FENDER COWLING RH (WCP)	Cracked	55.00 F	*55.00 F
13	8		*REAR FENDER COWLING CLIPS (WCP)	Not Necessary	16.00 F	*- F
14	1		*REAR FENDER INNER RH (WCP)	Repair	420.00 F	*- F
15	1		*REAR FENDER INNER TRIM RH (WCP)	Serviceable	195.00 F	*- F
16	1		*REAR DOOR RH (WCP)	Bent	420.00 F	*420.00 F
17	1		*REAR DOOR INNER LOCK (WCP)	Repair	130.00 F	*- F
18	1		*REAR DOOR RUBBER (AT DOOR) TOP (WCP)	Not Necessary	15.00 F	*- F
19	2		*REAR DOOR RUBBER (AT DOOR) SIDE (WCP)	Not Necessary	20.00 F	*- F
20	1		*REAR DOOR RUBBER (AT DOOR) LOWER (WCP)	Not Necessary	15.00 F	*- F
21	1		*SIDE SKIRT RH (WCP)	Serviceable	240.00 F	*- F
22	1		*REAR SHOCK ABSORBER RH - CHECK PRICE (NPA)	Serviceable	0.00 F	*- F
23	1			Serviceable	0.00 F	*- F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*REAR SHOCK ABSORBER TOP MOUNTING RH - CHECK PRICE (NPA)			
24	1		*SPORT RIM RHR - CHECK PRICE (NPA)	Serviceable	0.00 FS	*- FS
25	1		*TYRE RHR - CHECK PRICE (\$180.00) (90%)	Cut	0.00 FS	*162.00 FS
26	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
27	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
Supplementary #1						
28	1		*HORN RH (WCP)	Dented	25.00 F	*25.00 F
F=Franchise part. S=SpcNett.						
				Sub Total (S\$)	3,496.00	2,152.00
				+ Margin on L,N Items 10.00/10.00% (S\$)	343.60	193.00
				Total Parts (S\$)	3,839.60	2,345.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00	20.00
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	80.00	60.00
3	TO REMOVE & REINSTALL/REPLACE REAR FENDER GLASS RH.	New	100.00	60.00
4	TO REMOVE AND REINSTALL CUSHIONS; SEATS; BACKREST; INNER TRIM; GARNISH; ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	150.00	100.00
5	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	New	60.00	50.00
6	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR FENDER RH;REAR FENDER INNER PANEL RH.TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	1,150.00	720.00
7	TO SPRAY REAR BUMPER;REAR FENDER RH;REAR FENDER INNER PANEL RH;REAR DOOR RH;SIDE SKIRT RH.	New	1,000.00	720.00
Gross Labour Cost (\$\$)			2,580.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >