

REF: CS/FCI/19007592/4/d3⁷²
ASSIGNMENT (Office)
Client: Marcus
Merina chia
FCI
Date/Time: 12:58pm @ 30/4/19

Estimated Cost: 00
To: (P) WS/FP RES/FP RES/ENA/INV/MTG
To: (P) WS/FP RES/FP RES/ENA/INV/MTG
at: Workshop of
of
Policy No.
Claim No.
Date/Time: 23/04/19

CA / REV / REP / REV 24 HRS
Date/Time: 1:50pm @ 30/4/19
Person Contacted: Lee Lee
Vehicle: (P) OTE

Date/Time	Action/Instruction (✓) Estimate
	FBM 91214-X
	84A 9743E-NS/INC10003125/Cn
	DDA: 12/2/2010
2/5 @ 3:44pm	inform first capital pending estimate.

08/11/13 wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: FBM 912/H
 at Workshop m/s Evfu
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 9300
 IDAC Accident Report: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 2 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

HA6502

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBM 912/H Yr Regn: 5, 18
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Yamaha SNIPV C.C. 150
 Colour: Green A/C: Insured / Std / NI / NA
 Sp. Reading: 48443 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MH134607401H0077030
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or other
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 100/70-17
 R: 120-70-17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIRTSUMI /
 TOYO / YOKO or
 Front 6 mm Rear 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 L/Bal. 6 mm D.O.A. 23/4/19 D.O.I. 30/4/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rt. O/S 3.5
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

947 net 2798

7/5/19 2/5 2600 conf. and wh mnt rec.
(Red. 2743 40 151%)

RECEIVED 07 MAY 2019

Date/Time, File Pass to?

7/5 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

9/5/19

TOTAL

140
50
50+50
125
415

Report Format : TP

Lump Sum / I.B.I: (\$ 2600)

MOTOR SURVEY ASSIGNMENT

Date	25-04-2019	Our Ref No.	D19002766MFSH
Accident Date	23-04-2019	Claim Type.	Third Party
Insured Vehicle	SHA9743E	Third Party Vehicle.	FBM9121H
Survey Location	1 KAKI BUKIT AVE 6 #02-62 AUTOBAY @KAKI BUKIT		
Contact Person.	LEELEE TAN		
Contact No.	67527740/ 90696165	Fax No.	67528669
Survey Type	WITHOUT PREJUDICE:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	EROFIA MOTOR TRADING PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	MERINA CHIA SAN SAN		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 2 May 2019 3:44 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002766MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle FBM 9121H on 30/4/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 30 April 2019 1:49 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002766MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 30 April 2019 12:58 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: Sithara <Sithara@msfirstcapital.com.sg>; CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002766MFSH/1

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 3649Z

Vehicle Details

Vehicle No.: FBM9121H

Vehicle to be Exported: No

Intended Deregistration Date: 30 Apr 2019

Vehicle Make: YAMAHA

Vehicle Model: SNIPER T150

Primary Colour: Green

Manufacturing Year: 2017

Engine No.: G3E6E0342482

Chassis No.: MH3UG0740H0077030

Maximum Power Output: -

Open Market Value: \$2,054.00

Original Registration Date: 11 May 2018

First Registration Date: 11 May 2018

Transfer Count: 1

Actual ARF Paid: \$309.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 10 May 2028

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$7,204.00

COE Rebate Amount: \$6,502.00

Total Rebate Amount: \$6,502.00

The information contained herein is correct as at 30 Apr 2019

OK

Yamaha MXi T150 Sniper

Listing Type	Paid Ad
Brand	Yamaha (/listing/usedbike/brand/yamaha/)
Model	Yamaha MXi T150 Sniper (/listing/usedbike/model/yamaha-mxi-t150-sniper/)
Engine Capacity	150cc
Classification	Class 2B (/listing/usedbike/model/motorcycle-for-sale/class/class-2b/)
Registration Date	17/05/2016
COE Expiry Date	16/05/2026 (7 years left)
Mileage	-
No. of owners	-
Type of Vehicle	Cubs (/listing/usedbike/model/motorcycle-for-sale/cubs/)

Price: ^{SGD}\$7800

DETAILS

COE May 2026. As good as new. Low mileage of 10k. Previous owner seldom ride hence selling it. All in good original condition. Very well maintained bike. Trade in available. Lowest downpayment and interest rate. Price Negotiable. Any enquiries please call 81291192.

SIMILAR BIKES

[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](/LISTING/USEDBIKES/LISTING/)

Yamaha MXi T150 Sniper



Yamaha MXi T150 Sniper



W 706368
MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412212G)
4 Shenton Way, # 21-01, SGX Centre2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

CERTIFICATE OF INSURANCE

Road Transport Act, 1987 (Malaysia)
The Motor Vehicles (Third Party Risks) Rules, 1959 (Federation of Malaysia)
The Motor Vehicles (Third Party Risks and Compensation) Act (CAP. 189 of the Revised Edition) (Republic of Singapore)
The Motor Vehicles (Third Party Risks and Compensation) Rules, 1996 Edition (Republic of Singapore)
Or any Amendment, Act or Acts passed in substitution thereof.

CERTIFICATE NO : MSD/VMS/18-992688-WTT A0633-001/W0854

SUM INSURED : PMV

EXCESS : \$300(FIRE&THEFT) \$600(ENDT 2K)

S14236492

1. Index mark and Registration Number of Vehicle FBM9121H

YAMAHA

150 c.c.

2. Name of Policyholder TAN YEW TIT

3. Effective date of the Commencement of Insurance

for the purposes of the Act

1349PM 12/05/2018

4. Date of Expiry of Insurance

11/05/2019

5. Persons or Classes of Persons entitled to drive

a. The Policyholder.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered and licensed under the Road Traffic Act and its registration and licensing under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitation as to Use

Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

7. The Policy does not cover

1. Use for hire or reward.

2. Use for racing, pace-making, reliability trial or speed-testing.

3. Use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).

Repl CN: 60800820

13/06/2018 (T)

WTT-CI-04(04/14)

WTT INSURANCE AGENCIES PTE LTD

Underwriting Agent

For MSIG Insurance (Singapore) Pte. Ltd.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1423649Z



Name

TAN YEW TIT

陳友德

Race

CHINESE

Date of birth

04-06-1960

Sex

M

Country of birth

SINGAPORE

S1423649Z

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S1423649Z

Name

TAN YEW TIT

Birth Date: 04 Jun 1960

Issue Date: 11 Apr 2013



0021684061



3970510



NRIC No. S1423649Z

Date of issue

06-12-2006

Address

APT BLK 4 MARSILING ROAD
#04-5061
SINGAPORE 730004

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 2B	Motorcycles =< 200 cc	31 May 1985
Class 3	Motor Cars =< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg	24 Jul 1980

NP 428A



Licence No: S1423649Z

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Owner : Tan Yew Tit

Accident Date : 23-Apr-19

Vehicle No : FBM 9121 H

Vehicle Model : Yamaha Sniper
150

*not added
H/L
1/5 #2600
H/L
30/4/19*

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
2	Front fork tube assy	\$ <i>Bed/twr</i> 640.00 ✓
1	Front wheel rim	\$ <i>bed</i> 280.00 ✓
1	Fork under bracket	\$ <i>bed</i> 185.00 ✓
1	Front rim shaft	\$ <i>bed</i> 45.00 ✓
1	Front rim bearing	\$ <i>bed</i> 38.00 ✓
1	Front brake disc	\$ <i>Bed</i> 155.00 ✓
1	Handle-bar	\$ <i>Bed</i> 88.00 ✓
1	Handle-bar end -R/H	\$ <i>scr</i> 32.00 ✓
1	Hand grip (1 set)	\$ <i>11</i> 55.00 ✓
1	Handle-bar inner bracket	\$ <i>11</i> 68.00 ✓
2	Side mirrors	<i>o/s</i> \$ <i>scr</i> 110.00 <i>1pc55</i>
1	Brake lever	\$ <i>scr</i> 32.00 ✓
2	Front signals	\$ <i>o/s scr</i> 140.00 <i>1pc70</i>
1	Fairing assy (1 set)	\$ <i>cm</i> 495.00 ✓
2	Side cowling lamps	\$ <i>u/s cr</i> 160.00 <i>1pc80</i>
1	Radiator	\$ <i>pu 1</i> 458.00 ✓
1	Front footrest bracket	\$ <i>cm</i> 65.00 ✓
1	Front footrest rubber -R/H	\$ <i>70.1</i> 35.00 ✓
1	Brake pedal	\$ <i>cut</i> 42.00 ✓
1	Rear footrest -R/H	\$ <i>scr</i> 40.00 ✓
1	Rear footrest bracket	\$ <i>11</i> 78.00 ✓
1	Exhaust assy	\$ <i>R</i> 485.00 ✓
1	Exhaust protector - Rear	\$ <i>scr</i> 60.00 ✓
1	Exhaust protector- Front	\$ <i>scr</i> 45.00 ✓
1	Rear handle	\$ <i>11</i> 50.00 ✓
1	Exhaust pipe end cover	\$ <i>scr</i> 55.00 ✓
2	Rear signals	\$ <i>11</i> 120.00 ✓
		\$ 4,056.00
	Less 10%	\$ 405.60
		\$ 3,650.40

*2939
2645.1*

c/f: \$ 3,650.40

Special Nett Items

1	Number plate (1 set)	\$ 11	28.00	X
2	Fork oils	\$ 11	30.00	X
2	Fork oil seals	\$ 11	56.00	X
1	Steering cone (1 set)	\$ m	90.00	/
1	Rear box	\$ m7	280.00	200
1	Rear box bracket	\$ 11	100.00	X
1	Front tyre	\$ 11	120.00	X
1	Coolant	\$ 1ec	18.00	15
1	Sticker (1 set)	\$ m	95.00	80
		\$	817.00	

S/No.

Labour

1	To provide towing service.	\$	50.00	35
2	To check wiring and reset headlamp focusing	\$ 11	80.00	X
3	To provide labour.	\$	380.00	300
4	To repair body frame.	\$ 11	350.00	X
		\$	860.00	

Grand Total

\$ 5,327.40

120



EROFIA MOTOR TRADING PTE LTD

EROFIA hereby notifies the Repairer of the following:

- To be done before any spray painting
- To be done before any (s) during resurvey
- To be done before any (s) during resurvey
- This price survey is on a "Without Prejudice" basis
- No Repair and Re-survey is allowed
- Supplementary cost must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19007592/Utd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 09-05-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9743E	Veh. Inspected	FBM 9121H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002766MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	30/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA SNIPER	c.c	150	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MH3UG0740H0077030	Colour	GREEN	
Odometer	48443	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	100/70-17	PIRELLI	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	120/70-17	PIRELLI	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/04/2019	Inspection Date	30/04/2019	
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 9121H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	FRONT FORK TUBE ASSY	BENT / TWISTED	640.00	640.00
1	FRONT WHEEL RIM	BENT	280.00	280.00
1	FORK UNDER BRACKET	BENT	185.00	185.00
1	FRONT RIM SHAFT	BENT	45.00	45.00
1	FRONT RIM BEARING	BENT	38.00	38.00
1	FRONT BRAKE DISC	BENT	155.00	155.00
1	HANDLE-BAR	BENT	88.00	88.00
1	HANDLE-BAR END-R/H	SCRATCHED	32.00	32.00
1	SET HAND GRIP	NOT NECESSARY	55.00	-
1	HANDLE-BAR INNER BRACKET	NOT NECESSARY	68.00	-
2	SIDE MIRRORS	O/S BROKEN	110.00	55.00
1	BRAKE LEVER	SCRATCHED	32.00	32.00
2	FRONT SIGNALS	O/S CRACKED	140.00	70.00
1	SET FAIRING ASSY	CRACKED	495.00	495.00
2	SIDE COWLING LAMPS	O/S CRACKED	160.00	80.00
1	RADIATOR	PUNCTURE	458.00	458.00
1	FRONT FOOTREST BRACKET	CRACKED	65.00	65.00
1	FRONT FOOTREST RUBBER-R/H	TORN	35.00	35.00
1	BRAKE PEDAL	CUT	42.00	42.00
1	REAR FOOTREST-R/H	SERVICEABLE	40.00	-
1	REAR FOOTREST BRACKET	NOT NECESSARY	78.00	-
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	485.00	-
1	EXHAUST PROTECTOR-REAR	SCRATCHED	60.00	60.00
1	EXHAUST PROTECTOR-FRONT	SCRATCHED	45.00	45.00
1	REAR HANDLE	NOT NECESSARY	50.00	-
1	EXHAUST PIPE END COVER	SCRATCHED	55.00	55.00
2	REAR SIGNALS	NOT NECESSARY	120.00	-
	LESS 10% DISCOUNT		-405.60	-295.50
			3,650.40	2,659.50

Report Ref No. CS/FC119007592/Utd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SET NUMBER PLATE (SN)	NOT NECESSARY	28.00	-
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NECESSARY	90.00	90.00
1	REAR BOX (SN)	CUT	280.00	200.00
1	REAR BOX BRACKET (SN)	NOT NECESSARY	100.00	-
1	FRONT TYRE (SN)	NOT NECESSARY	120.00	-
1	COOLANT (SN)	NECESSARY	18.00	15.00
1	SET STICKER (SN)	NECESSARY	95.00	80.00
			817.00	385.00
	LABOUR			
	TO PROVIDE TOWING SERVICE.		50.00	35.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR INCLUSIVE OF THE REPAIR OF EXHAUST ASSY.		380.00	300.00
	TO REPAIR BODY FRAME.	NOT NECESSARY	350.00	-
			860.00	335.00
	GRAND TOTAL		5,327.40	3,379.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,600.00

Report Ref No. CS/FCI19007592/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.