

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0561/2019/DY/TF
Date : 30-Apr-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle : SMD 0556 M

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Lin Ai Hua
Address : Blk 637 Chua Chu Kang North 6
#13-241
Singapore 680637
Telephone : 92378785
Type of Claim : Third Party Claims
Policy No. : 1800015537-01
Vehicle No : **SLL 5296 A**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Feb-17
Engine No : CHZ 146673
Chassis No : WAUZZZ8V7H1027605
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 29-Apr-19
Place of Accident : 1 Yuan Ching Road Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLL 5296 A

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00 750
3	To respray front bumper and rhs front fender.	\$ 1,500.00 1100
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 4,152.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Parts for Accident Vehicle SLL 5296 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>del d</i>	\$ 1,830.00	✓
2	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	\$ 35.00	+
3	FRONT BUMPER AIR GUIDE GRILLE - RH <i>new</i>	\$ 171.00	+
4	FRONT FENDER - RH <i>Rep</i>	\$ 778.00	+
5	FRONT FENDER ATTACHMENT PARTS <i>} new</i>	\$ 65.00	+
6	FRONT FENDER BRACKER - RH	\$ 35.00	+
7	POP RIVET <i>new</i>	\$ 18.00	+
8	FRONT FENDER BRACE - RH <i>new</i>	\$ 88.00	+
9	FRONT WHEEL HOUSING ATTACHMENT PARTS <i>new</i>	\$ 81.00	+
10	FRONT WHEEL HOUSING LINER <i>new</i>	\$ 158.00	+
11	HEADLIGHT - RH <i>cut</i>	\$ 5,029.00	✓
12	HEADLIGHT LIFT CYLINDER - RH <i>new</i>	\$ 128.00	X
13	SUNDRIES <i>?</i>	\$ 400.00	?
TOTAL SPARE PARTS :		\$ 8,816.00	
TOTAL LABOUR CHARGES :		\$ 4,152.00	
GRAND TOTAL :		\$ 12,968.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 08/05/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant