



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SBH66U

Wong Foot Hin

80 Jalan Girang  
Singapore 359249

Mobile: 96381955

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

### Vehicle & Document Information

32483

SBH66U / 21/12/2018

0

WDD2130422A5693183

27492031686447

MB/MB E 200 SEDAN AVANTGARDE/AVANTGARDE

027 775 Iridium Sil/ 042 201 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	16/07/2019/ 10:03	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M BPNSUN

POLICY NO/ACC DATE : 1800151939 // 06.04.19

DRIVE IN/EXCESS : 10.04.19 // TP CAR SLU6055A-AXA INS

DATE IN/DATE SURVEY: 16.07.19 //

DIRECT SETTLEMENT:VIC ALPH-LKK // 15.05.19

A BPILAB

"USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO  
STANDARD SETTINGS.NETT"

0.10

380.00

A BPILAB

REMOVE & REPLACE ON REAR BUMPER

960 1200.00

A BPIRES

RESPRAY ON REAR BUMPER

600 1200.00

R REAR BUMPER

1.00 2011.82 00.00

2011.82

M REAR BUMPER CHROME MOULDING

1.00 312.57 00.00

312.57

M REAR LOWER BUMPER

1.00 269.37 00.00

269.37

M REAR CROSS MEMBER

1.00 789.61 00.00

789.61

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirmed & accepted by

7% GST on **Nett** 6,163.37 **431.44**

Authorized signatory and company stamp

**Total Payable 6,594.81**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SBH66U

Wong Foot Hin  
80 Jalan Girang  
Singapore 359249

### Vehicle & Document Information

WIP No 32483  
Reg No/Reg Date SBH66U / 21/12/2018  
Date In/Mileage 16/07/2019 / 8492  
Chassis No WDD2130422A5693183  
Engine No 27492031686447  
Make/Model MB/MB E 200 SEDAN AVANTGARDE/AVANTGARDE  
Colour/Trim 027 775 Iridium Sil/ 042 201 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator	
CSI00001	Cash	01/08/2019/ 14:42	VS	356 / Vincent Seah	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M BPNSUN  
POLICY NO/ACQ DATE : 1800151939 // 06/04/19  
DRIVE IN/EXCESS : 10/04/19 // TP OAR SUU6055A-AXA UNS  
DATE IN/DATE SURVEY: 16.07.19 // 16.07.19 RASUL-LKK 11:00AM  
DIRECT SETTLEMENT:VIC ALPEH-LKK // 15.05.19

A BPILAB  
"USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO  
STANDARD SETTINGS.NETT"

0.10 380.00

A BPILAB  
REMOVE & REPLACE ON REAR BUMPER

960.00

A BPIRES  
RESPRAY ON REAR BUMPER

600.00

X REAR BUMPER

1.00 2011.82 00.00

2011.82

X REAR BUMPER CHROME MOULDING

1.00 312.57 00.00

312.57

X REAR LOWER BUMPER

1.00 269.37 00.00

269.37

X RHR SIDE STABILITY (S)

1.00 80.80 00.00

80.80

ESTIMATE

3 days

Finalization

Confirmed & accepted by

7% GST on **Nett 4,614.56**  
**323.02**

Authorized signatory and company stamp

**Total Payable 4,937.58**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SBH66U

Wong Foot Hin

80 Jalan Girang  
Singapore 359249

### Vehicle & Document Information

WIP No **32483**  
Reg No/Reg Date **SBH66U / 21/12/2018**  
Date In/Mileage **16/07/2019 / 8192**  
Chassis No **WDD2130422A5893186**  
Engine No **27492031686447**  
Make/Model **MB/MB E 200 SEDAN AVANTGARDE/AVANTGARDE**  
Colour/Trim **027 775 Iridium Sil/ 042 201 Leather Bla**

Account No	Terms	Date/Time Printed	CSE	Operator	
CSI00001	Cash	01/08/2019/ 14:51	VS	356 / Vincent Seah	
Description of Goods/Services		Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : 1800151939 // 10610419  
DRIVE IN/EXCESS : 10.04.19 // TP CAR SUU6055A-AXA INS  
DATE IN/DATE SURVEY: 16.07.19 // 16.07.19 RASUL-LKK 11:00AM  
DIRECT SETTLEMENT: VIC ALPEN-LKK // 15.05.19  
X RHR SIDE STABILITY

1.00 80.80 00.00 80.80

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

7% GST on **Nett 80.80** **5.66**  
**Total Payable 86.46**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.