

COMMERCIAL

ASS. REC. BY:

REF: CS/FCI 19007598/ksd3n2

Special Instruction:

CWS

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Henry Kao

of FCI

Date/Time: 30.4.19 3.01p.m

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SUR 8753X

Insured: SHB 3009 B

at Workshop m/s CITY AUTO

Tel: 645 31235

of Blk B sin ming Road # 01-58

Policy No:

Claim No: D19002792 MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 25.4.2019

CA / REV / REP. / REV 24 HRS

rup''

H.O.D. Endorsement:

Date/Time: 30.4.19 3.12p.m

Person Contacted: Veronica Law

Vehicle IN/OUT

Date/Time

Action/Instruction Estimate (✓)

SUR 8753X - X

SHB 3009B - CS/FCI 1701017 / 1 / AvbK2

D.O.A - 19/04/2017

2/5 @ 4:30pm - Rense preli advise via email

8/5 1/1 Rep @ 2/5 of Cabinet.

(\$ 2,462.92 Red - 53%)

ASS. REC. BY:

REF: 1021

ASSIGNMENT

Kenneth

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s City Ave

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 1.131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SR8753X Yr Regn: 08, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Wagon
Make: Toyota C.C. 1800

Colour: M. Brown A/C: Insured / Std / NI / NA

Sp. Reading: 15251 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: ES460 . 0079332

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: 235/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm Rear 8 mm

L/Bal. 7 mm L/Bal. 8 mm

D.O.A. 25/4/11 D.O.I. 30/4/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

RECEIVED 09 MAY 2019

Date/Time, File Pass to?

09/05/19

1) Typist

Date/Time, File Return to?

2) _____

: Prell. Report

: Final Report

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation:

S - R.S. \$

Fees

Others

TOTAL

135
50
50+50
19
304

Report Format :

Lump Sum / I.B.I: (\$ 2,150/- H.S.)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002792MFSH

Date: 2/5/2019

Our Ref: CS/FCI19007598/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLR 8753X

Please be informed that we had conducted the inspection of the abovementioned vehicle 30/4/2019 at the premises of M/s City Auto have the following to report: -

Workshop Estimate Amount	: S\$	<u>4,612.92</u>
Revised Estimate Amount	: S\$	<u>2,005.76</u>
"Check" Items Amount	: S\$	<u>1,887.27</u>
Market Value	: S\$	<u> </u>
LTA Reimbursement Value	: S\$	<u> </u>
Nett Value	: S\$	<u> </u>

Description of Damage:

The vehicle sustained damages at the Rear o/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	26-04-2019	Our Ref No. D19002792MFSH
Accident Date	25-04-2019	Claim Type. Third Party
Insured Vehicle	SHB3009B	Third Party Vehicle. SLR8753X
Survey Location	BLK 8 SIN MING ROAD #01-58/60/62 SIN MING IND EST	
Contact Person.	VRONICA LAW	
Contact No.	64531235/ 0	Fax No. 64537944
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CITY AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 2 May 2019 4:30 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments; SUR
Cc: 'Henry Kao Cai Jie'
Subject: RE: SURVEY ASSESSMENT - D19002792MFSH/1
Attachments: PRELI ADVISED SLR 8753X.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLR 8753X

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 30 April 2019 3:11 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19002792MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 30 April, 2019 3:01 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002792MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201904-000608(00)

MS FIRST CAPITAL INSURANCE LTD
NO. 36
ROBINSON RD
CITY HOUSE
SINGAPORE 068877

Date : 30/04/2019
Vehicle No. : SLR8753X
Make/Model : TOYOTA HARRIER PREMIUM 2.0 A

Contact : -

Fax No. : 65073849

Not Authorized
Resurvey B4 paint

Mileage (km) : 0
Chassis No. : ZSU600079332
Accident Date : 25/04/2019 00:00:00
Claim No. : SHB3009B
Reference : SLR8753X
Policy No. : G300052691MCY

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Rear bumper	1.0	1,495.10	1,495.10 ✓
2	Rear bumper sponge	1.0	117.80	117.80 ✓
3	Rear bumper retainer	2.0	68.70	137.40 ✓
4	Rear bumper lower spoiler	1.0	389.20	389.20 ✓
5	Rear Bumper clips	8.0	4.20	33.60 ✓
6	Emblem - Harrier	1.0	67.75	67.75 ✓
7	Rear end panel	1.0	741.30	741.30 ✗
8	Rear end panel top garnish	1.0	357.80	357.80 ✗
9	RH reflector	1.0	390.60	390.60 ✗
	List Total :			3,730.55
	25% Discount S\$			932.63
				2,797.92
SPECIAL NET :				
1	Reverse sensor	1.0	350.00	350.00 ✓ 200
	SPECIAL NET Total S\$:			350.00
LABOUR :				
	* To remove and install reverse sensor	1.0	120.00	120.00 ✓ 50
	-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	600.00	600.00 ✓ 300
	- Spray painting on affected & replace parts	1.0	700.00	700.00 ✓ 500
	* To check and re-wiring	1.0	45.00	45.00 ✓ 15
				1,465.00

E. & O.E.

Total S\$: 4,612.92
GST 7% S\$: 322.90
Amount Due S\$: 4,935.82

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 1

Acknowledged by Repairer
Signature:

[Signature]
for CITY AUTO PTE LTD

Ks



CITY AUTO PTE LTD

One Stop Automotive Solutions

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
 TEL: 6453 1235, 6452 0850 FAX: 6453 7944
 24hrs Towing Services Tel 9823 9898
 Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

MS FIRST CAPITAL INSURANCE LTD
 NO. 36
 ROBINSON RD
 CITY HOUSE
 SINGAPORE 068877

Estimate : QUOT201904-000608(00)

Date : 30/04/2019
 Vehicle No. : SLR8753X
 Make/Model : TOYOTA HARRIER PREMIUM 2.0 A

Mileage (km) : 0
 Chassis No. : ZSU600079332
 Accident Date : 25/04/2019 00:00:00
 Claim No. : SHB3009B
 Reference : SLR8753X
 Policy No. : G300052691MCY

Contact : -

Fax No. 65073849

Not Authorized

Resurvey B4 paint

1/1 Spry @ 21gols @ 3 days

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Rear bumper	1.0	1,495.10	1,495.10
2	Rear bumper sponge	1.0	117.80	117.80
3	Rear bumper retainer	2.0	68.70	137.40
4	Rear bumper lower spoiler	1.0	389.20	389.20
5	Rear Bumper clips	8.0	4.20	33.60
6	Emblem - Harrier	1.0	67.75	67.75
7	Rear-end panel	1.0	741.30	741.30
8	Rear-end panel top garnish	1.0	357.80	357.80
9	RH reflector	1.0	390.60	390.60
List Total :				2,172.15
25% Discount S\$				543.04
				1,629.11
SPECIAL NET :				
1	Reverse sensor	1.0	350.00	350.00
SPECIAL NET Total S\$:				350.00
LABOUR :				
* To remove and install reverse sensor				120.00
-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts				600.00
- Spray painting on affected & replace parts				700.00
* To check and re-wiring				45.00
				365
				1,465.00

P- \$ 2,172.15

-25%

\$ 1,629.11

CN - \$ 350.00

L- \$ 365.00

\$ 2,844.11

-20%

\$ 2,275.29

1/1 - \$ 2,300

3 Days

2,172.15

932.63

2,797.92

Sheet

200SN

500

? 300

500

15%

Total S\$: 4,612.92
 GST 7% S\$: 322.90
 Amount Due S\$: 4,935.82

F & O.E.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 1

Acknowledged by Repairer

Signature:

for CITY AUTO PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19007598/Ksd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-05-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 3009B	Veh. Inspected	SLR 8753X
Policy No.		Coverage (\$)	0.00
Claim No.	D19002792MFSH	Excess (\$)	0.00
Assign From	HENRY KAO	Assign Date	30/04/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HARRIER (A)	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZSU600079332	Colour	METALLIC BROWN
Odometer	15251	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/55 R18	BRIDGESTONE	7 mm
L/H Front Tyre	235/55 R18	BRIDGESTONE	7 mm
R/H Rear Tyre	235/55 R18	BRIDGESTONE	8 mm
L/H Rear Tyre	235/55 R18	BRIDGESTONE	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/04/2019	Inspection Date	30/04/2019
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 8753X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED	1,495.10	1,495.10
1	REAR BUMPER SPONGE	CRACKED	117.80	117.80
2	REAR BUMPER RETAINER @\$68.70	O/S DISTORTED / N/S SERVICEABLE	137.40	68.70
1	REAR BUMPER LOWER SPOILER	DENTED / CUT	389.20	389.20
8	REAR BUMPER CLIPS @\$4.20	NECESSARY	33.60	33.60
1	EMBLEM-HARRIER	NECESSARY	67.75	67.75
1	REAR END PANEL	TO REPAIR SEE LABOUR	741.30	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	357.80	-
1	RH REFLECTOR	SERVICEABLE	390.60	-
	LESS 25% DISCOUNT		-932.63	-543.04
			2,797.92	1,629.11
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	SHORTED	350.00	200.00
			350.00	200.00
LABOUR				
	TO REMOVE AND INSTALL REVERSE SENSOR.		120.00	50.00
	TO KNOCK JACKOUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		600.00	300.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		700.00	500.00
	TO CHECK AND RE-WIRING.		45.00	15.00
	-		-	-
	-		-	-
	-		-	-
			1,465.00	865.00
GRAND TOTAL			4,612.92	2,694.11
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,150.00

Report Ref No. CS/FCI19007598/Ksd3n2



Report Ref No. CS/FCI19007598/Ksd3n2

A handwritten signature in black ink, consisting of the letters 'KSC' in a stylized, cursive font.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.