

35/4/2019

Registered in Merimex:



(VL-YB/NB)



Date/Time

DATE / PIC

1000

11

ller Typist

--	--	--	--

[illegible][illegible]

2		
---	--	--

✓		
---	--	--

Towing Invoice

		
---	--	--

4

2	1	1
---	---	---

[illegible]

12	
----	--

1	2	3
4	5	6

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

422

[illegible]

as possible

[illegible]

21

1. *Journal of the American Medical Association*, 2000; 283: 2686-2692.

State Senate

✓ GNA.

Surveyor

Tuphi

REF: ASM(AXA)

76021P

ASSIGNMENT

From: Date: 30/4/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJV 5042L
at Workshop n/s: Mova Automotive
of BIK 1008 Bkt merah lane 3 # 01-04

Insured

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS / up

Date: Person Contacted:

Vehicle: IN / OUT

Key

Veh No: SJV 5042L Yr Regn: 2010, Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Terra c.c. 1997

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 145363 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17 R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 30/4/19 130pm

Survey held at Mova Bkt

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Inform Key Repair Unit & SK

US \$500.00 with 6 repair days

CRD - \$2167.26 / 27%

6 repair days + 1 Sunday + 1 Saturday + 1 PR = 9 days

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

3 + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Main Office:
Mova Building
No. 22, Jalan Kiang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 9892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0068854-2

Estimate

29/04/2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
AXA TOWER #27-01
SINGAPORE 068811

Attention :- XA009

Page # :- 1

Veh # :- SJV5042L

Veh Model :- NISSAN TEANA 2.0

Estimate# :- CK419073

Claim # :-

ACC. Date :- 29/04/19

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
NET ITEMS :				
1.	REAR BOOT	1	PC bl- 862.10	862.10 ✓
2.	REAR BOOT LOGO	1	PC de- 68.40	68.40 ✓
3.	REAR BOOT EMBLEM "TEANA"	1	PC de- 87.30	87.30 ✓
4.	REAR BOOT EMBLEM "200XL"	1	PC de- 86.60	86.60 ✓
5.	REAR BOOT CHROME TOP	1	PC CR- 278.40	278.40 ✓
6.	REAR BOOT CHROME LOWER	1	PC CR- 332.20	332.20 ✓
7.	REAR BOOT LOCK TOP	1	PC bl- 178.10	178.10 ✓
8.	REAR BOOT CATCH	1	PC KX 65.20	65.20 X
9.	REAR BOOT RUBBER	1	PC de- 188.10	188.10 ✓
10.	REAR BOOT HINGE L+R	2	PC KX 110.20	220.40 X
11.	REAR LAMP L+R	2	PC RH-at- 379.20	758.40 ✓
12.	REAR LAMP COVER L+R	2	PC RH-at- 23.60	47.20 ✓
13.	REAR PANEL	1	PC ? 575.60	575.60 ✓
14.	REAR PANEL INNER TRIM	1	PC ? 295.30	295.30 ✓
15.	REAR PANEL INNER TRIM CLIPS	6	PC ? 3.90	23.40 ✓
16.	REAR BUMPER bumper	1	PC de- 875.60	875.60 ✓
17.	REAR BUMPER SPONGE	1	PC ? 141.70	141.70 X
18.	REAR BUMPER REINFORCEMENT	1	PC ? 313.20	313.20 ✓
19.	REAR BUMPER BRACKET L+R	2	PC ? 98.60	197.20 ✓
20.	REAR BUMPER CHROME L+R	2	PC ? 298.50	597.00 ✓
21.	REAR BUMPER CLIPS	10	PC de- 3.90	39.00 ✓
22.	REAR FLOOR PANEL (REPAIR)	1	PC	
23.	REAR FENDER L+R (REPAIR)	2	PC	
24.	REAR CHASSIS MEMBER (REPAIR)	1	PC	
NET TOTAL S\$				6,330.40
10% DISCOUNT S\$				-633.04
Supplementary				
Spare tool tray \$299.70 N de ✓				
Keyless sensor \$295.10 N de ✓				
				5,997.36
SPECIAL NET ITEMS :				
1.	REAR BUMPER SENSOR	1	PC de- 250.00	250.00
2.	REAR NUMBER PLATE	1	PC bl- 50.00	50.00
SPECIAL NET TOTAL S\$				300.00
LABOUR :				
TO CUT-WELD REAR PANEL, TO REPAIR REAR FLOOR PANEL, REAR FENDER L+R, REAR CHASSIS MEMBER TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS				
Supp				
5500.30				
594.80				
6095.10				
609.51 - 10%				
5485.59				
245.00 - s Nett				
1570.00 - LB				
\$7300.59				
TO SPRAY AFFECTED AREAS				840.00
TO REMOVE & REFIX LAGGAGE COMPARTMENT SIDE TRIM BOARD, CARPET AND OTHER ATTACHMENT PARTS				850.00
TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE				120.00
(6 day)				80.00

Estimate

29/04/2019

AXA INSURANCE PTE LTD
 8 SHENTON WAY
 AXA TOWER #27-01
 SINGAPORE 068811

Attention:- XA009

Page # :- 1 134740

Veh # :- SJV5042L

Veh Model :- NISSAN TEANA 2.0

Estimate# :- CK419073

Claim # :-

ACC. Date :- 29/04/19

Terms :- C.O.D Days

Remarks :-

Main Office:
 Move Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722
 Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088894-2

No.	Description	Qty	U.Price	Amounts S\$
	TO RUST PROOF AFFECTED AREAS			30 80.00
	LABOUR TOTAL S\$			\$1570 1,970.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 7,967.36

GST @ 7 % 557.72

AMOUNT DUE S\$ 8,525.08

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

Tanpin 97495749
 WP
 30/4/19 @ 330 pm
 Receiving after repair
 sup/khantawm
 6 days

Estimate

29/04/2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
AXA TOWER #27-01
SINGAPORE 068811

Attention :- **XA009**

Page # :- 1

Veh # :- SJV5042L

Veh Model :- NISSAN TEANA 2.0

Estimate# :- CK419073

Claim # :-

ACC. Date :- 29/04/19

Terms :- C.O.D Days

Remarks :-

Main Office:
 Mova Building
 No. 22, Jalin Klang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 100B,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 6314

Co. Reg. 198904033G
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

NET ITEMS :

1.	REAR BOOT	1	PC <i>bt</i> 962.10	962.10
2.	REAR BOOT LOGO	1	PC <i>ad</i> 68.40	68.40
3.	REAR BOOT EMBLEM "TEANA"	1	PC <i>ad</i> 87.30	87.30
4.	REAR BOOT EMBLEM "200XL"	1	PC <i>ad</i> 86.60	86.60
5.	REAR BOOT CHROME TOP	1	PC <i>?</i> 278.40	278.40
6.	REAR BOOT CHROME LOWER	1	PC <i>ad</i> 332.20	332.20
7.	REAR BOOT LOCK TOP	1	PC <i>bt</i> 178.10	178.10
8.	REAR BOOT CATCH	1	PC <i>KX</i> 65.20	65.20
9.	REAR BOOT RUBBER	1	PC <i>ad</i> 188.10	188.10
10.	REAR BOOT HINGE L+R	2	PC <i>KX</i> 110.20	220.40
11.	REAR LAMP L+R	2	PC <i>KH-at</i> 379.20	758.40
12.	REAR LAMP COVER L+R	2	PC <i>KH-int</i> 23.60	47.20
13.	REAR PANEL	1	PC <i>?</i> 575.60 <i>bt</i>	575.60
14.	REAR PANEL INNER TRIM	1	PC <i>?</i> 295.30 <i>ad</i>	295.30
15.	REAR PANEL INNER TRIM CLIPS	6	PC <i>?</i> 3.90 <i>ad</i>	23.40
16.	REAR BUMPER <i>Bumper</i>	1	PC <i>de</i> 875.60	875.60
17.	REAR BUMPER SPONGE	1	PC <i>?</i> 141.70 <i>Xun</i>	141.70
18.	REAR BUMPER REINFORCEMENT	1	PC <i>?</i> 313.20 <i>bt</i>	313.20
19.	REAR BUMPER BRACKET L+R	2	PC <i>ad</i> 98.60	197.20
20.	REAR BUMPER CHROME L+R	2	PC <i>ad</i> 298.50	597.00
21.	REAR BUMPER CLIPS	10	PC <i>ad</i> 3.90	39.00
22.	REAR FLOOR PANEL (REPAIR)	1	PC	
23.	REAR FENDER L+R (REPAIR)	2	PC	
24.	REAR CHASSIS MEMBER (REPAIR)	1	PC	

NET TOTAL S\$ 6,330.40
 10% DISCOUNT S\$ -633.04

5,697.36

SPECIAL NET ITEMS :

1.	REAR BUMPER SENSOR	1	PC <i>ad</i> 250.00 <i>200</i>	250.00
2.	REAR NUMBER PLATE	1	PC <i>ad</i> 50.00 <i>45</i>	50.00

SPECIAL NET TOTAL S\$ 300.00

LABOUR :

TO CUT-WELD REAR PANEL, TO REPAIR REAR FLOOR PANEL, REAR FENDER L+R, REAR CHASSIS MEMBER TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS 700 840.00

TO SPRAY AFFECTED AREAS 750 850.00

TO REMOVE & REFIX LAGGAGE COMPARTMENT SIDE TRIM BOARD, CARPET AND OTHER ATTACHMENT PARTS 60 120.00

TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE 30 80.00

Estimate

29/04/2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
AXA TOWER #27-01
SINGAPORE 068811

Attention :- **XA009**

Page # :- 1 134740

Veh # :- SJV5042L

Veh Model :- NISSAN TEANA 2.0

Estimate# :- CK419073

Claim # :-

ACC. Date :- 29/04/19

Terms :- C.O.D Days

Remarks :-

Main Office:
Mova Building
No. 22, Jalan Klang,
Singapore 159419
Tel: **(65) 6476 3333**
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/09
Singapore 159722
Tel: **(65) 6272 3892**
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
	TO RUST PROOF AFFECTED AREAS			30 80.00
	LABOUR TOTAL S\$			1,970.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 7,967.36

GST @ 7 % 557.72

AMOUNT DUE S\$ 8,525.08

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
wp
30/4/19 @ 330 pm
Resurvey after repair
surv/khantawm
\$ = 6 days

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	0390P
Vehicle Details	
Vehicle No.:	SJV5042L
Vehicle to be Exported:	No
Intended Deregistration Date:	03 May 2019
Vehicle Make:	NISSAN
Vehicle Model:	TEANA 2.0L CVT ABS D/AIRBAG 2WD
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	MR20889005A
Chassis No.:	JN1BDUJ32Z0001461
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$25,408.00
Original Registration Date:	28 Jan 2010
First Registration Date:	28 Jan 2010
Transfer Count:	4
Actual ARF Paid:	\$25,408.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jan 2020
PARF Rebate Amount:	\$12,704.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jan 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$21,899.00
COE Rebate Amount:	\$1,601.00
Total Rebate Amount:	\$14,305.00

The information contained herein is correct as at 03 May 2019

OK

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Tuesday, 30 April 2019 9:41 AM
To: assignments
Subject: FW: TP CLAIMS - SJV5042L AGAINST PC3305X DOA 29/04/2019 AT LORNIE HIGHWAY UNDERPASS
Attachments: RPT.PDF; EST.pdf

10:21am @ 30/4/19
Nitha
vehicle in
SURO Taufik.

Hi team

TP smart. Kindly assist.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nitha <nitha@movacom.sg>
Sent: Monday, 29 April, 2019 6:11 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Cc: keong@movacom.sg; 'Enny' <enny@movacom.sg>
Subject: TP CLAIMS - SJV5042L AGAINST PC3305X DOA 29/04/2019 AT LORNIE HIGHWAY UNDERPASS

Dear all ,

Kindly assign surveyor and revert officer in charge for the above mention case.

Thank you,

Best Regards,

Nitha

Claims Officer

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314





TRANSPORT & TRADING

General Email: enquiries@kaltransport.com.sg

KAL T&T SERVICES

Business Registration No: 53005838C

gess@kaltransport.com.sg

10th June 2019

To Whom may Concern,

Dear Sir/Mdm,

Employment Letter

This is to certify, Mr Tan Gai Kiang, IC no. S***5050E is our employee with vehicle Pc 3305X assigned to him.

If there is any queries, please call us at 6776 7371, Monday till Friday 9am – 430pm or you can email us at enquiries@kaltransport.com.sg

Thank you for your kind attention and prompt assistance

Yours faithfully


Michael Kwok
Senior Admin Manager



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 3/12/2019

Survey Details:

Date of loss	29-Apr-19
Date of appointment	30-Apr-19
Date of survey	30-Apr-19
Location of survey	MOVA AUTOMOTIVE PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SJV5042L
Make and Model	NISSAN TEANA 2.0L CVT ABS D/AIRBAG
Date of registration	28-Jan-10
Parf Rebate	
Market Value	\$ 20,000.00
Parf Rebate	\$ 14,322.00
Nett Loss	\$ 5,678.00

Repair details:

Initial Estimate	\$ 7,967.36
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 5,730.59
Check items (estimate)	\$ -
Labour	\$ 1,570.00
Total	\$ 7,300.59
Lump Sum(if applicable)	\$ 5,800.00

Number of days for repair	6
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

06 RECOMMENDED REPAIR DAYS + 1 SUNDAY + 1 SATURDAY + 1 PRS
= 9 DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 6,206.00	W/GST
Loss of use	\$ -	
Loss of rental (W/GST)	\$ 963.00	9days x \$107
Loss of income	\$ -	
LTA search fees	\$ 2.00	
Others	\$ -	
Proposed Total	\$ 7,171.00	



<MANDATE IA> - S9M01LSD {ACCIDENT INVOLVING PC 3305X & SJV 5042L ON 29/04/2019}

Type

🔗 Question

Message

LIABILITY: 100% BOLA S27- INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$7171.00 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL

Reply

Tax Invoice

20/12/2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
AXA TOWER #27-01
SINGAPORE 068811

Attention :- XA009

Page # :- 1 134740
Veh # :- SJV5042L
Veh Model :- NISSAN TEANA 2.0
Tax # :- CK632155
JOB # :- T250519
ACC. Date :- 29/04/19
Terms :- C.O.D Days
Remarks :-

Main Office:
Move Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/04
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 6314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
	Lump Sum Amount			5,500.00

E. & O.E.



AMOUNT S\$	5,500.00
GST @ 7 %	385.00
AMOUNT DUE S\$	5,885.00

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

 **Re:<MANDATE IA> - S9M01LSD {ACCIDENT INVOLVING
PC 3305X & SJV 5042L ON 29/04/2019}**

Type

 Question

Message

Hi, for COR, pls offer at \$5200 up to \$5500 (before 7% GST), for LOR, we agreed. TY.

[Reply](#)

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Dukit Merah Lane 3,
01-04/06/08/94
Singapore 159722

VIA EMAIL**WITHOUT PREJUDICE**

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 1989040330
GST Reg. M2-0086864-2

Our Ref : SJV5042L / T250519
Your Ref : TO BE ADVISED

Date : 8 November 2019

AXA INSURANCE PTE LTD
8 Shenton Way
#27-01
Singapore 068811.

Attn: Motor Claims Department

Dear Sir/Mdm

ACCIDENT INVOLVING: SJV5042L & PC3305X

DATE OF ACCIDENT: 29 APRIL 2019

ALONG: LORNIE HIGHWAY UNDERPASS

We refer to the above mentioned accident. We are claiming as per below:

Cost of Repairs	\$ 6,206.00
Loss of Use (\$__x __days)	\$
Loss of Rental (\$ 120.00 x 09 days) + 7% GST	\$ 1,155.60
Loss of Income (\$__x __days)	\$
Taxi Fees / E-License / Others	\$
LTA /GIA Search	\$ 2.00
Medical Fees	\$
Towing Fees	\$
Grand Total	\$ 7,363.60

Car date in: 29/04/2019 Car date out: 07/05/2019

Authorized Repair Days: 06 (TP/OD/WS/Recovery-of-Incidental-Costs)

Please pay the amount of **S\$ 7,363.60** in favor of **MOVA AUTOMOTIVE PTE LTD.**

If you have any enquiries, please call Ms Suann @ 62723892 or email suann@moval.com.sg

Yours faithfully,
MOVA AUTOMOTIVE PTE LTD
For Claims Manager

NOTE: # Please note that the Loss of Use will be paid based on negotiation and on the NIMA Protocol (Court Guideline).

- This is a computer generated letter and does not need a signature.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19007602/T1ga3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG			Date : 17-01-2020	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 3305X	Veh. Inspected	SVJ 5042L ✓	
Policy No.	P0986612	Coverage (\$)	0.00	
Claim No.	S9M01LSD	Excess (\$)	0.00	
Assign From		Assign Date	30/04/2019 ✓	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN TEANA	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JN1BDUJ32Z0001461	Colour	BLACK	
Odometer	145363	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	KUMHO	6 mm	
L/H Front Tyre	215/55 R17	KUMHO	6 mm	
R/H Rear Tyre	215/55 R17	KUMHO	6 mm ✓	
L/H Rear Tyre	215/55 R17	KUMHO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/04/2019	Inspection Date	30/04/2019	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 5042L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT (N) (CONSISTENT)	BENT	✓ 962.10	962.10
1	REAR BOOT LOGO (N) (CONSISTENT)	NECESSARY	✓ 68.40	68.40
1	REAR BOOT EMBLEM 'TEANA' (N) (CONSISTENT)	NECESSARY	✓ 87.30	87.30
1	REAR BOOT EMBLEM '200XL' (N) (CONSISTENT)	NECESSARY	✓ 86.60	86.60
1	REAR BOOT CHROME TOP (N) (CONSISTENT)	CRACKED	✓ 278.40	278.40
1	REAR BOOT CHROME LOWER (N) (CONSISTENT)	CUT	✓ 332.20	332.20
1	REAR BOOT LOCK TOP (N) (CONSISTENT)	BENT	✓ 178.10	178.10
1	REAR BOOT CATCH (N) (CONSISTENT)	TO REPAIR SEE LABOUR	✓ 65.20	-
1	REAR BOOT RUBBER (N) (CONSISTENT)	TWISTED	✓ 188.10	188.10
2	REAR BOOT HINGE L+R @\$110.20 (N) (CONSISTENT)	TO REPAIR SEE LABOUR	✓ 220.40	-
2	REAR LAMP L+R @\$379.20 (N) (CONSISTENT)	O/S CUT	✓ 758.40	379.20
2	REAR LAMP COVER L+R @\$23.60 (N) (CONSISTENT)	O/S CUT	✓ 47.20	23.60
1	REAR PANEL (N) (CONSISTENT)	BENT	✓ 575.60	575.60
1	REAR PANEL INNER TRIM (N) (CONSISTENT)	DEFORMED	295.30	295.30
6	REAR PANEL INNER TRIM CLIPS @\$3.90 (N) (CONSISTENT)	NECESSARY	✓ 23.40	23.40
1	REAR BUMPER (N) (CONSISTENT)	DEFORMED	✓ 875.60	875.60
1	REAR BUMPER SPONGE (N) (CONSISTENT)	NOT NECESSARY	✓ 141.70	-
1	REAR BUMPER REINFORCEMENT (N) (CONSISTENT)	BENT	✓ 313.20	313.20
2	REAR BUMPER BRACKET L+R @\$98.60 (N) (CONSISTENT)	N/S DEFORMED / O/S NECESSARY	✓ 197.20	197.20
2	REAR BUMPER CHROME L+R @\$298.50 (N) (CONSISTENT)	N/S DEFORMED / O/S CUT	✓ 597.00	597.00
10	REAR BUMPER CLIPS @\$3.90 (N) (CONSISTENT)	NECESSARY	✓ 39.00	39.00
1	REAR FLOOR PANEL (N) (CONSISTENT) (NPA)	TO REPAIR SEE LABOUR	-	-
2	REAR FENDER L+R (N) (CONSISTENT) (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR CHASSIS MEMBER (N) (CONSISTENT) (NPA)	TO REPAIR SEE LABOUR	-	-
1	SPARE TOOL TRAY (N) (CONSISTENT)	DEFORMED	299.70	299.70

Report Ref No. CC4/ASM19007602/T1ga3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	KEYLESS SENSOR (N) (CONSISTENT)	CRACKED	✓ 295.10	295.10
	LESS 10% DISCOUNT		-692.52	-609.51
			6,232.68	5,485.59
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER SENSOR (SN) (CONSISTENT)	NOT WORKING	✓ 250.00	200.00
1	REAR NUMBER PLATE (SN) (CONSISTENT)	BENT	✓ 50.00	45.00
			300.00	245.00
	<u>LABOUR</u>			
	TO CUT -WELD REAR PANEL ,TO REPAIR REAR FLOOR PANEL ,REAR FENDER L+R ,REAR CHASSIS MEMBER TO REMOVE & REFIX DAMAGED PARTS ,STRAIGHTEN & REALIGN AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF REAR BOOT CATCH,REAR BOOT HINGE L+R,REAR FLOOR PANEL,REAR FENDER L+R AND REAR CHASSIS MEMBER.		✓ 840.00	700.00
	TO SPRAY AFFECTED AREAS.		850.00	750.00
	TO REMOVE & REFIX LAGGAGE COMPARTMENT SIDE TRIM BOARD ,CARPET AND OTHER ATTACHMENT PARTS.		✓ 120.00	60.00
	TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE.		80.00	30.00
	TO RUST PROOF AFFECTED AREAS.		✓ 80.00	30.00
			1,970.00	1,570.00
GRAND TOTAL			8,502.68	7,300.59
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,800.00

Report Ref No. CC4/ASM19007602/T1ga3q2

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
 Automotive Assessor

HO LEONG CHUAN
 Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.

Service Request Details

Claim	59M01LSD
Reference	CC4/ASM19007602/T1ga3q2
Loss Date	29 April 2019
Report Date	30 Apr 2019 9:00:00 AM
Request Date	30 April 2019
Due Date	

Vendor Name	LIX AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	SJV5042L
Make	TPVD NISSAN
Model	TEANA 2.0L CVT ABS D/AIRBAG 2WD
Service Address	
...	
Primary Contact/Insured	

KAL TRANSPORT PTE LTD
11 DAIRY FARM HEIGHTS, #02-26 THE SKYWOODS, 677661, Singapore
67767371

Claim Handler

ANG Richard
richard.angbia@axa.com.sg

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	---------------

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (3).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
LKKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
LKKAdjustment1.a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority letter	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
LETTER TO OL.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
MANDATE IA DO 03122019.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 December 2019
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 December 2019
LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 December 2019
TP FINAL EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 December 2019
RENTAL INV.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 December 2019
PA&F COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 December 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 GIA SEARCH INVOICE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 December 2019
 OI LOA.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 June 2019
 TP ESTIMATE - MABICED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	13 May 2019
 IA.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	8 May 2019
 P0186612_EN_00293_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	ANG Richard	30 April 2019
 P0186612_CI_00293_0085_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	ANG Richard	30 April 2019
 TP PRI FROM WORKSHOP WITH GIA AND ESTIMATE.mig	Letters and Correspondence	Workshop	DHAKAL Raghav	30 April 2019
 HC305X INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	30 April 2019