

TTS EUROCARS PTE LTD

383 Sin Ming drive Singapore 575717

Date : 18/2/2016

RE: VEHICLE REPAIR QUOTATION

| | | |
|-------------------|---|-----------------------|
| Insurance Company | : | AXA Insurance Pte Ltd |
| Vehicle Reg No | : | SLH30D |
| Name of Insured | : | Tok Ah Chuan |
| Policy Number | : | |
| Date of Accident | : | 29.04.2019 |
| Tyre of Claim | : | Third Party Claim |
| Model | : | Honda Veze |
| Chassis No | : | RU11209067 |

We are please to submit our estimate of repairs to the above mention vehicle.

| | | Parts | Labour |
|----|--------------------------------------|-------------|--------|
| 1 | REAR BOOT <i>bt /</i> | \$ 972.40 | |
| 2 | REAR WINDSCREEN <i>2/2/10 X</i> | \$ 1,350.00 | |
| 3 | RR WINDSCREEN MNOULDING <i>nee /</i> | \$ 120.00 | |
| 4 | REAR BOOT LOCK <i>bt - ?</i> | \$ 157.00 | |
| 5 | REAR BOOT INNER TRIM BOARD | \$ 153.40 | |
| 6 | REAR BOOT "H" LOGO <i>nee X</i> | \$ 15.70 | |
| 7 | REAR BOOT "XRV" LOGO <i>nee /</i> | \$ 43.00 | |
| 8 | REAR BOOT LAMP RH <i>?</i> | \$ 264.60 | |
| 9 | REAR BOOT LAMP LH <i>?</i> | \$ 264.60 | |
| 10 | REAR BUMPER <i>nee /</i> | \$ 463.70 | |
| 11 | REAR END PANEL <i>repair</i> | \$ 411.90 | |
| 12 | REAR BUMPER SIDE RETAINER <i>X</i> | \$ 17.50 | |
| 13 | REAR BUMPER REFLECTOR RH <i>X</i> | \$ 141.10 | |
| 14 | REAR BUMPER REFLECTOR LH <i>X</i> | \$ 141.10 | |
| 15 | REAR SPARE TYRE PANEL <i>X</i> | \$ 662.20 | |
| 16 | REAR END PANEL TOP GARNISH <i>?</i> | \$ 92.30 | |
| 17 | REAR BUMPER CLIPS <i>nee /</i> | \$ 35.00 | |
| 18 | INNER TRIM CLIPS <i>nee /</i> | \$ 45.00 | |

| | |
|--------------------|--------------------|
| Sub Total Parts | \$ 5,350.50 |
| Less 20% | \$ 1,070.10 |
| Total Parts | \$ 4,280.40 |

| | | | |
|---|---|-------------|------------|
| 1 | Sundries | \$ 80.00 | <i>?</i> |
| 2 | Wiring connection and check. | \$ 120.00 | <i>30</i> |
| 3 | Tuff kote and spray anti rust proofing | \$ 120.00 | <i>60</i> |
| 4 | Labour charges to dismantle & refix rear boot, Rear bumper, rear end panel, spare tyre panel To repair and adjust affected portion to specific dimension. | \$ 1,500.00 | <i>500</i> |

| | | | |
|----|---|-------------------------|--------------------------|
| 5 | To spray paint rear boot, rear bumper, rear end panel, spare tyre panel and all other accident affected portion | \$ | 1,500.00 400 |
| 6 | Transfer rear boot mechanisms, locks, trims scuff plates | \$ | 250.00 80 |
| 7 | To remove and refix rear reverse camera, | \$ | 150.00 60 |
| 8 | To remove and refix rear bumper sensor, | \$ | 150.00 60 |
| 9 | To remove and refix rear spare tyre compartment trims, boards, scuff plates to facilitate repair | \$ | 450.00 X |
| 10 | To remove and refix rear exhaust tail pipe to facilitate repairs, conduct leak test | \$ | 250.00 X |
| 11 | To remove and refix rear passenger seats, carpets trims, seat belts to facilitate repair | \$ | 250.00 X |
| 12 | To remove and refix/ replace rear windscreen conduct water leak test, | \$ | 150.00 120 |
| 13 | Sealant for rear windscreen | \$ | 60.00 40 } 60 |
| 14 | Inner seal for rear windscreen | \$ | 50.00 } |
| 15 | Sealant for body panel, rear boot, rear end panel spare tyre panel | \$ | 150.00 40 |
| 16 | To conduct ECU programming, check and clear fault codes, restore programme modules | \$ | 450.00 100 |
| | Total (Labour) | \$ | <u>5,680.00</u> |
| | Sub Total : | \$4,280.40 + \$5,680.00 | \$ 9,960.40 |
| | GST 7% | | \$ 697.23 |
| | Grand Total : | | <u>\$ 10,657.63</u> |

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

Rasul
 Hp 90010068
 5 days
 P/P
 09/05/19 @ 1400 hrs
 Resin 64 paint