



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC: 201015366H

3RD PARTY CLAIM ESTIMATION

AIG Aisa Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way #07-16

Singapore 079120

Vehicle number	SMC19475
Make / Model	TOYOTA/ESTIMA
Chassis number	ARC500075076
Accident date	24 April 2019
Reference	1904-061

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER	1317.80
1	FRONT BUMPER TOP BEAM	389.75
2	FRONT BUMPER RETAINER	262.80
1	FRONT BUMPER LOWER MESH	261.55
1	FRONT BUMPER FOG LAMP LH	387.40
1	FRONT RH HEADLAMP	1400.17
1	FRONT BUMPER REINFORCEMENT	381.45
1	FRONT LH SHOCK ABSORBER	546.93
1	FRONT LH KNUCKLE ARM	665.54
1	FRONT LH LOWER ARM	775.66
1	FRONT LH WHEEL HUB BEARING	660.32
		7049.37
		1762.34
		5287.03
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
Balance B/F		5287.03
1 SET	FRONT BUMPER CLIP	30.00
1	RIM	600.00
1 BOT	BRAKE FULID	50.00
Subtotal		680.00
Balance C/F		5967.03
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
Balance B/F		5967.03
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	60.00
2	CHECK FRONT WHEEL ALIGNMENT	150.00
3	REMOVE AND REPLACE FRONT UNDERCARRIAGE	200.00
4	PANEL BEATING ON AFFECTED AREAS	700.00
5	SPRAY PAINTING ON AFFECTED AREAS	600.00
6	APPLY ANTI RUST ON AFFECTED AREAS	150.00
7	RENEW STICKER ON AFFECTED HEADLAMP	100.00
Subtotal		1960.00
Grand total		7927.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Less 25%

Signature:

Date:

Tauji 97495749 / 67418434

02 days

Resurvey after repair

suve@lkkauto.com

29/4/19 25pm