



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No.	: SQT19001879	Page	1
Registration No	: SDD2901T	Date	: 29. Apr 2019	Customer No.	: WZI007
Chassis No	: JHMRC1880GC206102	Svc Advisor	: RUEBEN THOMAS	Engine No	: K24W72012746
Model	: ODYSSEY 2.4 EX-S 16YM	Date Time	: 29. Apr 2019 8:28:17 AM	Surveyor Name	:
Owner's Name	: ZUBIR BIN ABDULLAH	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 26/4/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: ZUBIR BIN ABDULLAH OWNER INSURER: LIBERTY INSURANCE ACC DATE: 26/04/2019 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INTL. INSURANCE TP VEH: SH6354Y						
67010-T6A-000ZZ	PANEL COMPR.FR.DOOR / <i>Buc</i>	1	895.20	25	671.40	47.00	718.40
67324-T6A-305ZA	TAPE SETR.FR.DOOR SASH INNER / <i>Yucc.</i>	1	38.40	25	28.80	2.02	30.82
67325-T6A-003	TAPER.FR.DOOR SASH UPPER / <i>Buc</i>	1	37.30	25	27.97	1.96	29.93
67510-T6A-000ZZ	PANEL COMPR.SLIDE DOOR / <i>Buc</i>	1	1000.50	25	750.37	52.53	802.90
67821-T6A-305ZA	TAPE SETR.RR.DOOR SASH INNER / <i>Buc</i>	1	57.10	25	42.82	3.00	45.82
75312-T6A-J01ZD	GARNISH ASSYR.FR.DOOR LOWER / <i>Buc</i>	1	318.10	25	238.57	16.70	255.27
75313-T6A-J01ZL	GARN ASSY,R.SLIDE / <i>Buc</i>	1	307.60	25	230.70	16.15	246.85
74410-T6A-J01ZH	GARNISH ASSYR.WHEEL ARCH / <i>Buc</i>	1	36.00	25	27.00	1.89	28.89
60210-T6A-300ZZ	FENDER COMPR.FR. / <i>Buc</i>	1	548.60	25	411.45	28.80	440.25
42700-T6A-Q81	DISKALUMINIUM WHEEL 17X7J / <i>W.A.</i>	2	915.00	25	1372.50	96.08	1468.58
	Sum Item				3801.58	266.13	4,067.71
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1 ✓	180.00		180.00	12.60	192.60
	Sum Ext. Service				180.00	12.60	192.60
BOSUN	SUNDRIES	1 <i>20</i>	50.00		50.00	3.50	53.50
BKDR12R	REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST	1 ✓	380.00		380.00	26.60	406.60
BKDR32R	REMOVE & TRANSFER ITEMS TO NEW RR R SLIDING DR.	1 ✓	560.00		560.00	39.20	599.20

Printed on 29/4/2019 9:21:15 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SDD2901T
Chassis No : JHMRC1880GC206102
Model : ODYSSEY 2.4 EX-S 16YM
Owner's Name : ZUBIR BIN ABDULLAH
Ins Policy No. :
Date of Accident : 26/4/2019

Document No. : SQT19001879
Date : 29. Apr 2019
Customer No. : WZI007
Svc Advisor : RUEBEN THOMAS
Engine No : K24W72012746
Date | Time : 29. Apr 2019 8:28:17 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKFE12R	REMOVE & RENEW FR R FENDER. STRAIGHTEN ALIGN R.RR	1	560.00	✓	560.00	39.20	599.20
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	320.00	300.	320.00	22.40	342.40
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) 450	1	2900.00	2250	2900.00	203.00	3103.00
Sum Labor					4770.00	333.90	5,103.90

Survey By: Amir Qian - 82880282
Date & Time: 30/4/19
Excess: _____
Status: _____
Signature: _____

Total Amount 8,751.58 612.63 9,364.21
Total (Inclusive of GST) 9,364.21

6 Days.
before paint photos.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Printed on 29/4/2019 9:21:15 AM
This is a computer generated invoice. No signature is required.
Part prices are subjected to change without notice.
The above estimated cost of repair do not include any unforeseen damages.
GST Amount is calculated from individual line(s).
An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.
However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.