

AUTO BOLT SERVICES PTE LTD

8 Kaki Bukit Avenue 4 #03-55 Premier @ Kaki Bukit Singapore 415875

Email : autoboltsvc@singnet.com.sg

82613977

Tel : 6384 1066

Fax : 6384 1067

29 April 2019

Reg No.: GBB 3168 X
Model: RENAULT TRAFIC

TP COMPAC.
Ashes.

QTY	DESCRIPTION	AMT S\$
<u>List Items</u>		
1	Rear door -R/H <i>Repld</i>	\$ 2,400.00
1	Rear door glass inner seal <i>ne</i>	\$ 120.00
2	Rear door hinges <i>Repld</i> <i>Best</i>	\$ 320.00
1	Rear door inner checker <i>ne ne</i>	\$ 140.00
1	Rear door lock <i>Repld</i>	\$ 120.00
1	Rear door rubber <i>ne</i>	\$ 220.00
1	Rear door "Traffic" emblem -R/H <i>ne</i>	\$ 111.00
1	Rear door -L/H <i>Repld</i>	\$ 2,400.00
1	Rear door glass <i>shattered</i>	\$ 480.00
1	Rear door glass inner seal <i>ne</i>	\$ 120.00
2	Rear door hinges <i>Repld</i> <i>Best</i>	\$ 136.00
1	Rear door inner board <i>Repld</i>	\$ 380.00
1	Rear door lock <i>Repld</i>	\$ 120.00
1	Rear door outer garnish <i>ut</i>	\$ 115.00
1	Rear door outer handle <i>Repld</i>	\$ 175.00
1	Rear door rubber <i>ne</i>	\$ 251.00
1	Rear door "RENAULT" emblem -L/H <i>ne</i>	\$ 75.00
1	Rear wiper arm <i>Best</i>	\$ 207.00
1	Rear wiper motor <i>Repld</i>	\$ 308.00
2	Rear taillamps <i>Repld</i> <i>could</i>	\$ 730.00
2	Rear taillamp outer garnishes <i>Repld</i> <i>ut</i>	\$ 370.00
1	Rear centre end panel <i>Repld</i>	\$ 700.00
1	Rear centre end panel inner garnish <i>ne</i>	\$ 260.00
1	Rear bumper <i>Repld</i>	\$ 800.00
2	Rear bumper brackets <i>Repld</i>	\$ 210.00
1	Rear bumper inner garnish <i>ne</i>	\$ 185.00
2	Rear bumper reflectors <i>Repld</i> <i>could</i>	\$ 320.00
1	Rear bumper reinforcement <i>Best</i>	\$ 400.00
1	Rear floor panel <i>Repld</i>	\$ 1,068.00
1	Rear floor panel top cover <i>Repld</i> <i>ne</i>	\$ 184.00
1	Rear spare tyre carriage <i>Repld</i> <i>ne</i>	\$ 285.00
1	Rear spare tyre lock catch <i>ne</i>	\$ 89.50
1	Rear exhaust pipe <i>ne</i>	\$ 1,211.50
1	Rear exhaust mounting <i>ne</i>	\$ 28.50
1	Rear side panel -R/H <i>Repld</i>	\$ 2,450.00
		\$ 17,489.50
	Less 10%	\$ 1,748.95
		\$ 15,740.55

10543

9488.70

Special Nett Items

1	Rear door glass sealant -R/H	\$ 40 80.00
1	Rear door "70KM/H" sticker -R/H	\$ 15 25.00
1	Rear door glass sealant -L/H	\$ 40 80.00
1	Rear wiper blade <i>lt</i>	\$ ✓ 28.00
1	Rear bumper clip (1 set) <i>in</i>	\$ ✓ 45.00
1	Rear number plate with holder <i>Be</i>	\$ ✓ 45.00
1	Rear reverse sensor (1 set) <i>amp</i>	\$ 200 350.00
		\$ 653.00

413

S/N.Labour Charges

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 30 80.00
2	To remove and refit inner garnishes.	\$ 80 150.00
3	To remove and refit rear reverse sensor.	\$ 50 120.00
4	To transfer rear doors mechanism and wiring assembly.	\$ ✓ 150.00
5	To remove and refit rear windscreen glass.	\$ 160 180.00
6	To remove, refit and replace exhaust silencer and mountings.	\$ 150.00
7	To apply tuff kote.	\$ 80 200.00
8	Panel beating.	\$? 1,600.00 <i>low</i>
9	To respray painting on the affected areas.	\$? 1,500.00 <i>800</i>
		\$ 4,130.00

2350

Grand Total: \$ 20,523.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L

L/S 30/04/19.

96893735.

06 Days.

total: 12251.70

L/S: 9K (Nett Value)

08 Days.