

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0544/2019/DY/TF  
**Date** : 29-Apr-19

**Vehicle IS IN workshop. Kindly arrange for survey.**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mdm. Neelofur Sarwar Binti Ghulam Sarwar  
**Address** : 27C Surin Avenue  
Singapore 535607  
**Telephone** : HP +65 92315572  
**Type of Claim** : Own Damage Claim  
**Policy No.** : 1900021956  
**Vehicle No** : **SMJ 3249 Z** ✓  
**Model Code** : Audi A3 Sedan 1.0 TFSI 8v  
**Model / Year** : Feb-19  
**Engine No** : CHZ C26275  
**Chassis No** : WAUZZZ8VXK1016783  
**Mileage** : 4207 KM  
**Date In** : 29-Apr-19  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 28-Apr-19  
**Place of Accident** : Along Tampines St 83 towards-

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SMJ 3249 Z

S/n	Nature of Jobs	Estimated Charges
1	To remove and reinstall rear parking aid. Check function.	S/N \$ 280.00 ✓
2	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.	\$ <del>900.00</del> 500
3	To respray rear bumper.	\$ <del>800.00</del> 550
4	To carry out diagnostic check	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES - FRONT		: \$ <u>2,172.00</u>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SMJ 3249 Z

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>del</i>	\$ 1,793.00	✓
2	REAR BUMPER STICKY PAD <i>new</i>	\$ 21.00	+
3	REAR BUMPER FIXING PARTS <i>new</i>	\$ 175.00	+
4	REAR BUMPER TOP GUIDE SECTION - LH / RH <i>new</i>	\$ 30.00	+
5	REAR BUMPER TOP GUIDE SECTION PIN <i>new</i>	2 \$ 53.00	X
6	REAR BUMPER SPOILER <i>lit</i>	\$ 216.00	✓
7	REAR BUMPER REFLECTOR - RH	\$ 38.00	+
8	REAR BUMPER REINFORCEMENT	\$ 522.00	+
9	REAR BUMPER BRACKET - LH/ RH	\$ 51.00	X
10	REAR BUMPER GUIDE SECTION - RH	\$ 60.00	X
11	REAR BUMPER SENSOR	1 \$ 231.00	X
12	REAR BUMPER SENSOR SEAL RING	4 \$ 12.00	+
13	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		\$ 3,502.00	
TOTAL LABOUR CHARGES		\$ 2,172.00	
GRAND TOTAL		\$ 5,674.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian King  
Surveyed Date : 30/04/19.  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Authorised Repairs, 03 days

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Please Note

- : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant