

ASS. REC. BY:

REF: CS/FCI 19007638 / Kt d3ob

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Karant

of FCI

Date/Time: 30.4.19 4.50 pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SMA 92149

Insured:

SH 6456 L

at Workshop m/s Eastern Performance

Tel:

of Blk 5033 Amk, Ind Park 2 #01-251

Policy No:

Claim No:

D19002843 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

27.4.2019

CA / REV / REP. / REV 24 HRS

"wp"

Date/Time: 30.4.19 5.18 pm

H.O.D. Endorsement:

2.5.2019

Person Contacted:

Serink

Vehicle IN/OUT

Date/Time	Action/Instruction
	Estimate (✓) Inspection at 385 sin ming drive
	SMA 92149 - x
	SH 6456 L - x
3/5@2:21pm-	REUSED PREU ADVISE VIA EMAIL
12/6	03035-52 Cc form by email (Ref: 573569!65%)

REF: FCI

## ASSIGNMENT

From:

Date: 2.5. 2019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMA 9214G

at Workshop m/s: Extreme Performance

of 385 Sin Ming Drive

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

288k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

1-B1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

rap

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMA 9214G

Yr Regn:

06, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy CHR

C.C.

17PZ

Colour:

M. Blue

A/C: Insured / Std / NI / NA

Sp. Reading:

70624

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

84X10

2087787

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

27/4/19

D.O.I.

2/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 12 JUN 2019

Date/Time, File Pass to?



Preli. Report

1) D/b Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: TP

Lump Sum / (B): (\$ 3035.52)

160

50

90

15

235

**MOTOR SURVEY ASSIGNMENT**

Date	30-04-2019	Our Ref No. D19002843MFSH
Accident Date	27-04-2019	Claim Type. Third Party
Insured Vehicle	SH6456L	Third Party Vehicle. SMA9214G
Survey Location	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/259	
Contact Person.	SERENCE CHEE	
Contact No.	65662112/ 87990066	Fax No. 62593326
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Friday, 3 May 2019 2:21 PM  
**To:** Admin-D (LKKAuto); 'CWS Motor Claims'; assignments; SUR  
**Cc:** 'Karen Tan'  
**Subject:** RE: SURVEY ASSESSMENT - D19002843MFSH/1  
**Attachments:** PRELI ADVISED SMA 9214G.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SMA 9214G**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 30 April 2019 5:22 PM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** 'Karen Tan' <[karentan@msfirstcapital.com.sg](mailto:karentan@msfirstcapital.com.sg)>  
**Subject:** RE: SURVEY ASSESSMENT - D19002843MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed that repairer agreed to survey on 2/5/2019.

Best Regards,

**Summer Lee** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Tuesday, 30 April, 2019 4:50 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Karen Tan <[karentan@msfirstcapital.com.sg](mailto:karentan@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19002843MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002843MFSH

Date: 3/5/2019

Our Ref: CS/FCI19007638/Ktd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMA 9214G

Please be informed that we had conducted the inspection of the abovementioned vehicle 2/5/2019 at the premises of M/s Esteem Performance have the following to report: -

Workshop Estimate Amount	: S\$ <u>8,771.21</u>
Revised Estimate Amount	: S\$ <u>2,906.34</u>
"Check" Items Amount	: S\$ <u>2,418.86</u>
Market Value	: S\$ <u>                    </u>
LTA Reimbursement Value	: S\$ <u>                    </u>
Nett Value	: S\$ <u>                    </u>

Description of Damage:

The vehicle sustained damages at the rear portion.



**Comments/ Present Status:**

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/04/2019 12:14
Date Of Accident	27/04/2019 09:55
Exact Location Of Accident	PUNGGOL ROAD TOWARDS PIE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA9214G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ESTEEM LEASING PTE LTD
Co Reg No	201807215D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84447764
Alternative Phone No	OFFICE-67532112
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	C-HR
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5101728862
Cover Note Number	
<b>Driver</b>	
Name of Driver	BENNY CHUA KOK MENG
NRIC No	S77325711
Date Of Birth	01/11/1977
Occupation	OUTDOOR
Date Of Driving Pass	16/10/1997
Driving Experience	21 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84447764
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 336D ANCHORVALE CRESCENT #03-62
Postcode	544336
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PASSENGER
	GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	CANNOT BE UPLOADED
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH6456L
Vehicle Make/Model/Colour	MERC E220
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN YEOW KOON
NRIC/Passport Number	S6837483I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

27 APR 2019

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:

**NG WINO KIN JAMES**  
admin.vac@vicom.com.sg

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27/4/19 @ . I was travelling along Punggol Road  
towards TPE. All of sudden, vehicle B SH 6456L hit onto my  
Rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

GIARMC SketchPlanForm\_V3

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:

**NG WINO KIN JAMES**  
admin.vac@vicom.com.sg



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Repair Estimates

SMA 9214 G

*Not Attached*

*Resurvey B4 paint*

Parts	(a) Cost / List Price Items	\$	6,948.81
	Plus/Less 25%	\$	1,737.20
	<b>Total of Cost / List</b>	<b>\$</b>	<b>5,211.61</b>
	(b) Nett Price Items		
	Less		
	<b>Total of Nett Item</b>		
	(c) Special Nett Items	\$	379.60
<b>Total Parts Cost</b>		<b>\$</b>	<b>5,591.21</b>
<b>Labour</b>		<b>\$</b>	<b>3,180.00</b>
<b>Total</b>		<b>\$</b>	<b>8,771.21</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are based on 1 to 2 days delivery
- Third party survey is not allowed for "quick" jobs
- No illegal modification is allowed
- Supplement information is required and is subject to our approval. LKK Auto Consultants Company

Acknowledged by Repairer  
Signature:  
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor	:	<u>Kenneth</u>
Company	:	<u>LKK</u>
Survey conducted on	:	<u>2/5/19</u> at _____
<b>Remarks By Surveyor</b>		
(a)	The repair of this vehicle is <u>authorized</u> / is not authorized until further notice.	
(b)	Recommended Days of Repair	: <u>4-5</u> day(s)
(c)	Resurvey	: Required / <u>Not Required</u>
(d)	Excess	: \$ _____
(e)	Signature of surveyor	: <u>Le</u> Date: <u>2/5/19</u>



## ESTEEM PERFORMANCE PTE. LTD.

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : **SMA 9214 G**  
Make & Model : **TOYOTA CHR**  
Chassis No : **ZYX102087747**

Submit By : **Carmen Lim**  
Year Manufacture : **2017**  
Engine No. :

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	2	\$379.60	S.N	
2	Rear bumper	1	\$398.30		
3	Rear bumper clip	10	\$40.00		
4	Rear bumper side retainer LH	1	\$97.80		X
5	Rear bumper side retainer RH	1	\$97.80		X
6	Rear bumper bracket LH	1	\$122.67		X
7	Rear bumper bracket RH	1	\$122.67		X
8	Rear bumper reinforcement	1	\$398.90		
9	Rear bumper reflector LH	1	\$62.30		X
10	Rear bumper reflector RH	1	\$62.30		X
11	Rear bumper reflector garnish LH	1	\$108.70		X
12	Rear bumper reflector garnish RH	1	\$108.70		X
13	Rear bumper lower garnish Centre	1	\$397.60		
14	Rear bumper tow cover	1	\$21.69		
15	Tail door	1	\$1,022.50		
16	Tail door lock	1	\$478.40		X
17	Tail door emblem	1	\$61.70		
18	Wording "CH-R"	1	\$51.36		X
19	Wording "HYBRID"	1	\$49.87		X
20	Tail door garnish	1	\$882.70		X
21	Taildoor reflector LH	1	\$486.70		X
22	Taildoor reflector RH	1	\$489.70		X
23	Tail end panel	1	\$701.25		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Spare Parts**

Vehicle No. : **SMA 9214 G**  
Make & Model : **TOYOTA CHR**  
Chassis No : **ZYX102087747**

Submit By : **Carmen Lim**  
Year Manufacture : **2017**  
Engine No. :

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail end panel garnish <i>Sm</i>	1	\$295.50		<i>X</i>
25	Tail end panel garnish clip <i>rm</i>	8	\$28.00		<i>Z</i>
26	Boot weatherstrip <i>Sm</i>	1	\$361.70		<i>X</i>
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

*Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.*



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : **SMA 9214 G** Submit By : **Carmen Lim**  
Make & Model : **TOYOTA CHR** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,200.00	(400) 600 ✓
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,200.00	600
3	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>nn</i>	\$150.00	2
4	To remove & refit rear windscreen.	\$120.00	✓
5	To tuff coat.	\$150.00	300 ✓
6	To transfer boot mechanism to new boot	\$120.00	600
7	To conduct water leakage tests to ensure proper air and sealing	\$120.00	200
8	To remove & refit reverse sensor to assist work load	\$120.00	500

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19007638/Ktd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-06-2019	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SH 6456L	Veh. Inspected	SMA 9214G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002843MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	30/04/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA C-HR (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	ZYX102087747	Colour	METALLIC BLUE	
Odometer	70624	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	MICHELIN	5 mm	
L/H Front Tyre	225/50 R18	MICHELIN	5 mm	
R/H Rear Tyre	225/50 R18	MICHELIN	5 mm	
L/H Rear Tyre	225/50 R18	MICHELIN	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	27/04/2019	Inspection Date	02/05/2019	
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 9214G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	BUCKLED	398.30	398.30
10	REAR BUMPER CLIP	NECESSARY	40.00	40.00
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	97.80	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	97.80	-
1	REAR BUMPER BRACKET LH	TO REPAIR SEE LABOUR	122.67	-
1	REAR BUMPER BRACKET RH	TO REPAIR SEE LABOUR	122.67	-
1	REAR BUMPER REINFORCEMENT	BENT	398.90	398.90
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	62.30	-
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	62.30	-
1	REAR BUMPER REFLECTOR GARNISH LH	SERVICEABLE	108.70	-
1	REAR BUMPER REFLECTOR GARNISH RH	SERVICEABLE	108.70	-
1	REAR BUMPER LOWER GARNISH CENTRE	CRACKED	397.60	397.60
1	REAR BUMPER TOW COVER	MISSING	21.69	21.69
1	TAIL DOOR	BENT	1,022.50	1,022.50
1	TAIL DOOR LOCK	TO REPAIR SEE LABOUR	478.40	-
1	TAIL DOOR EMBLEM	NECESSARY	61.70	61.70
1	WORDING 'CH-R'	NOT NECESSARY	51.36	-
1	WORDING 'HYBRID'	NOT NECESSARY	49.87	-
1	TAIL DOOR GARNISH	SERVICEABLE	882.70	-
1	TAILDOOR REFLECTOR LH	SERVICEABLE	486.70	-
1	TAILDOOR REFLECTOR RH	SERVICEABLE	489.70	-
1	TAIL END PANEL	TO REPAIR SEE LABOUR	701.25	-
1	TAIL END PANEL GARNISH	SERVICEABLE	295.50	-
8	TAIL END PANEL GARNISH CLIP	NOT NECESSARY	28.00	-
1	BOOT WEATHERSTRIP	SERVICEABLE	361.70	-
	LESS 25% DISCOUNT		-1,737.20	-585.17
			5,211.61	1,755.52

Report Ref No. CS/FCI19007638/Ktd3e2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
2	REVERSE SENSOR (SN)	SERVICEABLE	379.60	-
			379.60	-
	<b><u>LABOUR</u></b>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA ,(REAR BUMPER ,TAILDOOR ,END PANEL,SPARE TYRE WELL PANEL).INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET LH,REAR BUMPER BRACKET RH,TAIL DOOR LOCK AND TAIL END PANEL.		1,200.00	400.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA ,(REAR BUMPER ,TAILDOOR,END PANEL,SPARE TYRE WELL PANEL).		1,200.00	600.00
	TO REMOVE & REFIT SPARE TYRE ,SPARE TYRE BOARD ,CARPET TRIM TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00
	TO TUFF KOTE.		150.00	30.00
	TO TRANSFER BOOT MECHANISM TO NEW BOOT.		120.00	60.00
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.		120.00	20.00
	TO REMOVE & REFIT REVERSE SENSOR TO ASSIT WORK LOAD.		120.00	50.00
			3,180.00	1,280.00
	<b>GRAND TOTAL</b>		<b>8,771.21</b>	<b>3,035.52</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,035.52</b>

Report Ref No. CS/FCI19007638/Ktd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.