

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : AXA INSURANCE SINGAPORE PTE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTHQ/TP/1904/014
Policy No:	5096462828-01	Date of Loss:	16/04/2019
Vehicle Reg. No.:	SJU9731K	Driveable?	no
Driver Age:	7/05/1988	Third Party Vehicle No.:	SJZ8871U
Any Injuries?	no	Contact No:	92745628
Insured/Claimant:	LIN HENG YONG	Driver:	LIN HENG YONG

Make/Model:	Kia, Carens - KNAFC523	Vehicle Reg. Date:	06/08/2009
Vehicle Colour:	WHITE	Engine Number:	
Chassis No:	KNAFW411MA5122296	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - MAJOR/MINOR RD
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	1,743.50
Miscellaneous Items	185.00
Labour	830.00
Paintwork Labour	790.00
Towing	0.00
Gross Total(S\$):	3,548.50
GST 7.00%(S\$):	248.40
Nett Amount(S\$):	3,796.90

This claim is handled by: Sky Toh T C

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER <i>20/10.1</i>	0.00	300.00	+10.00	330.00 ✓
2	1	FRONT BUMPER SIDE RETAINER LH <i>3.00</i>	0.00	10.00	+10.00	11.00 ✓
3	1	FRONT BUMPER BRACKET LH	0.00	20.00	+10.00	22.00
4	1	FRONT BUMPER FOG LAMP LH	0.00	130.00	+10.00	143.00
5	1	FRONT BUMPER FOG LAMP GARNISH LH	0.00	35.00	+10.00	38.50
6	1	FRONT BUMPER INNER SPONGE	0.00	50.00	+10.00	55.00
7	1	FRONT BUMPER REINFORCEMENT	0.00	100.00	+10.00	110.00
8	1	FRONT BUMPER LOWER GRILLE <i>11.00</i>	0.00	30.00	+10.00	33.00 X
9	1	FRONT HEADLAMP LH	0.00	280.00	+10.00	308.00
10	1	FRONT HEADLAMP LOWER BRACKET LH	0.00	55.00	+10.00	60.50
11	1	FRONT HEADLAMP PANEL LH <i>2.00</i>	0.00	230.00	+10.00	253.00 X
12	1	FRONT GRILLE	0.00	120.00	+10.00	132.00
13	1	FRONT FENDER LH <i>2.00</i>	0.00	190.00	+10.00	209.00 X
14	1	FRONT FENDER INNER SHIELD LH <i>11.00</i>	0.00	35.00	+10.00	38.50 X
15	1	BONNET <i>2.00</i>	0.00	0.00	+10.00	0.00 X

Total Parts (\$\$) 1,743.50

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER CLIPS <i>2.00</i>	0.00	30.00	0.00	30.00
2	1	FRONT BUMPER LOWER LIP <i>2.00</i>	0.00	90.00	0.00	90.00
3	1	FRONT NUMBER PLATE <i>5.00</i>	0.00	35.00	0.00	35.00
4	1	FRONT FENDER INNER SHIELD CLIPS <i>11.00</i>	0.00	30.00	0.00	30.00

Sub Total (\$\$) 185.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 <i>20</i>
2	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	800.00	800.00	0.00	800.00 <i>400</i>

Gross Labour Cost (\$\$) 830.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	40.00	40.00	0.00 <i>11</i>	40.00 X
2	1	To Carry-Out Body Cavity Preservation.	50.00	50.00	0.00 <i>7</i>	50.00 X
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and	700.00	700.00	0.00	700.00 <i>600</i>

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
-----	-----	-------------	------	--------	-------	------------

Waxing are also available.

Gross Labour Cost (\$\$)

790.00

< END OF ESTIMATES >

Noted
 2/5/19
 3 days.
 The ph. After rep =
 3/5/19

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To supply damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: