



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLQ2909J

Lee Poy Lang

7 Alexandra View
#32-05
Singapore 158741

Mobile: 96826691

Vehicle & Document Information

WIP No **32399**
Reg No/Reg Date **SLQ2909J / 03/07/2017**
Date In/Mileage **/ 0**
Chassis No **WDD2050402R287395**
Engine No **27491030983650**
Make/Model **MB/MB C 180 SEDAN (W205) "AVANTGARDE / A**
Colour/Trim **027 775 Iridium sil/ 041 101 Leather Bla**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	08/04/2019/ 14:50	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNUN POLICY NO/ACC DATE : 1700020759-01 // 07.04.19 DRIVE IN/EXCESS : 07.04.19 // TP CAR NO.: PZ1888Y=AXA DATE IN/DATE SURVEY: 07.04.19 // BY/AUTHORIZED ON :				
A BPILAB "USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT"			0.10	380.00 ✓
A BPILAB TRANSFER DOOR MECHANISM, ELECTRICAL COMPONENTS TO NEW DOOR- NETT RHR DR			0.19	400.00 X
A BPILAB REMOVE & REPLACE ON RHR DR, RHF DR				960 1920.00 ✓
A BPIRES RESpray ON RHR DR, RHF DOOR				1200 1800.00 ✓
M RIGHT REAR DOOR repair	1.00	2156.78	00.00	2156.78
M RHR DOOR WEATHERSTRIP X	1.00	290.54	00.00	290.54
M RHR DR SELF-ADHESIVE TRIM X	1.00	16.53	00.00	16.53
M FILLISTER HD.SCREW X	12.00	2.29	00.00	27.48
M RHR DR WINDOW RUN X	1.00	168.79	00.00	168.79
M RIGHT REAR DR FIXED WINDOW X	1.00	230.63	00.00	230.63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirmed & accepted by
Signature:
Date:

Nett **7,390.75**
7% GST on **7390.75** **517.35**
Total Payable 7,908.10

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany