

19/03/10

INS. CASE OWNER:

Winnil

CC4 ASM AXA1900

7648, T1

E63

LKK:
IDAC:

Surveyor:

Thantich

DOI:

ASSIGNMENT
2/1/10

Date / Time:

30/4/10

Registered in Merimen:

Pre-assign / CCU / FTE

SFU 93A



Insured Vehicle No.:

Name of Insured:

FU ming RD SERENG

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

26/4/10

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LOWA TIAM - EN IAN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

BMW

Place of Accident:

NIM RD

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SKC 999H

INSRS:
WSP:
Tel:
Liability:
RMKS:

W/L SWAGM

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SKC 999H - 0

SFU 93A - 0

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

Nil

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

w/p. \$250.00

collided
into parked
vehicle

11/9/10

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/3
Document no.
Document date 30-04-2019
Customer no. 5211043084
Customer GST-ID
Dealer 39999
Job order number 2019000419/ 1
Job order date 29-04-2019
Service Advisor SHU SHI TANG

Ms.
LIM
JEE MUAY
29C NIMS ROAD
Singapore 805115

License plate	Model code	First registration	VIN	Model	Mileage
SKC995H	BQ13HZ	16-01-2019	WWWZZZAUZKW040702	Golf Comfortline 1.4 TSI 92kW DSG	14

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
5G0807050B	Guide Piece BUMPER SIDE BRACKET RH	1	pcs.	19.18	28.00% #1	13.81	14.78
5G0821106B	Fender FENDER RH	1	pcs.	569.67	28.00% #1	410.16	438.87
5G0821136C	Cross Support FENDER BRACKET RH	1	pcs.	29.14	28.00% #1	20.98	22.45
N 90817302	Riveted Cap Nut	4	pcs.	1.14	28.00% #1	3.28	3.51
5G0805970N	Wheelhouse Liner FENDER LINER UPPER RH	1	pcs.	152.98	28.00% #1	110.15	117.86
N 90974701	Hexagon Socket Head Panel BOLT	8	pcs.	0.39	28.00% #1	2.25	2.41
6N0809966A	Expanding Nut	8	pcs.	0.81	28.00% #1	4.67	5.00
5G0821112C	Sound Absorber For Fender FENDER ELEMENT RH	1	pcs.	43.71	28.00% #1	31.47	33.67
5G2857508BQ9B9	Rear View Mirror Housing	1	pcs.	568.11	28.00% #1	409.04	437.67
5G0857538E GRU	Mirror Cap Primed MIRROR COVER RH	1	pcs.	150.42	28.00% #1	108.30	115.88
5G0857522A	Mirror Glass	1	pcs.	185.77	28.00% #1	133.75	143.11
5G4809052	Side Panel A/C PILLAR RH	1	pcs.	2,395.90	28.00% #1	1,725.05	1,845.80
D 506KD1A3	2k-Insert Foam	1	pcs.	130.29	28.00% #1	93.81	100.38
D 476KD1M2	Sealant Can Be Sprayed	1	pcs.	62.20	28.00% #1	44.78	47.91
D 007600A1	Inox-Spray	1	pcs.	62.88	28.00% #1	45.27	48.44
D 180003M2	2k-Body Adhesive	1	pcs.	398.47	28.00% #1	286.90	306.98
5G0071303B	Scuff Plate - Sill Panel	1	pcs.	381.00	28.00% #1	274.32	293.52
7D0000279A	Identification Plate STICKER (CHASSIS NO)	1	pcs.	447.20	28.00% #1	321.98	344.52
5G4831056AS	Door RHS FRT DOOR	1	pcs.	2,005.29	28.00% #1	1,443.81	1,544.88
D 378500A2	Sound Absorber Laminated DOOR INSULATOR	1	pcs.	38.79	28.00% #1	27.93	29.89
5G4837652B	Door Seal	1	pcs.	94.20	28.00% #1	67.82	72.57
5G4867912A	Door Seal Inner	1	pcs.	177.54	28.00% #1	127.83	136.78
8K0831402D	Door Hinge DOOR HINGE UPPER	1	pcs.	126.92	28.00% #1	91.38	97.78
8K0831402D	Door Hinge DOOR HINGE LOWER	1	pcs.	126.92	28.00% #1	91.38	97.78
N 91205802	Hex Bolt With Internal To	4	pcs.	1.66	28.00% #1	4.78	5.11
N 91203801	Bolt With Polygon Socket	2	pcs.	2.10	28.00% #1	3.02	3.23
WHT002109	Oval Hexagon Socket Head	1	pcs.	0.61	28.00% #1	0.44	0.47
N 90365913	Oval Hexagon Socket Head	2	pcs.	1.49	28.00% #1	2.15	2.30
5G0837249D	Check Rod Door	1	pcs.	70.93	28.00% #1	51.07	54.64
5G0837267	Cover CHECK ROD COVER	1	pcs.	12.44	28.00% #1	8.96	9.59
5TC837016A	Door Latch DOOR LOCK	1	pcs.	201.65	28.00% #1	145.19	155.35
5N0837111 9B9	Cap Satin Black	1	pcs.	3.27	28.00% #1	2.35	2.51

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Ms.
LIM
JEE MUAY
29C NIMS ROAD
Singapore 805115

Page 2/3
Document no.
Document date 30-04-2019
Customer no. 5211043084
Customer GST-ID
Dealer 39999
Job order number 2019000419/ 1
Job order date 29-04-2019
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SKC995H	BQ13HZ	16-01-2019	WVWZZZAUZKW040702	Golf Comfortline 1.4 TSI 92kW DSG	14

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
N 90581401	Plug	1	pcs.	0.53	28.00% #1	0.38	0.41
5G4837482H	Window Regulator Without	1	pcs.	371.62	28.00% #1	267.57	286.30
5G4837478D 5AP	Window Slot Seal Black	1	pcs.	78.02	28.00% #1	56.17	60.10
5G0035453G	RHS FRT DOOR TOP MLDG						
	Woofers	1	pcs.	71.53	28.00% #1	51.50	55.11
	DOOR SPEAKER						
WHT005353	Pop-Rivet	4	pcs.	0.44	28.00% #1	1.27	1.36
5G4867024A BNG	Door Trim Panel	1	pcs.	621.91	28.00% #1	447.78	479.12
5G2971162CN	RHS FRT DOOR BOARD						
	Harness For Door	1	pcs.	196.21	28.00% #1	141.27	151.16
8U0959845	RHS FRT DOOR WIRE HARNESS ASSY						
5G4833056AD	Boot With Retaining Frame	1	pcs.	25.00	28.00% #1	18.00	19.26
	Door	1	pcs.	2,005.29	28.00% #1	1,443.81	1,544.88
D 378500A2	RHS REAR DOOR						
	Sound Absorber Laminated	1	pcs.	38.79	28.00% #1	27.93	29.89
5G6839700D	DOOR INSULATOR						
	Door Seal Outer	1	pcs.	94.20	28.00% #1	67.82	72.57
5TA839016E	RHS REAR DOOR SEAL						
	Door Latch	1	pcs.	240.79	28.00% #1	173.37	185.51
5G6839902B 041	RHS REAR DOOR LOCK						
	Trim For Door Window Fram	1	pcs.	63.72	28.00% #1	60.28	64.50
5G6839478F 5AP	RHS REAR DOOR TRIM						
	Window Slot Seal Black	1	pcs.	78.02	28.00% #1	56.17	60.10
5G6839432J 5AP	RHS REAR DOOR TOP MLDG						
	Glass Channel Black	1	pcs.	218.59	28.00% #1	157.38	168.40
3AA868243A	RHS REAR DOOR CHANNEL SEAL						
3AA868246	Clip	4	pcs.	1.45	28.00% #1	4.18	4.47
5G6807417BQGRU	Clip-Lower Part	6	pcs.	1.45	28.00% #1	6.26	6.70
	Cover For Bumper Primed	1	pcs.	1,080.14	28.00% #1	777.70	832.14
5G6807394	REAR BUMPER						
	Guide Piece	1	pcs.	34.51	28.00% #1	24.85	26.59
5G0073147E FZZ	RR BUMPER SIDE BRACKET RH						
	Wheel Disc 'Alum.' With	1	pcs.	1,768.00	28.00% #1	1,272.96	1,362.07
311601361	RIM						
D 314D36M2	Rubber Valve	1	pcs.	3.22	28.00% #1	2.32	2.48
	Long-Life Underseal	1	pcs.	79.34	28.00% #1	57.12	61.12
	Harness Check and Short Circuit Check	1	pcs.	200.00	#1	200.00	214.00
	Diagnostic and Programming	1	pcs.	360.00	#1	360.00	385.20
	WHEEL ALIGNMENT	1	pcs.	300.00	#1	300.00	321.00
	R&R RIM & BALANCE	1	pcs.	50.00	#1	50.00	53.50
	LABOUR	12	pcs.	580.00	#1	6,960.00	7,447.20
	Spray Painting	10	pcs.	500.00	#1	5,000.00	5,350.00
	TRANSFER DOOR MECHANISM	2	pcs.	580.00	#1	1,160.00	1,241.20
	R&R REAR LUGGAGE TRIM	1	pcs.	580.00	#1	580.00	620.60
	VEHICLE ON BENCH	1	pcs.	1,200.00	#1	1,200.00	1,284.00
	R&R FRT SEAT & CARPET	1	pcs.	580.00	#1	580.00	620.60

290

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation Non binding - Preview

Ms.
LIM
JEE MUAY
29C NIMS ROAD
Singapore 805115

Page 3/3
Document no.
Document date 30-04-2019
Customer no. 5211043084
Customer GST-ID
Dealer 39999
Job order number 2019000419/ 1
Job order date 29-04-2019
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SKC995H	BQ13HZ	16-01-2019	WVWZZZAUZKW040702	Golf Comfortline 1.4 TSI 92kW DSG	14

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
--------------	-------------	----------	------	-------------------------	----------	---------------------------	---------------------------

AXA DIRECT SETTLEMENT, DOA:
28/04/2019, SURVEY BY:

Quotation valid till 06-05-2019

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#1		27,614.17	4,364.98	7%	1,932.99	4,364.98	27,614.17	29,547.16
Total		27,614.17	4,364.98		1,932.99	4,364.98	27,614.17	29,547.16

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97445749
WP
21/5/19 430pm
Resurvey before paint
20 days
sure lkkauto.com



<< Service Request Details

Claim

S9M01LSJ

Reference

None

Loss Date

28 April 2019

Report Date

30 Apr 2019 10:24:00 AM

Request Date

30 April 2019

Due Date

30 April 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

[Complete Work](#)[More >](#)

Vehicle Information

Incident Vehicle Registration #

SKC995H

Make

TPVD VOLKSWAGEN

Model

GOLF COMFORTLINE 1.4 L TSI 92KW DSG

Primary Contact/Insured

FU MING RONG SERENE

73 NIM ROAD, #06-01, 807584, Singapore

96790036

Claim Handler

HO Winnie

6568804833

winnie.ho@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Upload](#)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

08 July, 2019

FU MING RONG SERENE
73 NIM ROAD
#06-01
SINGAPORE 807584

Dear Sir/ Mdm

OUR REF : CC4/ASM19007648/T1fb3 // S9M01LSJ
YOUR REF : SFU 93A
ACCIDENT INVOLVING SFU 93A / SKC 995H AND OTHERS ALONG/AT NIM ROAD ON
28/04/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a third party claim(s) from VOLKSWAGEN CENTRE SINGAPORE acting on behalf of the owner of SKC 995H against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

As Insurers, they shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following to vivianlau@lkkauto.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Copy of the letter of authorization
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our

Summons in connection with this accident, please forward it to us immediately. You may email it to cst@axa.com.sg or deliver it by hand to AXA Customer Care Centre.

This letter should not be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), we shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact as at Ms Vivian Lau (LKK Handler) 6841 8625 or vivianlau@lkkauto.com Please quote our claim reference when you contact us that we can assist you more effectively.

Yours sincerely,



Ms Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
Email: vivianlau@lkkauto.com

cc AXA INSURANCE PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19007648/T1wb3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 16-09-2019



ATTN: WINNIE HO

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFU 93A	Veh. Inspected	SKC 995H
Policy No.		Coverage (\$)	0.00
Claim No.	S9M01LSJ	Excess (\$)	0.00
Assign From	WINNIE HO	Assign Date	30/04/2019

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN GOLF	c.c	1395
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	WVWZZZAUZKW040702	Colour	RED
Odometer	3392	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	PIRELLI	7 mm
L/H Front Tyre	225/45 R17	PIRELLI	7 mm
R/H Rear Tyre	225/45 R17	PIRELLI	7 mm
L/H Rear Tyre	225/45 R17	PIRELLI	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/04/2019	Inspection Date	02/05/2019
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 9 TUAS AVE SINGAPORE 639176		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	20 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 995H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	GUIDE PIECE: BUMPER SIDE BRACKET RH (SN) (CONSISTENT)	* CHECK	13.81	-
1	FENDER: FENDER RH (SN) (CONSISTENT)		410.16	410.16
1	CROSS SUPPORT: FENDER BRACKET RH (SN) (CONSISTENT)	BENT	20.98	20.98
4	RIVETTED CAP NUT (SN) (CONSISTENT)	NECESSARY	3.28	3.28
1	WHEELHOUSE LINER: FENDER LINER UPPER RH (SN) (CONSISTENT)	CUT	110.15	110.15
8	HEXAGON SOCKET HEAD PANEL: BOLT (SN) (CONSISTENT)	NECESSARY	2.25	2.25
8	EXPANDING NUT (SN) (CONSISTENT)	NECESSARY	4.67	4.67
1	SOUND ABSORBER FOR FENDER: FENDER ELEMENT RH (SN) (CONSISTENT)	NECESSARY	31.47	31.47
1	REAR VIEW MIRROR HOUSING (SN) (CONSISTENT)	CRACKED	409.04	409.04
1	MIRROR CAP PRIMED: MIRROR COVER RH (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	108.30	-
1	MIRROR GLASS (SN) (CONSISTENT)	* CHECK	133.75	-
1	SIDE PANEL: A/C PILLAR RH (SN) (CONSISTENT)	BENT	1,725.05	1,725.05
1	2K-INSERT FOAM (SN) (CONSISTENT)	NECESSARY	93.81	93.81
1	SEALANT CAN BE SPRAYED (SN) (CONSISTENT)	NECESSARY	44.78	44.78
1	INOX-SPRAY (SN) (CONSISTENT)	NECESSARY	45.27	45.27
1	2K-BODY ADHESIVE (SN) (CONSISTENT)	NECESSARY	286.90	286.90
1	SCUFF PLATE - SILL PANEL (SN) (CONSISTENT)	DEFORMED	274.32	274.32
1	IDENTIFICATION PLATE: STICKER (CHSSIS NO) (SN) (CONSISTENT)	NECESSARY	321.98	321.98
1	DOOR: RHS FRT DOOR (SN) (CONSISTENT)	BENT	1,443.81	1,443.81
1	SOUND ABSORBER LAMINATED: DOOR INSULATOR (SN) (CONSISTENT)	NECESSARY	27.93	27.93
1	DOOR SEAL (SN) (CONSISTENT)	NECESSARY	67.82	67.82
1	DOOR SEAL INNER (SN) (CONSISTENT)	* CHECK	127.83	-
1	DOOR HINGE: DOOR HINGE UPPER (SN) (CONSISTENT)	BENT	91.38	91.38
1	DOOR HINGE: DOOR HINGE LOWER (SN) (CONSISTENT)	BENT	91.38	91.38
4	HEX BOLT WITH INTERNAL TO (SN) (CONSISTENT)	NECESSARY	4.78	4.78

Report Ref No. CC4/ASM19007648/T1wb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	BOLT WITH POLYGON SOCKET (SN) (CONSISTENT)	NECESSARY	3.02	3.02
1	OVAL HEXAGON SOCKET HEAD (SN) (CONSISTENT)	NECESSARY	0.44	0.44
2	OVAL HEXAGON SOCKET HEAD (SN) (CONSISTENT)	NECESSARY	2.15	2.15
1	CHECK ROD DOOR (SN) (CONSISTENT)	* CHECK	51.07	-
1	COVER: CHECK ROD COVER (SN) (CONSISTENT)	* CHECK	8.96	-
1	DOOR LATCH: DOOR LOCK (SN) (CONSISTENT)	* CHECK	145.19	-
1	CAP SATIN BLACK (SN) (CONSISTENT)	NECESSARY	2.35	2.35
1	PLUG (SN) (CONSISTENT)	NECESSARY	0.38	0.38
1	WINDOW REGULATOR WITHOUT (SN) (CONSISTENT)	* CHECK	267.57	-
1	WINDOW SLOT SEAL BLACK: RHS FRT DOOR TOP MLDG (SN) (CONSISTENT)	CUT	56.17	56.17
1	WOOFER: DOOR SPEAKER (SN) (CONSISTENT)	* CHECK	51.50	-
4	POP-RIVET (SN) (CONSISTENT)	NECESSARY	1.27	1.27
1	DOOR TRIM PANEL: RHS FRONT DOOR BOARD (SN) (CONSISTENT)	* CHECK	447.78	-
1	HARNESS FOR DOOR: RHS FRT DOOR WIRE, HARNESS ASSY (SN) (CONSISTENT)	* CHECK	141.27	-
1	BOOT WITH RETAINING FRAME (SN) (CONSISTENT)	* CHECK	18.00	-
1	DOOR: RHS REAR DOOR (SN) (CONSISTENT)	BENT	1,443.81	1,443.81
1	SOUND ABSORBER LAMINATED: DOOR INSULATOR (SN) (CONSISTENT)	NECESSARY	27.93	27.93
1	DOOR SEAL OUTER: RHS REAR DOOR SEAL (SN) (CONSISTENT)	NECESSARY	67.82	67.82
1	DOOR LATCH: RHS REAR DOOR LOCK (SN) (CONSISTENT)	NECESSARY	173.37	173.37
1	TRIM FOR DOOR WINDOW FRAM: RHS REAR DOOR TRIM (SN) (CONSISTENT)	* CHECK	60.28	-
1	WINDOW SLOT SEAL BLACK: RHS REAR DOOR TOP MLDG (SN) (CONSISTENT)	CUT	56.17	56.17
1	GLASS CHANNEL BLACK: RHS REAR DOOR CHANNEL SEAL (SN) (CONSISTENT)	CUT	157.38	157.38
4	CLIP (SN) (CONSISTENT)	NECESSARY	4.18	4.18
6	CLIP - LOWER PART (SN) (CONSISTENT)	NECESSARY	6.26	6.26
1	COVER FOR BUMPER PRIMED: REAR BUMPER (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	777.70	-
1	GUIDE PIECE: RR BUMPER SIDE BRACKET RH (SN) (CONSISTENT)	* CHECK	24.85	-

Report Ref No. CC4/ASM19007648/T1wb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WHEEL DISC 'ALUM.' WITH: RIM (SN) (CONSISTENT)	CUT	1,272.96	1,272.96
1	RUBBER VALVE (SN) (CONSISTENT)	NECESSARY	2.32	2.32
1	LONG-LIFE UNDERSEAL (SN) (CONSISTENT)	NECESSARY	57.12	57.12
			11,224.17	8,846.31
	LABOUR			
	HARNESS CHECK AND SHORT CIRCUIT CHECK.		200.00	200.00
	DIAGNOSTIC AND PROGRAMMING.		360.00	360.00
	WHEEL ALIGNMENT.		300.00	300.00
	R&R RIM & BALANCE.		50.00	50.00
	LABOUR. INCLUSIVE OF THE REPAIR OF MIRROR CAP PRIMED: MIRROR COVER RH AND COVER FOR BUMPER PRIMED: REAR BUMPER.		6,960.00	5,800.00
	SPRAY PAINTING.		5,000.00	3,750.00
	TRANSFER DOOR MECHANISM.		1,160.00	580.00
	R&R REAR LUGGAGE TRIM.		580.00	290.00
	VEHICLE ON BENCH.	* CHECK	1,200.00	-
	R&R FRT SEAT & CARPET.		580.00	290.00
			16,390.00	11,620.00
GRAND TOTAL			27,614.17	20,466.31
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$2,691.86 NETT)				20,466.31

Report Ref No. CC4/ASM19007648/T1wb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.