

Surveyor: Kelvin

REF:

NS/INC19007651/KISD39

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Insured Vehicle No: _____

at Workshop m/s _____

of: _____

Insured: SHB 9000K

Policy No: _____

Claims No: MT/1042408-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vch: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 7243D Yr Reg: 22 Nov 2018Type: M/Car / M/Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make: Hyundai cc 1500Colour: Blue A/C: Ins / Std / NI / NASp. Reading: 43599 T/Radio: Ins / Std / NI / NA

Eng/No: _____

C/No: KMH C851CVK4115118Gen. Cond: Good / Fair / Poor / BurntSteering: In order / for / Jammed / Leaked / Burnt orBrakes: In order / for / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD for / Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / for / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 29/4/19 D.O.I. 30/4/19Survey held at CDAE (Logan)

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Noxolium found</u>
	<u>premiller foxi under Nfuel</u>
	<u>SHD 7243D - X</u>
	<u>SHB 9000K - CC4/ASM18019027/Klj 9352</u>
<u>12/5/19</u>	<u>Went PIP \$ 6352.98 / 4 hrs.</u>
	<u>(\$ 3,277.52 Red - 34%)</u>

RECEIVED 17 MAY 2019

Date/Time, File Pass to?

☐ : Prel. ReportDays Of Repair: 4

Typist

☒ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

Add Fee: ☐ : Site Insp \$

Survey Fee:

Transportation:

\$ + \$ = \$

\$6,352.98 e/p

TP Claims against NTUC Income: Follow-Through Survey

Date : 16/05/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1042298-002	CITYCAB PTE LTD	SHA 9815G	SDG 7527S	29/04/2019	11:50	\$ 1,330.00	\$ 750.00
2	MT/1042124-002	COMFORT TRANSPORTATION PTE LTD	SHA 7643Z	SHB 8754A	29/04/2019	08:20	\$ 3,007.20	\$ 1,900.00
3	MT/1042408-002	COMFORT TRANSPORTATION PTE LTD	SHD 7243D	SHB 9000K	29/04/2019	23:25	\$ 9,630.50	\$ 6,352.98

Address	BLK 52 MARINE TERRACE #13-211
Postcode	440052
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : -
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB9000K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	CHIANG SER HUAT
NRIC/Passport Number	S1143004Z
Contact Number	
Address	
Postcode	
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	FRT

No. Of Passenger (Including Driver)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199203821E

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Loke Wei Yong

30/4/19

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29/4/19 at about 23:25 hrs, I picked up a female passenger from Terminal 3. When I driving at above said location, veh in front applied brake to stop and I doing so. A few second later, I felt an impact from my taxi behind. Veh B it front portion collided onto the rear portion of my taxi. No injury reported in this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO REG NO: 199703821K

Policyholder's Signature
Date & Time:

1-SK
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Loke Wei Yeng
30/4/19

REPAIR ESTIMATE*

VEHICLE NO : SHD 7243D

MAKE :

MODEL : HYUNDAI IONIO

NTUC - C/P/P


LKK - Calvin


DATE 30/4/2019 11:30

CLC

P.12

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>Bent</i>			\$ 2,480.00	
	Boot Lid Lock Upper <i>X 5</i>			\$ 224.00	
	Boot Lid 'H' Emblem <i>new</i>			\$ 28.00	
	Emblem -Hybrid <i>new</i>			\$ 24.30	
	Emblem -Ioniq <i>X 2</i>			\$ 31.30	X
	Emblem -Blue Drive (LH/RH) <i>X 2</i>	\$	26.60	\$ 53.20	
	Boot Lid Glass, Upper <i>X 5</i>			\$ 543.30	
	Boot Lid Glass, Lower <i>new (changed)</i>			\$ 384.90	
	Rear Bumper <i>Bent</i>			\$ 459.40	
	Rear Bumper Reinforcement <i>Bent</i>			\$ 294.80	
	Rear Bumper Reinforcement Bracket (LH/RH) <i>Bent</i>	\$	138.10	\$ 276.20	
	Rear Bumper Centre Moulding Assy <i>new</i>			\$ 451.25	
	Rear Bumper Lower Centre Moulding Assy <i>new</i>			\$ 47.50	
	Rear Bumper Side Bracket (LH/RH) <i>new</i>	\$	33.10	\$ 66.20	
	Rear Bumper Cover Clips <i>new</i>			\$ 22.00	
	Rear Bumper Under Centre Cover <i>new</i>			\$ 225.00	
	Rear Bumper Rear Hook <i>new</i>			\$ 5.40	
	Rear Bumper Reflector Lamp (LH/RH) <i>LH X 2 RH 1 new</i>	\$	31.90	\$ 63.80	
	Rear Bumper Towing Cover <i>X 5</i>			\$ 98.80	
	Rear Panel <i>X repair</i>			\$ 532.00	
	Rear Panel Garnish <i>new</i>			\$ 155.00	
	Rear Panel Lower Panel <i>X repair</i>	\$	39.40	\$ 78.80	
	Exhaust Pipe Insulator <i>new</i>			\$ 35.00	
	Exhaust Silencer <i>Bent</i>			\$ 943.50	
	Exhaust Pipe Hanger <i>new</i>			\$ 29.20	
	Exhaust Pipe Centre <i>new</i>			\$ 573.60	
	Rear Windscreen Glass <i>X 2</i>			\$ 607.20	
	Rear Windscreen Moulding <i>X 2</i>			\$ 28.20	
	SUB TOTAL			\$ 8,762.25	
	LESS 20%			\$ 1,752.45	
	DISCOUNTED TOTAL			\$ 7,009.80	
	Boot Lid Comfort Logo Sticker <i>new</i>			\$ 30.00	Nett
	Rear No.Plake <i>new</i>			\$ 25.00	Nett
	Rear Bumper Reverse Sensor <i>5 shot</i>			\$ 135.70	Nett
	Rear Windscreen Sealant <i>X 1 new</i>			\$ 46.00	Nett
				\$ 236.70	

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			600
	Panel Beating		CLC	\$ 800.00
	Spray Painting Charge			\$ 900.00 600
	Wiring Charge		P2/2	\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 50
	Remove/Refix Rear Windscreen Glass			\$ 120.00 100
	Remove/Refix Reverse Sensor			\$ 120.00 30
	Remove/Refix Exhaust Pipe			\$ 150.00 60
	TOTAL LABOUR			\$ 2,340.00
	ESTIMATE TOTAL			\$ 9,586.50
				9630.50
	1 call in 1 call			
	30/4/19 1245hrs			
	4 days			
	PIP			
	Before Paint photo			
 K&K Auto Consultants hereby notify the Repairer of the following: - To rectify before/after spray painting - To supply damaged parts using recovery - Final prices are subject to confirmation - Cost parts survey is on a "Without Prejudice" basis - Legal modification is allowed - Supplementary items must be surveyed and subject to final approval from Insurance Company Acknowledged by Repairer: Signature: _____ Date: _____				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				



DATE : 29/04/2019

[illegible]

Our Job Ref No : 305291664
Date : 05/10/19

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK vac Fax :
Attn : KALVIN
Vehicle Reg No. : SHD7243D 29.04.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SHB9000K
2. The finalized amount shall be:
- | | |
|---|-------------------|
| (a) Spare Parts after List discount | <u>\$4,872.98</u> |
| (b) Labour Charges | <u>\$1,480.00</u> |
| Total for Part-By-Part Repair Cost | <u>\$6,352.98</u> |
| (c) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: | |
| Final Lumpsum Repair cost | |
3. Estimated normal period for repairs: 4 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.
- We confirm the estimates and finalized amount
- Signature : [Signature] Signature : [Signature]
Name : CHIANG Name : Kalvin
Tel : 62148314 Date : 13/5/19
Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305291664
 REGN NO : SHD7243D
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 22.11.2018
 DATE/TIME IN : 30.04.2019 08:20
 ACCIDENT DATE : 29.04.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2256-G	IONIQ PANEL ASSY-TAIL GAT	1	2,480.00	20.00	1,984.00
0002	04-01-0104-2270-G	IONIQ EMBLEM-HYBRID	1	24.30	20.00	19.44
0003	04-01-0104-2271-G	IONIQ EMBLEM-IONIQ	1	28.00	20.00	22.40
0004	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52
0005	04-01-0104-2288-G	IONIQ BEAM-RR BUMPER	1	294.80	20.00	235.84
0006	04-01-0104-2533-G	IONIQV2 MOULDING ASSY-RR	1	451.25	20.00	361.00
0007	04-01-0104-2545-G	IONIQVC MOULDING-REAR BUM	1	47.50	20.00	38.00
0008	04-01-0104-2540-G	IONIQVC COVER-RR BPR UNDE	1	225.00	20.00	180.00
0009	04-01-0104-2532-G	IONIQVC BRACKET ASSY-RR B	1	33.10	20.00	26.48
0010	04-01-0104-2531-G	IONIQVC BRACKET ASSY-RR B	1	33.10	20.00	26.48
0011	04-01-0104-0852-G	IONIQVC REFLECTOR/REFLEX	1	31.90	20.00	25.52
0012	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0013	09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1	135.70	2.00-	135.70

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305291664
 REGN NO : SHD7243D
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 22.11.2018
 DATE/TIME IN : 30.04.2019 08:20
 ACCIDENT DATE : 29.04.2019

JOB / PARTS DESCRIPTION		QTY IND UNIT-PRICE DISC% AMOUNT				
0014	28-01-0103-0005-A (I40/SONATA)REAR BOOT LOG	1	15.00	0.20	15.00	
0015	28-01-0103-0006-A (I40/SONATA)REAR BOOT TEL	1	15.00	0.02-	15.00	
0016	05-01-0199-0032-A (ALL)WINDSCREEN AHESIVE-3	1	46.00	0.00	46.00	
0017	04-01-0104-3819-G IONIQ STAY-RR BUMPER LH	1	138.10	20.00	110.48	
0018	04-01-0104-3919-G IONIQ STAY-RR BUMPER RH	1	138.10	20.00	110.48	
0019	04-01-0104-2546-G IONIQVC COVER-RR BUMPER S	1	27.50	20.00	22.00	
0020	04-01-0104-2547-G IONIQVC COVER-RR BUMPER S	1	27.50	20.00	22.00	
0021	02-01-0104-2099-G IONIQVC MUFFLER ASSY-REAR	1	943.50	20.00	754.80	
0022	04-01-0104-2544-G IONIQVC CAP-RR HOOK	1	5.40	20.00	4.32	
0023	04-01-0104-2257-G IONIQ GLASS ASSY-TAIL GAT	1	384.90	20.00	307.92	
0024	FNPS NO PLATE(S)	1 N	25.00	2.00-	25.00	

SUB-TOTAL : 4,872.98

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305291664
REGN NO : SHD7243D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 22.11.2018
DATE/TIME IN : 30.04.2019 08:20
ACCIDENT DATE : 29.04.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

JOB NATURE

0000 PB	PANEL BEATING	600.00
0001 SP	SPRAYPAINT CHARGE	600.00
0002 17-01	CHECK ALL LIGHTING	20.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	20.00
0004 20-204	REMOVE/REFIX UPHOLSTERY ASST REPAIR	50.00
0005 20-06-210R	REMOVE & REPLACE REAR W/SCREEN.	100.00
0006 20-06	REMOVE/REFIX EXHAUST PIPE TO ASST REP	60.00
0007 20-05	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 1,480.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305291664
REGN NO : SHD7243D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 22.11.2018
DATE/TIME IN : 30.04.2019 08:20
ACCIDENT DATE : 29.04.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 6,352.98

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19007651/K1sd3q2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 23-05-2019



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SHB 9000K	Veh. Inspected	SHD 7243D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1042408-002	Excess (\$)	0.00
Assign From		Assign Date	30/04/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KMHC851CVKU115118	Colour	BLUE
Odometer	43599	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MICHELIN	8 mm
L/H Front Tyre	195/65 R15	MICHELIN	8 mm
R/H Rear Tyre	195/65 R15	MICHELIN	8 mm
L/H Rear Tyre	195/65 R15	MICHELIN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	29/04/2019	Inspection Date	30/04/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 7243D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID	BENT	2,480.00	2,480.00
1	BOOT LID LOCK UPPER	SERVICEABLE	224.00	-
1	BOOT LID "H" EMBLEM	NECESSARY	28.00	28.00
1	EMBLEM-HYBRID	NECESSARY	24.30	24.30
1	EMBLEM- IONIQ	NOT NECESSARY	31.30	-
2	EMBLEM-BLUE DRIVE (LH/RH) @\$26.60	SERVICEABLE	53.20	-
1	BOOT LID GLASS,UPPER	SERVICEABLE	543.30	-
1	BOOT LID GLASS,LOWER	NECESSARY / DAMAGED	384.90	384.90
1	REAR BUMPER	DEFORMED	459.40	459.40
1	REAR BUMPER REINFORCEMENT	BENT	294.80	294.80
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$138.10	BENT	276.20	276.20
1	REAR BUMPER CENTRE MOULDING ASSY	CRACKED	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	CRACKED	47.50	47.50
2	REAR BUMPER SIDE BRACKET (LH/RH) @\$33.10	CRACKED	66.20	66.20
10	REAR BUMPER COVER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER UNDER CENTRE COVER	CRACKED	225.00	225.00
1	REAR BUMPER REAR HOOK	CRACKED	5.40	5.40
2	REAR BUMPER REFLECTOR LAMP (LH/RH) @\$31.90	O/S CRACKED / N/S SERVICEABLE	63.80	31.90
1	REAR BUMPER TOWING COVER	SERVICEABLE	98.80	-
1	REAR PANEL	TO REPAIR SEE LABOUR	532.00	-
1	REAR PANEL GARNISH	SERVICEABLE	155.00	-
2	REAR PANEL LOWER PANEL @\$39.40	TO REPAIR SEE LABOUR	78.80	-
1	EEXHAUST PIPE INSULATOR	SERVICEABLE	35.00	-
1	EXHAUST SILENCER	BENT	943.50	943.50
1	EXHAUST PIPE HANGER	SERVICEABLE	29.20	-
1	EXHAUST PIPE CENTRE	SERVICEABLE	573.60	-
1	REAR WINDSCREEN GLASS	NOT NECESSARY	607.20	-

Report Ref No. NS/INC19007651/K1sd3q2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	28.20	-
1	BUMPER COVER LH	CRACKED	27.50	27.50
1	BUMPER COVER RH	CRACKED	27.50	27.50
	LESS 20% DISCOUNT		-1,763.37	-1,159.07
			7,053.48	4,636.28
	<u>SPECIAL NETT ITEMS</u>			
1	BOOT LID COMFORT LOGO STICKER (SN)	NECESSARY	30.00	30.00
1	REAR NO PLATE (SN)	CRACKED	25.00	25.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
			236.70	236.70
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR PANEL AND REAR PANEL LOWER PANEL .		800.00	600.00
	SPRAY PAINTING CHARGE.		900.00	600.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.		50.00	20.00
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	50.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	100.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	30.00
	REMOVE/REFIX EXHAUST PIPE.		150.00	60.00
			2,340.00	1,480.00
	GRAND TOTAL		9,630.18	6,352.98

RECOMMENDED COST OF REPAIRS (CONFIRMED)			6,352.98
--	--	--	-----------------

Report Ref No. NS/INC19007651/K1sd3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.