REF:	199/
SS. REC. BY: MCVCLS	SSIGNMENT
	Veh No: SDFSC Yr Regn: 91/8
rom: Date:	Type, M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
stimated Cost	Truck/Trailer or 4
D / TP / WS / TP RES / OD RES / EVA / INV / MV	1 1 100 0 1061
o Inspect Vehicle No:	A 10 December 1 Post 1 MI 1 MA
Workshop m/s	Colour Armin IPS
10000	Sp. Reading 70 2
sured: 63885006	CINO: WAUZEZ F 5 1 JA 1 (429
olicy No.	_
laims No.	Gen. Cond. Good / Fair / Poor / Burnt
um Insured: Excess:	Steering: Iperder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
flake of Veh:	Modi: Nil (S/Rim-/ STD A/Rim or
A	Tyre Size: F: 245/4027/8
(Policy Condition)	R:
GERBIN. The Ven had commenced its	BS / DUN / EXNOVA / GY / FS / LIZA MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	Front Rear
DAC Accident Rport: Consistent? : Yes or No	R/Bal. mm R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 7 mm L/Bal. mm
Est Repairs	D.O.A. 29/4/18 D.O.I. 30/4/15
Lum Sum: 1/h/\ % 3 Val.: Yes or No	Survey held at
CA   REV   REP.   24 HRS 43461	Des. of Damages, Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN /	
Date / Time Action / Instruction 47A 6 4200	The U/C / Chassis frame / Body Structure affected due to collision.
have video of fold	175.09 (Red - \$10,099.)6/44.1)
* 6 vepacy days + 1 PH	+ 1 sunday + 2PRS = 10 days.
Data/Time, File Pass to? : Prell. Report	Days Of Repair:
Final Banari	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
	Fee:   : Site Insp (\$ ) _s+Rs_s
004/000	: Interview (\$ ) Photos
Report Format :	: Tech. Invs (\$ ) Others
Lump,Sum / I.B.I: (\$	:Weekend (\$
N	TOTAL

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711 Tel: 67472112 (5 lines) Fax: 67438032 Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

#### SM/SDF59C/1904058

29th April 2019

The Manager Motor Claim Department India International Insurance Pte Ltd 64 Cecil Street #04/05 IOB Building Singapore 049711

Date of Accident

29th April 2019

Location

Blk 50 Ubi Ave 3 Carpark

Third Party Claim Vehicle No :

GBB 9500 E

Repair Cost For Vehicle No

SDF 59 C Audi A5

Estimate Supply of Parts & Labours

No.	Particulars	Or Oty	Price	Amounts
1	Front fender LH	1	819.90	\$ 819.90
2	Front fender cowling LH	72-71	256.55	\$ 256.55
3	Front fender cowling clips LH	Ner 1set	55.00	\$ 55.00
4	Front fender reflector LH	70 m 1	111.25	\$ 111.25
5	Front fender side garnish LH	7011	23.85	\$ 23.85
6	Front fender top garnish LH	711-1	34.65	\$ 34.65
7	Front fender bracket LH	I see 2	56.25	\$ 112.50 -
8	Headlamp assy LH	152, cm 1	7,186.65	\$ 7,186.65
9	Front bumper fascia	0 000	1,610.95	\$ 1,610.95
10	Front bumper clips	ner 1set	221.50	\$ 221.50 -
11	Front bumper side retainer LH	Cm 1	25.55	\$ 25.55
12	Front bumper air duct LH	0.1	58.65	\$ 58.65-
13	Front support panel	11	800.75	s 800.75 X
14	Running board side skirt LH	R. 1	589.10	\$ 589.10
15	Running board side skirt bracket LH	11	16.85	\$ 16.85 ×
16	Front door pillar LH (outer)	R 1	1,572.00	\$ 1,572.00 X
17	Radiator top garnish	71/01	91.35	\$ 91.35
18	Radiator top garnish clips	12 1set	25.00	\$ 25.00
19	Front grille assy	111	2,170.45	\$ 2,170.45
20	Front grille emblem	101	93.65	\$ 93.65
21	Radiator top bracket	an 1	138.45	\$ 138.45
	and the second of the second o			\$16,014.60

+

ret All

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711 Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg Bus. Reg No: 199502604 E GST No: 19-9502604-E

### SM/SDF59C/1904058

29th April 2019

Particulars		2	tv	Price	_	mounts
Balance b/f	61	4.		50.55	21	6,014.60
Front wheel house top garnish LH	7 6	1211	1		3	53.55
Front wheel house top garnish clips LH	975	ner	1		5	35.00
24 Front wheel rim LH (s/net)		1	1	1,911.45		لـ 1,911.45
				-	\$1	8,014.60
ur Charges :-					E	Amounts
ut, renew, knocking & welding front door pilla	r LH, front aighten & r	fender L e-align b	H, f	ront	\$	2,100.00 }
					7 \$	120.00 ×
we & install air con system, vacuum & top up	gas				~ S	120.00
kote on damage parts					S	120.00
outerise wheel alignment					\$	180.000
painting on damage parts					S	1,880.00 /
k all lighting after repairs					\$	60.00 ٤
						4.600.00
ur Charge				3		4,580.00
	Balance b/f Front wheel house top garnish LH Front wheel house top garnish clips LH Front wheel rim LH (s/net)  ar Charges:-  at, renew, knocking & welding front door pillar transl, remove & install all damage parts, strive & install radiator assy, engine cooling system we with the install air consystem, vacuum & top up tote on damage parts outerise wheel alignment painting on damage parts all lighting after repairs	Balance b/f Front wheel house top garnish LH Front wheel house top garnish clips LH Front wheel rim LH (s/net)  ar Charges:-  at, renew, knocking & welding front door pillar LH, front rt panel, remove & install all damage parts, straighten & reve & install radiator assy, engine cooling system & conducte & install air con system, vacuum & top up gas cote on damage parts  at each of the painting on damage parts all lighting after repairs	Balance b/f Front wheel house top garnish LH Front wheel house top garnish clips LH Front wheel rim LH (s/net)  ar Charges:  at, renew, knocking & welding front door pillar LH, front fender Let panel, remove & install all damage parts, straighten & re-align to the weak install radiator assy, engine cooling system & conduct pressure & install air con system, vacuum & top up gas tote on damage parts buterise wheel alignment painting on damage parts all lighting after repairs	Balance b/f Front wheel house top garnish LH Front wheel house top garnish clips LH Front wheel rim LH (s/net)  In Charges:  Int, renew, knocking & welding front door pillar LH, front fender LH, first panel, remove & install all damage parts, straighten & re-align body we & install radiator assy, engine cooling system & conduct pressure to we & install air con system, vacuum & top up gas note on damage parts  State on damage parts	Balance b/f Front wheel house top garnish LH Front wheel house top garnish clips LH Front wheel rim LH (s/net)  I 1,911.45  Front wheel rim LH (s/net)  Front wheel rim LH (s/net)  I 1,911.45  Front wheel rim LH (s/net)  I 1,911.45  Front wheel rim LH (s/net)  Front wheel rim LH (s/net)  I 1,911.45  Fr	Balance b/f Front wheel house top garnish LH Front wheel house top garnish clips LH Front wheel rim LH (s/net)  In Charges:  Int, renew, knocking & welding front door pillar LH, front fender LH, front rt panel, remove & install all damage parts, straighten & re-align body ve & install air con system, vacuum & top up gas  In the contract of the cont

GST will be reflected in the final bills.

Total Amount

Notes: -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.



7-11100.1 P-10545.09 1-4-2150.00

\$22,594.60

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711 Tel: 67472112 (5 lines) Fax: 67438032 Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

#### SM/SDF59C/1904058

22nd May 2019

The Manager Motor Claim Department India International Insurance Pte Ltd 64 Cecil Street #04/05 IOB Building Singapore 049711

Date of Accident

29th April 2019

Location

Blk 50 Ubi Ave 3 Carpark

Third Party Claim Vehicle No :

GBB 9500 E

Repair Cost For Vehicle No

SDF 59 C Audi A5

Supplementary Supply of Parts

No.	Particulars		Oty	Price	A	mounts
1	Front fender top bracket LH (8W6821471)		Bed 1	22.10	5	22.10-
2	Front fender bracket LH (8W6821131B)	1	2/1	75.25	\$	75.25
3	Front pillar panel LH (8W6809075)	157	13/1	43.75	5	43.75
4	Support lock bracket (8W6807771)	1	2/1	98.65	S	98.65
	***				S	239.75

GST will be reflected in the final bills.

477874.75

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711 Tel: 67472112 (5 lines) Fax: 67438032 Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

#### SM/SDF59C/1904058

29th April 2019

The Manager Motor Claim Department India International Insurance Pte Ltd 64 Cecil Street #04/05 IOB Building Singapore 049711

Date of Accident

29th April 2019

Location

Blk 50 Ubi Ave 3 Carpark

Third Party Claim Vehicle No :

GBB 9500 E

Repair Cost For Vehicle No

SDF 59 C Audi A5

Estimate Supply of Parts & Labours

No.	Particulars	Or Oty	Price	Amounts
1	Front fender LH	1	819.90	\$ 819.90
2	Front fender cowling LH	12:21	256.55	\$ 256.55
3	Front fender cowling clips LH	de Iset	55.00	\$ 55.00
4	Front fender reflector LH	70 m 1	111.25	\$ 111.25
5	Front fender side garnish LH	TO.11	23.85	\$ 23.85
6	Front fender top garnish LH	71-51	34.65	\$ 34.65
7	Front fender bracket LH	Ser 2	56.25	\$ 112.50
8	Headlamp assy LH	Care 1	7,186.65	\$ 7,186.65
9	Front bumper fascia	205 1	1,610.95	\$ 1,610.95
10	Front bumper clips	nen 1set	221.50	\$ 221.50
11	Front bumper side retainer LH	Cru I	25.55	\$ 25.55
12	Front bumper air duct LH	0.71	58.65	\$ 58.65
13	Front support panel	1	800.75	\$ 800.75
14	Running board side skirt LH	1	589.10	\$ 589.10
15	Running board side skirt bracket LH	471	16.85	\$ 16.85 ×
16	Front door pillar LH (outer)	21	1,572,00	\$ 1,572.00 X
17	Radiator top garnish	7261	91.35	\$ 91.35
18	Radiator top garnish clips	12- Iset	25.00	\$ 25.00
19	Front grille assy	1	2,170.45	\$ 2,170.45
20	Front grille emblem	1	93.65	\$ 93.65
21	Radiator top bracket	Cru 1	138.45	\$ 138.45
				\$16,014.60

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711 Tel: 67472112 (5 lines) Fax: 67438032 Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

#### SM/SDF59C/1904058

29th April 2019

No.	Particulars Balance b/f	<u>Qtv</u>	Price	Amounts \$16,014.60
22	Front wheel house top garnish LH	7211	53.55	\$ 53.55
23	Front wheel house top garnish clips LH	re I	35.00	\$ 35.00
24	Front wheel rim LH (s/net)	1	1,911.45	\$ 1,911.45 ×
				\$18,014.60

Labour Charges :-		Amounts
Cut out, renew, knocking & welding front door pillar LH, front fender LH, front support panel, remove & install all damage parts, straighten & re-align body	5	\$ 2,100.00
Remove & install radiator assy, engine cooling system & conduct pressure test	175	120.00 ×
Remove & install air con system, vacuum & top up gas	5	120.00
Tuff-kote on damage parts	5	120.00
Computerise wheel alignment	5	180.00
Spray painting on damage parts		1,880.00 / 201
Check all lighting after repairs		60.00
Labour Charge		\$ 4,580.00
Total Amount		\$22,594.60

GST will be reflected in the final bills.

Notes: -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.



# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	4348K
/ehicle No.:	SDF59C
/ehicle to be Exported:	No
ntended Deregistration Date:	02 May 2019
Vehicle Make:	AUDI
Vehicle Model:	A5 SB 2.0 TFSI S TRONIC (DESIGN)
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	CVK064493
Chassis No.:	WAUZZZF51JA114294
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$37,954.00
Original Registration Date:	12 Sep 2018
First Registration Date:	12 Sep 2018
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$45,136.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Sep 2028
PARF Rebate Amount: Intended COE Rebate Details	\$33,852.00
COE Expiry Date:	11 Sep 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,429.00
COE Rebate Amount:	\$30,348.00
Total Rebate Amount:	\$64,200.00

The information contained herein is correct as at 02 May 2019

OK

### Nivitha (LKK Auto)

From:

Motor Claim - III <motorclaim@iii.com.sg>

Sent:

Tuesday, 30 April 2019 2:37 PM

To:

Specialists Motor Pte Ltd; 'sur@lkkauto.com'; Admin-D (LKKAuto)

Cc:

Lalitha Krishnan - III

Subject:

RE: ACCIDENT INVOLVING SDF59C AND GBB9500E ON 29/04/2019 AT BLK 50 UBI

AVE 3 CARPARK

Attachments:

0412\_001.pdf; SDF59C (25).jpg; SDF59C (26).jpg; SDF59C (27).jpg; SDF59C (28).jpg

333pmc 30/4/19 vehicle in aways on 2/5/19

Dear Sir / Mdm.

Please conduct a survey on TP vehicle SDF59C and let us have your report urgently.

This claim will be handled by Ms Lalitha.

\*Kindly upload this survey request email to merimen.

Thank You.

#### Best Regards, **Gabriel Wee**



64 Cecil Street; #05 - IOB Building Singapore 049711 Tel: 6347 6100, Ext - 248

From: Specialists Motor Pte Ltd [mailto:cardoc@singnet.com.sg]

Sent: 30 April, 2019 1:41 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: RE: ACCIDENT INVOLVING SDF59C AND GBB9500E ON 29/04/2019 AT BLK 50 UBI AVE 3 CARPARK

Without Prejudice

Dear Gabriel Wee

Please assign LKK Auto Consultants Pte Ltd to survey the vehicle SDF59C.

Thanks & Regards Irene Ting 6747 2112

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]

Sent: Tuesday, 30 April, 2019 1:17 PM

To: Specialists Motor Pte Ltd

Subject: RE: ACCIDENT INVOLVING SDF59C AND GBB9500E ON 29/04/2019 AT BLK 50 UBI AVE 3 CARPARK

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- Automobile Inspection Services Pte Ltd
- Autoprobe Consultants
- VP Appraisal
- Form Team Adjusters Pte Ltd
- Infiniti Appraisal Service
- JP Knights Adjusters
- LBS Auto Consultants Pte Ltd
- Priority Services
- RT Appraisal
- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

#### Best Regards, Gabriel Wee



64 Cecil Street; #05 - IOB Building Singapore 049711

Tel: 6347 6100, Ext - 248

From: Specialists Motor Pte Ltd [mailto:cardoc@singnet.com.sg]

Sent: 30 April, 2019 11:33 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: ACCIDENT INVOLVING SDF59C AND GBB9500E ON 29/04/2019 AT BLK 50 UBI AVE 3 CARPARK

Without Prejudice

Dear Sir/Madam

Attached the estimate, GIA report and photos for your perusal.

Our client (SDF59C) is claiming against your insured (GBB9500E).

Kindly check for us the above claim liability as soon as possible.

And also Kindly arrange the surveyor to survey the vehicle SDF59C at Specialists Motor Pte Ltd Blk 3018A, Ubi Road 1 #01-24/25/26 Singapore 408711


Thanks & Regards Irene Ting 6747 2112

From: cardoc@singnet.com.sg [mailto:cardoc@singnet.com.sg]

Sent: Tuesday, 30 April, 2019 10:04 AM

To: CARDOC

Subject: Attached Image



Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

#### DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

#### DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

it may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment. India International Insurance Pte Ltd.

Registration No. 198703792-K

## Cecilia Chong (LKK Auto)

From:

Cecilia Chong (LKK Auto)

Sent:

Friday, 17 May 2019 3:36 PM

To:

Lalitha Krishnan - III

Cc:

Hsiao Tong (LKKAuto); Admin A

Subject:

RE: Your ref: GBB 9500E (Our ref: CC4/III7677/Ugb3) \*\*\* ACCIDENT INVOLVING GBB

9500E & SDF 59C ON 29/04/2019 \*\*\*

Dear Lalitha,

Noted with many thanks

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong @lkkauto.com fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lalitha Krishnan - III [mailto:lalitha@iii.com.sg]

Sent: Friday, 17 May 2019 2:29 PM

To: Cecilia Chong (LKK Auto) < Cecilia Chong@lkkauto.com>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Your ref: GBB 9500E (Our ref: CC4/III7677/Ugb3) \*\*\* ACCIDENT INVOLVING GBB 9500E & SDF 59C ON

29/04/2019 \*\*\*

Dear Cecilia

We refer to your email below dated 7.5.19.

Liability appears to be against Id as he had admitted he had moved right to hit TPV which is clearly seen in the video footage. You may agree for direct settlement.

Best Regards
LalithaKrishnan
Motor Claims Department
India International Insurance Pte Ltd
64 Cecil Street, #04/#05 IOB Building, Singapore 049711
DID: 6347 6139 Fax: 6224 4174



From: Cecilia Chong (LKK Auto) [mailto:CeciliaChong@lkkauto.com]

Sent: Tuesday, May 07, 2019 12:50 PM
To: Lalitha Krishnan - III < lalitha@iii.com.sg>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Your ref: GBB 9500E (Our ref: CC4/III7677/Ugb3) \*\*\* ACCIDENT INVOLVING GBB 9500E & SDF 59C ON

29/04/2019 \*\*\*

Dear Lalitha,

Kindly refer to attached for the AVF submitted by TP.

Would be very much appreciate if you able to give us your instruction in the liability. Many thanks

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong @lkkauto.com fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

# **Print Received Message**

This mail is associated with:

\*SDF59C (MFL2019D0000417) [GBB9500E] ACE DRIVE PTE LTD Apr 29 2019 12:00PM

[TAK PRODUCTS & SERVICES PTE LTD] Specialists Motor Pte Ltd

From

India International Insurance Pte Ltd (HQ) (III\_SG), sent on 14/10/2019 09:59 AM.

To

Subject Alert - Adj Mandate Approved (S\$15560.00) - SDF59C - Claim Handler: Lalitha Krishnan

Approved:15560.00.		

# ...CLAIM SUBFOLDER...(Pending for Survey Report) Direct Settlement

LAIM SUB	FOLDER TRA	The second secon						Tana a			
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	At	j Submitted	Ins Auth'ed	Statu			
Main	07 May 2019 Edit Reg		30 Apr 2019 00:00 Edit Adj Rpt	S\$12,735.0 Edit Estima	Children (CO)	12,735.09 View Rpt		Repo	Pending for Survey Report Cancel Case		
	Main	Ŋ R	leference	Clair	n Detail:		Docume	nts	1_	Show All	
CLAIM SU	BFOLDER DE	TAILS				[Created	by adjuster]				
insured:	TAK PRO	DUCTS & SERVI	CES PTE LTD, Co. I	Reg. No.: -							
Main Claimant:	ACE DRIV	CE DRIVE PTE LTD									
Vehicle Reg No.:	SDF59C	SDF59C Date of Loss: 29/04/2019 12:00 - :59 [7 Months and 17 Days From LTA Reg Date (Man						an Yr)]			
Claim Type	TP / MFL2019D0000417 Policy/Cover Note No.: D19MFL0000018										
Vehicle Reg No. (Insured):	GBB9500E POICY NO. VFX/P1861952 (Claimant):										
(man-cay)				Ex	cess:						
Repairer:	Specialist	s Motor Pte Ltd	(HQ) Blk 3018A Ub	Road 1, #01-	24/25/26	, 408711 Ubi -	Tel: 6747 2112	2			
Handling Insurer:	India Int	ernational Insur	rance Pte Ltd (HQ)	- Tel: 634761	00 [Ha	ndled by Lalit	ha Krishnan -	6347 6139]			
Claimant's Insurer:			<b>1Q)</b> - Tel: 6880 4888								
Adjuster:	LKK Auto	Consultants Pte	e Ltd (HQ) - Tel: 62	56-3561 [H	endled by	MARCUS CH	ua] [Final	Rpt due 1	13/05/2	019]	
ASSOCIA	TED MAIL RE	CEIVED					113	View All	Compose	Case Mai	
• 111_SG (	14/10/2019):	Alert - Adj Man	date Approved (5\$	15560.00) - 5	DF59C -	Claim Handl	er: Lalitha Kri	s			
ALL ASSO	CIATED TAS	KS=				View All	Search Tasks	Create Ne	w Task	Complet	
Due Dat		Type Tasi	k Group Subjec	t Handler	Assi	gned By	Completed C	n Cre	ated On	Done	

Page 1 of 3 Merimen e-Claims

#### Claim Documents

\*SDF59C (MFL2019D0000417) [GBB9500E] ACE DRIVE PTE LTD Apr 29 2019 12:00PM [TAK PRODUCTS & SERVICES PTE LTD] Specialists Motor Pte Ltd

Vide	eo		1 per s	page 🔻	82
Na	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Prin
1	17/05/19 14:26	Video - Accident	6	Load MP4	
2	17/05/19 14:26	Video - Accident	0	Load AVI	-
Pho	tos/Images		3 per j	page 🔻	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnall	Prin
1	06/05/19 15:16	Odometer Reading	0	Load JPG	80
2	06/05/19 15:16	General View	0	Load JPG	Ø
3	06/05/19 15:16	Chassis Number	0	Load JPG	2
4	06/05/19 15:16	General View	0	Load JPG	2
5	06/05/19 15:16	General View	0	Load JPG	80
6	06/05/19 15:16	General View	0	Load JPG	8
7	06/05/19 15:16	General View	0	Load JPG	W
8	06/05/19 15:16	General View	0	Load JPG	2
9	06/05/19 15:16	General View	0	Load JPG	V
10	06/05/19 15:16	General View	0	Load JPG	V
11	06/05/19 15:16	General View	0	Load JPG	82
12	06/05/19 15:16	General View	0	Load JPG	V
13	06/05/19 15:16	General View	0	Load JPG	
14	06/05/19 15:16	General View	0	Load JPG	V
15	06/05/19 15:16	General View	0	Load JPG	V
16	06/05/19 15:16	General View	0	Load JPG	V
17	06/05/19 15:16	General View	0	Load 3PG	V
18	06/05/19 15:16	General View	0	Load JPG	V
19	06/05/19 15:16	General View	0	Load JPG	12
20	06/05/19 15:16	General View	0	Load JPG	N
21	06/05/19 15:16	General View	0	Load JPG	V
22	06/05/19 15:16	General View	0	Load JPG	V
23	06/05/19 15:16	General View	0	Load JPG	V
24	06/05/19 15:16	General View	0	Load 3PG	V
25	06/05/19 15:16	General View	0	Load 3PG	2
26	06/05/19 15:16	General View	0	Load JPG	R
27	06/05/19 15:16	General View	0	Load JPG	V
28	06/05/19 15:16	General View	0	Load JPG	R
29	06/05/19 15:16	General View	0	Load JPG	R
30	06/05/19 15:16	General View	0	Load JPG	N.
31	06/05/19 15:16	General View	0	Load JPG	E.
32	06/05/19 15:16	General View	0	Load JPG	V
33	06/05/19 15:16	General View	0	Load JPG	R
34	06/05/19 15:16	General View	0	Load JPG	R
35	06/05/19 15:16	General View	0	Load JPG	1 EZ
36	06/05/19 15:16	General View	8	Load JPG	R
37	06/05/19 15:16	General View	0	Load JPG	V
	110000000000000000000000000000000000000	General View	0	Load JPG	Z
38	06/05/19 15:16	General View General View	0	Load JPG	2

Page 2 of 3 Merimen e-Claims

Vide	10		1 per page	V	V
Na	Finalized On	India International Insurance Pte Ltd (HQ)		mbnall	-
40	06/05/19 15:16	General View	1.08	id JPG	2
<b>\$1</b>	06/05/19 15:16	General View	1.0a	id JPG	8
12	06/05/19 15:16	General View	€ Loa	d JPG	2
13	06/05/19 15:16	General View	■ Los	id JPG	82
14	06/05/19 15:16	General View	€ Loa	d JPG	V
45	06/05/19 15:16	General View	€ Los	d JPG	82
46	06/05/19 15:16	General View	O tos	nd JPG	V
47	06/05/19 15:16	General View		od JPG	V
48	06/05/19 15:16	General View		d JPG	R
19	06/05/19 15:16	General View		d JPG	V
-		General View		d JPG	8
50	06/05/19 15:16	PER MONTH (10/10/2001   10/10	-	id JPG	8
51	06/05/19 15:16	General View		ATTICL TO	2
52	06/05/19 15:16	General View		id JPG	
53	06/05/19 15:16	General View		id JPG	N
54	06/05/19 15:16	General View		d JPG	V
55	06/05/19 15:16	General View		id JPG	2
56	06/05/19 15:16	General View	6 Los	id JPG	2
57	06/05/19 15:16	General View	O Los	id JPG	2
58	06/05/19 15:16	General View	6 Los	d JPG	2
59	06/05/19 15:16	General View	<b>●</b> Los	d JPG	2
60	06/05/19 15:16	General View	O Los	id JPG	8
61	06/05/19 15:16	General View		nd JPG	2
52	06/05/19 15:16	General View		ed JPG	2
- H-1	Community or state of the	General View		nd JPG	2
53	06/05/19 15:16	Department of the Control of the C		ed JPG	2
54	06/05/19 15:16	General View		10000	2
65	06/05/19 15:16	General View		ed JPG	-
66	06/05/19 15:16	General View		ad JPG	2
67	06/05/19 15:16	General View		od JPG	2
68	06/05/19 15:16	General View		ad JPG	R
69	06/05/19 15:16	General View		ad JPG	2
70	06/05/19 15:16	General View	<b>3</b> Los	ad JPG	2
71	06/05/19 15:16	General View	O Los	ad JPG	2
72	06/05/19 15:16	General View	O Los	ad JPG	2
73	06/05/19 15:16	General View	1 Los	ad JPG	1
74	06/05/19 15:16	General View	O Los	ad JPG	D
75	06/05/19 15:16	General View		ad JPG	2
76	06/05/19 15:16	General View		ad JPG	2
77	06/05/19 15:16	General View		ad JPG	8
	- and - Control to the Time.	TARLES DE LA CALLES		ad JPG	E
78	06/05/19 15:16	General View		CONTRACTOR O	E
79	06/05/19 15:16	General View		ad JPG	+
80	06/05/19 15:16	General View		ad JPG	2
81	06/05/19 15:16	General View		ad JPG	2
82	06/05/19 15:16	General View		ad JPG	5
83	06/05/19 15:16	General View		ad JPG	6
84	06/05/19 15:16	General View	O Los	ad JPG	5
85	06/05/19 15:16	General View	O Los	ad JPG	2
86	06/05/19 15:16	General View	■ Los	ad JPG	5
87	06/05/19 15:16	General View	O Los	ad JPG	5
88	06/05/19 15:16	General View		ad JPG	5
89	06/05/19 15:16	General View		ad JPG	5
90	06/05/19 15:16	General View		ad JPG	5
91	-	General View		ad JPG	6
	06/05/19 15:16	I Committee Comm		ad JPG	5
92	06/05/19 15:16	General View			*
93	06/05/19 15:16	General View		ad JPG	5
94	06/05/19 15:16	General View	1 Los	ad JPG	1 5

Page 3 of 3 Merimen e-Claims

Vide	10		1 per s	age V	2
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnall	Print
96	06/05/19 15:16	General View	0	Load JPG	8
97	06/05/19 15:16	General View	0	Load 3PG	12
98	06/05/19 15:16	General View	0	Load JPG	20
99	06/05/19 15:16	General View	0	Load JPG	
100	06/05/19 15:16	General View	0	Load JPG	8
101	06/05/19 15:16	General View	0	Load 3PG	Ø
Doc	Documentation 1 per pag		oage 🔻	82	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/05/19 18:18	EMAIL FROM III DD 30042019	0	Load PDF	
2	02/05/19 18:18	TP EST & GIA REPORT	0	Load PDF	
3	02/05/19 19:36	TP ESTIMATE- MARKED	0	Load PDF	
4	04/10/19 16:14	WORKSHOP INVOICE	0	Load PDF	
5	04/10/19 16:14	LTA SEARCH	0	Load PDF	
6	04/10/19 16:14	LOD	0	Load PDF	
7	24/12/19 11:37	AUTHORISATION TO ACT FORM	0	Load PDF	_
8	24/12/19 11:37	DISCHARGE VOUCHER	0	Load PDF	
9	24/12/19 11:37	RENTAL RECEIPT	0	Load PDF	
10	24/12/19 11:37	GIROFORM	0	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	03/05/19 08:53	Singapore Accident Statement	0	Load PDF	

## **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured:	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

Page 1 of 4 Adjuster Report

### LKK Auto Consultants Pte Ltd (Co Reg. No. 199607 198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/III19007677/UGB3N2

Date:

24/12/2019

REFERENCE

India International Insurance Pte Handling Insurer:

Policy No:

D19MFL0000018

Claimant Vehicle No:

SDF59C

Insured Vehicle No:

GBB9500E

Date of Loss:

29/04/2019

Nature of Claim:

TP

Claim MFI 2019D0000417

No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SDF59C

Make & Model:

AUDI A5, 2.0 (A)

12/09/2018 (Man. Year: 2018)

Engine No:

CVK064493

Reg. Date: Colour:

Chassis No: Odometer:

WAUZZZF51JA114294 9627 km

Engine Capacity:

1984 cc

Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

245/40Z R18

Rear Tyre Size:

No

245/40Z R18

Front Tyre Size: Front Left Side: Front Right Side:

Michelin 7 mm

Rear Left Side: Rear Right Side:

Michelin 7 mm Michelin 7 mm

Michelin 7 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,254.35	10,545.09	7,709.26	42.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,580.00	2,190.00	2,390.00	52.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,834.35	12,735.09	10,099.26	44.23
+ GST 7.00/7.00% (S\$)	1,598.40	891.46	706.94	44.23
Nett Amount (S\$)	24,432.75	13,626.55	10,806.20	44.23
+ Car Rental (10.0 x	S\$160.50/day) (S\$)	1,605.00		
+ Do	oc/Search Fee (S\$)	7.45		

Nett Liability (S\$)

INSPECTION

Date of Assignment:

30/04/2019

Date Inspected:

30/04/2019 Inspected At:

Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26

Singapore 408711

15,239.00

Estimated Period of Repair:

6.0 days

Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Page 3 of 4

## REPAIR DETAILS

Referen					
Part Source:		(Last Synchronised: 04 Oct 2019)			
Parts:	N/A	AUDI A5 2.0 (A) (Model not available in database)			
Labour:	Repairer's	(Price-denominated Standard List)			
Print Code:	e: (Unsubmitted, no print-code for SDF59C)				
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page				
Further Info:	tems/values no	t in reference catalogue are prefixed with an asterisk *.			

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Distorted	819.90 F	*819.90 FL
2	1		*FRONT FENDER COWLING LH	Torn	256.55 F	*256,55 FL
3	1		'SET FRONT FENDER COWLING CLIPS LH	Necessary	55.00 F	*55.00 FL
4	1		*FRONT FENDER REFLECTOR LH	Torn	111.25 F	*111.25 FL
5	1		*FRONT FENDER SIDE GARNISH LH	Torn	23.85 F	*23.85 FL
6	1		*FRONT FENDER TOP GARNISH LH	Torn	34.65 F	*34.65 FL
7	2		*FRONT FENDER BRACKET LH	Bent	112.50 F	*112.50 FL
8	1		*HEADLAMP ASSY LH	Cracked	7,186.65 F	*7,186.65 FL
9	1		*FRONT BUMPER FASCIA	Distorted	1,610.95 F	*1,610.95 FL
10	1		*SET FRONT BUMPER CLIPS	Necessary	221.50 F	*221.50 FL
11	1		*FRONT BUMPER SIDE RETAINER LH	Cracked	25.55 F	*25.55 FL
12	1		*FRONT BUMPER AIR DUCT LH	Distorted	58.65 F	*58.65 FL
13	1		*FRONT SUPPORT PANEL	Repair	800.75 F	*-FL
14	1		*RUNNING BOARD SIDE SKIRT LH	Repair	589.10 F	*-FL
15	1		*RUNNING BOARD SIDE SKIRT BRACKET LH	Not Necessary	16.85 F	*-FL
16	1		*FRONT DOOR PILLAR LH (OUTER)	Repair	1,572.00 F	*-FL
17	1		*RADIATOR TOP GARNISH	Torn	91.35 F	*91.35 FL
18	1		SET RADIATOR TOP GARNISH CLIPS	Necessary	25.00 F	*25.00 FL
19	1		*FRONT GRILLE ASSY	Not Necessary	2,170.45 F	*-FL
20	1		*FRONT GRILLE EMBLEM	Not Necessary	93.65 F	*-FL
21	1		*RADIATOR TOP BRACKET	Cracked	138.45 F	*138.45 FL
22	1		*FRONT WHEEL HOUSE TOP GARNISH LH	Torn	53.55 F	*53.55 FL
23	1		*FRONT WHEEL HOUSE TOP GARNISH CLIPS LH	Necessary	35.00 F	*35.00 FL
24	1		*FRONT WHEEL RIM LH	Repair	1,911.45FS	*-FS
25	1		*FRONT FENDER TOP BRACKET LH	Bent	22.10F	*22.10FL
26	1		*FRONT FENDER BRACKET LH	Bent	75.25 F	*75.25 FL
27	1		*FRONT PILLAR PANEL LH	Bent	43.75 F	*43.75 FL
28	1		*SUPPORT LOCK BRACKET	Bent	98.65 F	*98.65 FL
F=Fn	anchise	part. S=Spo	Nett. L=ListItemDisc.			
				Sub Total (S\$)		11,100.10
			<ul> <li>List Item Discount on L Items</li> </ul>	0.00/5.00% (S\$)	0.00	555.01
						40.545.05
				Total Parts (SS)	18 254 35	10.545.09

Total Parts (S\$) 18,254.35 10,545.09

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	CUT OUT ,RENEW ,KNOCKING & WELDING FRONT DOOR PILLAR LH ,FRONT FENDER LH ,FRONT SUPPORT PANEL ,REMOVE & INSTALL ALL DAMAGE PARTS ,STRAIGHTEN & RE-ALIGN BODY	New	2,100.00	800.00
2	REMOVE & INSTALL RADIATOR ASSY, ENGINE COOLING SYSTEM & CONDUCT PRESSURE TEST	New	120.00	0.00
3	REMOVE & INSTALL AIR CON SYSTEM, VACUUM & TOP UP HAS	New	120.00	0.00
4	TUFF-KOTE ON DAMAGE PARTS	New	120.00	50.00
5	COMPUTERISE WHEEL ALIGNMENT	New	180.00	80.00
6	SPRAY PAINTING ON DAMAGE PARTS	New	1,880.00	1,200.00
7	CHECK ALL LIGHTING AFTER REPAIR	New	60.00	60.00
	Gross Labour	Cost (S\$)	4,580.00	2,190.00
	Report was unsubmitted during	g this print-out.		

< END OF ESTIMATES >