

# SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SDF59C/1904058

29<sup>th</sup> April 2019

The Manager  
Motor Claim Department  
India International Insurance Pte Ltd  
64 Cecil Street  
#04/05 IOB Building  
Singapore 049711

not allowed  
to be repaired  
body  
30/4/19

Date of Accident : 29<sup>th</sup> April 2019  
Location : Blk 50 Ubi Ave 3 Carpark  
Third Party Claim Vehicle No : GBB 9500 E  
Repair Cost For Vehicle No : SDF 59 C Audi A5

P/P \$

Estimate Supply of Parts & Labours

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Front fender LH	Dis 1	819.90	\$ 819.90 ✓
2	Front fender cowling LH	Dis 1	256.55	\$ 256.55 ✓
3	Front fender cowling clips LH	Dis 1set	55.00	\$ 55.00 ✓
4	Front fender reflector LH	Dis 1	111.25	\$ 111.25 ✓
5	Front fender side garnish LH	Dis 1	23.85	\$ 23.85 ✓
6	Front fender top garnish LH	Dis 1	34.65	\$ 34.65 ✓
7	Front fender bracket LH	Dis 2	56.25	\$ 112.50 ✓
8	Headlamp assy LH	Dis 1	7,186.65	\$ 7,186.65 ✓
9	Front bumper fascia	Dis 1	1,610.95	\$ 1,610.95 ✓
10	Front bumper clips	Dis 1set	221.50	\$ 221.50 ✓
11	Front bumper side retainer LH	Dis 1	25.55	\$ 25.55 ✓
12	Front bumper air duct LH	Dis 1	58.65	\$ 58.65 ✓
13	Front support panel	1	800.75	\$ 800.75 ?
14	Running board side skirt LH	1	589.10	\$ 589.10 ?
15	Running board side skirt bracket LH	1	16.85	\$ 16.85 X
16	Front door pillar LH (outer)	1	1,572.00	\$ 1,572.00 X
17	Radiator top garnish	Dis 1	91.35	\$ 91.35 ✓
18	Radiator top garnish clips	Dis 1set	25.00	\$ 25.00 ✓
19	Front grille assy	1	2,170.45	\$ 2,170.45 ?
20	Front grille emblem	1	93.65	\$ 93.65 ?
21	Radiator top bracket	Dis 1	138.45	\$ 138.45 ✓
				<u>\$16,014.60</u>

# SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SDF59C/1904058

29<sup>th</sup> April 2019

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
	Balance b/f			\$16,014.60
22	Front wheel house top garnish LH	7211 1	53.55	\$ 53.55
23	Front wheel house top garnish clips LH	22 1	35.00	\$ 35.00
24	Front wheel rim LH (s/net)	2 1	1,911.45	\$ 1,911.45
				\$18,014.60

**Labour Charges :-**

	<u>Amounts</u>
Cut out, renew, knocking & welding front door pillar LH, front fender LH, front support panel, remove & install all damage parts, straighten & re-align body	\$ 2,100.00 ?
Remove & install radiator assy, engine cooling system & conduct pressure test	\$ 120.00 X
Remove & install air con system, vacuum & top up gas	\$ 120.00 ?
Tuff-kote on damage parts	\$ 120.00 50
Computerise wheel alignment	\$ 180.00 80
Spray painting on damage parts	\$ 1,880.00 1200
Check all lighting after repairs	\$ 60.00 ✓
Labour Charge	\$ 4,580.00
Total Amount	\$22,594.60

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

We request Customers hence notify the Receiver of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: