

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SDF59C/1904058

29th April 2019

The Manager
Motor Claim Department
India International Insurance Pte Ltd
64 Cecil Street
#04/05 IOB Building
Singapore 049711

not Helmut
LH
taken to 6 Behrnpz
Gdy.
30/4/19
P/P \$ 12735.09

Date of Accident : 29th April 2019
Location : Blk 50 Ubi Ave 3 Carpark
Third Party Claim Vehicle No : GBB 9500 E
Repair Cost For Vehicle No : SDF 59 C Audi A5

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front fender LH	Dis 1	819.90	\$ 819.90
2	Front fender cowling LH	72.1	256.55	\$ 256.55
3	Front fender cowling clips LH	ner 1set	55.00	\$ 55.00
4	Front fender reflector LH	70.1 1	111.25	\$ 111.25
5	Front fender side garnish LH	70.1 1	23.85	\$ 23.85
6	Front fender top garnish LH	71.1 1	34.65	\$ 34.65
7	Front fender bracket LH	bet 2	56.25	\$ 112.50
8	Headlamp assy LH	cm 1	7,186.65	\$ 7,186.65
9	Front bumper fascia	Dis 1	1,610.95	\$ 1,610.95
10	Front bumper clips	ner 1set	221.50	\$ 221.50
11	Front bumper side retainer LH	cm 1	25.55	\$ 25.55
12	Front bumper air duct LH	Dis 1	58.65	\$ 58.65
13	Front support panel	2 1	800.75	\$ 800.75
14	Running board side skirt LH	R. 1	589.10	\$ 589.10
15	Running board side skirt bracket LH	11 1	16.85	\$ 16.85
16	Front door pillar LH (outer)	R 1	1,572.00	\$ 1,572.00
17	Radiator top garnish	71.1 1	91.35	\$ 91.35
18	Radiator top garnish clips	1.1 1set	25.00	\$ 25.00
19	Front grille assy	11 1	2,170.45	\$ 2,170.45
20	Front grille emblem	1.1 1	93.65	\$ 93.65
21	Radiator top bracket	cm 1	138.45	\$ 138.45
				\$16,014.60

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SDF59C/1904058

29th April 2019

No.	Particulars	Qty	Price	Amounts
	Balance b/f			\$16,014.60
22	Front wheel house top garnish LH	1	53.55	\$ 53.55
23	Front wheel house top garnish clips LH	1	35.00	\$ 35.00
24	Front wheel rim LH (s/net)	1	1,911.45	\$ 1,911.45
				<u>\$18,014.60</u>

Labour Charges :-

Cut out, renew, knocking & welding front door pillar LH, front fender LH, front support panel, remove & install all damage parts, straighten & re-align body

Remove & install radiator assy, engine cooling system & conduct pressure test

Remove & install air con system, vacuum & top up gas

Tuff-kote on damage parts

Computerise wheel alignment

Spray painting on damage parts

Check all lighting after repairs

Amounts

\$ 2,100.00

\$ 120.00

\$ 120.00

\$ 120.00

\$ 180.00

\$ 1,880.00

\$ 60.00

Labour Charge

\$ 4,580.00

Total Amount

\$22,594.60

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

Acknowledged by Repairer

Signature:

Date:

2-11/00-1

5%

2-10545.09

1-6 2190.00

12735.09

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SDF59C/1904058

22nd May 2019

The Manager
Motor Claim Department
India International Insurance Pte Ltd
64 Cecil Street
#04/05 IOB Building
Singapore 049711

Date of Accident : 29th April 2019
Location : Blk 50 Ubi Ave 3 Carpark
Third Party Claim Vehicle No : GBB 9500 E
Repair Cost For Vehicle No : SDF 59 C Audi A5

Supplementary Supply of Parts

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Front fender top bracket LH (8W6821471)	Ref 1	22.10	\$ 22.10 ✓
2	Front fender bracket LH (8W6821131B)	Ref 1	75.25	\$ 75.25 ✓
3	Front pillar panel LH (8W6809075)	Ref 1	43.75	\$ 43.75 ✓
4	Support lock bracket (8W6807771)	Ref 1	98.65	\$ 98.65 ✓
				<u>\$ 239.75</u>

GST will be reflected in the final bills.