

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0540/2019/DY
Date : 26-Apr-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Daniel Guido Romeike
Address : 25 Moonstone Lane
#11-01
Singapore 328465
Telephone : Tel +65 92958298
Type of Claim : Own Damage Claims
Policy No. : 2100477194-02
Vehicle No : **SJW 5768 X**
Model Code : A1 SB 1.0 TFSI S tro
Model / Year : Jul-16
Engine No : CHZ 105671
Chassis No : WAUZZZ8X9GB116246
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Apr-19
Place of Accident : Cairnhill Road turning to Cairnhill Rise

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97445749
to

30/4/19 @ 1152.

03 days

Exp: to be advise

Surve lkkauto.com

Authorise

less than \$8K.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJW 5768 X

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy.	s/n \$ 360.00 ✓
2	To dismantle and renew front bumper and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,200.00 500.
3	To respray front bumper.	\$ 800.00 550.
4	To carry out diagnostic check.	s/n \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 2,552.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJW 5768 X

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	
1	FRONT BUMPER	\$	1,407.00 <i>de ✓</i>
2	FRONT BUMPER FIXING PARTS	\$	224.00 ?
3	FRONT BUMPER ADAPTER - RH	\$	15.00 ✓
4	FRONT BUMPER LOWER GRILLE - CENTER	\$	178.00 ✓
5	FRONT BUMPER CLOSING ELEMENT	\$	152.00 ?
6	FRONT BUMPER AIR GUIDE GRILLE - LH	\$	367.00 X
7	RADIATOR GRILLE	\$	894.00 <i>one ✓</i>
8	FRONT REINFORMCENT BAR	\$	630.00 ?
9	FOAM FILLER PIECE	\$	107.00 ?
10	HEADLIGHT MOUNTING - LH	\$	107.00 ?
11	HEADLIGHT - LH	\$	1,792.00 ?
12	HEADLIGHT LIFT CYLINDER - LH	\$	128.00 ?
13	HORN - LOW TONE	\$	206.00 X
14	FRONT BUMPER AIR GUIDE - LH	\$	28.00 ?
15	FRONT NO PLATE	\$	40.00 <i>by ✓</i>
16	SUNDRIES	\$	300.00 ?
TOTAL SPARE PARTS CHARGES		\$	6,575.00
TOTAL LABOUR CHARGES		\$	2,552.00
GRAND TOTAL		\$	9,127.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.