

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5600A

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

PART

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMPR BRACKET SIDE RH REAR
- 5 1 BUMPR RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMPR BRACKET SIDE LH REAR
- 8 1 BUMPR RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 BOOT REAR
- 14 1 BOOT FINISHER
- 15 1 BOOT WHEATERSTRIP
- 16 1 BOOT REFLECTOR LAMP LH
- 17 1 BOOT REFLECTOR LAMP RH
- 18 1 BOOT BADGE 'RENAULT'
- 19 1 BOOT BADGE
- 20 1 BOOT STRUT LH
- 21 1 BOOT STRUT RH
- 22 1 BOOT HINGE LH
- 23 1 BOOT HINGE RH
- 24 1 BOOT INNER TRIM
- 25 1 BOOT SWITCH
- 26 1 BOOT LOCK
- 27 1 BOOT LOCK CATCH
- 28 2 LICENCE PLATE LAMP
- 29 2 BOOT RUBBER PLUG

0•c
 1,108•46 +
 768•84 +
 135•97 +
 44•99 +
 43•61 +
 777•52 +
 2,872•68 +
 493•35 +
 225•36 +
 225•36 +
 367•84 +
 3,299•13 +
 552•55 +
 986•7 +
 1,471•77 +
 =
 13,374•13 *
 13,374•13 x
 90•%
 12,036•717 *
 0•c
 880•+
 1,200•+
 90•+
 60•+
 60•+
 100•+
 120•+
 =
 2,510•*
 0•c
 161•53 +
 66•+
 33•+
 66•+
 30•+
 30•+
 5•+
 40•+
 100•+
 30•=
 561•53 *
 0•c
 12,036•72 +
 2,510•+
 561•53 =
 15,108•25 *
 15,108•25 x
 80•%
 12,086•6 *

45 → \$12,050