

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5600A

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

AAD1904-267

*Not Authorized
U/Sing &***SHC 5600A**

VF1ABL15AUC279401

RENAULT

LATITUDE

28.4.2019

CHINA TAIPING

30/9/2014

PART**LIST**

PART	LIST
1 1 BUMPER COVER REAR	\$ <i>By</i> 1,108.46 ✓
2 1 BUMPER LOWER REAR	\$ <i>Ad/Ln</i> 768.84 —
3 1 BUMPER BRACKET CTR REAR	\$ <i>Ln</i> 113.47 ✓
4 1 BUMPER BRACKET SIDE RH REAR	\$ <i>Ln</i> 135.97 ✓
5 1 BUMPER RETAINER RH REAR	\$ <i>Ln</i> 44.99 ✓
6 1 BUMPER REFLECTOR RH	\$ <i>Ln</i> 43.61 ✓
7 1 BUMPER BRACKET SIDE LH REAR	\$ <i>DIT</i> 135.97 —
8 1 BUMPER RETAINER LH REAR	\$ <i>CM</i> 44.99 —
9 1 BUMPER REFLECTOR LH	\$ <i>CM</i> 43.61 —
10 1 BUMPER BEAM REAR	\$ <i>By</i> 777.52 —
11 1 BUMPER BEAM BRACKET LH REAR	\$ <i>N</i> 225.95 X
12 1 BUMPER BEAM BRACKET RH REAR	\$ <i>N</i> 225.95 X
13 1 BOOT REAR	\$ <i>By</i> 2,872.68 ✓
14 1 BOOT FINISHER	\$ <i>Ln</i> 470.06 X
15 1 BOOT WHEATERSTRIP	\$ <i>DIT/LN</i> 323.05 <i>50/LN</i>
16 1 BOOT REFLECTOR LAMP LH	\$ <i>CM</i> 493.35 —
17 1 BOOT REFLECTOR LAMP RH	\$ <i>Ln</i> 493.35 X
18 1 BOOT BADGE 'RENAULT'	\$ <i>N</i> 225.36 —
19 1 BOOT BADGE	\$ <i>N</i> 225.36 —
20 1 BOOT STRUT LH	\$ <i>Ln</i> 276.08 ✓
21 1 BOOT STRUT RH	\$ <i>Ln</i> 276.08 X
22 1 BOOT HINGE LH	\$ <i>By</i> 367.84 ✓
23 1 BOOT HINGE RH	\$ <i>N</i> 367.84 X
24 1 BOOT INNER TRIM	\$ <i>Ln</i> 586.45 X
25 1 BOOT SWITCH	\$ <i>N</i> 168.13 X
26 1 BOOT LOCK	\$ <i>N</i> 202.67 X
27 1 BOOT LOCK CATCH	\$ <i>Ln</i> 74.40 X
28 2 LICENCE PLATE LAMP	\$ <i>Ln</i> 50.52 X
29 2 BOOT RUBBER PLUG	\$ <i>Ln</i> 221.81 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5600A

30	1 FENDER PANEL REAR RH	\$	R 3,299.13 X
31	1 WHEELARCH REAR RH	\$	Sn 543.47 X
32	1 FENDER PANEL INNER TRIM REAR RH	\$	Sn 671.45 X
33	1 FENDER PANEL REAR LH	\$	Bu 3,299.13 ✓
34	1 WHEELARCH REAR LH	\$	Sn 543.47 X
35	1 TAILLAMP LH	\$	CM 552.55 ✓
36	1 TAILLAMP PANEL LH	\$	R 986.70 ✓
37	1 TAILLAMP RH	\$	Sn 552.55 X
38	1 TAILLAMP PANEL RH	\$	R 986.70 X
39	1 OUTER PANEL REAR (End Panel)	\$	R 1,471.77 ✓
40	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sn 404.56 X
41	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R 2,189.88 X
42	1 SPARE WHEEL PANEL TRIM	\$	Sn 612.21 X
43	1 EXHAUST REAR	\$	R 7,489.05 X
44	1 EXHAUST CAP REAR	\$	R 230.49 X

TOTAL	\$	35,197.49
10%	\$	3,519.75
	\$	31,677.74

Special Nett

1	1SET PARKING AID	\$	Sn 700.00 X
2	1SET REAR BUMPER CLIP	\$	R 66.00 ✓
3	1SET BUMPER BRACKET CTR CLIP	\$	R 33.00 ✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	R 10.00 X
5	1SET BUMPR RETAINER RH CLIP RR	\$	R 20.00 X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	R 10.00 X
7	1SET BUMPR RETAINER CLIP LH RR	\$	R 20.00 X
8	1SET BUMPER LOWER REAR RIVET	\$	R 22.00 X
9	1SET BUMPER LOWER REAR CLIP	\$	R 66.00 ✓
10	1 EXHAUST MOUNTING REAR	\$	Sn 17.82 X
11	1SET BOOT FINISHER CLIP	\$	R 24.20 X
12	1 REAR BOOT STICKER 'TRANS-CAB'	\$	R 80.00 30sn
13	1 REAR BOOT STICKER '6555-3333'	\$	R 80.00 30sn

Trans-cab Auto Services Pte Ltd

AAD1904-267

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5600A

15	1SET FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
18	1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
19	1 TAILLAMP CLIP RH	\$	nn	5.00	X
20	1 TAILLAMP CLIP LH	\$	nn	5.00	✓
21	2 REAR WINDSCREEN SELANT	\$	nn	80.00	40SA-
22	1 WINDSCREEN MOULDING	\$	nn	100.00	—
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	30SA-
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sl	385.00	X
25	1 SPARE TYRE	\$	sl	330.00	X

TOTAL \$ 2,280.02

TOTAL PARTS \$ 33,957.76

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	8801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	12001
To Rust-Proofing Of The Affected Areas.	\$	170.00	901
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd

AAD1904-267

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5600A

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 10cl
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	12cl
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X

TOTAL \$ 14,340.00 14720

Over All Total \$ 48,297.76 48677.76

(LUMP SUM)

(Repair Days) ~~20 DAYS~~
8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: