

# Sketch Plan Pg. 5



redefining / insurance

Date: 18/10/18

To: Owner of Vehicle Number: SPC 2736B

The following has been advised to you via your workshop, Ah Lim Motor Company through their staff, Zila / Eileen / Mui Hong.

Please tick the applicable box if you had been advice on the content as seen below:

- ☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- ☐ You had been advised by the workshop on the liability and merits of the case accordingly.
- ☐ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- ☐ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- ☐ There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- ☐ The estimated waiting time for the spare parts to arrive is \_\_\_\_\_. The estimated arrival time does not include the repair period.
- ☐ You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.
- ☐ For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.
- For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using **any combination** of genuine original parts and/or original equipment manufacturer (OEM) parts.
- ☐ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ☐ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
- ☒ Others Reporting Only.

Signed and acknowledge by:

SWAPNA & [Signature]

Name and signature of policyholder/authorised driver

[Signature]

Name and signature of workshop personnel including company stamp



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo






Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo





Accident Photo



Accident Photo



Accident Photo





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-18-150038  
Date of Request: 28/09/2018

Your Ref No: Online Purchase

Hup Motor Trading & Service  
Blk 9004 Tampines Street 93  
#01-120  
Singapore 528838

Dear Sir/Madam,

Enquiry Date 28/09/2018  
Enquiry By David Ang Beng Yeow  
TP Vehicle No. SKC2736B  
Accident Date 26/09/2018

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKC2736B	AXA Insurance Pte Ltd	04/01/2018-03/01/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-150038

Date of Request: 28/09/2018

Your Ref No: Online Purchase

Hup Motor Trading & Service  
Blk 9004 Tampines Street 93  
#01-120  
Singapore 528838

Dear Sir/Madam,

Enquiry Date 28/09/2018  
Enquiry By David Ang Beng Yeow  
TP Vehicle No. SKC2736B  
Accident Date 26/09/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2924/09/18 Your Ref: \_\_\_\_\_ Date: 28th Sep 2018

MR SOO MENG HAN  
61, Kaki Bukit Avenue 1,  
#04-23, Shun Li Industrial Park,  
Singapore 417943

### Estimate cost of repair to TOYOTA VIOS 1.5 (A) Saloon - SJZ 6733 Z

1 pc front bumper	X Repair		\$ 407.20
8 pcs front bumper top clips	@ \$ 3.60		28.80
8 pcs front bumper lower clips	@ \$ 3.80		30.40
1 pc front bumper n/s side retainer			54.80
1 pc front bumper n/s top bracket		XNN	112.60
1 pc front bumper logo emblem			47.60
1 pc n/s head lamp assy			525.30
1 pc n/s head lamp bracket			18.50
1 pc front n/s fender	X Repair		530.10
1 pc front n/s fender emblem			38.40
1 pc front n/s fender inner shield			148.90
8 pcs front n/s fender inner shield clips	@ \$ 3.80	XNN	30.40
1 pc front n/s sport rim			580.00
1 pc front n/s shock absorber shaft			352.50
1 pc front n/s lower arm			792.30
			<u>\$ 3,697.80</u>
	Less 25%		<u>\$ 924.45</u>
			<u>\$ 2,773.35</u>

To wiring check up & adjust headlight alignment.	40.00	20
To check & adjust front wheel alignment & balancing.	120.00	80
To remove & refix front n/s shock absorber shaft, lower arm, wheel bearing hub & necessary parts.	200.00	X fvn
To Tuff-Kote on all affected accident parts.	60.00	X
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts.	600.00	250
To putty & respray painting on all affected accident parts.	850.00	450
	<u>800</u>	
	<u>\$ 4,643.35</u>	

Dollars : Four Thousand Six Hundred Forty Three And Cents Thirty Five Only

HUP MOTOR TRADING & SERVICE

.....  
.....  
.....

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18017746/Gjb3s2-1

C/O: SEAH ONG & PARTNERS LLP  
36 ROBINSON ROAD  
#12-03 CITY HOUSESINGAPORE 068877

Date : 27-06-2019



Code : ASM

**1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)**

Insured Veh.	SKC 2736B	Veh. Inspected	SJZ 6733Z
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00XEY	Excess (\$)	0.00
Assign From	XIN YI	Assign Date	30/04/2019

**2. Vehicle Particulars & Condition**

Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	MR053HY9305172767	Colour	SILVER
Odometer	192907	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	195/55R15	BRIDGESTONE	6 mm
L/H Front Tyre	195/55R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195/55R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195/55R15	BRIDGESTONE	6 mm

**4. Description of Damages**

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.
--

**5. General Information**

Accident Date	26/09/2018	Inspection Date	02/05/2019
Survey held at	HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>3 Working Days</b>
-------------------------------------	-----------------------





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 6733Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER	REPAIRED SEE LABOUR	407.20	-
8	FRONT BUMPER TOP CLIPS @ \$3.60	NOT NECESSARY	28.80	-
8	FRONT BUMPER LOWER CLIPS @ \$3.80	NOT NECESSARY	30.40	-
1	FRONT BUMPER N/S STICKER RETAINER	NOT NECESSARY	54.80	-
1	FRONT BUMPER N/S TOP BRACKET	NOT NECESSARY	112.60	-
1	FRONT BUMPER LOGO EMBLEM	NOT NECESSARY	47.60	-
1	N/S HEAD LAMP ASSY	NOT NECESSARY	525.30	-
1	N/S HEAD LAMP BRACKET	NOT NECESSARY	18.50	-
1	FRONT N/S FENDER	REPAIRED SEE LABOUR	530.10	-
1	FRONT N/S FENDER EMBLEM	NOT NECESSARY	38.40	-
1	FRONT N/S FENDER INNER SHIELD	NOT NECESSARY	148.90	-
8	FRONT N/S FENDER INNER SHIELD CLIPS @ \$3.80	NOT NECESSARY	30.40	-
1	FRONT N/S SPORT RIM	NOT NECESSARY	580.00	-
1	FRONT N/S SHOCK ABSORBER SHAFT	NOT NECESSARY	352.50	-
1	FRONT N/S LOWER ARM	NOT NECESSARY	792.30	-
	LESS 25% DISCOUNT		-924.45	-
			2,773.35	-
<b>LABOUR</b>				
	TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT.		40.00	20.00
	TO CHECK & ADJUST FRONT WHEEL ALIGNMENT & BALANCING.		120.00	80.00
	TO REMOVE & REFIX FRONT N/S SHOCK ABSORBER SHAFT, LOWER ARM, WHEEL BEARING HUB & NECESSARY PARTS.	NOT NECESSARY	200.00	-
	TO TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS.	NOT NECESSARY	60.00	-
	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT N/S FENDER.		600.00	250.00

Report Ref No. CC4/ASM18017746/Gjb3s2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS.		850.00	450.00
			1,870.00	800.00
GRAND TOTAL			4,643.35	800.00
RECOMMENDED COST OF REPAIRS				800.00

Report Ref No. CC4/ASM18017746/Gjb3s2-1

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT NOT AGREED WITH OUR OFFER

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.