



Case Details

Case Reference Number : TAX/04/19/2114
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1046G

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-6676-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 26/04/2019 04:35 AM
 Vehicle Age(In Months) : 18

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			ABSORBER SET, SHOCK, FRONT LH	1	398.10	398.10	25.00	298.58	Replace	0	0	Check ▾	
One Time Key In	Main			LINK ASSY, FRONT STABILIZER , RH & LH	1	196.70	196.70	25.00	147.52	Replace	0	0	Check ▾	
One Time Key In	Main			LOWER ARM SUBASSY, FRONT LH	1	631.60	631.60	25.00	473.70	Replace	0	0	Check ▾	
One Time Key In	Main			JOINT ASSY, LWR BALL , RH & LH	1	200.10	200.10	25.00	150.07	Replace	0	0	Check ▾	
One Time Key In	Main			END SET, TIE ROD, LH	1	155.90	155.90	25.00	116.93	Replace	0	0	Check ▾	
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL , LH	1	576.00	576.00	25.00	432.00	Replace	1	432.00	Replace ▾	
One Time Key In	Main			PLATE, REAR WHEEL HOUSE, FRONT LH	1	26.80	26.80	25.00	20.10	Replace	0	0	Check ▾	
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR LH	1	1,249.60	1,249.60	25.00	937.20	Replace	1	0	Repair ▾	
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace ▾	
Total Spare Part Cost									97,680.99			Surveyor Total	13,196.15	
Lump Sum Discount (%)									0.00			Lump Sum Dis (%)	0	
Final Spare Part Cost									97,680.99			Final Sur Total	13,196.15	

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			HINGE ASSY, FRONT DOOR , UPPER LH	1	82.10	82.10	25.00	61.57	Replace	0	0	Not Give ▾	
One Time Key In	Main			HINGE ASSY, FRONT DOOR , LOWER LH	1	92.10	92.10	25.00	69.07	Replace	0	0	Not Give ▾	
One Time Key In	Main			CHECK ASSY, FRONT DOOR	1	153.50	153.50	25.00	115.13	Replace	0	0	Check ▾	
One Time Key In	Main			LOCK ASSY, FRONT DOOR LH	1	544.70	544.70	10.00	490.23	Replace	0	0	Check ▾	
One Time Key In	Main			WEATHERSTRIP, FRONT DOOR LH	1	223.80	223.80	25.00	167.85	Replace	0	0	Check ▾	
One Time Key In	Main			DOOR LOCK STRIKER	1	38.00	38.00	25.00	28.50	Replace	0	0	Check ▾	
One Time Key In	Main			WEATHERSTRIP, FRONT DOOR FIX WINDOW , LH	1	74.30	74.30	25.00	55.72	Replace	0	0	Check ▾	
One Time Key In	Main			GLASS, FRONT DOOR FIX WINDOW , LH	1	309.90	309.90	25.00	232.42	Replace	0	0	Check ▾	
One Time Key In	Main			FRAME SUB-ASSY, FRONT DOOR , FRONT LOWER LH	1	140.50	140.50	25.00	105.38	Replace	0	0	Check ▾	
One Time Key In	Main			MOULDING, FRONT DOOR WINDOW FRAME , FRONT LH	1	37.40	37.40	25.00	28.05	Replace	0	0	Check ▾	
One Time Key In	Main			MOULDING ASSY, FRONT DOOR BELT, LH	1	88.60	88.60	25.00	66.45	Replace	0	0	Check ▾	
One Time Key In	Main			GLASS SUB-ASSY, FRONT DOOR , LH	1	796.70	796.70	25.00	597.53	Replace	0	0	Check ▾	
One Time Key In	Main			DOOR FRONT WINDOW REGULATOR SUBASSY, LH	1	230.80	230.80	25.00	173.10	Replace	0	0	Check ▾	
One Time Key In	Main			DOOR FRONT MOTOR ASSY, POWER WINDOW REGULATOR , LH	1	768.60	768.60	10.00	691.74	Replace	0	0	Check ▾	

Total Spare Part Cost	97,680.99	Surveyor Total	13,196.15
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	97,680.99	Final Sur Total	13,196.15

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW , LH	1	1,283.90	1,283.90	10.00	1,155.51	Replace	1	1,155.51	Replace ▾	
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	89.50	89.50	25.00	67.13	Replace	1	67.13	Replace ▾	
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR , LH	1	1,243.90	1,243.90	25.00	932.93	Replace	1	932.93	Replace ▾	
One Time Key In	Main			WEATHERSTRIP, REAR DOOR , NO.2 , LH	1	33.20	33.20	25.00	24.90	Replace	0	0	Check ▾	
One Time Key In	Main			HINGE ASSY, REAR DOOR , LOWER LH	1	73.30	73.30	25.00	54.97	Replace	0	0	Check ▾	
One Time Key In	Main			HINGE ASSY, REAR DOOR , UPPER LH	1	83.30	83.30	25.00	62.47	Replace	0	0	Check ▾	
One Time Key In	Main			CHECK ASSY, REAR DOOR	1	153.50	153.50	25.00	115.13	Replace	0	0	Check ▾	
One Time Key In	Main			WEATHERSTRIP, REAR DOOR LH	1	174.40	174.40	25.00	130.80	Replace	0	0	Check ▾	
One Time Key In	Main			DOOR LOCK REAR , LH	1	544.70	544.70	10.00	490.23	Replace	0	0	Check ▾	
One Time Key In	Main			DOOR LOCK STRIKER	1	38.00	38.00	25.00	28.50	Replace	0	0	Check ▾	
One Time Key In	Main			DOOR REAR MOTOR ASSY, POWER WINDOW REGULATOR , LH	1	768.60	768.60	10.00	691.74	Replace	0	0	Check ▾	
One Time Key In	Main			DOOR REAR WINDOW REGULATOR SUBASSY, LH	1	200.70	200.70	25.00	150.52	Replace	0	0	Check ▾	
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace ▾	
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	824.80	25.00	618.60	Replace	1	618.60	Replace ▾	

Total Spare Part Cost	97,680.99	Surveyor Total	13,196.15
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	97,680.99	Final Sur Total	13,196.15

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			LINER, REAR FENDER , LH	1	135.80	135.80	25.00	101.85	Replace	1	101.85	Replace ▾	
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give ▾	
One Time Key In	Main			WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	1	0	Repair ▾	
One Time Key In	Main			CAP SUB-ASSY, WHEEL	1	175.80	175.80	25.00	131.85	Replace	0	0	Not Give ▾	
One Time Key In	Main			GUIDE, RADIATOR AIR,	1	93.90	93.90	25.00	70.43	Replace	0	0	Check ▾	
One Time Key In	Main			GUIDE, RADIATOR AIR , UPPER	1	44.70	44.70	25.00	33.53	Replace	0	0	Check ▾	
One Time Key In	Main			GUIDE, RADIATOR AIR , LH	1	58.80	58.80	25.00	44.10	Replace	0	0	Check ▾	
One Time Key In	Main			GUIDE, RADIATOR AIR , RH	1	54.60	54.60	25.00	40.95	Replace	0	0	Check ▾	
One Time Key In	Main			RADIATOR ASSY	1	1,841.10	1,841.10	25.00	1,380.82	Replace	0	0	Check ▾	
One Time Key In	Main			GROMMET (FOR RADIATOR LOWER SUPPORT)	2	12.70	25.40	25.00	19.05	Replace	0	0	Check ▾	
One Time Key In	Main			CUSHION, (FOR RADIATOR UPPER SUPPORT)	2	9.80	19.60	25.00	14.70	Replace	0	0	Check ▾	
One Time Key In	Main			FAN RADIATOR , LH	1	181.80	181.80	25.00	136.35	Replace	0	0	Check ▾	
One Time Key In	Main			FAN RADIATOR , RH	1	233.00	233.00	25.00	174.75	Replace	0	0	Check ▾	
One Time Key In	Main			FAN SHROUD RADIATOR	1	219.30	219.30	25.00	164.48	Replace	0	0	Check ▾	

Total Spare Part Cost	97,680.99	Surveyor Total	13,196.15
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	97,680.99	Final Sur Total	13,196.15

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MOTOR, COOLING FAN , LH	1	543.50	543.50	10.00	489.15	Replace	0	0	Check ▼	
One Time Key In	Main			MOTOR, COOLING FAN , RH	1	443.40	443.40	10.00	399.06	Replace	0	0	Check ▼	
One Time Key In	Main			HOSE, RADIATOR , NO.1	1	42.60	42.60	25.00	31.95	Replace	0	0	Check ▼	
One Time Key In	Main			HOSE, RADIATOR , NO.2	1	40.20	40.20	25.00	30.15	Replace	0	0	Check ▼	
One Time Key In	Main			TANK, RESERVE SEALED W/O CAP	1	127.00	127.00	25.00	95.25	Replace	0	0	Check ▼	
One Time Key In	Main			HOSE, WATER BYPASS , NO.1	1	37.40	37.40	25.00	28.05	Replace	0	0	Check ▼	
One Time Key In	Main			HOSE, WATER BYPASS , NO.2	1	37.40	37.40	25.00	28.05	Replace	0	0	Check ▼	
One Time Key In	Main			HOSE, WATER BYPASS , NO.3	1	20.10	20.10	25.00	15.08	Replace	0	0	Check ▼	
One Time Key In	Main			HOSE, WATER BYPASS , NO.4	1	13.20	13.20	25.00	9.90	Replace	0	0	Check ▼	
One Time Key In	Main			HOSE, WATER BYPASS , NO.8	1	37.90	37.90	25.00	28.42	Replace	0	0	Check ▼	
One Time Key In	Main			PIPE, WATER BYPASS , NO.1	1	11.00	11.00	25.00	8.25	Replace	0	0	Check ▼	
One Time Key In	Main			PIPE, WATER BYPASS , NO.2	1	11.00	11.00	25.00	8.25	Replace	0	0	Check ▼	
One Time Key In	Main			PIPE, WATER BYPASS , NO.3	1	56.40	56.40	25.00	42.30	Replace	0	0	Check ▼	
One Time Key In	Main			PIPE, RADIATOR	1	32.90	32.90	25.00	24.67	Replace	0	0	Check ▼	

Total Spare Part Cost

97,680.99

Surveyor Total

13,196.15

Lump Sum Discount (%)

0.00

Lump Sum Dis (%)

0

Final Spare Part Cost

97,680.99

Final Sur Total

13,196.15

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MOTOR, COOLING FAN , LH	1	543.50	543.50	10.00	489.15	Replace	0	0	Check v	
One Time Key In	Main			MOTOR, COOLING FAN , RH	1	443.40	443.40	10.00	399.06	Replace	0	0	Check v	
One Time Key In	Main			HOSE, RADIATOR , NO.1	1	42.60	42.60	25.00	31.95	Replace	0	0	Check v	
One Time Key In	Main			HOSE, RADIATOR , NO.2	1	40.20	40.20	25.00	30.15	Replace	0	0	Check v	
One Time Key In	Main			TANK, RESERVE SEALED W/O CAP	1	127.00	127.00	25.00	95.25	Replace	0	0	Check v	
One Time Key In	Main			HOSE, WATER BYPASS , NO.1	1	37.40	37.40	25.00	28.05	Replace	0	0	Check v	
One Time Key In	Main			HOSE, WATER BYPASS , NO.2	1	37.40	37.40	25.00	28.05	Replace	0	0	Check v	
One Time Key In	Main			HOSE, WATER BYPASS , NO.3	1	20.10	20.10	25.00	15.08	Replace	0	0	Check v	
One Time Key In	Main			HOSE, WATER BYPASS , NO.4	1	13.20	13.20	25.00	9.90	Replace	0	0	Check v	
One Time Key In	Main			HOSE, WATER BYPASS , NO.8	1	37.90	37.90	25.00	28.42	Replace	0	0	Check v	
One Time Key In	Main			PIPE, WATER BYPASS , NO.1	1	11.00	11.00	25.00	8.25	Replace	0	0	Check v	
One Time Key In	Main			PIPE, WATER BYPASS , NO.2	1	11.00	11.00	25.00	8.25	Replace	0	0	Check v	
One Time Key In	Main			PIPE, WATER BYPASS , NO.3	1	56.40	56.40	25.00	42.30	Replace	0	0	Check v	
One Time Key In	Main			PIPE, RADIATOR	1	32.90	32.90	25.00	24.67	Replace	0	0	Check v	

Total Spare Part Cost	97,680.99	Surveyor Total	13,196.15
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	97,680.99	Final Sur Total	13,196.15

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			HOSE, RADIATOR , NO.3	1	29.60	29.60	25.00	22.20	Replace	0	0	Check ▼	
One Time Key In	Main			HOSE, WATER BYPASS, NO.5	1	13.20	13.20	25.00	9.90	Replace	0	0	Check ▼	
One Time Key In	Main			PIPE, WATER BYPASS, NO.5	1	51.80	51.80	25.00	38.85	Replace	0	0	Check ▼	
One Time Key In	Main			HOSE, WATER BYPASS, NO.6	1	13.20	13.20	25.00	9.90	Replace	0	0	Check ▼	
One Time Key In	Main			PIPE SUB-ASSY, EGR W/COOLER	1	1,168.70	1,168.70	25.00	876.53	Replace	0	0	Check ▼	
One Time Key In	Main			VALVE ASSY, EGR	1	685.20	685.20	25.00	513.90	Replace	0	0	Check ▼	
One Time Key In	Main			VALVE, DUTY VACUUM SWITCHING	1	115.10	115.10	25.00	86.32	Replace	0	0	Check ▼	
One Time Key In	Main			INLET SUB-ASSY, WATER THERMOSTAT	1	91.20	91.20	25.00	68.40	Replace	0	0	Check ▼	
One Time Key In	Main			HOSE, WATER BYPASS, NO.14	1	37.40	37.40	25.00	28.05	Replace	0	0	Check ▼	
One Time Key In	Main			INVERTER WATER PUMP ASSY	1	432.00	432.00	25.00	324.00	Replace	0	0	Check ▼	
One Time Key In	Main			HOSE, HV WATER PUMP INLET	1	37.90	37.90	25.00	28.42	Replace	0	0	Check ▼	
One Time Key In	Main			HOSE, HV WATER PUMP OUTLET	1	29.60	29.60	25.00	22.20	Replace	0	0	Check ▼	
One Time Key In	Main			TANK ASSY, INVERTER RESERVE	1	371.30	371.30	25.00	278.48	Replace	0	0	Check ▼	
One Time Key In	Main			HOSE, INVERTER COOLING INLET	1	43.10	43.10	25.00	32.33	Replace	0	0	Check ▼	

		Total Spare Part Cost		97,680.99			Surveyor Total		13,196.15		
		Lump Sum Discount (%)		0.00			Lump Sum Dis (%)		0		
		Final Spare Part Cost		97,680.99			Final Sur Total		13,196.15		

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			HOSE, INVERTER COOLING OUTLET	1	29.60	29.60	25.00	22.20	Replace	0	0	Check ▼	
One Time Key In	Main			HOSE, INVERTER RADIATOR INLET	1	40.70	40.70	25.00	30.53	Replace	0	0	Check ▼	
One Time Key In	Main			COOLER, MOTOR COOLING	1	249.10	249.10	10.00	224.19	Replace	0	0	Check ▼	
One Time Key In	Main			INVERTER ASSY	1	4,843.10	4,843.10	10.00	4,358.79	Replace	0	0	Check ▼	
One Time Key In	Main			PROTECTOR, INVERTER	1	26.30	26.30	25.00	19.73	Replace	0	0	Check ▼	
One Time Key In	Main			BRACKET, INVERTER, NO.1	1	206.00	206.00	25.00	154.50	Replace	0	0	Check ▼	
One Time Key In	Main			BRACKET, INVERTER, NO.2	1	174.80	174.80	25.00	131.10	Replace	0	0	Check ▼	
One Time Key In	Main			COVER SUB-ASSY, INVERTER	1	90.40	90.40	25.00	67.80	Replace	0	0	Check ▼	
One Time Key In	Main			CABLE, MOTOR	1	203.20	203.20	10.00	182.88	Replace	0	0	Check ▼	
One Time Key In	Main			WIRE, ENGINE ROOM MAIN	1	6,138.00	6,138.00	10.00	5,524.20	Replace	0	0	Check ▼	
One Time Key In	Main			WIRE, AIR CONDITIONER	1	445.70	445.70	10.00	401.13	Replace	0	0	Check ▼	
One Time Key In	Main			WIRE, ENGINE	1	2,154.30	2,154.30	10.00	1,938.87	Replace	0	0	Check ▼	
One Time Key In	Main			WIRE, ENGINE, NO.3	1	260.40	260.40	10.00	234.36	Replace	0	0	Check ▼	
One Time Key In	Main			WIRE, ENGINE, NO.4	1	51.20	51.20	10.00	46.08	Replace	0	0	Check ▼	

Total Spare Part Cost	97,680.99	Surveyor Total	13,196.15
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	97,680.99	Final Sur Total	13,196.15

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BATTERY	1	1,584.90	1,584.90	10.00	1,426.41	Replace	0	0	Check ▼	
One Time Key In	Main			CLAMP SUB-ASSY, BATTERY	1	41.40	41.40	25.00	31.05	Replace	0	0	Check ▼	
One Time Key In	Main			CLAMP, BATTERY, NO.2	1	43.30	43.30	25.00	32.47	Replace	0	0	Check ▼	
One Time Key In	Main			COVER, FUSIBLE LINK	1	28.30	28.30	25.00	21.23	Replace	0	0	Check ▼	
One Time Key In	Main			BLOCK ASSY, FUSIBLE LINK	1	99.80	99.80	10.00	89.82	Replace	0	0	Check ▼	
One Time Key In	Main			BLOCK, JUNCTION	1	15.80	15.80	10.00	14.22	Replace	0	0	Check ▼	
One Time Key In	Main			SENSOR ASSY, BATTERY STATE	1	256.80	256.80	10.00	231.12	Replace	0	0	Check ▼	
One Time Key In	Main			HOLDER, BATTERY CURRENT SENSOR	1	11.70	11.70	10.00	10.53	Replace	0	0	Check ▼	
One Time Key In	Main			BRACKET, ENGINE CONTROL COMPUTER, NO.1	1	18.50	18.50	25.00	13.88	Replace	0	0	Check ▼	
One Time Key In	Main			BRACKET, ENGINE CONTROL COMPUTER, NO.2	1	16.90	16.90	25.00	12.67	Replace	0	0	Check ▼	
One Time Key In	Main			COMPUTER, ENGINE CONTROL	1	3,009.10	3,009.10	10.00	2,708.19	Replace	0	0	Check ▼	
One Time Key In	Main			INLET, AIR CLEANER, NO 1	1	130.50	130.50	25.00	97.88	Replace	0	0	Check ▼	
One Time Key In	Main			INLET, AIR CLEANER, NO 2	1	93.90	93.90	25.00	70.43	Replace	0	0	Check ▼	
One Time Key In	Main			INLET, AIR CLEANER, NO 3	1	35.30	35.30	25.00	26.47	Replace	0	0	Check ▼	

Total Spare Part Cost	97,680.99	Surveyor Total	13,196.15
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	97,680.99	Final Sur Total	13,196.15

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			CLAMP (FOR AIR CLEANER HOSE , NO.2)	1	9.00	9.00	25.00	6.75	Replace	0	0	Check ▼	
One Time Key In	Main			CLAMP (FOR AIR CLEANER INLET , NO.1)	2	7.10	14.20	25.00	10.65	Replace	0	0	Check ▼	
One Time Key In	Main			CLAMP (FOR RESONATOR INTAKE AIR)	1	7.10	7.10	25.00	5.32	Replace	0	0	Check ▼	
One Time Key In	Main			HOSE, AIR CLEANER , NO.1	1	62.10	62.10	25.00	46.58	Replace	0	0	Check ▼	
One Time Key In	Main			RESONATOR, INTAKE AIR	1	14.90	14.90	25.00	11.18	Replace	0	0	Check ▼	
One Time Key In	Main			BRACKET, AIR CLEANER	1	26.90	26.90	25.00	20.17	Replace	0	0	Check ▼	
One Time Key In	Main			AIR CLEANER ASSY	1	956.20	956.20	25.00	717.15	Replace	0	0	Check ▼	
One Time Key In	Main			TUBE, UNION (FOR AIR CLEANER HOSE)	1	19.40	19.40	25.00	14.55	Replace	0	0	Check ▼	
One Time Key In	Main			BODY ASSY, THROTTLE	1	1,942.40	1,942.40	10.00	1,748.16	Replace	0	0	Check ▼	
One Time Key In	Main			MANIFOLD, INTAKE	1	867.70	867.70	25.00	650.78	Replace	0	0	Check ▼	
One Time Key In	Main			SENSOR ASSY, VACUUM (FOR E.F.I.)	1	601.90	601.90	25.00	451.42	Replace	0	0	Check ▼	
One Time Key In	Main			COVER SUB-ASSY, ENGINE	1	262.70	262.70	25.00	197.02	Replace	0	0	Check ▼	
One Time Key In	Main			BRACKET, ENGINE COVER	1	17.90	17.90	25.00	13.42	Replace	0	0	Check ▼	
One Time Key In	Main			ENGINE ASSY	1	25,615.20	25,615.20	25.00	19,211.40	Replace	0	0	Check ▼	

Total Spare Part Cost	97,680.99		Surveyor Total	13,196.15	
Lump Sum Discount (%)	0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost	97,680.99		Final Sur Total	13,196.15	

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			INSULATOR SUB-ASSY, ENGINE MOUNTING, RH	1	382.60	382.60	25.00	286.95	Replace	0	0	Check ▼	
One Time Key In	Main			BRACKET, ENGINE MOUNTING, RH	1	171.10	171.10	25.00	128.32	Replace	0	0	Check ▼	
One Time Key In	Main			ROD, ENGINE MOVING CONTROL , NO.2	1	155.30	155.30	25.00	116.48	Replace	0	0	Check ▼	
One Time Key In	Main			ROD, ENGINE MOVING CONTROL	1	174.80	174.80	25.00	131.10	Replace	0	0	Check ▼	
One Time Key In	Main			INSULATOR, ENGINE MOUNTING, LH	1	258.00	258.00	25.00	193.50	Replace	0	0	Check ▼	
One Time Key In	Main			FRONT REINFORCEMENT SIDE RH	1	128.20	128.20	25.00	96.15	Replace	0	0	Check ▼	
One Time Key In	Main			FRONT REINFORCEMENT SIDE LH	1	129.30	129.30	25.00	96.98	Replace	0	0	Check ▼	
One Time Key In	Main			COVER ASSY, ENGINE UNDER CENTER SET	1	452.80	452.80	25.00	339.60	Replace	1	339.60	Replace ▼	
One Time Key In	Main			COVER, ENGINE UNDER SIDE RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Check ▼	
One Time Key In	Main			COVER, ENGINE UNDER SIDE LH	1	76.90	76.90	25.00	57.68	Replace	0	0	Check ▼	
One Time Key In	Main			COVER, ENGINE UNDER, REAR	1	36.50	36.50	25.00	27.38	Replace	0	0	Check ▼	
One Time Key In	Main			INSERT, CONSOLE BOX, FRONT NO.1	1	93.90	93.90	25.00	70.43	Replace	0	0	Check ▼	
One Time Key In	Main			INSERT, CONSOLE BOX, FRONT NO.2	1	89.20	89.20	25.00	66.90	Replace	0	0	Check ▼	
One Time Key In	Main			PANEL SUB-ASSY, INSTRUMENT CLUSTER FINISH, LOWER CENTER	1	144.80	144.80	25.00	108.60	Replace	0	0	Check ▼	
Total Spare Part Cost									97,680.99	Surveyor Total		13,196.15		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									97,680.99	Final Sur Total		13,196.15		

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace ▾	
One Time Key In	Main			COVER, FR BUMPER LH	1	28.10	28.10	25.00	21.08	Replace	1	21.08	Replace ▾	
One Time Key In	Main			COVER, FR BUMPER RH	1	28.10	28.10	25.00	21.08	Replace	1	21.08	Replace ▾	
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace ▾	
One Time Key In	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	1	251.70	Replace ▾	
One Time Key In	Main			EMBLEM ASSY FRONT	1	87.10	87.10	25.00	65.32	Replace	1	65.32	Replace ▾	
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	1	123.75	Replace ▾	
One Time Key In	Main			BRACKET, FR BUMPER	1	99.80	99.80	25.00	74.85	Replace	0	0	Check ▾	
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	1	35.00	Replace ▾	
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	1	25.00	Replace ▾	
One Time Key In	Main			SEAL, HOOD TO FR END	1	24.40	24.40	25.00	18.30	Replace	0	0	Check ▾	
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	1	61.72	Replace ▾	
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	1	57.68	Replace ▾	
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Check ▾	

Total Spare Part Cost	97,680.99	Surveyor Total	13,196.15
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	97,680.99	Final Sur Total	13,196.15

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	1	518.33	Replace ▾	
One Time Key In	Main			ABSORBER, FR BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	0	0	Check ▾	
One Time Key In	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.88	Replace	1	178.88	Replace ▾	
One Time Key In	Main			EXTENSION SUBASSY, LH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check ▾	
One Time Key In	Main			EXTENSION SUBASSY, RH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check ▾	
One Time Key In	Main			LAMP ASSY, FOG, LH	1	910.20	910.20	10.00	819.18	Replace	0	0	Check ▾	
One Time Key In	Main			LAMP ASSY, FOG, RH	1	910.20	910.20	10.00	819.18	Replace	0	0	Check ▾	
One Time Key In	Main			COVER ASSY, ENGINE	1	180.10	180.10	25.00	135.07	Replace	0	0	Check ▾	
One Time Key In	Main			HOOD SUB-ASSY	1	938.40	938.40	25.00	703.80	Replace	1	703.80	Replace ▾	
One Time Key In	Main			INSULATOR, HOOD	1	393.90	393.90	25.00	295.42	Replace	1	295.42	Replace ▾	
One Time Key In	Main			INSULATOR, HOOD CLIP	6	2.30	13.80	25.00	10.35	Replace	6	10.35	Replace ▾	
One Time Key In	Main			HINGE ASSY, HOOD, LH	1	57.00	57.00	25.00	42.75	Replace	1	42.75	Replace ▾	
One Time Key In	Main			HINGE ASSY, HOOD, RH	1	57.00	57.00	25.00	42.75	Replace	1	42.75	Replace ▾	
One Time Key In	Main			BRACKET, HOOD STAY,	1	11.60	11.60	25.00	8.70	Replace	0	0	Check ▾	
Total Spare Part Cost									97,680.99		Surveyor Total		13,196.15	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)		0	
Final Spare Part Cost									97,680.99		Final Sur Total		13,196.15	