



Section A - Accident Details

Registration Number	SHB1046G
Case Reference Number	TAX/04/19/2114
Registration Date	10/10/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	THINGARAN S/O THANGARAJOO
Type of Accident	Head To Side
Accident Date and Time	26/4/2019 12:35 PM
Accident Reported Date and Time	29/4/2019 10:11 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	26/4/2019 12:36 PM
Replacement Vehicle issued?	No
Job Card Number	24101273
Special Instruction to ARC, if any	TOWED \$90
Prepared Date and Time	29/4/2019 3:27 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$3,211.00	\$1,800.00
Total Spray Cost	\$7,938.00	\$1,950.00
Total Spare Part Cost	\$97,680.99	\$13,196.21
Total Other Cost	\$3,428.00	\$420.00
TOTAL COST	\$112,255.99	\$17,366.21 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	24.0	12.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	30/04/2019 6:10 PM	30/04/2019 1:29 PM
Signature		
Remarks		p/p repair, photo before paint.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1909-0463	Invoice Number	
Quotation Date	26.09.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$1,859.00	\$800.00
TO REPAIR RH PORTION	\$338.00	\$200.00
TO REPAIR LH PORTION	\$1,014.00	\$800.00
Total Labour	\$3,211.00	\$1,800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY RADIATOR SUPPORT LOWER	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY APRON PANEL RH	\$180.00	\$0.00
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
TO RESPRAY FRT MEMBER, RH	\$180.00	\$0.00
TO RESPRAY FRT MEMBER, LH	\$180.00	\$0.00
TO RESPRAY FRONT PILLAR LH	\$180.00	\$0.00
RESPRAY WHEEL CAP	\$720.00	\$0.00
TO RESPRAY RIM	\$720.00	\$200.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY VIEW MIRROR	\$360.00	\$50.00
TO RESPRAY ROCKER PANEL MOULDING	\$360.00	\$100.00
TO RESPRAY RH REAR DOOR	\$378.00	\$0.00
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$0.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$7,938.00	\$1,950.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$126.00	\$90.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$300.00	\$40.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO TOP UP A/C GAS	\$120.00	\$0.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO ALIGN CHASSIS	\$350.00	\$0.00
TO REMOVE & REFIT FUEL TANK	\$120.00	\$0.00
TO REMOVE & REFIT EXHAUST	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$50.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$250.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$480.00	\$50.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$100.00
TO REMOVE AND REFIT WIRE HARDESS	\$250.00	\$0.00
TO REMOVE AND REFIT INVERTER CONVERTER	\$120.00	\$0.00
TO REMOVE & REFIT FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$3,426.00	\$420.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		4852080492	ABSORBER SET, SHOCK, FRONT LH	0.00	\$398.10	0.00	\$0.00	Replace	Check X
		4882047040	LINK ASSY, FRONT STABILIZER, RH & LH	0.00	\$196.70	0.00	\$0.00	Replace	Check X
		4806947060	LOWER ARM SUBASSY, FRONT LH	0.00	\$631.60	0.00	\$0.00	Replace	Check X
		4333019115	JOINT ASSY, LWR BALL, RH & LH	0.00	\$200.10	0.00	\$0.00	Replace	Check X
		4504749195	END SET, TIE ROD, LH	0.00	\$155.90	0.00	\$0.00	Replace	Check X
		7586047900	MOULDING ASSY, BODY ROCKER PANEL, LH	1.00	\$576.00	25.00	\$432.00	Replace	Replace ✓
		6563247080	PLATE, REAR WHEEL HOUSE, FRONT LH	0.00	\$26.80	0.00	\$0.00	Replace	Check X
		6700247162	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,249.60	100.00	\$0.00	Replace	Repair ✓
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace ✓
		6872012151	HINGE ASSY, FRONT DOOR, UPPER LH	0.00	\$82.10	0.00	\$0.00	Replace	Not Given X
		6874012120	HINGE ASSY, FRONT DOOR, LOWER LH	0.00	\$92.10	0.00	\$0.00	Replace	Not Given X
		6861047040	CHECK ASSY, FRONT DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Check X
		6904047100	LOCK ASSY, FRONT DOOR LH	0.00	\$544.70	0.00	\$0.00	Replace	Check X
		6786247050	WEATHERSTRIP, FRONT DOOR LH	0.00	\$223.80	0.00	\$0.00	Replace	Check X
		6941020110	DOOR LOCK STRIKER	0.00	\$38.00	0.00	\$0.00	Replace	Check X
		6821647010	WEATHERSTRIP, FRONT DOOR FIX WINDOW, LH	0.00	\$74.30	0.00	\$0.00	Replace	Check X
		6812647030	GLASS, FRONT DOOR FIX WINDOW, LH	0.00	\$309.90	0.00	\$0.00	Replace	Check X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63655592
Estimator Telephone Number : 68862623
Accident Reporting Number : 88682672

Date Generated : 02/10/2019

User ID : PohSuan

67402470 10	FRAME SUB-ASSY, FRONT DOOR, FRONT LOWER LH	0.00	\$140.50	0.00	\$0.00	Replace	Check	X
75752470 10	MOULDING, FRONT DOOR WINDOW FRAME, FRONT	0.00	\$37.40	0.00	\$0.00	Replace	Check	X
75720470 40	MOULDING ASSY, FRONT DOOR BELT, LH	0.00	\$88.60	0.00	\$0.00	Replace	Check	X
68102472 30	GLASS SUB-ASSY, FRONT DOOR, LH	0.00	\$796.70	0.00	\$0.00	Replace	Check	X
69802210 10	DOOR FRONT WINDOW REGULATOR SUBASSY, LH	0.00	\$230.80	0.00	\$0.00	Replace	Check	X
85720471 40	DOOR FRONT MOTOR ASSY, POWER WINDOW	0.00	\$768.60	0.00	\$0.00	Replace	Check	X
87940474 40	MIRROR ASSY, OUTER REAR VIEW, LH	1.00	\$1,283.90	10.00	\$1,155.51	Replace	Replace	
87945470 60A1	COVER, OUTER MIRROR, LH	1.00	\$89.50	25.00	\$67.13	Replace	Replace	
67004472 10	PANEL SUB-ASSY, REAR DOOR, LH	1.00	\$1,243.90	25.00	\$932.93	Replace	Replace	
67896470 10	WEATHERSTRIP, REAR DOOR, NO.2, LH	0.00	\$33.20	0.00	\$0.00	Replace	Check	X
68780520 31	HINGE ASSY, REAR DOOR, LOWER LH	0.00	\$73.30	0.00	\$0.00	Replace	Check	X
68760201 22	HINGE ASSY, REAR DOOR, UPPER LH	0.00	\$83.30	0.00	\$0.00	Replace	Check	X
68630470 50	CHECK ASSY, REAR DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Check	X
67872470 51	WEATHERSTRIP, REAR DOOR LH	0.00	\$174.40	0.00	\$0.00	Replace	Check	X
69080522 80	DOOR LOCK REAR, LH	0.00	\$544.70	0.00	\$0.00	Replace	Check	X
69410201 10	DOOR LOCK STRIKER	0.00	\$38.00	0.00	\$0.00	Replace	Check	X
85710471 50	DOOR REAR MOTOR ASSY, POWER WINDOW	0.00	\$768.60	0.00	\$0.00	Replace	Check	X
69804470 20	DOOR REAR WINDOW REGULATOR SUBASSY, LH	0.00	\$200.70	0.00	\$0.00	Replace	Check	X
	PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	
61602471 60	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$824.80	25.00	\$618.60	Replace	Replace	
65638470 60	LINER, REAR FENDER, LH	1.00	\$135.80	25.00	\$101.85	Replace	Replace	
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
42611474 50	WHEEL, DISC	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair	
42602471 80	CAP SUB-ASSY, WHEEL	0.00	\$175.80	0.00	\$0.00	Replace	Not Given	X
16592370 20	GUIDE, RADIATOR AIR,	0.00	\$93.90	0.00	\$0.00	Replace	Check	X
16594370 10	GUIDE, RADIATOR AIR, UPPER	0.00	\$44.70	0.00	\$0.00	Replace	Check	X
16595370 50	GUIDE, RADIATOR AIR, LH	0.00	\$58.80	0.00	\$0.00	Replace	Check	X
16593370 40	GUIDE, RADIATOR AIR, RH	0.00	\$54.60	0.00	\$0.00	Replace	Check	X
16400373 10	RADIATOR ASSY	0.00	\$1,841.10	0.00	\$0.00	Replace	Check	X
90480400 21	GROMMET (FOR RADIATOR LOWER CUSHION, (FOR RADIATOR UPPER SUPPORT)	0.00	\$12.70	0.00	\$0.00	Replace	Check	X
16523370 10	CUSHION, (FOR RADIATOR UPPER SUPPORT)	0.00	\$9.80	0.00	\$0.00	Replace	Check	X
16361370 60	FAN RADIATOR, LH	0.00	\$181.80	0.00	\$0.00	Replace	Check	X
16361370 70	FAN RADIATOR, RH	0.00	\$233.00	0.00	\$0.00	Replace	Check	X
16711371 60	FAN SHROUD RADIATOR	0.00	\$219.30	0.00	\$0.00	Replace	Check	X
16363370 60	MOTOR, COOLING FAN, LH	0.00	\$543.50	0.00	\$0.00	Replace	Check	X
16363361 60	MOTOR, COOLING FAN, RH	0.00	\$443.40	0.00	\$0.00	Replace	Check	X
16571372 10	HOSE, RADIATOR, NO.1	0.00	\$42.60	0.00	\$0.00	Replace	Check	X
16572372 10	HOSE, RADIATOR, NO.2	0.00	\$40.20	0.00	\$0.00	Replace	Check	X
164A237 012	TANK, RESERVE SEALED W/O CAP	0.00	\$127.00	0.00	\$0.00	Replace	Check	X
16261371 50	HOSE, WATER BYPASS, NO.1	0.00	\$37.40	0.00	\$0.00	Replace	Check	X
16264371 20	HOSE, WATER BYPASS, NO.2	0.00	\$37.40	0.00	\$0.00	Replace	Check	X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 83685682
Estimator Telephone Number : 88662623
Accident Reporting Number : 88662872

Date Generated : 03/10/2019

User ID : PohSuan

16267370 90	HOSE, WATER BYPASS , NO.3	0.00	\$20.10	0.00	\$0.00	Replace	Check	X
16281371 00	HOSE, WATER BYPASS , NO.4	0.00	\$13.20	0.00	\$0.00	Replace	Check	X
16296370 10	HOSE, WATER BYPASS , NO.8	0.00	\$37.90	0.00	\$0.00	Replace	Check	X
16268371 00	PIPE, WATER BYPASS , NO.1	0.00	\$11.00	0.00	\$0.00	Replace	Check	X
16268371 20	PIPE, WATER BYPASS , NO.2	0.00	\$11.00	0.00	\$0.00	Replace	Check	X
16279370 20	PIPE, WATER BYPASS, NO.3	0.00	\$56.40	0.00	\$0.00	Replace	Check	X
16577370 90	PIPE, RADIATOR	0.00	\$32.90	0.00	\$0.00	Replace	Check	X
16573370 20	HOSE, RADIATOR , NO.3	0.00	\$29.60	0.00	\$0.00	Replace	Check	X
16282370 90	HOSE, WATER BYPASS, NO.5	0.00	\$13.20	0.00	\$0.00	Replace	Check	X
16278370 20	PIPE, WATER BYPASS, NO.5	0.00	\$51.80	0.00	\$0.00	Replace	Check	X
16283370 21	HOSE, WATER BYPASS, NO.6	0.00	\$13.20	0.00	\$0.00	Replace	Check	X
25601370 30	PIPE SUB-ASSY, EGR W/COOLER	0.00	\$1,168.70	0.00	\$0.00	Replace	Check	X
25620371 50	VALVE ASSY, EGR	0.00	\$685.20	0.00	\$0.00	Replace	Check	X
90910122 76	VALVE, DUTY VACUUM SWITCHING	0.00	\$115.10	0.00	\$0.00	Replace	Check	X
16031370 10	INLET SUB-ASSY, WATER THERMOSTAT	0.00	\$91.20	0.00	\$0.00	Replace	Check	X
16267371 00	HOSE, WATER BYPASS, NO.14	0.00	\$37.40	0.00	\$0.00	Replace	Check	X
G904047 040	INVERTER WATER PUMP ASSY	0.00	\$432.00	0.00	\$0.00	Replace	Check	X
G922E47 010	HOSE, HV WATER PUMP INLET	0.00	\$37.90	0.00	\$0.00	Replace	Check	X
G922F47 010	HOSE, HV WATER PUMP OUTLET	0.00	\$29.60	0.00	\$0.00	Replace	Check	X
G91H047 011	TANK ASSY, INVERTER RESERVE	0.00	\$371.30	0.00	\$0.00	Replace	Check	X
G922A47 010	HOSE, INVERTER COOLING INLET	0.00	\$43.10	0.00	\$0.00	Replace	Check	X
G922C47 010	HOSE, INVERTER COOLING OUTLET	0.00	\$29.60	0.00	\$0.00	Replace	Check	X
G922H47 010	HOSE, INVERTER RADIATOR INLET	0.00	\$40.70	0.00	\$0.00	Replace	Check	X
G125A47 010	COOLER, MOTOR COOLING	0.00	\$249.10	0.00	\$0.00	Replace	Check	X
G920049 115	INVERTER ASSY	0.00	\$4,843.10	0.00	\$0.00	Replace	Check	X
G921E47 010	PROTECTOR, INVERTER	0.00	\$26.30	0.00	\$0.00	Replace	Check	X
G921447 070	BRACKET, INVERTER, NO.1	0.00	\$206.00	0.00	\$0.00	Replace	Check	X
G921547 050	BRACKET, INVERTER, NO.2	0.00	\$174.80	0.00	\$0.00	Replace	Check	X
G902247 050	COVER SUB-ASSY, INVERTER	0.00	\$90.40	0.00	\$0.00	Replace	Check	X
G114847 070	CABLE, MOTOR	0.00	\$203.20	0.00	\$0.00	Replace	Check	X
8211147J 21	WIRE, ENGINE ROOM MAIN	0.00	\$6,138.00	0.00	\$0.00	Replace	Check	X
821H2470 10	WIRE, AIR CONDITIONER	0.00	\$445.70	0.00	\$0.00	Replace	Check	X
82121472 22	WIRE, ENGINE	0.00	\$2,154.30	0.00	\$0.00	Replace	Check	X
82123470 60	WIRE, ENGINE, NO.3	0.00	\$260.40	0.00	\$0.00	Replace	Check	X
82124121 60	WIRE, ENGINE, NO.4	0.00	\$51.20	0.00	\$0.00	Replace	Check	X
28800371 30	BATTERY	0.00	\$1,584.90	0.00	\$0.00	Replace	Check	X
74404470 30	CLAMP SUB-ASSY, BATTERY	0.00	\$41.40	0.00	\$0.00	Replace	Check	X
74482470 10	CLAMP, BATTERY, NO.2	0.00	\$43.30	0.00	\$0.00	Replace	Check	X
82621470 20	COVER, FUSIBLE LINK	0.00	\$28.30	0.00	\$0.00	Replace	Check	X
82620470 90	BLOCK ASSY, FUSIBLE LINK	0.00	\$99.80	0.00	\$0.00	Replace	Check	X
82671470 40	BLOCK, JUNCTION	0.00	\$15.80	0.00	\$0.00	Replace	Check	X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 03/10/2019

User ID : PohSuan

28850370	70	SENSOR ASSY, BATTERY STATE	0.00	\$256.80	0.00	\$0.00	Replace	Check	X
28859370	30	HOLDER, BATTERY CURRENT SENSOR	0.00	\$11.70	0.00	\$0.00	Replace	Check	X
89667471	00	BRACKET, ENGINE CONTROL COMPUTER,	0.00	\$18.50	0.00	\$0.00	Replace	Check	X
89668470	50	BRACKET, ENGINE CONTROL COMPUTER,	0.00	\$16.90	0.00	\$0.00	Replace	Check	X
89661477	01	COMPUTER, ENGINE CONTROL	0.00	\$3,009.10	0.00	\$0.00	Replace	Check	X
17751371	10	INLET, AIR CLEANER, NO 1	0.00	\$130.50	0.00	\$0.00	Replace	Check	X
17752371	21	INLET, AIR CLEANER, NO 2	0.00	\$93.90	0.00	\$0.00	Replace	Check	X
17753370	10	INLET, AIR CLEANER, NO 3	0.00	\$35.30	0.00	\$0.00	Replace	Check	X
96111107	50	CLAMP (FOR AIR CLEANER HOSE , NO.2)	0.00	\$9.00	0.00	\$0.00	Replace	Check	X
96111106	50	CLAMP (FOR AIR CLEANER INLET , NO.1)	0.00	\$7.10	0.00	\$0.00	Replace	Check	X
96111104	30	CLAMP (FOR RESONATOR INTAKE AIR)	0.00	\$7.10	0.00	\$0.00	Replace	Check	X
17881373	30	HOSE, AIR CLEANER , NO.1	0.00	\$62.10	0.00	\$0.00	Replace	Check	X
17893371	30	RESONATOR, INTAKE AIR	0.00	\$14.90	0.00	\$0.00	Replace	Check	X
17771370	20	BRACKET, AIR CLEANER	0.00	\$26.90	0.00	\$0.00	Replace	Check	X
17700373	30	AIR CLEANER ASSY	0.00	\$956.20	0.00	\$0.00	Replace	Check	X
90904060	08	TUBE, UNION (FOR AIR CLEANER HOSE)	0.00	\$19.40	0.00	\$0.00	Replace	Check	X
22030370	60	BODY ASSY, THROTTLE	0.00	\$1,942.40	0.00	\$0.00	Replace	Check	X
17120371	10	MANIFOLD, INTAKE	0.00	\$887.70	0.00	\$0.00	Replace	Check	X
89421260	30	SENSOR ASSY, VACUUM (FOR E.F.I.)	0.00	\$601.90	0.00	\$0.00	Replace	Check	X
12601370	10	COVER SUB-ASSY, ENGINE	0.00	\$262.70	0.00	\$0.00	Replace	Check	X
12631370	10	BRACKET, ENGINE COVER	0.00	\$17.90	0.00	\$0.00	Replace	Check	X
19000378	00	ENGINE ASSY	0.00	\$25,615.20	0.00	\$0.00	Replace	Check	X
12305373	40	INSULATOR SUB-ASSY, ENGINE MOUNTING, RH	0.00	\$382.60	0.00	\$0.00	Replace	Check	X
12315370	60	BRACKET, ENGINE MOUNTING, RH	0.00	\$171.10	0.00	\$0.00	Replace	Check	X
12364370	40	ROD, ENGINE MOVING CONTROL , NO.2	0.00	\$155.30	0.00	\$0.00	Replace	Check	X
12363370	30	ROD, ENGINE MOVING CONTROL	0.00	\$174.80	0.00	\$0.00	Replace	Check	X
12372373	11	INSULATOR, ENGINE MOUNTING, LH	0.00	\$258.00	0.00	\$0.00	Replace	Check	X
51107470	20	FRONT REINFORCEMENT SIDE RH	0.00	\$128.20	0.00	\$0.00	Replace	Check	X
51108470	20	FRONT REINFORCEMENT SIDE LH	0.00	\$129.30	0.00	\$0.00	Replace	Check	X
51410470	20	COVER ASSY, ENGINE UNDER CENTER SET	1.00	\$452.80	25.00	\$339.60	Replace	Replace	X
51443470	20	COVER, ENGINE UNDER SIDE RH	0.00	\$76.90	0.00	\$0.00	Replace	Check	X
51444470	10	COVER, ENGINE UNDER SIDE LH	0.00	\$76.90	0.00	\$0.00	Replace	Check	X
51442470	30	COVER, ENGINE UNDER, REAR	0.00	\$36.50	0.00	\$0.00	Replace	Check	X
58816470	60C0	INSERT, CONSOLE BOX, FRONT NO.1	0.00	\$93.90	0.00	\$0.00	Replace	Check	X
58817470	60C0	INSERT, CONSOLE BOX, FRONT NO.2	0.00	\$89.20	0.00	\$0.00	Replace	Check	X
55408470	60C0	PANEL SUB-ASSY, INSTRUMENT CLUSTER	0.00	\$144.80	0.00	\$0.00	Replace	Check	X
52119479	62	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace	X
52128479	06	COVER, FR BUMPER LH	1.00	\$28.10	25.00	\$21.08	Replace	Replace	X
52127479	07	COVER, FR BUMPER RH	1.00	\$28.10	25.00	\$21.08	Replace	Replace	X
52161160	10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	X
53101470	80	GRILLE SUB-ASSY	1.00	\$335.60	25.00	\$251.70	Replace	Replace	X

75310470 60	EMBLEM ASSY FRONT	1.00	\$87.10	25.00	\$65.33	Replace	Replace	✓
53112472 40	GRILLE, RADIATOR	1.00	\$165.00	25.00	\$123.75	Replace	Replace	✓
52114471 90	BRACKET, FR BUMPER	0.00	\$99.80	0.00	\$0.00	Replace	Check	X
	NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace	✓
	NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace	✓
53395470 40	SEAL, HOOD TO FR END	0.00	\$24.40	0.00	\$0.00	Replace	Check	X
52116470 50	SUPPORT, FR BUMPER LH	1.00	\$82.30	25.00	\$61.73	Replace	Replace	✓
52115470 50	SUPPORT, FR BUMPER RH	1.00	\$76.90	25.00	\$57.68	Replace	Replace	✓
52611471 40	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Check	X
52021471 10	REINFORCEMENT FRONT UPPER	1.00	\$691.10	25.00	\$518.33	Replace	Replace	✓
52618470 90	ABSORBER, FR BUMPER LOWER	0.00	\$117.00	0.00	\$0.00	Replace	Check	X
52132470 10	REINFORCEMENT FRONT LOWER	1.00	\$238.50	25.00	\$178.88	Replace	Replace	✓
52103470 10	EXTENSION SUBASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Check	X
52102470 20	EXTENSION SUBASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Check	X
81220470 20	LAMP ASSY, FOG, LH	0.00	\$910.20	0.00	\$0.00	Replace	Check	X
81210470 20	LAMP ASSY, FOG, RH	0.00	\$910.20	0.00	\$0.00	Replace	Check	X
51420470 30	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Check	X
53301471 10	HOOD SUB-ASSY	1.00	\$938.40	25.00	\$703.80	Replace	Replace	✓
53341470 40	INSULATOR, HOOD	1.00	\$393.90	25.00	\$295.43	Replace	Replace	✓
90467090 50	INSULATOR, HOOD CLIP	6.00	\$2.30	25.00	\$10.35	Replace	Replace	✓
53420471 30	HINGE ASSY, HOOD, LH	1.00	\$57.00	25.00	\$42.75	Replace	Replace	✓
53410471 30	HINGE ASSY, HOOD, RH	1.00	\$57.00	25.00	\$42.75	Replace	Replace	✓
53336470 10	BRACKET, HOOD STAY,	0.00	\$11.80	0.00	\$0.00	Replace	Check	X
53440470 60	SUPPORT ASSY, HOOD	0.00	\$41.80	0.00	\$0.00	Replace	Check	X
53452470 50	HOLDER, HOOD STAY	0.00	\$16.60	0.00	\$0.00	Replace	Check	X
90959013 69	CLAMP (FOR HOOD LOCK CONTROL CABLE)	0.00	\$4.20	0.00	\$0.00	Replace	Check	X
53510471 40	LOCK ASSY, HOOD	0.00	\$131.10	0.00	\$0.00	Replace	Check	X
53630470 90	CABLE ASSY, HOOD	0.00	\$53.20	0.00	\$0.00	Replace	Check	X
85381470 90	NOZZLE, FRONT WASHER	0.00	\$34.10	0.00	\$0.00	Replace	Check	X
75536470 20	MOULDING LH	1.00	\$83.30	25.00	\$62.48	Replace	Replace	✓
75535470 20	MOULDING RH	0.00	\$83.30	0.00	\$0.00	Replace	Check	X
55708472 30	WIPER GARNISH LOUVER SUB-ASSY	0.00	\$666.90	0.00	\$0.00	Replace	Check	X
90467092 42	WIPER GARNISH LOUVER SUB-ASSY, CLIP	0.00	\$3.20	0.00	\$0.00	Replace	Check	X
55754470 70	WIPER GARNISH SHIELD, COWL WATER, LH	0.00	\$18.90	0.00	\$0.00	Replace	Check	X
55753470 90	WIPER GARNISH SHIELD, COWL WATER, RH	0.00	\$18.90	0.00	\$0.00	Replace	Check	X
61014470 10	PILLAR, FRONT BODY, LH	0.00	\$339.40	0.00	\$0.00	Replace	Check	X
60118470 20	COVER SUB-ASSY, FRONT PILLAR, UPR LH	0.00	\$96.90	0.00	\$0.00	Replace	Check	X
88790281 00	THERMISTOR ASSY	0.00	\$68.00	0.00	\$0.00	Replace	Check	X
53289470 72	COVER, RADIATOR	0.00	\$227.80	0.00	\$0.00	Replace	Check	X
53205479 00	SUPPORT S/A UPPER	0.00	\$364.90	0.00	\$0.00	Replace	Check	X
53028470 10	SUPPORT SUB-ASSY LOWER	0.00	\$397.40	0.00	\$0.00	Replace	Check	X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 6365582
Estimator Telephone Number : 8862623
Accident Reporting Number : 6662672

Date Generated : 03/10/2018

User ID : PohBuan

5320347901	SUPPORT S/A LH	0.00	\$237.00	0.00	\$0.00	Replace	Check	X
5320247901	SUPPORT S/A RH	0.00	\$237.00	0.00	\$0.00	Replace	Check	X
5321747030	BRACE, HOOD LOCK SUPPORT	0.00	\$76.20	0.00	\$0.00	Replace	Check	X
5321447050	SUPPORT, RADIATOR UPPER LH	0.00	\$76.70	0.00	\$0.00	Replace	Check	X
5321347050	SUPPORT, RADIATOR UPPER RH	0.00	\$76.70	0.00	\$0.00	Replace	Check	X
8118547691	UNIT, HEADLAMP, LH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	/
8114547691	UNIT, HEADLAMP, RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	/
8105647690	COMPUTER SUBASSY, HEADLAMP, LH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check	X
8101647690	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check	X
5380747020	SEAL SUB-ASSY, RH	0.00	\$50.20	0.00	\$0.00	Replace	Check	X
5380847020	SEAL SUB-ASSY, LH	0.00	\$50.20	0.00	\$0.00	Replace	Check	X
8651047050	HORN ASSY, HIGH	0.00	\$112.80	0.00	\$0.00	Replace	Check	X
8652047030	HORN ASSY, LOW	0.00	\$112.80	0.00	\$0.00	Replace	Check	X
8846010320	AIR CON CONDENSER ASSY	0.00	\$1,317.70	0.00	\$0.00	Replace	Check	X
8871047160	TUBE & ACCESSORY	0.00	\$574.40	0.00	\$0.00	Replace	Check	X
8870347080	HOSE SUB-ASSY, DISCHARGE	0.00	\$337.10	0.00	\$0.00	Replace	Check	X
8870447100	HOSE SUB-ASSY, SUCTION	0.00	\$541.90	0.00	\$0.00	Replace	Check	X
8870747090	PIPE SUB-ASSY, SUCTION	0.00	\$389.60	0.00	\$0.00	Replace	Check	X
8868847710	BRACKET, COOLER REFRIGERANT HOSE,	0.00	\$13.20	0.00	\$0.00	Replace	Check	X
8868847700	BRACKET, COOLER REFRIGERANT HOSE,	0.00	\$18.70	0.00	\$0.00	Replace	Check	X
	COOLANT	0.00	\$12.30	0.00	\$0.00	Replace	Check	X
5380147080	FENDER SUB-ASSY, FR, RH	1.00	\$933.10	25.00	\$699.83	Replace	Replace	/
7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace	/
5382747050	PROTECTOR, FR FENDER RH	0.00	\$90.40	0.00	\$0.00	Replace	Check	X
5387547070	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Check	X
5385147061	PAD, FR WHEEL RH	0.00	\$57.70	0.00	\$0.00	Replace	Check	X
5370147111	APRON SUB-ASSY, FRONT FENDER, RH	0.00	\$944.20	0.00	\$0.00	Replace	Check	X
5710147070	MEMBER SUB-ASSY, FR RH	0.00	\$2,012.70	0.00	\$0.00	Replace	Check	X
5710247090	MEMBER SUB-ASSY, FR LH	0.00	\$1,959.50	0.00	\$0.00	Replace	Check	X
	TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace	/
42611-47450	WHEEL, DISC FRONT	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair	/
4260247180	CAP SUB-ASSY, WHEEL	0.00	\$175.80	0.00	\$0.00	Replace	Not Given	X
4851080815	ABSORBER SET, SHOCK, FRONT RH	0.00	\$398.10	0.00	\$0.00	Replace	Check	X
4321147040	KNUCKLE, STEERING, RH	0.00	\$555.20	0.00	\$0.00	Replace	Check	X
4355047020	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Check	X
4882047040	LINK ASSY, FRONT STABILIZER, RH & LH	0.00	\$196.70	0.00	\$0.00	Replace	Check	X
4806847060	LOWER ARM SUBASSY, FRONT RH	0.00	\$631.60	0.00	\$0.00	Replace	Check	X
4333019115	JOINT ASSY, LWR BALL, RH & LH	0.00	\$200.10	0.00	\$0.00	Replace	Check	X
4341047040	SHAFT ASSY, FRONT DRIVE, RH	0.00	\$1,295.70	0.00	\$0.00	Replace	Check	X
4504649255	END SET, TIE ROD, RH	0.00	\$155.90	0.00	\$0.00	Replace	Check	X
4551047140	GEAR ASSY, STEERING	0.00	\$1,620.70	0.00	\$0.00	Replace	Check	X



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63685592
Estimator Telephone Number: 68682823
Accident Reporting Number: 68682872

Date Generated: 03/10/2018
User ID: PohSuan

7585047910	MOULDING ASSY, BODY ROCKER PANEL, RH	0.00	\$578.00	0.00	\$0.00	Replace	Check	X
5816547030	COVER, FRONT FLOOR UNDER, RH	0.00	\$427.30	0.00	\$0.00	Replace	Check	X
5816647030	COVER, FRONT FLOOR UNDER, LH	0.00	\$425.50	0.00	\$0.00	Replace	Check	X
5839047010	COVER ASSY, CENTER FLOOR UNDER, RH	0.00	\$306.90	0.00	\$0.00	Replace	Check	X
5762847020	COVER ASSY, CENTER FLOOR UNDER, LH	0.00	\$390.20	0.00	\$0.00	Replace	Check	X
6563147080	PLATE, REAR WHEEL HOUSE, FRONT RH	0.00	\$26.80	0.00	\$0.00	Replace	Check	X
6700147152	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,249.60	100.00	\$0.00	Replace	Repair	R
	STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	
6700347210	PANEL SUB-ASSY, REAR DOOR, RH	0.00	\$1,243.90	0.00	\$0.00	Replace	Not Given	X
	PIXEL STICKER	0.00	\$60.00	0.00	\$0.00	Replace	Not Given	X
6160147150	PANEL SUB-ASSY, FENDER REAR RH	0.00	\$824.80	0.00	\$0.00	Replace	Check	X
6563747060	LINER, REAR FENDER, RH	0.00	\$135.80	0.00	\$0.00	Replace	Check	X
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
4261147450	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Check	X
4260247180	CAP SUB-ASSY, WHEEL	0.00	\$175.80	0.00	\$0.00	Replace	Not Given	X
4853080791	ABSORBER SET, SHOCK, REAR RH & LH	0.00	\$116.80	0.00	\$0.00	Replace	Check	X
4877047010	ARM ASSY, UPPER CONTROL, REAR RH	0.00	\$352.40	0.00	\$0.00	Replace	Check	X
4873047010	ARM ASSY, REAR SUSPENSION, NO.2 RH &	0.00	\$497.50	0.00	\$0.00	Replace	Check	X
4230447050	CARRIER SUB-ASSY, REAR AXLE, RH	0.00	\$802.70	0.00	\$0.00	Replace	Check	X
4871047010	ARM ASSY, REAR SUSPENSION, NO.1 RH &	0.00	\$200.80	0.00	\$0.00	Replace	Check	X
4876047010	ARM ASSY, TRAILING, REAR RH	0.00	\$239.70	0.00	\$0.00	Replace	Check	X
4883047010	LINK ASSY, REAR STABILIZER, RH & LH	0.00	\$149.40	0.00	\$0.00	Replace	Check	X
5215947913	COVER, RR BUMPER ASSY	0.00	\$423.90	0.00	\$0.00	Replace	Check	X
5256647900	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Check	X
5256547900	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	X
5257647040	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Check	X
5257547040	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given	X
5380247100	FENDER SUB-ASSY, FR, LH	1.00	\$933.10	25.00	\$699.83	Replace	Replace	
7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace	
5382847070	PROTECTOR, FR FENDER LH	1.00	\$90.40	25.00	\$67.80	Replace	Replace	
5387647110	LINER, FR FENDER, LH	1.00	\$194.30	25.00	\$145.73	Replace	Replace	
5385247041	PAD, FR WHEEL LH	1.00	\$57.70	25.00	\$43.28	Replace	Replace	
5370247101	APRON SUB-ASSY, FRONT FENDER, LH	0.00	\$944.20	0.00	\$0.00	Replace	Check	X
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
42611-47450	WHEEL, DISC FRONT	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair	R
4260247180	CAP SUB-ASSY, WHEEL	0.00	\$175.80	0.00	\$0.00	Replace	Not Given	X
Total			\$122,989.96		\$13,196.21			

13,196.21
+ 1,800.00
+ 2,370.00
17,366.21

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									