



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

02 May 2019

QUOT201905-000002
HHTPCLAIMS19-64

LONPAC INSURANCE BHD.
300 BEACH RD, #17-04/07
THE CONCOURSE
SINGAPORE 199555

Attn: Motor Claims Department

ACCIDENT INVOLVING SKW3080Y & GZ2296E ON 11/04/2019 AT 71 PIONEER RD (TUAS AMENITY CENTRE) CARPARK AT ABOUT 1230 HOURS

Insured : SALINA
Vehicle Registration No. : SKW3080Y
Vehicle Make : HONDA
Vehicle Model : ODYSSEY 2.4 EXV-S CVT SR
Vehicle Chassis No. : JHMRC1890FC204964
Policy No. : 5084615042-02
Date of Accident : 11/04/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Front Bumper <i>CVT</i>		\$ 696.30
2	10	Front Bumper Clip <i>nee</i>	\$ 3.90	\$ 39.00 30
3	1	Front Bumper Retainer (RH) <i>un x</i>		\$ 22.50
				\$ 757.80
			Less 20%	\$ 151.56
				\$ 606.24
		To dismantle & change front bumper.		\$ 300.00 200
		To spray front bumper and front RH fender.		\$ 500.00 400
				\$ 1,406.24
			7% GST	\$ 98.44
			Total	\$ 1,504.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Authorised by Claims Dept

Hue Jie - LKK
24/6/19

U/S 3days

[Signature]

Total - \$950/-