

ASS. REC. BY:

REF:

TMI/ 003/TMI19007710/Ksd3⁵²

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SMG 2768P

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$72,842.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 5385RYr Regn: 01, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: 707 Renault Latitude

c.c.

1798Colour: M. White / R.

A/C:

Insured / Std / NI / NA

Sp. Reading: 41052

T/Radio:

Insured / Std / NI / NA

Eng/No: JTD KB 3FU 903078P22C/No: VI-19615A06Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: M1 / S/Rim / STD A/Rim orTyre Size: F: 155/55R15 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 28/4/19

Survey held at

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 30/4/19

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

SHD 5385R - 003/FEI/SC05054/Kvhd1

SMG 2768P x

Date: 8/12/19

3/5/19

Email to TMI

RECEIVED 13 JUN 2019

13/6 8 2441.65 Lummi

C 34. 8 34,476.82 Red - 94%)

Date/Time, File Pass to?

13/06/19

1)

Type: 54

Date/Time, File Return to?

☐ : Prell. Report☒ : Final ReportDays Of Repair: 2Resurvey No. of Trip: 1Survey Fee: 250

Transportation: _____

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$ 2,441.65)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 3 May 2019 8:29 AM
To: SUR; motorclaims@tokiomarine.com.sg
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD,
DOA: 28/4/2019, SHD 5385R (TP VEHICLE), SMG 2768P (OI VEHICLE)
Attachments: EST.pdf; GIA.pdf; POLICE REPORT.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 5385R at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 30/4/2019

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler on behalf of Shirley

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/04/2019 11:43
Date Of Accident	28/04/2019 19:10
Exact Location Of Accident	ECP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD5385R
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.8 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	KEE TIEN TECK
NRIC No	S8135845A
Date Of Birth	26/10/1981
Occupation	OUTDOOR
Date Of Driving Pass	10/08/2011
Driving Experience	7 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87267507
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 676A YISHUN RING ROAD #02-1910
Postcode	761676
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : MALE
Passenger 4	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOUGANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 60 HOUGANG AVE 9 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4890999 - FAX NO: 63128989
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please see the attach Police Report T/20190428/2077.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMG2768P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	KEE TIEN TECK
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHD5385R
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Amenda
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

per see attach police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Amanda
Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Police Report Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190428/2077

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

1 of 3

Report No. T/20190428/2077

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/04/2019 20:44		Vide Report No.:		Station Diary No.: 146
Informant's Particulars				
Name of Informant: KEE TIEN TECK		Address: APT BLK 676A YISHUN RING ROAD #02-1910 SINGAPORE 761676		
ID Type / ID No.: NRIC NO / S8135845A		Contact No.: Home/Office: Mobile: 87267507		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 37	Date of Birth: 26/10/1981	Type of Informant: Driver	
Race: Chinese		Language:	Institution / School Name:	
Occupation: Taxi driver		Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident				
Type of Accident: Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 28/04/2019 19:10	Type of Location: Straight Road	
Location: Along Road 1 EAST COAST EXPRESSWAY				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume:		
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD5385R	Car					4
SMG2768P	Car					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190428/2077

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

3 of 3

Report No. T/20190428/2077

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 KOH PEI QI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 28/04/2019 20:44
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt IRMAN BIN MOHAMAD SAID SN 005 Contact No.: 65476145	Classification Of Case:
Authentication Stamp NP168	Signature

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD5385R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B96580
Chassis No.:	JTDKB3FU903078922
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	11 Jan 2019
First Registration Date:	11 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jan 2027
PARF Rebate Amount:	\$10,685.00

Intended COE Rebate Details

COE Expiry Date:	10 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$20,838.00
COE Rebate Amount:	\$16,670.00
Total Rebate Amount:	\$27,355.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 29 Apr 2019

OK

Trans-cab Auto Services Pte Ltd

AAD1904-263

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5385R

*Not Authorised**Resurvey B4 paint
82441.65*

Vehicle No.:

SHD 5385R

Chassis No.:

JTDKB3FU903078922

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

28.4.2019

Third Party Insurer :

TOKIO MARINE

Date of Registration :

11/1/2019

PART**LIST**

1	1 FRONT BUMPER	\$	<i>Bu</i> 499.90 ✓
2	1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	<i>Sn</i> 101.20 X
3	1 REINFORCEMENT, FRONT BUMPER	\$	<i>A</i> 696.40 X
4	1 ABSORBER, FRONT BUMPER, LOWER	\$	<i>Sn</i> 130.20 ✓
5	1 ABSORBER, FRONT BUMPER ENERGY	\$	<i>Sn</i> 78.10 X
6	1 FRONT BUMPER SIDE RETAINER RH	\$	<i>D.I</i> 78.00 X
7	1 FRONT BUMPER SIDE RETAINER LH	\$	<i>Sub</i> 78.00 X
8	1 FRONT BUMPER SUPPORT	\$	<i>Sn</i> 81.70 X
9	1 EXTENSION, FRONT BUMPER, RH	\$	<i>Sn</i> 117.80 X
10	1 EXTENSION, FRONT BUMPER, LH	\$	<i>Sn</i> 117.80 X
11	1 FRONT LED LAMP (LOWER) RH	\$	<i>Sn</i> 907.75 X
12	1 FRONT LED LAMP (LOWER) LH	\$	<i>Sn</i> 907.75 X
13	1 FRONT HEADLAMP RH	\$	<i>Sn</i> 2,909.04 X
14	1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	<i>Sn</i> 492.30 X
15	1 MOTOR, HEADLAMP LEVELING, RH	\$	<i>Sn</i> 413.10 X
16	1 FRONT HEADLAMP LH	\$	<i>Sn</i> 2,909.04 X
17	1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	<i>Sn</i> 492.30 X
18	1 MOTOR, HEADLAMP LEVELING, RH	\$	<i>Sn</i> 413.10 X
19	1 FRONT FENDER RH	\$	<i>B</i> 945.30 ✓
20	1 EXTENSION, FRONT FENDER, RH	\$	<i>A</i> 48.80 X
21	1 COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$	<i>Sn</i> 98.30 X
22	1 LINER, FRONT FENDER, RH	\$	<i>D.I</i> 200.70 ✓
23	1 FRONT FENDER EMBLEM RH	\$	<i>Mr</i> 86.50 ✓
24	1 SEAL, FENDER APRON MUDGUARD, RH	\$	<i>Sn</i> 50.90 X
25	1 FRONT BONNET	\$	<i>A</i> 950.50 X
26	1 FRONT LOWER ARM	\$	<i>Sn</i> 631.90 X
27	1 FRONT SHOCK ABSORBER	\$	<i>Sn</i> 398.20 X
28	1 SHAFT ASSY, FRONT DRIVE, RH	\$	<i>A</i> 1,186.20 X
29	1 ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH	\$	<i>Sn</i> 637.50 X

Trans-cab Auto Services Pte Ltd

AAD1904-263

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5385R

30	1 KNUCKLE, STEERING, RH	\$	562.30	} X
31	1 LINK ASSY, FRONT STABILIZER, RH	\$	199.00	
32	1 BAR, STABILIZER, FRONT	\$	360.30	
33	1 SUPPORT SUB-ASSY, FRONT SUSPENSION, RH	\$	200.60	
34	1 ABSORBER ASSY, SHOCK, FRONT RH	\$	401.80	
35	1 COCK ASSY, RESERVE TANK	\$	117.80	
		\$	18,500.08	
25%		\$	4,625.02	
		\$	13,875.06	

Special Nett

1	1 FRONT WHEEL RIM	\$	1,570.55	X
2	1 FRONT WHEEL RIM COVER → 256	\$	175.80	✓
3	1 CLIP, FRONT FENDER LINER	\$	22.00	✓
TOTAL		\$	1,768.35	
TOTAL PARTS		\$	15,643.41	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	4,200.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	4001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To transfer of Fender fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1904-263**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5385R

To transfer of front windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	601
To vacuum, replace, refix and recharge air condenser	\$	nn 380.00	X
To replace, refix and top up coolant for radiator	\$	~ 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	~ 170.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	~ 380.00	X

TOTAL \$ 10,400.00**Over All Total \$ 39,918.47**

26043.41

(PART-BY-PART) Repair Days

14 days

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 May 2019		03 May 2019 10:35 Edit Adj Rpt	S\$2,441.65 Edit Estimates	S\$2,441.65 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LUMENS AUTO PTE. LTD., Co. Reg. No.: 201426961K		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD5385R	Date of Loss:	28/04/2019 19:00 - :59 [3 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1903138	Policy/Cover Note No.:	MJ001357 (Third Party Only) Coverage: 30/09/2018 - 29/09/2019
Vehicle Reg. No. (Insured):	SMG2768P	Policy No. (Claimant):	
		Excess:	S\$2,000.00
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Jeffrey Tay - 65926413]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 14/05/2019]		
Adj Asg. Remarks:	OUR INSD HAS NOT RPT THE ACCIDENT.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SHD5385R (M1903138)**
[SMG2768P]
TP
TRANS-CAB SERVICES PTE LTD
Apr 28 2019 7:00PM
[LUMENS AUTO PTE. LTD.]
Trans-cab Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/06/19 13:54	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	13/06/19 13:54	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	13/06/19 13:54	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	13/06/19 13:54	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	13/06/19 13:54	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	13/06/19 13:54	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	13/06/19 13:54	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	13/06/19 13:54	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	13/06/19 13:54	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	13/06/19 13:54	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	13/06/19 13:54	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	13/06/19 13:54	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	13/06/19 13:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
14	13/06/19 13:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page ▼ ☒

No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	03/05/19 10:22	GIA	1	Load PDF	
2	03/05/19 10:22	EST	1	Load PDF	
3	03/05/19 10:22	P RPT	1	Load PDF	
4	17/06/19 13:00	Letter of Demand from Third Party	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19007710/KSD3S2

Date: 21/06/2019

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MJ001357

Claimant Vehicle No : SHD5385R

Insured Vehicle No : SMG2768P

Date of Loss: 28/04/2019

Nature of Claim: TP

Claim No: M1903138

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD5385R

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZR2B96580

Reg. Date: 11/01/2019 (Man. Year: 2018)

Chassis No: JTDKB3FU903078922

Colour: Metallic White/Red

Odometer: 41052 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size:

195/65R15

Front Left Side: Goodyear 8 mm

Rear Left Side:

Goodyear 8 mm

Front Right Side: Goodyear 8 mm

Rear Right Side:

Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,643.41	1,511.65	14,131.76	90.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,400.00	930.00	9,470.00	91.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	26,043.41	2,441.65	23,601.76	90.62
+ GST 7.00/7.00% (S\$)	1,823.04	170.92	1,652.12	90.62
Nett Amount (S\$)	27,866.45	2,612.57	25,253.88	90.62

INSPECTION

Date of Assignment: 03/05/2019

Date Inspected: 30/04/2019 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Jun 2019)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD5385R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	499.90 FL	*499.90 FL
2	1		*BRACKET,FRONT BUMPER EXTENSION MOUNTING	Serviceable	101.20 FL	*- FL
3	1		*REINFORCEMENT,FRONT BUMPER	Repair	696.40 FL	*- FL
4	1		*ABSORBER,FRONT BUMPER,LOWER	Serviceable	130.20 FL	*- FL
5	1		*ABSORBER,FRONT BUMPER,ENERGY	Serviceable	78.10 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	78.00 FL	*78.00 FL
7	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	78.00 FL	*- FL
8	1		*FRONT BUMPER SUPPORT	Serviceable	81.70 FL	*- FL
9	1		*EXTENSION,FRONT BUMPER,RH	Serviceable	117.80 FL	*- FL
10	1		*EXTENSION,FRONT BUMPER,LH	Serviceable	117.80 FL	*- FL
11	1		*FRONT LED LAMP (LOWER) RH	Serviceable	907.75 FL	*- FL
12	1		*FRONT LED LAMP (LOWER) LH	Serviceable	907.75 FL	*- FL
13	1		*FRONT HEADLAMP RH	Serviceable	2,909.04 FL	*- FL
14	1		*COMPUTER SUB-ASSY.HEADLAMP,RH NO 1	Serviceable	492.30 FL	*- FL
15	1		*MOTOR HEADLAMP LEVELING,RH	Serviceable	413.10 FL	*- FL
16	1		*FRONT HEADLAMP LH	Serviceable	2,909.04 FL	*- FL
17	1		*COMPUTER SUB-ASSY.HEADLAMP,RH NO 1	Serviceable	492.30 FL	*- FL
18	1		*MOTOR HEADLAMP LEVELING,RH	Serviceable	413.10 FL	*- FL
19	1		*FRONT FENDER RH	Bent	945.30 FL	*945.30 FL
20	1		*EXTENSION,FRONT FENDER,RH	Repair	48.80 FL	*- FL
21	1		*COVER SUB-ASSY,FRONT PILLAR,UPR RH	Serviceable	98.30 FL	*- FL
22	1		*LINER,FRONT FENDER,RH	Distorted	200.70 FL	*200.70 FL
23	1		*FRONT FENDER EMBLEM RH	Necessary	86.50 FL	*86.50 FL
24	1		*SEAL,FENDER APRON MUDGUARD,RH	Serviceable	50.90 FL	*- FL
25	1		*FRONT BONNET	Repair	950.50 FL	*- FL
26	1		*FRONT LOWER ARM	Serviceable	631.90 FL	*- FL
27	1		*FRONT SHOCK ABSORBER	Serviceable	398.20 FL	*- FL
28	1		*SHAFT ASSY,FRONT DRIVE,RH	Repair	1,186.20 FL	*- FL
29	1		*ARM SUB-ASSY,FRONT SUSPENSION LOWER NO 1 RH	Serviceable	637.50 FL	*- FL
30	1		*KNUCKLE STEERING,RH	Serviceable	562.30 FL	*- FL
31	1		*LINK ASSY,FRONT STABILIZER,RH	Serviceable	199.00 FL	*- FL
32	1		*BAR,STABILIZER FRONT	Serviceable	360.30 FL	*- FL
33	1		*SUPPORT SUB-ASSY,FRONT SUSPENSION,RH	Serviceable	200.60 FL	*- FL
34	1		*ABSORBER ASSY,SHOCK,FRONT RH	Serviceable	401.80 FL	*- FL
35	1		*COCK ASSY,RESERVE TANK	Serviceable	117.80 FL	*- FL
36	1		*FRONT WHEEL RIM	Serviceable	1,570.55 FS	*- FS
37	1		*FRONT WHEEL RIM COVER	Dented	175.80 FS	*131.85 FS
38	1		*CLIP,FRONT FENDER LINER	Necessary	22.00 FS	*22.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,268.43	1,964.25
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,625.02	452.60

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					15,643.41	1,511.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,200.00	440.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,200.00	400.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
5	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
8	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER	New	380.00	0.00
9	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
10	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER	New	170.00	0.00
11	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT,VACUUM AND CHARGE-IN-GAS	New	380.00	0.00
Gross Labour Cost (\$\$)			10,400.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >