

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 EMAIL: atautoconsultant@gmail.com
Co. Reg. No. : 53368526E

Date of Estimate: 29.04.2019
Vehicle No: SLS7860X
Owner: ISLAND CAR RENTAL & LEASING PTE LTD
Date of Accident: 28.04.2019
Make & Model: BMW 740LI 3.0
Chassis No : WBAKB42080CY83090

Not Withheld
L1 Imp 8?
Resurvey After Paint
4 days
Kenneth
96910663

ESTIMATE FOR ACCIDENT VEHICLE NO SLS7860X

PARTS

- | | |
|---|-----------------------------------|
| 1 | 1 Front bumper |
| 2 | 1 Front bumper fog lamp grille RH |
| 3 | 1 Front bumper retainer RH |
| 4 | 1 Headlamp RH |
| 4 | 1 Front fender RH |

SUB TOTAL
LESS 5%
DISCOUNTED SUB TOTAL

Bulb	\$1,930.00	✓
	\$188.00	✓
m	\$68.00	✓
Car	\$3,339.00	✓
n	\$1,556.00	X
	<u>\$7,081.00</u>	
	\$354.05	
	<u>\$6,726.95</u>	

S. NETT ITEM

- | | |
|---|--------------------------------|
| 1 | 1set Rear bumper clips |
| 2 | 1pc Front sensor |
| 3 | 1pc Front 360 blindspot cam RH |

SUB TOTAL
LESS 0 %
DISCOUNTED SUB TOTAL

m	\$60.00	✓
sun	\$410.00	✓
	\$668.00	✓
	<u>\$1,138.00</u>	
	\$0.00	
	<u>\$1,138.00</u>	

LABOUR

- | | |
|---|---|
| 1 | Panel beating for replace and repair affected parts |
| 2 | Spray painting on accident areas |
| 3 | Wiring charges |
| 4 | Reprogramming 360 cam |
| 5 | Apply undercoating to above affected areas |

SUB TOTAL (LABOUR)

	\$800.00	400l
	\$800.00	500l
	\$100.00	20l
	\$250.00	✓
n	\$250.00	X
	<u>\$2,200.00</u>	

SUB TOTAL (PARTS)	\$6,726.95
SUB TOTAL (S.NETT)	\$1,138.00
SUB TOTAL (LABOUR)	\$2,200.00
ESTIMATED GRAND TOTAL	\$10,064.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: