

Kg

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
 HP: 8386 8989 EMAIL: atautoconsultant@gmail.com
 Co. Reg. No. : 53368526E

Date of Estimate: 29.04.2019
 Vehicle No: SLS7860X
 Owner: ISLAND CAR RENTAL & LEASING PTE LTD
 Date of Accident: 28.04.2019
 Make & Model: BMW 740LI 3.0
 Chassis No : WBAKB42080CY83090

Not Notarise
 L1Lmp 85400h
 Purnny Abu Parnt
 4 day

Henrich
 96910883

Henrich ~~Henrich~~ Henrich@1kkauto.com

ESTIMATE FOR ACCIDENT VEHICLE NO SLS7860X

PARTS

- | | | |
|---|-----------------------------------|---------|
| 1 | 1 Front bumper | 1850L |
| 2 | 1 Front bumper fog lamp grille RH | |
| 3 | 1 Front bumper retainer RH | |
| 4 | 1 Headlamp RH | 3050.00 |
| 4 | 1 Front fender RH | |

SUB TOTAL
 LESS 5%
 DISCOUNTED SUB TOTAL

Bud na	\$1,930.00	✓
Sm	\$188.00	X
m	\$68.00	✓
cn	\$3,339.00	✓
n	\$1,556.00	X
	<u>\$7,081.00</u>	
	<u>\$354.05</u>	
	<u>\$6,726.95</u>	

S. NETT ITEM

- | | | |
|---|--------------------------------|--------|
| 1 | 1set Rear bumper clips | |
| 2 | 1pc Front sensor | 265.00 |
| 3 | 1pc Front 360 blindspot cam RH | |

SUB TOTAL
 LESS 0 %
 DISCOUNTED SUB TOTAL

m	\$60.00	✓
sn	\$410.00	✓
scn	\$668.00	✓
	<u>\$1,138.00</u>	
	<u>\$0.00</u>	
	<u>\$1,138.00</u>	

LABOUR

- | | |
|---|---|
| 1 | Panel beating for replace and repair affected parts |
| 2 | Spray painting on accident areas |
| 3 | Wiring charges |
| 4 | Reprogramming 360 cam |
| 5 | Apply undercoating to above affected areas |

SUB TOTAL (LABOUR)

	\$800.00	4001
	\$800.00	5001
	\$100.00	201
	\$250.00	7201
nn	\$250.00	X
	<u>\$2,200.00</u>	

SUB TOTAL (PARTS)	\$6,726.95
SUB TOTAL (S.NETT)	\$1,138.00
SUB TOTAL (LABOUR)	\$2,200.00
ESTIMATED GRAND TOTAL	\$10,064.95

Sub
 fender bracket

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 EMAIL: atautoconsultant@gmail.com
Co. Reg. No. : 53368526E

Date of Estimate: 29.04.2019
Vehicle No: SLS7860X
Owner: ISLAND CAR RENTAL & LEASING PTE LTD
Date of Accident: 28.04.2019
Make & Model: BMW 740Li 3.0
Chassis No : WBAKB42080CY83090

SUPPLEMENTARY ESTIMATE FOR ACCIDENT VEHICLE NO SLS7860X

SUPPLEMENTARY PARTS

1 1 Front fender bracket RH

SUB TOTAL
LESS 5%
DISCOUNTED SUB TOTAL

DIT \$138.00 ✓
\$138.00
\$6.90
\$131.10

SUB TOTAL (SUB PARTS) \$131.10

ESTIMATED GRAND TOTAL \$131.10