

Trans-cab Auto Services Pte Ltd

AAD1904-266

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9909P

Not Authored
11/12/19 & 33501

Vehicle No.:	SHB 9909P
Chassis No.:	VF1ABL15AUC273469
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	29.4.2019
Third Party Insurer :	TOKIO MARINE
Date of Registration :	30/8/2013

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>DIT</i> 181.75 ✓
1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68 X
1	BUMPER RETAINER FRT RH	\$	<i>DIT</i> 150.77 ✓
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88 X
1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80 X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
1	HEADLAMP RH	\$	<i>mycom</i> 1,184.43 ✓
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
1	FENDER PANEL FRT RH	\$	<i>Bu</i> 783.83 ✓
1	WHEELARCH FRT RH	\$	<i>SL</i> 278.84
1	FENDER BRACKET LOWER RH	\$	<i>SL</i> 15.79
1	FENDER INSULATOR RH	\$	<i>SL</i> 130.84
1	WIPER RESERVOIR	\$	<i>SL</i> 348.25
1	WIPER RESERVOIR NECK	\$	<i>SL</i> 136.11
1	WIPER RESERVOIR MOTOR	\$	<i>SL</i> 270.06
1	RADIATOR GRILLE	\$	<i>SL</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75
1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 615.90
1	FRAME FULL SUPPORT BRACKET	\$	<i>SL</i> 89.79

TOTAL	\$	11,264.31
10%	\$	1,126.43
TOTAL	\$	10,137.88

Trans-cab Auto Services Pte Ltd**AAD1904-266**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9909P**Specical Nett**

1SET	BUMPER CLIP FRT	\$	<i>nn</i> 66.00 ✓
1	BUMPER BRACKET CLIP FRT RH	\$	<i>nn</i> 12.00 X
1	BUMPER SUPPORT CLIP FRT RH	\$	<i>nn</i> 10.50 X
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>nn</i> 69.00 X
		\$	157.50

TOTAL PARTS \$ 10,295.38**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00 <i>400</i>
Putty and spray painting of the affected portion.	\$	3,000.00 <i>440</i>
To rust-proofing of the affected areas.	\$	170.00 <i>30</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 <i>20</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00 X
To replace, refix and top up coolant for radiator	\$	<i>nn</i> 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1904-266**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9909P

To vacuum, replace, refix and recharge Air
Intercooler

\$ *nn* 170.00 X

TOTAL	\$	8,210.00
--------------	-----------	-----------------

Over All Total	\$	18,505.38
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~10 DAYS~~*2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey must be on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: